

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Owner : Muhammad Luqman
Bin Abdullah

Accident Date : 27 Jul 2018

Vehicle No : FT 7147 M

Vehicle Model : Yamaha RXZ

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender	\$ 65.00
2	Fork inner tubes	\$ 210.00
2	Fork outer tubes	\$ 220.00
1	Fork under bracket	\$ 145.00
1	Front brake disc	\$ 135.00
1	Front rim	\$ 150.00
1	Front rim spooky (1 set)	\$ 60.00
1	Front rim shaft	\$ 38.00
1	Top cowling	\$ 85.00
1	Windshield	\$ 32.00
1	Lamp stay	\$ 50.00
1	Headlamp	\$ 70.00
2	Side mirrors	\$ 70.00
2	Front signals	\$ 80.00
2	Handle bars	\$ 136.00
1	Hand grip (1 set)	\$ 35.00
2	Handle bar ends	\$ 36.00
1	Brake lever	\$ 25.00
1	Clutch lever	\$ 25.00
1	Meter assy	\$ 420.00
1	Fuel tank	\$ 400.00
1	Front footrest -L/H	\$ 32.00
1	Front footrest bracket	\$ 55.00
1	Gear pedal	\$ 32.00
1	Rear footrest -L/H	\$ 28.00
1	Rear tailboard -L/H	\$ 70.00
1	Rear taillamp	\$ 75.00
		\$ 2,779.00
	Less 10%	\$ 277.90
		\$ 2,501.10

Special Nett Items

1	Number plate (1 set)	\$	scr	28.00	10
2	Fork oils	\$	ru	30.00	/
2	Fork oil seals	\$	ru	56.00	/
1	Steering cone (1 set)	\$	ru	75.00	/
1	ERP IU	\$	src	170.00	X
		\$		359.00	

S/No. **Labour**

1	To provide towing service.	\$	35	50.00
2	To provide labour.	\$	280	380.00
3	To repair body frame.	\$	17	350.00
		\$		780.00

Grand Total

\$ 3,640.10

Dollars: Three Thousand Six Hundred Forty And Ten Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: