



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE

Company Registration No. 201118055N

ESTIMATE

Weltronics Marketing
Singapore

Contact: 98300986

TP 111
Vivian

Code: C101844

Date in: 06/10/2018

Vehicle Num.: PC6913X

Model: Mercedes Benz V220 CDI Extra-Long

AT

Chassis/Eng#: WDF44781523342690/65195034230638

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Rear Bumper <i>Reh d</i>	1	1430.00	1780 1430.00 ✓
Rear Bumper Reverse Sensor <i>1 piece damaged</i>	3	185.00	555.00 185 ✓
Rear Bumper Side Reflector RH <i>Not in</i>	1	58.00	58.00 ✓
Rear Bumper Side Retainer RH <i>in</i>	1	68.00	68.00 ✓
Rear Tailgate <i>Dented</i>	1	2065.00	1892 2065.00 ✓
Rear Tailgate 'Logo' Emblem <i>3 pieces</i>	1	48.00	48.00 ✓
Rear Tailgate 'V220d' Emblem	1	58.00	58.00 ✓
Rear Taillamp RH <i>Not in</i>	1	745.00	745.00 ✓
Subtotal before discount			5,027.00
Percentage discount 10%			502.70
Sub-total 1			4,524.30
Rear Bumper Clips (Set)(SN) <i>Not in</i>	1	50.00	50.00 30 ✓
Rear Bumper Protector (SN) <i>Not in</i>	1	120.00	120.00 20 ✓
Rear Tailgate '70km/h' Sticker (SN) <i>Not in</i>	1	25.00	25.00 15 ✓
Subtotal before discount			195.00
Percentage discount 0%			0.00
Sub-total 2			195.00
Parts-total			4,719.30



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE  PERFORMANCE

Company Registration No. 201118055N

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	100.00 30
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	120.00 50
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	600.00 400
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	880. 600.00 400
To apply anti-rust chemical on repaired and replaced panel.	80.00 x
Labour Total	1,500.00
Parts & Labour Total	6,219.30

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim, 96893735
1/s 09/10/18.

04 Days.

total: 4181.10

H/s: 3.3k.

3.3k