

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.08.2018

Time: 17:00:42

Page: 1

AXA-4S

TS
1710

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305194890
 REGN NO : SHD4809S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 31.08.2013
 DATE/TIME IN : 01.08.2018 12:15
 ACCIDENT DATE : 01.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	Ry
0002 04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	49.00	20.00	39.20	✓
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	✓
0004 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00	200	50.00	net

SUB-TOTAL : 589.68

JOB NATURE

0000 L	PANEL BEATING	280.00	200
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	✓
0002 L	R/I REVERSE SENSOR	120.00	30

SUB-TOTAL : 600.00

TOTAL : 1,189.68

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

LKK Auto Consultants Pte Ltd
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjil 97495749
 WP
 2/8/18 @ 430pm
 02 days
 Resurvey after repair
 sur@lkkauto.com