

2/10/2017

ASS. REC. BY:

REF: 033/LPC18009490/Nid3-1

Special Instruction:

Paper Survey

Surveyor

Naz

ASSIGNMENT (Office)

From (Person):

Eric WOO

of

LPC

Date/Time: 02/08/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GV 13696

Insured:

YL 98036

at Workshop m/s

Cosmopolitan

Tel:

6546 7728 / 90264369

of

4 Leyang Walk

Policy No:

Claim No:

18/18/18/VC00/020628

Sum Insured:

Excess:

Make of Veh:

D.O.A

09042018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

24/05/2018 2:01pm

Person Contacted:

Michael

Vehicle

C/L OUT

Date/Time	Action/Instruction (X) Estimate
	GV 13696 - X
	YL 98036 - X
1/6/18	Submit PRS report
	Naz,

Pls see my remarks.

3/9/18 Submit LS \$1850 (Red 700, 279), 5 days

31/8/2018

RECEIVED 03 SEP 2018

Naz

NGP

LPC

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop no: _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Job No: GV 13646 Page: 6 DEC 2001
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI L300 No: 2477
Colour: WHITE A/C: Insured / Std / Nil / NA
Sp. Reading: 361,014 "Pacq: Insured / Std / Nil / NA
Eng No: _____
C.No: JMAJNP15VYAC001589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 A14 C
R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front	Rear
R/Bal. <u>4</u> mm	R/Bal. <u>0</u> mm
L/Bal. <u>4</u> mm	L/Bal. <u>4</u> mm
D.O.A. <u>9/4/18</u>	D.O.I. <u>24/1/18 @ 09:56 PM</u>

Survey held at CORPORATE ENCL 5

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 0-1 JUL 2018

Date/Time File Pass to: ☐ : Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Date/Time File Return to:

116- typist

Add Fee: ☐ : Site Insp \$

☐ : Inter. \$

☐ : Tech. \$

☐ : Rep. \$

Report Format: PRS

Lump Sum (L.B.): \$

Transporter

3-PR

Photo

Draw

1190
1190

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 2 August 2018 2:35 PM
To: assignments@lkkauto.com; 'Nivitha (LKK Auto)'
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/18/18/VC00/020628 Your Ref: CL/180533/T/COS.sg Accident involving YL9803G & GV1369G at Parkway Loading Bay on 9/4/18
Attachments: 02082018143014.pdf

Hi Nivitha

We attach TP survey report and photographs for your surveyor's comment.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: ERIC WOO JUN KIAT
Sent: Wednesday, 23 May, 2018 4:56 PM
To: assignments@lkkauto.com
Cc: Sally; MT_Claim_SG
Subject: FW: Our Ref: 18/18/18/VC00/020628 Your Ref: CL/180533/T/COS.sg Accident involving YL9803G & GV1369G at Parkway Loading Bay on 9/4/18

Dear Catherine / Nivitha,

Please take note of the name of workshop for survey.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Sally [<mailto:info@catherinelimllc.com>]
Sent: Wednesday, 23 May, 2018 4:50 PM
To: ERIC WOO JUN KIAT
Subject: RE: Our Ref: 18/18/18/VC00/020628 Your Ref: CL/180533/T/COS.sg Accident involving YL9803G & GV1369G at Parkway Loading Bay on 9/4/18

Dear Eric

Name of workshop is – Cosmopolitan.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01

Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]
Sent: Wednesday, May 23, 2018 2:23 PM
To: Sally
Cc: assignments@lkkauto.com; MT_Claim_SG
Subject: RE: Our Ref: 18/18/18/VC00/020628 Your Ref: CL/180533/T/COS.sg Accident involving YL9803G & GV1369G at Parkway Loading Bay on 9/4/18

Dear Sally,

Thank you for your list of surveyors.

We regret we are not agreeable to your panel of surveyor as listed.

We shall be assigning to LKK Auto Consultants Pte Ltd to conduct the survey on your client's vehicle No: GV 1369G.

Please advise us the name of the workshop to conduct survey.

Dear Catherine / Nivitha,

FYA.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Sally [<mailto:info@catherinelimllc.com>]
Sent: Wednesday, 23 May, 2018 1:57 PM
To: ERIC WOO JUN KIAT
Subject: RE: Our Ref: 18/18/18/VC00/020628 Your Ref: CL/180533/T/COS.sg Accident involving YL9803G & GV1369G at Parkway Loading Bay on 9/4/18

Dear Eric (Without Prejudice)

We refer to your email.

Our client is not agreeable to your list of surveyor and wish to appoint Sebastien Lim as single joint expert.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Wednesday, May 23, 2018 12:20 PM

To: Sally

Cc: MT_Claim_SG

Subject: Our Ref: 18/18/18/VC00/020628 Your Ref: CL/180533/T/COS.sg Accident involving YL9803G & GV1369G at Parkway Loading Bay on 9/4/18

WITHOUT PREJUDICE

SAVE AS TO COST

Dear Sir / Madam,

We refer to your fax of 23 May 2018.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Cosmopolitan Engineering Service Pte Ltd
4 Loyang Walk
Singapore 508787

Date : 05/06/2018

Reference No : CAS/18-06/001

General Information

Registration No. : GV 1369G
Accident Date : 09/04/2018

Particulars of Damaged Vehicle

Colour	: White	Make & Model	: Mitsubishi L300
Engine Capacity	: 2477 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 361007	Engine No.	: 4D56KG4647
Chassis No.	: JMAJNP15VYA001584	Steering	: In Order
Registration Date	: 06/12/2001	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	185R14	FALKEN	30%
L/H Front Tyre	185R14	FALKEN	50%
R/H Rear Tyre	185R14	FALKEN	50%
L/H Rear Tyre	185R14	FALKEN	50%

Inspection

Repairer : Cosmopolitan Engineering Service Pte Ltd
4 Loyang Walk Singapore 508787

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$4,282.70
Revised Amount : \$2,550.00
Less Excess : -
Nett Total : \$2,550.00

Remarks

- (A) Survey was done on 23/05/2018
- (B) Re-survey was done on 25/05/2018
- (C) Re-survey after repair was done on 31/05/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : GV 1369G

Our ref : CAS/18-06/001

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – NETT ITEMS</u>					
1	1pc	Front cab panel	Dented/Warped	836.00	836.00
2	1pc	Front windscreen rubber	Necessary	126.00	126.00
3	2pcs	Front headlamp rim @ \$142.00	Serviceable	284.00	-
4	1pc	Front bumper	Dented/Deformed	641.00	641.00
5	2pcs	Front bumper pad @ \$68.00	Deformed	136.00	136.00
6	1pc	Front bumper reinforcement	Dented/Bent	365.00	365.00
7	1pc	Front chassis crossmember – center	Repair	315.00	-
				2,703.00	2,104.00
		Less 10%		(270.30)	(210.40)
			Sub total	2,432.70	1,893.60
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Front no plate	Damaged	30.00	30.00
			Sub total	2,462.70	1,923.60
<u>LABOUR & MISC. CHARGES</u>					
1		To remove, refix front windscreen		120.00	80.00
2		To check front electrical wiring & refocus headlamp		50.00	20.00
3		To respray undercoating		50.00	30.00
4		To respray painting & etc		800.00	500.00
5		Panel beating, remove & replacing above parts		800.00	600.00
			Grand total	4,282.70	3,153.60
Recommended cost of lump sum repair (To its pre-accident condition)					2,550.00

Constant Appraiser Services

Vehicle No : GV 1369G

Our ref : CAS/18-06/001

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$2,550.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,

Constant Appraiser Services

A handwritten signature in black ink, appearing to read 'Lim Yong Tian (Sebastian)', is written over a circular stamp. The stamp contains the text 'CONSTANT APPRAISER SERVICES' around the perimeter and 'CAS' in the center.

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)


MSAAA

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18009490/Nvd3e2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date : 04-09-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 9803G	Veh. Inspected	GV 1369G	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VC00/020628	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI L300	c.c	2477	
Engine No.	HIDDEN	Year of Reg.	2001	
Chassis No.	JMAJNP15VYA001584	Colour	WHITE	
Odometer	361014	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14C	FALKEN	4 mm	
L/H Front Tyre	185 R14C	FALKEN	4 mm	
R/H Rear Tyre	185 R14C	FALKEN	4 mm	
L/H Rear Tyre	185 R14C	FALKEN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2018	Inspection Date	24/05/2018	
Survey held at	COSMOPOLITAN ENGRG. SERVICES PTE. LTD. 4 LOYANG WALK SINGAPORE 508787			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 1369G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT CAB PANEL	DENTED	836.00	600.00
1	FRONT WINDSCREEN RUBBER	NECESSARY	126.00	126.00
2	FRONT HEADLAMP RIM @\$142.00	SERVICEABLE	284.00	-
1	FRONT BUMPER	CRACKED	641.00	641.00
2	FRONT BUMPER PAD @\$68.00	NECESSARY	136.00	136.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	365.00	-
1	FRONT CHASSIS CROSSMEMBER - CENTER	TO REPAIR SEE LABOUR	315.00	-
	LESS 10% DISCOUNT		-270.30	-150.30
			2,432.70	1,352.70
SPECIAL NETT ITEMS				
1	FRONT NO PLATE (SN)	DENTED	30.00	30.00
			30.00	30.00
LABOUR				
	TO REMOVE, REFIX FRONT WINDSCREEN.		120.00	80.00
	TO CHECK FRONT ELECTRICAL WIRING & REFOCUS HEADLAMP.		50.00	20.00
	TO RESPRAY UNDERCAOTING.		50.00	30.00
	TO RESPRAY PAINTING & ETC.		800.00	400.00
	PANEL BEATING, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT CHASSIS CROSSMEMBER - CENTER.		800.00	400.00
			1,820.00	930.00
GRAND TOTAL			4,282.70	2,312.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CS3/LPC18009490/Nvd3e2-1

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.