

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5871J**AAD1807-262**

1/8118
 Not Notified
 11 Sep 860006

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5871J

VF1ABL15AUC280969

RENAULT

LATITUDE

30.7.2018

EQ**PART****LIST**

1	DOOR PANEL REAR RH	\$	2,844.66	
1	DOOR GUIDE REAR RH	\$	176.82	
1	DOOR HINGE UPPER RH	\$	274.50	
1	DOOR HINGE LOWER RH	\$	300.55	
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06	
1	DOOR LOCK REAR RH	\$	908.75	
1	DOOR HANDLE OUTER REAR RH	\$	126.49	
1	DOOR HANDLE CAP REAR RH	\$	35.52	
1	DOOR HANDLE SEAL REAR RH	\$	7.89	
1	DOOR HANDLE COVER REAR RH	\$	13.22	
1	DOOR HANDLE MODULE REAR RH	\$	133.60	
1	DOOR REGULATOR REAR RH	\$	1,135.10	
1	DOOR REGULATOR MOTOR REAR RH	\$	893.75	
1	DOOR REGULATOR NUT REAR L70Y	\$	12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31	
1	DOOR FINISHER REAR RH	\$	423.10	
1	DOOR MOULDING REAR RH	\$	176.82	
1	DOOR MOULDING CLIP L70Y	\$	5.92	
1	DOOR MOULDING SCREW L70Y	\$	6.91	
1	DOOR CASING REAR RH	\$	1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	30.39	
1	DOOR CASING CLIP	\$	12.63	
1	DOOR CASING LIGHT L70Y	\$	48.74	
1	DOOR FINISHER INNER REAR RH	\$	323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33	
1	DOOR GRAB HANDLE REAR RH	\$	210.96	

X

Trans-cab Auto Services Pte Ltd

AAD1807-262

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5871J

1	DOOR BLIND REAR RH	\$	Sn 741.80 X
1	DOOR WHEATHESTRIIP REAR RH	\$	Oditi 410.66 508m
1	DOOR SEAL REAR RH	\$	Sn 162.02 X
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Sn 229.31 X
1	DOOR WAIST SEAL OUTER REAR RH	\$	Sn 334.69 X
1	DOOR WAIST SEAL INNER REAR RH	\$	Sn 115.64 X
1	FENDER PANEL REAR RH	\$	Bt 3,299.13 ✓
1	FENDER PANEL INNER TRIM REAR	\$	Sn 671.45
1	WHEELARCH REAR RH	\$	N 543.47
1	DOOR MIRROR ASSY RH	\$	Sn 1,483.40
1	ROCKER PANEL INNER GARNISH RH	\$	Sn 466.51
1	ROCKER PANEL INNER RH	\$	N 1,024.79
1	ROCKER PANEL CENTER RH	\$	N 990.25
1	BUMPER COVER REAR	\$	N 1,108.46
1	BUMPER LOWER REAR	\$	Sn 768.84
1	BUMPER BRACKET CTR REAR	\$	Sn 113.47
1	BUMEPR BRACKET SIDE RH REAR	\$	Sn 135.97
1	BUMEPR RETAINER RH REAR	\$	Sn 44.99

	\$	22,573.43
10%	\$	2,257.34
	\$	20,316.08

Specical Nett

2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00 X
1SET	WHEELARCH CLIP FRT LH	\$	nn 30.50 X
1	REAR DOOR STICKER '6555-3333'	\$	nn 80.00 605m
1	DOOR CHECK BOLT	\$	nn 22.69
1	DOOR GUIDE SCREW	\$	nn 10.85
1	DOOR HINGE BOLT	\$	nn 10.85
1	DOOR HINGE NUT RH	\$	nn 14.60
1	DOOR CHECK BOLT	\$	nn 22.69
1	DOOR CHECK NUT	\$	nn 3.75
1	DOOR LOCK SCREW L70Y	\$	nn 6.12
1	DOOR CATCH SCREW L70Y	\$	nn 10.06

Trans-cab Auto Services Pte Ltd

AAD1807-262

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5871J

TOTAL	\$	262.13
-------	----	--------

TOTAL PARTS	\$	20,578.21
-------------	----	-----------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	800
Putty and spray painting of the affected portion.	\$	4,200.00	660
To rust-proofing of the affected areas.	\$	170.00	60
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	60
To dismantle advertisement sticker	\$	170.00	nn X
Towing Fees.	\$	120.00	nn X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	nn X

Trans-cab Auto Services Pte Ltd**AAD1807-262**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5871J

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *nn* 380.00 *X*

TOTAL	\$	11,620.00
--------------	-----------	------------------

Over All Total	\$	32,198.21
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15~~ **DAYS***6 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: