

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3793
Date Estimated : 31/07/2018
Prepared By : Wong Guo Xiang

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Abel Yap Tien Hock (Ye Tianfu)
27 Anchorvale Crescent
#05-33

singapore 544657

- ACCOUNT - 2000
CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGC408J	WF0EXXWPCEGL54643	05/09/2017	Mon 2.0 5Dr	0

DESCRIPTION

SUNDRIES

REPLACE / REPAIR REAR BUMPER, REAR BUMPER
EXTENSION, REAR BUMPER BEAM

RESPRAY REAR BUMPER, REAR BUMPER EXTENSION

TO CONDUCT WIRING CONNECTION & CHECK (NETT)

TO REMOVE & REFIX REVERSE SENSOR (NETT)

TO REMOVE & REFIX REAR BOOT COMPARTMENT INNER TRIM &
GARNISH (NETT)

TUFF KOTE @ \$60 PER PANEL

TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR
FAULT CODE (NETT)

VALUE

~~30~~ 150.00

~~600~~ 1,800.00

~~600~~ 1,800.00

150.00

150.00

X 300.00

X 60.00

~~450~~ 600.00

Total Labour 1: 5,010.00

PART NUMBER DESCRIPTION

DS7317K835NA BUMPER ASSY - REAR, PRIMED
XWAA

DS7317E911ME RR MOULDING
5UAW

DS7317K922EA RR COVER, PRIMED
XWAA

DS7317B861CD RR BPR CTRL BRACKET MTG <CC>

DS7317E899BC RR BUMPER ISOLATOR <BB>

DG9317970DC RR REINFORCEMENT

QTY	PRICE	DISC	VALUE
1	1,838.00	10.00	DE 1,654.20

1	580.00	10.00	DE 522.00
---	--------	-------	----------------------

1	60.00	10.00	X 54.00
---	-------	-------	---------

1	124.00	10.00	? 111.60
---	--------	-------	----------

1	95.00	10.00	? 85.50
---	-------	-------	---------

1	582.00	10.00	? 523.80
---	--------	-------	----------

Total Parts : 2,951.10

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : BG 3793

Page No. : 2 of 2

Date Estimated : 31/07/2018

Prepared By : Wong Guo Xiang

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGC408J	WF0EXXWPCEGL54643	05/09/2017	Mon 2.0 5Dr	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 900100G8
3 days
02/08/18 @ 1110
Res by paint

Labour 1	:	5,010.00
Parts	:	2,951.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	557.28
Grand Total	:	<u>8,518.38</u>

Customer Service Office

Contact

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.