# Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date: 31/7/2018

## **RE: VEHICLE REPAIR QUOTATION**

Insurance Company : EQ Insurance Company Ltd

Vehicle Reg No : SKL4575M

Name of Insured : SIME DARBY SERVICES PTE LTD

Policy Number : B29040568MCY
Date of Accident : 30/7/2018

Tyre of Claim : TP CLAIM Model : BMW X3 2

 Model
 : BMW X3 2.0 XDRIVE20I (A)

 Chassis No
 : WBAWX320600B28120

We are please to submit our estimate of repairs to the above mention vehicle.

			Parts Labour
	1 RR LH DOOR	1	\$ 1,422.1074
	2 LH RR DOOR UPPER BRACKET	1	\$ 57.15
	3 LH RR DOOR LOWER BRACKET	1	\$ 55.50 🗶
	4 HANDLE BRACKET LH PRIME COATED	1	\$ 70.70 🗶
	5 COVERING DOOR, PRIMED LEFT	1	\$ 35.35 7
	6 HANDLE BRACKET BASE LH	1	\$ 7.50 Nec /
	7 OUTER WEATHERSTRIP RR LHS DOOR	1	\$ 107.95 ~
	8 LH SYSTEM LATCH	1	\$ 241.85 🔀
	9 WINDOW FRAME COVER RR LH DOOR	1	\$ 72.95
1	0 DOOR WEATHERSTRIP REAR	1	\$ 142.35 %
1	1 REAR LH DOOR WINDOW FRAME COVER	1	\$ 96.40
	2 RR LH WINDOW LIFTER W/O MOTOR	1	\$ 290.68
	3 DRIVE FOR WINDOW LIFTER LH	1	\$ 312.05
	4 REAR LH WHEEL ARCH COVER	1	\$ 166.95
	5 BASE, LOCK CYLINDER LEFT	1	\$ 7.50
1	6 MOULDING ROCKER PANEL RR LH (XLINE)	1	\$ 125.30

Sub Total Parts = \$3,212.28

Total Parts = \$ 3,212.28

#### Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date: 31/7/2018

#### **RE: VEHICLE REPAIR QUOTATION**

Insurance Company

EQ Insurance Company Ltd

Vehicle Reg No

SKL4575M

Name of Insured

SIME DARBY SERVICES PTE LTD

Policy Number

B29040568MCY

Date of Accident

30/7/2018

Tyre of Claim

TP CLAIM

Model Chassis No BMW X3 2.0 XDRIVE20I (A)

WBAWX320600B28120

We are please to submit our estimate of repairs to the above mention vehicle.

1 2	SUNDRIES LABOUR TO REMOVE, REALIGN AND REPLACE DAMAGE AREA REAR DOOR LH,	\$	150.00 20		
-	FRONT DOOR LH, REAR FENDER LH		600		
3	TO PUTTY AND SPRAY PAINT REAR DOOR LH, FRONT DOOR LH, REAR FENDER LH ROCKER PANEL LH AND ALL AFFECTED AREAS	\$ 1	1,400.00700		
4	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING	\$	15000 8-6		
5	LABOUR TO REMOVE AND REFIT UPHOLDSTERY, TRIM, GARNISHES, TO	\$	300.00		
	FACILITATE CUTTING AND WELDING WORKS.		150		
6	TUFF KOTE, ANTI RUST PRESERVATIONS, BODY CAVITY PRESERVATIONS.	\$	120.00 50		
7	SEALANT FOR BODY PANELS.	\$	120.00 60		
9	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES.	\$	600.00 220		
10	REMOVE AND REFIX FRONT DOOR FITTING, AND MECHANICAL COMPONENTS.	2	300.00 120		
11	TRANSFER AND REFIX REAR DOOR LH FITTING, GLASS, TRIM AND	4	300.00 ×		
11	MECHANICAL COMPONENTS.	φ	300.00		
12	TO CONDUCT WHEEL ALIGNMENT	\$	250.00		
	Total (Labour)	<b>\$ 5,090.00 \$ 8,302.28</b>			
	Sub Total :				
	GST 7%	\$	\$ 581.16		
	Grand Total :	\$ 8	3,883.44		

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

### GRANT CHONG (64777413 / 93366862)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Regul Hp 90010068
6 days
00/08/18 @ 1050
Reg be paint