

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

Not Approved
Wale
6/8/18
take photo before
20.17.
4 day.

M/S : SIM KWANG OO
BLK 114 KITCHENER LINK #08-31
SINGAPORE 207223

Estimate No: EST1503918
Date: 31 Jul 2018
Policy No: GA148950
Veh Reg No: SKM3823Z
Make/Model: B.M.W. X6 XDRIVE35I
AWD SR DSC NAV HUD
LED

ATTN: LONPAC

Your Ref No: TP 0718-5171
Claim Type: Third Party
Accident Date: 31/07/2018
TP Veh Reg No: EX 9613 L

Chassis No: WBAFG22090L597322
Engine No: 03228414N55B30A
Reg. Date: 09/05/2013

Estimate Repair Cost to Vehicle No :SKM3823Z

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 FRONT BUMPER <i>Dis</i>	1,218.600	1 PC	1,218.60	<i>✓</i>
2 FRONT BUMPER LOWER <i>Dis</i>	234.6000	1 PC	234.60	<i>✓</i>
3 FRONT BUMPER CENTRE LOWER LIP, NO 3 <i>17X</i>	176.7500	1 PCS	176.75	<i>X</i>
4 FRONT BUMPER RIVET CLIPS <i>rec</i>	5.0000	10 PCS	50.00	<i>✓</i>
5 FRONT BUMPER SIDE HOLDER - LH <i>bal</i>	301.1000	1 PC	301.10	<i>✓</i>
6 FRONT BUMPER SIDE HOLDER - RH <i>11</i>	301.1000	1 PC	301.10	<i>X</i>
7 FRONT BUMPER SENSOR	236.8500	6 PC	1,421.10	<i>?</i>
8 FRONT BUMPER SENSOR WIRE	162.0500	1 PCS	162.05	<i>?</i>
9 FRONT BUMPER FOG LAMP - LH	258.1500	1 PC	258.15	<i>?</i>
10 FRONT BUMPER FOG LAMP COVER, SILVER - LH	50.3000	1 PCS	50.30	<i>?</i>
11 FRONT BUMPER FOG LAMP COVER, BLACK - LH	84.2800	1 PCS	84.28	<i>?</i>
12 FRONT BUMPER FOG LAMP - RH <i>11</i>	258.1500	1 PC	258.15	<i>X</i>
13 FRONT BUMPER FOG LAMP COVER, SILVER - RH <i>11</i>	50.3000	1 PCS	50.30	<i>X</i>
14 FRONT BUMPER FOG LAMP COVER, BLACK - RH <i>11</i>	84.2500	1 PCS	84.25	<i>X</i>
15 FRONT BUMPER REINFORCEMENT <i>11</i>	708.1500	1 PC	708.15	<i>X</i>
16 LHF FENDER	1,397.400	1 PCS	1,397.40	<i>?</i>
17 LHF FENDER COWLING, FRONT <i>10.11</i>	179.2500	1 PCS	179.25	<i>✓</i>
18 LH FENDEWR COWLING, REAR <i>10.11</i>	179.2500	1 PCS	179.25	<i>✓</i>
19 LHF FENDER COWLING CLIPS <i>rec</i>	5.0000	10 PCS	50.00	<i>✓</i>
20 LHF FENDER OUTER WHEEL ARCH GARNISH <i>120/125</i>	202.4500	1 PCS	202.45	<i>✓</i>
21 LHF FENDER SIGNAL LAMP <i>120</i>	45.0000	1 PCS	45.00	<i>✓</i>
22 LHF FENDER LAMP	37.9500	1 PCS	37.95	<i>?</i>
23 LHF FENDER TOP RUBBER	65.6500	1 PCS	65.65	<i>?</i>
24 AIRCON FAN COWLING <i>11</i>	300.5000	1 PCS	300.50	<i>X</i>
25 LH HEADLAMP	5,433.550	1 PCS	5,433.55	<i>?</i>
26 LH HEADLAMP LOWER RETAINER	254.0500	1 PCS	254.05	<i>?</i>
27 LH HEADLAMP SIDE RETAINER	33.1500	1 PCS	33.15	<i>?</i>
28 LHF TYRE RIM	1,654.200	1 PCS	1,654.20	<i>?</i>
29 LHF TYRE RIM BMW STICKER, SMALL	24.3000	1 PCS	24.30	<i>?</i>
30 BONNET BMW LOGO <i>11</i>	69.5000	1 PCS	69.50	<i>X</i>
31 LHF DOOR XDRIVE 321 WORDING <i>11</i>	93.8500	1 PCS	93.85	<i>X</i>
32 FOG LAMP COVER LH	67.3500	1 PCS	67.35	<i>?</i>
33 FOG LAMP COVER RH	67.3500	1 PCS	67.35	<i>?</i>
			15,513.63	
Less 5%			775.68	14,737.95

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : SIM KWANG OO
BLK 114 KITCHENER LINK #08-31
SINGAPORE 207223

ATTN: LONPAC

Your Ref No: TP 0718-5171
Claim Type: Third Party
Accident Date: 31/07/2018
TP Veh Reg No: EX 9613 L

Estimate No: **EST1503918**
Date: 31 Jul 2018
Policy No: GA148950
Veh Reg No: **SKM3823Z**
Make/Model: B.M.W. X6 XDRIVE35I
AWD SR DSC NAV HUD
LED
Chassis No: WBAFG22090L597322
Engine No: 03228414N55B30A
Reg. Date: 09/05/2013

Estimate Repair Cost to Vehicle No :SKM3823Z

Description	U/Price	Quantity	Price S\$	Amount S\$
Labour				
34 TO KNOCK OUT DENTS, REMOVE, REPLACE LHF FRONT FENDER & REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	600
35 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,000.000	1 JOB	1,000.00	600
36 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
37 TO 4 WHEEL ALIGNMENT	60.0000	1 JOB	60.00	✓
38 TO RESET CHECK LIGHT	60.0000	1 JOB	60.00	✓
39 TO REMOVE, REPLACE LHF TYRE RIM & BALANCING	50.0000	1 JOB	50.00	11 ✓
40 TO TUFF-KOTE	60.0000	1 JOB	60.00	11 X
			2,050.00	2,050.00
Total				S\$ 16,787.95
Add GST @ 7%				1,175.16
Total Amount Payable				S\$ 17,963.11

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND NINE HUNDRED SIXTY THREE AND CENTS ELEVEN ONLY

For **PROGRESSIVE AUTOMOTIVE PTE LTD**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: