

ASS. REC. BY:

REF: CS/CT18014092/R1cd36

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): manishof Thyagarajof CT1Date/Time: 2/8/18 @ 1:24pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 3267L

Insured:

SKN 3993K

at Workshop m/s

Performance

Tel:

63190174

of

303 Alexandra Road

Policy No:

DMPCSN 3017 641802

Claim No:

SNM18D03780C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4:36pm @ 2/8/18

Person Contacted:

Caroline

Vehicle-IN/OUT

Date/Time

Action/Instruction

(c)

Estimate

SLN 3267L - NA/INC17010232/14DOA: 25/5/2017SKN 3993K - X.

Passul

REF: CT1

85221

# ASSIGNMENT

From Date: 07082018

Veh No: SLN 3267L Yr Regn: 2017 APR

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLN 3267L  
at Workshop m/s: Performance  
of: 303 Alexandra Rd

Make: B.M.W 1160 C.C. 1496  
Colour: BLUE A/C Insured / Std / NI / NA  
Sp. Reading: 22301 T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

Policy No.

C/No: WBA1V72040V944671

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured

Excess

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)


Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Murning



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 205/55R16  
R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front R/Bal. 6 mm Rear R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

D.O.A. 28/07/18 D.O.I. 07/08/18

Survey held at PERFORMANCE

CA / REV / REP. / 24 HRS

Des. of Damages Fr. / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/12 Continued final sig \$18,008.50 and 10 days with Caroline. (Red. 280.70, 14%)

27/12/2018

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: 10

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time: File Return to?

Transportation

2)

Add Fee: ☐ Site Insp / \$

1 \$ + RE. 21

☐ Interview / \$

1 Ethos

☐ Tech. Insp / \$

1 Ethos

☐ Weekend / \$

1

Report Format: TP

Lump Sum / 18,008.50

TOTAL

220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18014092/R1rd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-08-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKN 3993K	Veh. Inspected	SLN 3267L
Policy No.	DMPCSN3017641802	Coverage (\$)	0.00
Claim No.	SNM18D03780C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	02/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	28/07/2018	Inspection Date	07/08/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2018		02 Aug 2018 13:24 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TEO SHU MEI		
Vehicle Reg. No.:	SLN3267L	Date of Loss:	28/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03780C02	Policy/Cover Note No.:	DMPCSN3017641802
Vehicle Reg. No. (Insured):	SKN3993K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/08/2018]		
Adj Asg. Remarks:	EST \$19,097.15, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Celine Fong (LKKAUTO)

---

**From:** Celine Fong (LKKAUTO)  
**Sent:** Wednesday, 26 December 2018 7:00 PM  
**To:** 'PBSP'  
**Cc:** Rasul (LKKAUTO); SUR; Hsiao Tong (LKKAUTO); Veron Chen (LKKAUTO)  
**Subject:** RE: URGENT REMINDER: FINAL REPORT / SLN3267L

Dear Caroline,

Confirmed final fig \$18,008.50

Repair days: 10

Thank you for the 2019 calendar.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [celinefong@lkkauto.com](mailto:celinefong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Friday, 21 December 2018 1:46 PM  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** URGENT REMINDER: FINAL REPORT / SLN3267L

URGENT REMINDE

---

**From:** PBSP  
**Sent:** Monday, 19 November 2018 3:29 PM  
**To:** Rasul (LKK Auto); SUR  
**Subject:** FINAL REPORT / SLN3267L

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 13,018.00

**Janice Lee (LKKAUTO)**

---

**From:** PBSP <pml-pbsp@sime-darby.com.sg>  
**Sent:** Monday, November 19, 2018 3:29 PM  
**To:** Rasul (LKKAUTO); SUR  
**Subject:** FINAL REPORT / SLN3267L  
**Attachments:** Final Report SLN3267L\_2.pdf; Final Report SLN3267L.pdf; SKM\_558e18111913020.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 13,018.00  
Total Parts : 4,990.50  
Total Labour & Parts : 18,008.50

Repair days: 10

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8522I
<b>Vehicle Details</b>	
Vehicle No.:	SLN3267L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCH DSC LED
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	38069884B37D15A
Chassis No.:	WBA1V72040V944671
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$25,094.00
Original Registration Date:	28 Apr 2017
First Registration Date:	28 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$12,132.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2027
PARF Rebate Amount:	\$9,099.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$44,032.00
<b>Total Rebate Amount:</b>	<b>\$53,131.00</b>

The information contained herein is correct as at 15 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/07/2018 12:57
Date Of Accident	28/07/2018 11:35
Exact Location Of Accident	DEMPSEY ROAD TOWARDS HOLLAND VILLAGE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN3267L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TEO SHU MEI
NRIC No	S8938522I
Email Address	TEOSHUMEI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90119148
Alternative Phone No	OTHERS-NOPHONE
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	116D 5DR HATCH DSC LED
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/17/VP00/100161
Cover Note Number	
<b>Driver</b>	
Name of Driver	TEO SHU MEI
NRIC No	S8938522I
Date Of Birth	27/10/1989
Occupation	INDOOR
Date Of Driving Pass	18/07/2013
Driving Experience	5 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90119148
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	TEOSHUMEI@GMAIL.COM



Address	84A JALAN HAJI ALISA
Postcode	268562
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

-

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN3993K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA SWEA KENG
NRIC/Passport Number	S1769314Z
Contact Number	96723201
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKV6891J
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	CHRISTINA ILSE RUEDL
NRIC/Passport Number	G5876496K
Contact Number	83385999
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# **SKETCH PLAN**

## **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature


Date & Time:  
28 July 2018  
1:06pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SLN 3267 L	ACCIDENT DATE & TIME: 28 JULY 2018 / 11.25am.
CONTACT NUMBER: 90119148	E-MAIL ADDRESS: TEOSTHUME1@GMAIL.COM
LOCATION: Dempsey Road towards Holland village	
I was stationary at the traffic light when car B hit me, causing me to hit car C.	
Lady driving the car C had some whiplash, so did I.	
We have exchanged particulars (driver licence and contact number), taken photos of our vehicles and I have dash camera footage of the accident.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy	<input checked="" type="checkbox"/> Claim Third Party
<input checked="" type="checkbox"/> Claim OD/TP at other workshop	<input type="checkbox"/> Reporting Only

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 28 July 2018  
12.58

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Car In c/c

IM Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

02 AUG 2018

## ESTIMATE

Estimate No. : b1 47901  
Date Estimated : 02/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

### - ESTIMATE REPAIR FOR -

Teo Shu Mei  
84A JALAN HAJI ALIAS

SINGAPORE 268562

### - ACCOUNT -

135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN3267L	V944671	28/04/2017	116d	0

#### DESCRIPTION

To replace front bumper, air duct, rear bumper, tailgate and attachments including repair tail panel. - repair front R.H. bumper	✓ 5950	5000	3400	5,950.00
Painting front bumper, rear bumper, tailgate and tail panel	✓ 4132	3461	3333	3,704.00
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.			250	295.00
To supply front emboss number plate.			24	83.00
To supply rear emboss number plate.			84	83.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.			451	551.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.			150	177.00
To remove and install boot compartment carpet and garnish to facilitate repairs.			230	271.00
To carry out body cavity preservation. (Per panel).			100	118.00
To remove and install rear view cameras including program and conduct checks for proper function.			226	266.00

Sundries.

150.00

0 Mount to speed bench

#664 564

\* r & r rear w/s \$574  
\* water leak test - \$73

Total Labour 1:

11,628.00

DESCRIPTION

QTY PRIC

VALUE

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 47901  
Date Estimated : 02/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN3267L	V944671	28/04/2017	116d	0

DESCRIPTION	QTY	PRIC	VALUE
CLAMP	1	3.20	3.20
BOOTLID	1	1,108.45	1,108.45
FRT BUMPER TOP MOUNT	1	361.65	361.65
IMPACT ABSORNER TOP	1	42.45	42.45
GRILLE MIDDLE BOTTOM	1	115.50	115.50
FRT BUMPER LH INSERT	1	32.15	32.15
FRT BUMPER RH INSERT	1	32.15	32.15
FRT BUMPER PANEL PRIMED	1	786.20	786.20
SET PDC HOLDER FRONT	1	23.10	23.10
REAR BUMPER CARRIER	1	385.25	385.25
REAR BUMPER CENTRE GUIDE (M)	1	57.45	57.45
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	54.50
REAR BUMPER PRIMED (RFC)	1	947.35	947.35
REAR PDC HOLDER SET	1	23.10	23.10
LH GRILLE (BASIS)	1	81.95	81.95
RH GRILLE (BASIS)	1	81.95	81.95
FRT BUMPER LOWER MOUNT	1	128.00	128.00
AIR DUCT RADIATOR	1	56.65	56.65
AIR DUCT MIDDLE LOWER SECTION	1	51.50	51.50
PLAQUE 82MM	1	69.50	69.50
PLAQUE 82MM	1	69.50	69.50
THIRD STOPLAMP	1	169.90	169.90
NUMBER PLATE LIGHT LED	2	23.20	46.40
PDC sensor	2	368.80	737.60
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
REVERSING CAMERA	1	681.10	681.10
(DG/SL) ADHESIVE SET K6	1	53.05	53.05

Total Parts : 6,219.80

Claims OD / 3rd Party / Uninsured Losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date of Loss: 07/08/18 @ 1040	Excess \$: _____
Surveyor's Name: [Signature]	Sign: _____
Surveyor's Tel: _____	Authorized: Yes / No
Authorized Date: _____	Time: _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P/L Yes / No	
Surveyor's E-mail: _____	
No. of Working Days Recommended: 9 days + 1 day	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour 1	:	11,628.00
Approved by Repairer	:	6,219.80
Signature: Labour 2	:	0.00
Date: Excess	:	0.00
Total GST @ 7%	:	1,249.35
Grand Total	:	19,097.15

HIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Car Ins c/c

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

02 AUG 2018

## ESTIMATE

Estimate No. : b1 47901  
Date Estimated : 02/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

### - ESTIMATE REPAIR FOR -

Teo Shu Mei  
84A JALAN HAJI ALIAS

SINGAPORE 268562

### - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN3267L	V944671	28/04/2017	116d	0

#### DESCRIPTION

To replace front bumper,air duct,rear bumper,tailgate and attachments including repair tail panel.

5950 3400 5,980.00

Painting front bumper,rear bumper,tailgate and tail panel

4132 3333 3,704.00

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

250 295.00

To supply front emboss number plate.

24 83.00

To supply rear emboss number plate.

84 83.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To remove and install rear view cameras including program and conduct checks for proper function.

226 266.00

Sundries.

150.00

Total Labour 1: 11,628.00

DESCRIPTION

QTY

PRIC

VALUE

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 47901  
Date Estimated : 02/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN3267L	V944671	28/04/2017	116d	0

DESCRIPTION	QTY	PRIC	VALUE
CLAMP	10	3.20	32
BOOTLID	1	1,108.45	1,108.45
FRT BUMPER TOP MOUNT	1	361.65	361.65
IMPACT ABSORNER TOP	1	42.45	42.45
GRILLE MIDDLE BOTTOM	1	115.50	115.50
FRT BUMPER LH INSERT	1	32.15	32.15
FRT BUMPER RH INSERT	1	32.15	32.15
FRT BUMPER PANEL PRIMED	1	786.20	786.20
SET PDC HOLDER FRONT	1	23.10	23.10
REAR BUMPER CARRIER	1	385.25	385.25
REAR BUMPER CENTRE GUIDE (M)	1	57.45	57.45
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	54.50
REAR BUMPER PRIMED (RFC)	1	947.35	947.35
REAR PDC HOLDER SET	1	23.10	23.10
LH GRILLE (BASIS)	1	81.95	81.95
RH GRILLE (BASIS)	1	81.95	81.95
FRT BUMPER LOWER MOUNT	1	128.00	128.00
AIR DUCT RADIATOR	1	56.65	56.65
AIR DUCT MIDDLE LOWER SECTION	1	51.50	51.50
PLAQUE 82MM	1	69.50	69.50
PLAQUE 82MM	1	69.50	69.50
THIRD STOPLAMP	1	169.90	169.90
NUMBER PLATE LIGHT LED	2	23.20	46.40
PDC sensor	2	368.80	737.60
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
REVERSING CAMERA	1	681.10	681.10
(DG/SL) ADHESIVE SET K6	2	53.05	106.10

Total Parts : 6,219.80

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 07/08/18 @ 1040 Claim No.

Date &amp; Time 07/08/18 @ 1040 Excess \$5

Surveyor's Name R. K. M. Sign

Surveyor's Tel. 63190100

Authorized Date 07/08/18 Time 10:40

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Labour 1 : 11,628.00

Parts : 6,219.80

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 1,249.35

Grand Total : 19,097.15

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

20,989.20

10.7.18 9C



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 47901  
Date Estimated : 02/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Teo Shu Mei

84A JALAN HAJI ALIAS

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

SINGAPORE 268562

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLN3267L	V944671	28/04/2017	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To mount vehicle on speed bench to facilitate re-alignment of body/chassis in accordance with BMW specifications	564.00		564.00	
# To remove and install rear windscreen glass to facilitate repairs	574.00		574.00	✓
# To conduct water leak tests	75.00		75.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EMBLEM BUTTON *	103.40	1.00		103.40
# BUMP STOP *	4.00	10.00		40.00
# PLAQUE 82MM	69.50	1.00	rpt	X 69.50
# PLAQUE 82MM	69.50	1.00	rpt	X 69.50
# (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00		263.10
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85

Total Labour : 1,213.00  
Total Parts : 597.20  
Total Labour & Parts : 1,810.20

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 47901  
Date Estimated : 02/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Teo Shu Mei  
84A JALAN HAJI ALIAS

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

SINGAPORE 268562

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SLN3267L	V944671	28/04/2017	116d	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
* To replace front/rear bumper and attachments, tailgate, air duct radiator and attachments, third stoplamp include to pull and straighten on accident areas, to make good the tail end panel, front RH fender and knocking out dents caused by the accident	5950.00		5,950.00			
* To spray paint front bumper, rear bumper, tailgate, tail end panel and front RH fender	4132.00		4,132.00			
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights	250.00		250.00			
To supply front emboss number plate.	83.00		83.00			
To supply rear emboss number plate.	83.00		83.00			
To transfer lock mechanism from old to new tailgate include conducting checks on new tailgate central locking system for proper function	451.00		451.00			
To remove old PDC assembly, replace damaged parts and reconnect to new bumper include conducting checks for proper function	150.00		150.00			
* To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
* To remove and install rear view camera to facilitate repairs include programming and conducting checks for proper function	226.00		226.00			
# To mount vehicle on speed bench to facilitate re-alignment of body/chassis in accordance with BMW specifications	564.00		564.00			
# To remove and install rear windscreen glass to facilitate repairs	574.00		574.00			
# To conduct water leak tests	75.00		75.00			
Sundries	150.00		150.00			

# Performance Motors Limited

A member of the Sims Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.20	10.00		32.00
BOOTLID	1,108.45	1.00		1,108.45
FRT BUMPER TOP MOUNT	361.65	1.00		361.65
IMPACT ABSORNER TOP	42.45	1.00		42.45
GRILLE MIDDLE BOTTOM	115.50	1.00		115.50
FRT BUMPER PANEL PRIMED	786.20	1.00		786.20
SET PDC HOLDER FRONT	23.10	1.00		23.10
REAR BUMPER CARRIER	385.25	1.00		385.25
REAR BUMPER PRIMED (RFC)	947.35	1.00		947.35
REAR PDC HOLDER SET	23.10	1.00		23.10
LH GRILLE (BASIS)	81.95	1.00		81.95
RH GRILLE (BASIS)	81.95	1.00		81.95
(A) # EMBLEM BUTTON *	103.40	1.00		103.40
(A) # BUMP STOP *	4.00	10.00		40.00
AIR DUCT RADIATOR	56.65	1.00		56.65
AIR DUCT MIDDLE LOWER SECTION	51.50	1.00		51.50
# PLAQUE 82MM	69.50	1.00		69.50
# PLAQUE 82MM	69.50	1.00		69.50
THIRD STOPLAMP	169.90	1.00		169.90
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20
(A) # (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85
(A) # (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00		263.10
(A) # (DG/SL) ADHESIVE SET K6	53.05	2.00		106.10
(A) # (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85

### # SUPPLEMENTARY ITEMS

Total Labour :	13,018.00
Total Parts :	4,990.50
Total Labour & Parts :	18,008.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	18,008.50
GST @7%:	1,260.60
Grand Total :	19,269.10

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2018		02 Aug 2018 13:24 <a href="#">Edit Adj Rpt</a>	<b>S\$18,008.50</b> <a href="#">Edit Estimates</a>	<b>S\$18,008.50</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>TEO SHU MEI</b>								
Vehicle Reg. No.:	<b>SLN3267L</b>	Date of Loss:	28/07/2018 00:00 - :59 [15 Months From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D03780C02</b>	Policy/Cover Note No.:	DMPCSN3017641802						
Vehicle Reg. No. (Insured):	<b>SKN3993K</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Jowyn Tay</b> - 6389 6174]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 14/08/2018]								
Adj Asg. Remarks:	EST \$19,097.15, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLN3267L (SNM18D03780C02)**  
**[SKN3993K]**  
**TP**  
**TEO SHU MEI**  
**Jul 28 2018 12:00AM**  
**[-]**  
**Performance Motors Limited**

Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	26/12/18 19:12	General View							Load PDF		
2	26/12/18 19:12	Photographs of Damaged Parts							Load PDF		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	02/08/18 13:23	REPAIR EST WITH TP GIA							Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/01/19 10:58	Supplementary							Load PDF		

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014092/R1CD3E2

Date: 03/01/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3017641802

Claimant Vehicle  
No : SLN3267LInsured Vehicle  
No : SKN3993K

Date of Loss: 28/07/2018

Nature of Claim: TP

Claim  
No: SNM18D03780C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLN3267L

Make &amp; Model: BMW 116D, 1.6 (A)

Reg. Date: 28/04/2017 (Man. Year: 2017)

Colour: Blue

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 38069884B37D15A

Chassis No: WBA1V72040V944671

Odometer: 22301 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,214.85	5,306.50	1,908.35	26.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,525.00	12,702.00	-177.00	-1.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>19,739.85</b>	<b>18,008.50</b>	<b>1,731.35</b>	<b>8.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,381.79</b>	<b>1,260.60</b>	<b>121.19</b>	<b>8.77</b>
<b>Nett Amount (S\$)</b>	<b>21,121.64</b>	<b>19,269.10</b>	<b>1,852.54</b>	<b>8.77</b>

## INSPECTION

Date of Assignment: 02/08/2018

Date Inspected: 07/08/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 10.0 days

**Adjuster:** MOHD RASUL

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
<b>Parts:</b> 144	BMW 116D 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLN3267L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
3	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
4	10		*CLAMP	Necessary	32.00 FS	*32.00 FS
5	1		*BOOTLID	Bent	1,108.45 FS	*1,108.45 FS
6	1		*FRT BUMPER TOP MOUNT	Cracked	361.65 FS	*361.65 FS
7	1		*IMPACT ABSORNER TOP	Cracked	42.45 FS	*42.45 FS
8	1		*GRILLE MIDDLE BOTTOM	Cracked	115.50 FS	*115.50 FS
9	1		*FRT BUMPER LH INSERT	Not Necessary	32.15 FS	*- FS
10	1		*FRT BUMPER RH INSERT	Not Necessary	32.15 FS	*- FS
11	1		*FRT BUMPER PANEL PRIMER	Deformed	786.20 FS	*786.20 FS
12	1		*SET PDC HOLDER FRONT	Necessary	23.10 FS	*23.10 FS
13	1		*REAR BUMPER CARRIER	Bent	385.25 FS	*385.25 FS
14	1		*REAR BUMPER CENTRE GUIDE (M)	Serviceable	57.45 FS	*- FS
15	1		*REAR BUMPER TOWING EYE COVER PRIMED	Serviceable	54.50 FS	*- FS
16	1		*REAR BUMPER PRIMED (RFC)	Deformed	947.35 FS	*947.35 FS
17	1		*SET REAR PDC HOLDER	Necessary	23.10 FS	*23.10 FS
18	1		*LH GRILLE (BASIS)	Scratched	81.95 FS	*81.95 FS
19	1		*RH GRILLE (BASIS)	Scratched	81.95 FS	*81.95 FS
20	1		*FRT BUMPER LOWER MOUNT	Not Necessary	128.00 FS	*- FS
21	1		*AIR DUCT RADIATOR	Deformed	56.65 FS	*56.65 FS
22	1		*AIR DUCT MIDDLE LOWER SECTION	Cracked	51.50 FS	*51.50 FS
23	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
24	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
25	1		*THIRD STOPLAMP	Necessary	169.90 FS	*169.90 FS
26	2		*NUMBER PLATE LIGHT LED	Not Necessary	46.40 FS	*- FS
27	2		*PDC SENSOR	Not Necessary	737.60 FS	*- FS
28	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
29	1		*REVERSING CAMERA	Not Necessary	681.10 FS	*- FS
30	2		*(DG/SL) ADHESIVE SET K6	Necessary	106.10 FS	*106.10 FS
31	1		*EMBLEM BUTTON	Necessary	103.40 FS	*103.40 FS
32	10		*BUMP STOP	Necessary	40.00 FS	*40.00 FS
33	1		*PLAQUE 82MM	Repeated	69.50 FS	*- FS
34	1		*PLAQUE 82MM	Repeated	69.50 FS	*- FS
35	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
36	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
37	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
Total Parts (S\$)					7,214.85	5,306.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER, AIR DUCT, REAR BUMPER, TAILGATE AND ATTACHMENTS INCLUDING REPAIR TAIL PANEL	New	5,950.00	5,950.00
2	PAINTING FRONT BUMPER, REAR BUMPER, TAILGATE AND TAIL PANEL	New	3,704.00	4,132.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	295.00	250.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
5	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
8	TO REMOVE AND INSTALL REAR VIEW CAMERAS INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	266.00	226.00
9	TO MOUNT VEHICLE ON SPEED BENCH TO FACILITATE RE-ALIGNMENT OF BODY / CHASSIS IN ACCORDANCE WITH BMW SPECIFICATIONS	New	564.00	564.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS	New	574.00	574.00
11	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
Gross Labour Cost (S\$)			<b>12,525.00</b>	<b>12,702.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >