

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47901
Date Estimated : 02/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Teo Shu Mei
84A JALAN HAJI ALIAS

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

SINGAPORE 268562

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLN3267L	V944671	28/04/2017	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To mount vehicle on speed bench to facilitate re-alignment of body/chassis in accordance with BMW specifications	564.00		564.00	
# To remove and install rear windscreen glass to facilitate repairs	574.00		574.00	/
# To conduct water leak tests	75.00		75.00	/

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EMBLEM BUTTON *	103.40	1.00		103.40
# BUMP STOP *	4.00	10.00		40.00
# PLAQUE 82MM	69.50	1.00	rpt	X 69.50
# PLAQUE 82MM	69.50	1.00	rpt	X 69.50
# (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00		263.10
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85

Total Labour : 1,213.00
Total Parts : 597.20
Total Labour & Parts : 1,810.20