

ASS. REC. BY:

REF: CS/FCI/8014095/Ktd3ⁿ² Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): cws Karen Tan of FCI Date/Time: 2/8/18 @ 4.26pm

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 1060P Insured: SHC 8806 D

at Workshop m/s Ah Lim Motor Tel: 6483 1214

of 176 Sin Ming Drive # 05-12

Policy No: Claim No: D18005833MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 31/07/2018

(Client's Record) Insp: Ah Lim Motor (AMK)

CA / REV / REP. / REV 24 HRS (DS) 31/07/10am ow H.O.D. Endorsement:

Date/Time: 4.29pm @ 2/8/18 Person Contacted: zila Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SJG 1060P - x
	SHC 8806D - CS3 / FCI 15010590 / Yvbd1 DOA: 14/6/2015
	lump sum \$1950, 3 days. (Red: 1098.40; 36%)

(08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From:

Date: 8/8/18

Estimated Cost:

OR ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

SJG1060P

at Workshop m/s

Ah Lim Motor

of

No.10, Amk Ind. Park 2A # 01-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

10 am @ owner

Make of Veh:

waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

835k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

(DS)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJG1060P

Yr Regn:

06, 08

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make:

Honda Civic

c.c.

1595

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

172758

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMF046208S201804

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orModi: Nil ☐ S/Rim ☐ STD ☒ Rrim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

d

mm

R/Bal.

d

mm

L/Bal.

d

mm

L/Bal.

d

mm

D.O.A.

31/7/18

D.O.I.

31/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/8 PM call to Nint

RECEIVED 27 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

☒

: Final Report

24/10 Typist

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

1950/-

130

50

50

14

244



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014095/Ktd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8806D	Veh. Inspected	SJG 1060P
Policy No.		Coverage (\$)	0.00
Claim No.	D18005833MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	02/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/07/2018	Inspection Date	03/08/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	01-08-2018	Our Ref No. D18005833MFSH
Accident Date	31-07-2018	Claim Type. Third Party
Insured Vehicle	SHC8806D	Third Party Vehicle. SJG1060P
Survey Location	176 SIN MING DRIVE #05-12 SIN MING AUTOCARE	
Contact Person.	KEE MUI HONG	
Contact No.	64831244/ 0	Fax No. 64836170
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST


Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Sketch Plan Pg. 3



Hp: 90383213 ②

Home: 65540568 ①

clear/dry

1 pax.

No injury

No video

HP: 2 pax.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
13 Sep 1905

NP 428A



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4876C

Vehicle Details

Vehicle No.: SJG1060P
Vehicle to be Exported: Yes
Intended De-registration Date: 31 Jul 2018
Vehicle Make: HONDA
Vehicle Model: CIVIC 1.6L VTI AUTO
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: R16A13005500
Chassis No.: JHMFD46208S201804
Maximum Power Output: 92.0 kW (123 bhp)
Open Market Value: \$19,096.00
Original Registration Date: 20 Jun 2008
First Registration Date: 20 Jun 2008
Transfer Count: 2
Actual ARF Paid: \$19,096.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Jun 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$19,107.00
COE Rebate Amount: \$18,671.00
Total Rebate Amount: \$18,671.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Jul 2018

OK



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HONG AH KHEE
36 LENTOR PLAIN

SINGAPORE 786538

ATTN:

Your Ref No: -

Claim Type: Third Party

Accident Date: 31/07/2018

TP Veh Reg No: SHC8806D

Estimate No: MC0913313

Date: 31 Jul 2018

Policy No: GA118227

Veh Reg No: SJG1060P

Make/Model: HONDA CIVIC 1.6 VTI

Estimate Repair Cost to Vehicle No :SJG1060P

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP LH	1 PC	790.40	✓
2 HEADLAMP LOWER BEAM LH	1 PC	29.10	X
3 FRONT BUMPER	1 PC	638.00	✓
4 FRONT BUMPER SIDE RETAINER LH	1 PC	12.00	—
5 FRONT BUMPER CLIPS	10 PC	31.00	—
6 FOGLAMP LH	1 PC	250.20	X
7 FRONT FENDER LH	1 PC	537.00	✓
8 FRONT FENDER COWLING LH	1 PC	94.80	X
9 FRONT FENDER COWLING CLIPS	8 PC	28.00	X
		2,410.50	
	Less 20%	482.10	1,928.40
LABOUR			
10 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	200
11 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X
12 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD : TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	400
13 TO SPRAY FRONT BUMPER, FRONT FENDER LH	1 PC	500.00	400
		1,120.00	1,120.00
		Total	S\$ 3,048.40
		Add GST @ 7%	213.39
		Total Amount Payable	S\$ 3,261.79

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWO HUNDRED SIXTY ONE AND CENTS SEVENTY NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair completion
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014095/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8806D	Veh. Inspected	SJG 1060P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005833MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMF46208S201804	Colour	METALLIC GREY	
Odometer	172758	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	8 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	8 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/07/2018	Inspection Date	03/08/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 1060P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP LH	CUT	790.40	790.40
1	HEADLAMP LOWER BEAM LH	TO REPAIR SEE LABOUR	29.10	-
1	FRONT BUMPER	CRACKED	638.00	638.00
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	12.00	12.00
10	FRONT BUMPER CLIPS	NECESSARY	31.00	31.00
1	FOGLAMP LH	SERVICEABLE	250.20	-
1	FRONT FENDER LH	BUCKLED	537.00	537.00
1	FRONT FENDER COWLING LH	SERVICEABLE	94.80	-
8	FRONT FENDER COWLING CLIPS	NOT NECESSARY	28.00	-
	LESS 20% DISCOUNT		-482.10	-401.68
			1,928.40	1,606.72
	<u>LABOUR</u>			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.	NOT NECESSARY	40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	-
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF HEADLAMP LOWER BEAM LH.		500.00	400.00
	TO SPRAY FRONT BUMPER,FRONT FENDER LH.		500.00	400.00
			1,120.00	820.00
GRAND TOTAL			3,048.40	2,426.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CS/FCI18014095/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.