LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Josey Loh Date: 13 Aug 2018

Preliminary Advice

Insured Vehicle No : SKZ9365X

TP Vehicle No : SLJ6787D Accident Date : 15/07/2018

Make : TOYOTA WISH Assignment Date : 03/08/2018

Date of Inspection : 07/08/2018 Est. Duration of Repair : 4-5/Days

Inspection At : KING'S AUTO SPRAY PAINT PTE. LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 6,295.91 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 2,970.97 |
| Check Items (Estimated) | :S\$ | 1,410.10 |
| Total | :S\$ | 4,381.07 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
| | | Kindly let us have your authorisation. |
| | | |

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :We have not authorized repairs.