

31-7-18

King's Auto Spray Paint Pte Ltd
160 Sin Ming Drive #05-16 Sing Ming Autocity
Singapore 575722

YAP SI RONG

Not Authorised
11km @?
4-5 days, Assembly After Pain
Re: Estimate cost for SLJ 6787D TOYOTA WISH

SUPPLY OF PARTS:

ipc rear boot lid	R \$1275.91 ✓
ipc rear boot lid logo	m 70.09 ✓
ipc rear boot lid outer handle	sn 239.00 x
2pc rear boot lid reflector @ 269.00	sn 538.00 x
ipc rear boot lid emblem	m 35.49 ✓
ipc rear boot lid rubber inner	sn 302.51 x
ipc rear boot lid lock	sn 361.60 ✓
ipc rear boot lid wiper motor	sn 577.40 x
ipc rear windscreen midg	m 135.20 ✓
ipc rear center panel	453.80 ?
ipc rear center panel top trim	253.00 ?
ipc rear bumper	sn 691.00 ✓
2pc rear bumper brackets @ 48.44	m 96.88 x
8pc rear bumper clips @ 4.00	m 32.00 ✓
2pc rear bumper retainer side @ 57.00	sn 114.00 x
2pc rear bumper retainer top @ 56.00	sn 112.00 x

\$5287.88

1321.97

\$3965.91

m 70.00 40sn

140.00 12cl

sn 200sn 280.00

80.00 6cl

LABOUR:

ipc rear windscreen sealant
To dismantle & replace rear windscreen glass
1set rear bumper sensor
To transfer rear boot lid wiper motor & system
to new parts

Renew the above mentioned parts
Knocking, cutting, welding & straighten rear
damaged parts

spray paintings

\$ 880.00 ?

60cl \$ 880.00

\$6295.91

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirm: attach 25%
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer:
Signature: _____
Date: _____