

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tr, Tinesh

Date: 13 Aug 2018

**Preliminary Advice**

Vehicle No	: SLT8025D	Accident Date	: 27/07/2018
Make	: AUDI Q2	Policy No.	: 1700077441
Assignment Date	: 03/08/2018	Excess	: S\$400.00
Date of Inspection	: 03/08/2018	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,308.00
Revised Amount	:S\$	10,928.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	1,003.00
Total	:S\$	11,931.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	57,703.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,297.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments : SUPPLEMENTARY AMOUNT \$ 4,789.00