

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M**AAD1807-295***Not Authorised
11/12/18 @ 1850h*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 9833M

VF1ABL15AUC277414

RENAULT

LATITUDE

30.7.2018

EQ

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>add</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 BOOT REAR	\$	<i>R</i> 2,872.68 } X
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
19	1 BOOT BADGE	\$	<i>na</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Stk</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1807-295**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M

30	1 FENDER PANEL REAR LH	\$	<i>N</i>	3,299.13	}
31	1 WHEELARCH REAR LH	\$	<i>Su</i>	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Su</i>	671.45	
33	1 FENDER PANEL REAR RH	\$	<i>N</i>	3,299.13	
34	1 WHEELARCH REAR RH	\$	<i>Su</i>	543.47	
35	1 TAILLAMP RH	\$	<i>Su</i>	552.55	
36	1 TAILLAMP PANEL RH	\$	<i>N</i>	986.70	
37	1 TAILLAMP LH	\$	<i>Su</i>	552.55	
38	1 TAILLAMP PANEL LH	\$	<i>N</i>	986.70	
39	1 OUTER PANEL REAR (End Panel)	\$	<i>N</i>	1,471.77	
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Su</i>	404.56	
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>N</i>	2,189.88	
42	1 SPARE WHEEL PANEL TRIM	\$	<i>Su</i>	612.21	
43	1 EXHAUST REAR	\$	<i>N</i>	7,489.05	
44	1 EXHAUST CAP REAR	\$	<i>N</i>	230.49	
45	1 CHASSIS PANEL REAR RH	\$	<i>N</i>	3,766.43	
46	1 KUCKLE ARM REAR RH L70Y	\$	<i>Su</i>	736.67	
47	1 BRAKE DISC REAR L70Y	\$	<i>Su</i>	525.91	
48	1 WHEEL HUB NUT L70Y	\$	<i>Su</i>	51.11	
49	1 WHEEL HUB CAP L70Y	\$	<i>Su</i>	57.82	
50	1 ABS SENSOR REAR RH L70Y	\$	<i>Su</i>	255.75	
51	1 REAR AXLE L70Y	\$	<i>Su</i>	4,167.03	
52	1 AXLE ARM RH L70Y	\$	<i>Su</i>	117.22	
53	1 LOWER ARM REAR RH L70Y	\$	<i>Su</i>	905.99	
54	1 ABSORBER REAR	\$	<i>Su</i>	389.75	
55	1 STABILIZER BAR REAR RH	\$	<i>Su</i>	604.65	
56	1 BRAKE CALIPER REAR RH	\$	<i>Su</i>	1,300.67	
57	1 WHEEL HOUSING PANEL REAR RH	\$	<i>N</i>	4,682.09	
58	1 CHASSIS PANEL REAR RH	\$	<i>N</i>	3,766.43	
TOTAL		\$		56,525.01	
10%		\$		5,652.50	
		\$		50,872.51	

Special Nett

1 1SET PARKING AID	\$	<i>Su</i>	700.00	X
2 1SET REAR BUMPER CLIP	\$	<i>N</i>	66.00	✓
3 1SET BUMPER BRACKET CTR CLIP	\$	<i>N</i>	33.00	✓
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>N</i>	10.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-295**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M

5 1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	sn	17.82	
11 1SET BOOT FINISHER CLIP	\$	nn	24.20	
12 1 BOOT STICKER "Trans-cab"	\$	nn	30.00	
13 1 BOOT STICKER "6555-3333"	\$	nn	30.00	
14 1 BOOT INNER TRIM CLIP	\$	nn	45.00	
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	
19 1 TAILLAMP CLIP RH	\$	nn	5.00	
20 1 TAILLAMP CLIP LH	\$	nn	5.00	
21 2 REAR WINDSCREEN SELANT	\$	nn	80.00	
22 1 WINDSCREEN MOULDING	\$	nn	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	
25 1 SPARE TYRE	\$	sn	330.00	
26 1 RIGHT REAR TYRE	\$	sn	330.00	
27 1 RIGHT REAR TYRE RIM	\$	sn	380.00	

TOTAL \$ 2,935.02**TOTAL PARTS \$ 53,807.53****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	2001
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-295**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9833M

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X

TOTAL \$ 12,540.00**Over All Total \$ 66,347.53****(LUMP SUM)****Repair Days****28 DAYS****2 days****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: