

Surveyor: Ming Yau | 6, 116 180 14119, 44334 | 12V  
MACUS | ASSIGNMENT | 318/18 | 318/2018  
 DOI: 318/18 | Date / Time: 318/2018  
 Registered in Merimen: 318/2018  
 Pre-assign / CCU / FTE: YP 24818

Insured Vehicle No.: 686 3602 T | Claim No.: 7213 232 310/64  
 Name of Insured: Chang Kong Enterprises | Policy No.:   
 Insured Tel No.:  | HP:  | Make / Model: Hugay Ave 3  
 Excess Sec II :SS:  | D.O.A.: Y/E/2018 | Place of Accident: Hugay Ave 3  
 Is driver the owner? (YES / NO) | Nature of Accident:   
 If NO, Driver Name / Age:  | OI GIA REPORT: YES / NO | TP GIA REPORT: YES / NO  
 Driver Tel No.:  | (V/L: YES / NO) | Insured Liability: % | Final ? Yes / No

INSRs: WSP: 24818 | INSRs: WSP: 24818 | INSRs: WSP: 24818 | INSRs: WSP: 24818  
 Tel: 24818 | Tel: 24818 | Tel: 24818 | Tel: 24818  
 Liability: 24818 | Liability: 24818 | Liability: 24818 | Liability: 24818  
 RMKS: 24818 | RMKS: 24818 | RMKS: 24818 | RMKS: 24818

| Date / Time | STAGE                                    | DATE / PIC |
|-------------|--|------------|
| 10/8        | Non-Reporting ltr (1st)                  |            |
| 10/8        | Non-Reporting ltr (2nd)                  |            |
| 10/8        | Non-Reporting ltr (Final)                |            |
| 10/8        | Notification ltr (if non-pickup)         |            |
| 10/8        | Call OE: <u>11/9/18</u>                  |            |
| 10/8        | After call ltr to OE: <u>4/10/18</u>     |            |
| 10/8        | Documentation Check List: Handler Typist |            |
| 10/8        | Notification ltr (if non-pickup)         |            |
| 10/8        | After call ltr to OE:                    |            |
| 10/8        | Authorisation To Act:                    |            |
| 10/8        | Release Voucher:                         |            |
| 10/8        | Final Repair Bill:                       |            |
| 10/8        | Car Rental Invoice:                      |            |
| 10/8        | Towing Invoice:                          |            |
| 10/8        | LTA / GIA:                               |            |
| 10/8        | Medical Bill:                            |            |
| 10/8        | PIR:                                     |            |
| 10/8        | Mandate/Reject Instruction:              |            |
| 10/8        | LOD:                                     |            |
| 10/8        | Payment Breakdown Form:                  |            |
| 10/8        | Post-Repair Photos:                      |            |
| 10/8        | Others:                                  |            |

PRELIMINARY ADVICE Date/Time: 10/2/2018 | Sent By: HMK  
 FINALIZATION Date/Time: 10/2/2018 | Confirm with: Johnson Chen | Confirm by:   
 Repair Cost: SS 10,600.00 (8 days) Reduction: 53 % | Email:  Call:   
 FINAL SETTLEMENT Date/Time: 12/12/2018 | Confirm with: Johnson Chen | Email: 12/12/18 Call:   
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 | If NO or B 28, Ass. Lin: 100%  
 Repair Cost: (w/ GST) SS 11,342.00 | 3 car chain collision, 02 is best car  
 Loss of Rental (LOR): SS 1,070.00 (10 days) 2400.00 + 7% GST  
 Loss of Use (LOU): SS - (5 x days)  
 Loss of Income (LOI): SS - (5 x days)  
 LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]  
 GIA/LTA Search: SS 7.49  
 Medical: SS -  
 Disbursement: SS - (e.g. Tow/ Independent)  
 Legal Cost: SS -  
 Total: SS 12,419.49 | Global Sum SS:   
 FINAL PAYMENT Date/Time:  | Confirm with:  | Email:  Call:   
 Payee 1: SS 12,419.49 | Name: Tan Lim Motor Pte Ltd  
 Payee 2: (Strike if N.A.) SS | Name:   
 Payee 3: (Strike if N.A.) SS | Name:



AIGAsia Insured's Veh No : YP2481B  
Date of Accident : 02 August 2018

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual  
Chassis No : JTFHT02P000179801

| S/No | Quantity | Description                                     | Amount      |
|------|----------|---|-------------|
|      |          | <u>LIST ITEMS</u>                               |             |
| 01   | 1 pc     | tailgate lid                                    | \$ 1,855.00 |
| 02   | 1 pc     | tailgate lid Toyota Sticker                     | \$ 48.50    |
| 03   | 1 pc     | tailgate lid Hiace sticker                      | \$ 48.50    |
| 04   | 1 pc     | tailgate lid outer garnish                      | \$ 185.00   |
| 05   | 1 pc     | tailgate lid lock                               | \$ 285.00   |
| 06   | 1 pc     | tailgate lid lock sticker                       | \$ 78.50    |
| 07   | 1 pc     | tailgate lid weatherstrip                       | \$ 368.00   |
| 08   | 1 pc     | tailgate lid key lock                           | \$ 0.00     |
| 09   | 2 pc     | tailgate lid damper stay @ \$0.00               | \$ 0.00     |
| 10   | 2 pc     | tailgate lid side catch @ \$35.00               | \$ 70.00    |
| 11   | 2 pc     | tailgate lid side catch latch @ \$3.00          | \$ 6.00     |
| 12   | 1 pc     | tailgate lid lock actuator                      | \$ 0.00     |
| 13   | 1 pc     | tailgate lid inner trimboard                    | \$ 456.80   |
| 14   | 10 pc    | tailgate lid inner trimboard clips @ \$4.50     | \$ 45.00    |
| 15   | 2 pc     | tailgate lid drain grommed @ \$0.00             | \$ 0.00     |
| 16   | 1 pc     | tailgate lid centre emblem badge                | \$ 78.00    |
| 17   | 1 pc     | rear windshield glass                           | \$ 289.00   |
| 18   | 1 pc     | rear windshield glass weatherstrip              | \$ 0.00     |
| 19   | 2 pc     | rear license plate lamp @ \$85.00               | \$ 170.00   |
| 20   | 1 pc     | rear wiper motor                                | \$ 685.00   |
| 21   | 1 pc     | rear wiper arm                                  | \$ 0.00     |
| 22   | 1 pc     | rear wiper arm cover                            | \$ 0.00     |
| 23   | 1 pc     | rear wiper blade                                | \$ 0.00     |
| 24   | 1 pc     | third brake light                               | \$ 0.00     |
| 25   | 2 pc     | rear lamp @ \$322.70                            | \$ 645.40   |
| 26   | 1 pc     | n/s rear lamp vertical panel outer              | \$ 303.70   |
| 27   | 1 pc     | n/s rear lamp vertical panel inner              | \$ 457.70   |
| 28   | 1 pc     | n/s rear lamp inner 1/4 panel                   | \$ 45.60    |
| 29   | 1 pc     | n/s rear lamp lower apron                       | \$ 102.60   |
| 30   | 1 pc     | n/s rear wheel mudguard                         | \$ 1,451.00 |
| 31   | 1 pc     | rear end panel                                  | \$ 798.50   |
| 32   | 1 pc     | rear end panel inner top garnish                | \$ 128.00   |
| 33   | 1 pc     | rear bumper                                     | \$ 395.00   |
| 34   | 1 pc     | rear bumper beam                                | \$ 232.10   |
| 35   | 2 pc     | rear bumper side retainer @ \$27.00             | \$ 54.00    |
| 36   | 4 pc     | rear bumper side retainer holder clips @ \$4.50 | \$ 18.00    |
| 37   | 1 pc     | spare tyre - carriage deck                      | \$ 269.60   |
| 38   | 1 pc     | rear exhaust box                                | \$ 945.00   |
| 39   | 2 pc     | rear exhaust box mount @ \$45.00                | \$ 90.00    |

not Authorized  
3/8/18  
Take photo before  
8 day.  
1/5 \* 10.600

96.

**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
 Tel : 68585151 ( 24 Hours ) Fax : 68580877  
 GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : YP2481B  
 Date of Accident : 02 August 2018

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual  
 Chassis No : JTFHT02P000179801

| S/No                              | Quantity | Description   | Amount       |
|-----------------------------------|----------|---|--------------|
| <u>LIST ITEMS</u>                 |          |   |              |
| 40                                | 1 pc     | front bumper <i>as/oe</i>   | \$ 500.30    |
| 41                                | 1 pc     | front bumper reinforcement top <i>ref</i>   | \$ 382.70    |
| 42                                | 1 pc     | front bumper beam bottom <i>R</i>   | \$ 345.00    |
| 43                                | 2 pc     | front bumper side holder @ \$122.60 <i>11</i>   | \$ 245.20    |
| 44                                | 2 pc     | front bumper side retainer @ \$170.10 <i>11</i>                                       | \$ 340.20    |
| 45                                | 2 pc     | front bumper tow cover @ \$20.00 <i>11</i>  | \$ 40.00     |
| 46                                | 2 pc     | front bumper spot lamp garnish @ \$50.00 <i>11</i>                                    | \$ 100.00    |
| 47                                | 1 pc     | front bumper centre air grille <i>CR</i>  | \$ 480.00    |
| 48                                | 2 pc     | head lamp @ \$638.00 <i>one</i>   | \$ 1,276.00  |
| 49                                | 1 pc     | radiator grille <i>CR</i>   | \$ 334.20    |
| 50                                | 1 pc     | radiator grille brace panel <i>R</i>  | \$ 61.50     |
| 51                                | 1 pc     | air-con condensor <i>11</i>   | \$ 1,431.90  |
| 52                                | 1 pc     | radiator assy <i>11</i>   | \$ 2,257.67  |
| Less 25 %                         |          |   | \$ 16,268.17 |
|                                   |          |   | \$ 4,067.04  |
|                                   |          |   | \$ 12,201.13 |
| <u>SPECIAL NETT ITEMS</u>         |          |   |              |
| 53                                | 1 pc     | tailgate lid 70km/h sticker <i>ref</i>  | \$ 25.00     |
| 54                                | 1 pc     | tailgate lid accessory sticker <i>ref</i>   | \$ 100.00    |
| 55                                | 1 pc     | rear license plate <i>ref</i>   | \$ 80.00     |
| 56                                | 1 pc     | reverse camera lens <i>shut</i>   | \$ 600.00    |
| 57                                | 1 pc     | sundrice and clips <i>11</i>  | \$ 180.00    |
| 58                                | 1 pc     | rear bumper parking sensor <i>shut</i>  | \$ 450.00    |
| 59                                | 1 pc     | front license plate <i>ref</i>  | \$ 80.00     |
|                                   |          |   | \$ 1,515.00  |
| <u>LABOUR &amp; MISC. CHARGES</u> |          |   |              |
| 01                                |          | Towing charges  | \$ 11 100.00 |
| 02                                |          | To check electrical lighting concerned  | \$ 80.00     |
| 03                                |          | To rust-proofing of the affected areas  | \$ 250.00    |
| 04                                |          | To reinstall of rear bumper parking sensor  | \$ 150.00    |
| 05                                |          | To remove and refit interior fittings, trimmings, garnish and other, to enable repair | \$ 11 280.00 |
| 06                                |          | To remove and refit rear windscreen glass   | \$ 180.00    |
| 07                                |          | To repair and realign rear exhaust box  | \$ 11 180.00 |
| 08                                |          | To transfer of tailgate fittings, fixture and perform waterseepage test               | \$ 150.00    |

19400.39  
 x 0.75  
 14550.28

115544  
 86648

10  
 15  
 300  
 X  
 200  
 15

X  
 30  
 100  
 50  
 X  
 120  
 X  
 60

AIGAsia Insured's Veh No : YP2481B

Date of Accident : 02 August 2018



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual  
Chassis No : JTFHT02P000179801

| S/No | Quantity | Description   | Amount              |
|------|----------|---|---------------------|
|      |          | <b>LABOUR &amp; MISC. CHARGES</b>   |                     |
| 09   |          | To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack. | \$ 550.00           |
| 10   |          | To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.   | \$ 200.00           |
| 11   |          | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.                         | \$ 2,900.00         |
| 12   |          | Putty and spray painting of the affected portion.   | \$ 1,600.00         |
|      |          |   | \$ 6,620.00         |
|      |          | <b>Total</b>  | <b>\$ 20,336.13</b> |

CKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

13265.00  
10612

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

SELL

USED CAR PARTS & ACCESSORIES

online!

MYCARFORUM

MARKETPLACE

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Rare 1 Owner 2003 Nissan Single-cab Pickup Truck!

1 Owner Since 2003! Engine, Gearbox, Brakes In Good Running Condition! Direct Owner StarAd

HIN LUNG AUTO

Ho Bee Group

One Stop Car Hub

Finance, Insurance, Workshop

New and Used Cars

30 years of car sale

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

Toyota Hiace

Advanced Search

Submit

|  | Make         | Model    | Price    | Depreciation | Reg Date    | Eng Cap  | Mileage    | Veh Type | Status    |
|--|--------------|----------|----------|--------------|-------------|----------|------------|----------|-----------|
| Search Selection   | Toyota Hiace |          | Any      | Any          | 2015        | Any      | Any        | Any      | Available |
|  | Toyota Hiace | Commuter | \$62,800 | \$8,520 /yr  | 14-Dec-2015 | 2,982 cc | 17,000 km  | Bus      | Available |
| <div><b>Fuel Type:</b> Diesel</div> <div>1 Owner! Low Mileage Of 17,000km Only. Point A To B Only. Low Depreciation \$8K Only. 11+1 Seaters. Flexible Loan With Low Interest Rate Available. Powerful Yet Quiet Engine. Well Maintained Exterior A...</div> <div>Roadlink Auto Pte Ltd</div> <div>Posted: 01-Aug-2018    Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota</div> |              |          |          |              |             |          |            |          |           |
|  | Toyota Hiace |          | \$57,800 | \$7,930 /yr  | 17-Nov-2015 | 2,982 cc | -          | Van      | Available |
| <div><b>Fuel Type:</b> Diesel</div> <div>Confirm Cheapest In Town Yet Price Still Negotiable! 5 Doors! Fully Borneo Agent Serviced! Only 1 Owner! Low Mileage Done, 100% Accident Free, Original...</div> <div>Posted: 31-Jul-2018    Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota</div>  |              |          |          |              |             |          |            |          |           |
|  | Toyota Hiace | Commuter | \$72,800 | \$10,220 /yr | 17-Sep-2015 | 2,982 cc | -          | Bus      | Available |
| <div><b>Fuel Type:</b> Diesel</div> <div>13 Seater GL Model Hi-Roof, Rare And Only One In The Market. Tip Top Condition, Excellent Surround Sound And Microphone System. Original Paintwork And Original Seat. High Trade In And High Loan Availa...</div> <div>ABWIN Bus Pte Ltd</div> <div>Posted: 30-Jul-2018    Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota</div>      |              |          |          |              |             |          |            |          |           |
|  | Toyota Hiace | Commuter | \$72,800 | \$10,330 /yr | 19-Aug-2015 | 2,982 cc | -          | Bus      | Available |
| <div><b>Fuel Type:</b> Diesel</div> <div>13+1 Seaters Super GL Hi Roof Excursion Bus. Original Condition. Low Depreciation. Direct Owner.</div> <div>Posted: 26-Jul-2018    Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota</div>  |              |          |          |              |             |          |            |          |           |
| <div>Car Buying</div> <div>Car Selling</div> <div>Car Ownership</div> <div>Car Aftermarket</div> <div>On The Move</div> <div>Lifestyle</div> <div>Blue Types Owner</div> <div>Latest Special Offers from Tyresac!</div>  |              |          |          |              |             |          |            |          |           |
|  | Toyota Hiace | Commuter | \$69,800 | \$9,990 /yr  | 27-Jul-2015 | 2,982 cc | -          | Bus      | Available |
| <div><b>Fuel Type:</b> Diesel</div> <div>\$500 Drive Away! Borneo Model 14 Seater Excursion Bus With Auto Sliding Door And Foldable Rear Seats For More Luggage Room. Very Well Maintained. Call For More Enquiries.</div> <div>ABWIN (1994) Pte Ltd</div> <div>Posted: 25-Jul-2018    Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota</div>                                   |              |          |          |              |             |          |            |          |           |
|  | Toyota Hiace | Commuter | \$72,500 | \$10,510 /yr | 26-Jun-2015 | 2,982 cc | 105,100 km | Bus      | Available |
| <div><b>Fuel Type:</b> Diesel</div> <div>Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!</div> <div>Think One Automobile &amp; Trading</div> <div>Posted: 24-Jul-2018    Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota</div>   |              |          |          |              |             |          |            |          |           |

Compare

http://www.sgcarmart.com/used\_cars/listing.php?RGD=2015&MOD=Toyota Hiace&RPG=20&VEH=0... 03-Aug-18

 > Back to OneMotoring**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0783H

**Vehicle Details**

Vehicle No.: GBE3602T

Vehicle to be Exported: No

Intended De-registration Date: 03 Aug 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR  
MANUAL

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 1KD2560762

Chassis No.: JTFHT02P000179801

Maximum Power Output: -

Open Market Value: \$27,741.00

Original Registration Date: 06 Nov 2015

First Registration Date: 06 Nov 2015

Transfer Count: 0

Actual ARF Paid: \$1,388.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 05 Nov 2025

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$43,809.00

COE Rebate Amount: \$31,785.00

**Total Rebate Amount: \$31,785.00**

The information contained herein is correct as at 03 Aug 2018

OK



AI GAsia Insured's Veh No : YP2481B

Date of Accident : 02 August 2018



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual

Chassis No : JTFHT02P000179801

| S/No | Quantity | Description   | Amount      |
|------|----------|---|-------------|
|      |          | <b>LIST ITEMS</b>   |             |
| 01   | 1 pc     | tailgate lid <i>Body</i>                                  | \$ 1,855.00 |
| 02   | 1 pc     | tailgate lid Toyota Sticker <i>new</i>                    | \$ 48.50    |
| 03   | 1 pc     | tailgate lid Hiace sticker <i>new</i>                     | \$ 48.50    |
| 04   | 1 pc     | tailgate lid outer garnish <i>garnish</i>                 | \$ 185.00   |
| 05   | 1 pc     | tailgate lid lock <i>Tw/1</i>                             | \$ 285.00   |
| 06   | 1 pc     | tailgate lid lock sticker <i>Tw/1</i>                     | \$ 78.50    |
| 07   | 1 pc     | tailgate lid weatherstrip <i>Tw/1</i>                     | \$ 368.00   |
| 08   | 1 pc     | tailgate lid key lock <i>11</i>                           | \$ 0.00     |
| 09   | 2 pc     | tailgate lid damper stay @ \$.00 <i>11</i>                | \$ 0.00     |
| 10   | 2 pc     | tailgate lid side catch @ \$35.00 <i>11</i>               | \$ 70.00    |
| 11   | 2 pc     | tailgate lid side catch latch @ \$3.00 <i>11</i>          | \$ 6.00     |
| 12   | 1 pc     | tailgate lid lock actuator                                | \$ 0.00     |
| 13   | 1 pc     | tailgate lid inner trimboard <i>Del/warp</i>              | \$ 0.00     |
| 14   | 10 pc    | tailgate lid inner trimboard clips @ \$4.50 <i>new</i>    | \$ 45.00    |
| 15   | 2 pc     | tailgate lid drain grommed @ \$.00 <i>11</i>              | \$ 0.00     |
| 16   | 1 pc     | tailgate lid centre emblem badge <i>new</i>               | \$ 0.00     |
| 17   | 1 pc     | rear windshield glass <i>shaded</i>                       | \$ 0.00     |
| 18   | 1 pc     | rear windshield glass weatherstrip                        | \$ 0.00     |
| 19   | 2 pc     | rear license plate lamp @ \$85.00 <i>11</i>               | \$ 170.00   |
| 20   | 1 pc     | rear wiper motor <i>11</i>                                | \$ 685.00   |
| 21   | 1 pc     | rear wiper arm <i>11</i>                                  | \$ 0.00     |
| 22   | 1 pc     | rear wiper arm cover <i>11</i>                            | \$ 0.00     |
| 23   | 1 pc     | rear wiper blade <i>11</i>                                | \$ 0.00     |
| 24   | 1 pc     | third brake light <i>11</i>                               | \$ 0.00     |
| 25   | 2 pc     | rear lamp @ \$322.70 <i>n/s 322.70</i>                    | \$ 645.40   |
| 26   | 1 pc     | n/s rear lamp vertical panel outer <i>3.65.00</i>         | \$ 0.00     |
| 27   | 1 pc     | n/s rear lamp vertical panel inner <i>11</i>              | \$ 0.00     |
| 28   | 1 pc     | n/s rear lamp inner 1/4 panel <i>3.65.00</i>              | \$ 0.00     |
| 29   | 1 pc     | n/s rear lamp lower apron <i>cm</i>                       | \$ 0.00     |
| 30   | 1 pc     | n/s rear wheel mudguard <i>3.65.00/2pc</i>                | \$ 1,451.00 |
| 31   | 1 pc     | rear end panel <i>3.65.00</i>                             | \$ 798.50   |
| 32   | 1 pc     | rear end panel inner top garnish <i>Tw/1</i>              | \$ 0.00     |
| 33   | 1 pc     | rear bumper <i>Dis</i>                                    | \$ 395.00   |
| 34   | 1 pc     | rear bumper beam <i>ns</i>                                | \$ 232.10   |
| 35   | 2 pc     | rear bumper side retainer @ \$27.00 <i>n/s cm</i>         | \$ 54.00    |
| 36   | 4 pc     | rear bumper side retainer holder clips @ \$4.50 <i>11</i> | \$ 18.00    |
| 37   | 1 pc     | spare tyre - carriage deck <i>11</i>                      | \$ 0.00     |
| 38   | 1 pc     | rear exhaust box <i>11</i>                                | \$ 945.00   |
| 39   | 2 pc     | rear exhaust box mount @ \$45.00 <i>11</i>                | \$ 90.00    |



AlGAsia Insured's Veh No : YP2481B

Date of Accident : 02 August 2018



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual

Chassis No : JTFHT02P000179801

| S/No | Quantity                   | Description  | Amount       |
|------|----------------------------|--|--------------|
|      |                            | <u>LIST ITEMS</u>  |              |
| 40   | 1 pc                       | front bumper <i>no/oe</i>  | \$ 500.30    |
| 41   | 1 pc                       | front bumper reinforcement top <i>ret</i>  | \$ 382.70    |
| 42   | 1 pc                       | front bumper beam bottom <i>R</i>  | \$ 345.00    |
| 43   | 2 pc                       | front bumper side holder @ \$122.60 <i>11</i>  | \$ 245.20    |
| 44   | 2 pc                       | front bumper side retainer @ \$170.10 <i>21</i>  | \$ 340.20    |
| 45   | 2 pc                       | front bumper tow cover @ \$20.00 <i>11</i>   | \$ 40.00     |
| 46   | 2 pc                       | front bumper spot lamp garnish @ \$50.00 <i>11</i>                                     | \$ 100.00    |
| 47   | 1 pc                       | front bumper centre air grille <i>cm</i>   | \$ 480.00    |
| 48   | 2 pc                       | head lamp @ \$638.00 <i>one</i>  | \$ 1,276.00  |
| 49   | 1 pc                       | radiator grille <i>cm</i>  | \$ 334.20    |
| 50   | 1 pc                       | radiator grille brace panel <i>R</i>   | \$ 61.50     |
| 51   | 1 pc                       | air-con condensor <i>11</i>  | \$ 1,431.90  |
| 52   | 1 pc                       | radiator assy <i>11</i>  | \$ 2,257.67  |
|      |                            |  | \$ 16,268.17 |
|      |                            | Less 25 %  | \$ 4,067.04  |
|      |                            |  | \$ 12,201.13 |
|      |                            | <u>SPECIAL NETT ITEMS</u>  |              |
| 53   | 1 pc                       | tailgate lid 70km/h sticker <i>ret</i>   | \$ 25.00     |
| 54   | 1 pc                       | tailgate lid accessory sticker <i>ret</i>  | \$ 100.00    |
| 55   | 1 pc                       | rear license plate <i>ret</i>  | \$ 80.00     |
| 56   | 1 <del>pc</del> <i>ret</i> | reverse camera lens <i>shut</i>  | \$ 600.00    |
| 57   | 1 pc                       | sundrice and clips <i>11</i>   | \$ 180.00    |
| 58   | 1 <del>pc</del> <i>ret</i> | rear bumper parking sensor <i>shut</i>   | \$ 450.00    |
| 59   | 1 pc                       | front license plate <i>ret</i>   | \$ 80.00     |
|      |                            |  | \$ 1,515.00  |
|      |                            | <u>LABOUR &amp; MISC. CHARGES</u>  |              |
| 01   |                            | Towing charges.  | \$ 100.00    |
| 02   |                            | To check electrical lighting concerned.  | \$ 80.00     |
| 03   |                            | To rust-proofing of the affected areas.  | \$ 250.00    |
| 04   |                            | To reinstall of rear bumper parking sensor.  | \$ 150.00    |
| 05   |                            | To remove and refit interior fittings, trimmings, garnish and other, to enable repair. | \$ 11 280.00 |
| 06   |                            | To remove and refit rear windscreen glass.   | \$ 180.00    |
| 07   |                            | To repair and realign rear exhaust box.  | \$ 11 180.00 |
| 08   |                            | To transfer of tailgate fittings, fixture and perform waterseepage test.               | \$ 150.00    |

—  
 —  
 X  
 X  
 X  
 X  
 —  
 —  
 X  
 X  
 X  
 10  
 15  
 300  
 X  
 200  
 15  
 7  
 30  
 100  
 50  
 X  
 120  
 X  
 60

AIGAsia Insured's Veh No : YP2481B

Date of Accident : 02 August 2018



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual

Chassis No : JTFHT02P000179801

| S/No   | Quantity | Description  | Amount              |
|--|----------|--|---------------------|
| 09   |          | <b>LABOUR &amp; MISC. CHARGES</b><br>To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack. | \$ 550.00           |
| 10   |          | To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.  | \$ 200.00           |
| 11   |          | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.  | \$ 2,900.00         |
| 12   |          | Putty and spray painting of the affected portion.  | \$ 1,600.00         |
|  |          |  | \$ 6,620.00         |
|  |          | <b>Total</b>   | <b>\$ 20,336.13</b> |
| <div style="border: 1px solid black; padding: 10px; margin: 10px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div> |          |  |                     |

X

X

2200

1400



## View Received Message

This mail is associated with :

**\*GBE3602T (7213232310SG)**  
**[YP24818]**

TP

PHARMED IMPORT & EXPORT PTE LTD

Aug 2 2018 12:00AM

[CHIANG KANG ENTERPRISES]

Tan Lim Motor Pte Ltd

|       |           |                |               |                |         |
|-------|-----------|----------------|---------------|----------------|---------|
| Reply | Reply All | Mark as Unread | Print Message | Delete Message | Forward |
|-------|-----------|----------------|---------------|----------------|---------|

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 06/08/2018 09:36 AM.  
**To** LKK\_HQ  
**Subject** No OI GIA Report (YP24818 VS GBE3602T)

Hi

Pls be advice that no OI GIA report received  
Pls find OI details below for your further actions:

OI name : Chiang Kang Enterprises

Address :  
4 Petain Road  
Petain Court  
Singapore 208086

Thank you.

Regards,

Syaza Indina Azlan

### DOCUMENTS SUMMARY

There are no documents.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18014119/Ufa3

10<sup>th</sup> Aug 2018

**Chiang Kang Enterprises**  
4 Petain Road  
Petain Court  
Singapore 208086

Dear Sirs,

**ACCIDENT INVOLVING YP 2481B AND GBE 3602T ON 02/08/2018 ALONG/  
AT HOUGANG AVENUE 3**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Poh Kin, Chong  
Claims  
Tel : 6841 2132  
Fax: 6741 4108  
Email : pohkin@lkkauto.com

c.c. *Claims Manager*  
*AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## Poh Kin (LKKAuto)

**From:** Johnson Chua <johnson.chua@tlimotor.com.sg>  
**Sent:** Wednesday, 12 December 2018 10:50 AM  
**To:** Poh Kin (LKKAuto)  
**Cc:** 'Wei Shong'  
**Subject:** LKK Ref: CC6/AIG18014119/Ufa3; TLM Ref: TP002082018 (GBE 3602T: DOA: 02.08.2018)

**Importance:** High

**Categories:** clear

Dear Poh Kin,

We refer to your email below.

Please let us have your Discharge Voucher for the settlement sum of \$12,419.49 as soon as possible. Thank you.

Regards,



**Johnson Chua**  
[johnson.chua@tlimotor.com.sg](mailto:johnson.chua@tlimotor.com.sg)

O. +65 6858 5151  
F. +65 6858 0877

**Tan Lim Motor Pte Ltd**  
51 Defu Lane 10  
Singapore 539216  
<http://www.tlimotor.com.sg>

**Confidentiality Notice:** This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place a program, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

**From:** Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]  
**Sent:** Tuesday, 11 December 2018 8:57 PM  
**To:** Johnson Chua <johnson.chua@tlimotor.com.sg>  
**Cc:** 'Wei Shong' <wei.shong@tlimotor.com.sg>  
**Subject:** Our Ref: CC6/AIG18014119/Ufa3; Your Ref: TP002082018 (GBE 3602T: DOA: 02.08.2018)  
**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC6/AIG18014119/Ufa3  
Your Ref: TP002082018

Dear Johnson,

We refer to the above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:

|                           |               |
|---------------------------|---------------|
| 1. Cost of Repair (w/gst) | S\$ 11,342.00 |
|---------------------------|---------------|

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Tuesday, 11 December 2018 8:57 PM  
**To:** Johnson Chua  
**Cc:** 'Wei Shong'  
**Subject:** Our Ref: CC6/AIG18014119/Ufa3; Your Ref: TP002082018 (GBE 3602T: DOA: 02.08.2018)

**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC6/AIG18014119/Ufa3  
Your Ref: TP002082018

Dear Johnson,

We refer to the above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:

|  |                             |
|--|-----------------------------|
| 1. Cost of Repair (w/gst)                    | S\$ 11,342.00               |
| 2. Loss of Rental (\$100.00 x 10 days)+7%gst | S\$ 1,070.00                |
| 3. LTA search fee                            | <u>S\$ 7.49</u>             |
|  | <u><b>S\$ 12,419.49</b></u> |

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Wednesday, 28 November 2018 6:55 PM  
**To:** 'Lee, Ming-Yao'  
**Cc:** Admin A  
**Subject:** <Seek Mandate> Your Ref: 7213232310SG \* Our Ref: CC6/AIG18014119/Ufa3  
[ACCIDENT INVOLVING YP 2481B (OI) & GBE 3602T (TP) ON 02/08/2018]

**Importance:** High

Your Ref: 7213232310SG  
Our Ref: CC6/AIG18014119/Ufa3

Dear George,

### ROAD TRAFFIC ACCIDENT INVOLVING YP 2481B (OI) & GBE 3602T (TP) AND OTHERS ALONG HOUGANG AVENUE 3 ON 02/08/2018

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle. Liability is down against our insured driver.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "Tan Lim Motor Pte Ltd" is as follows: -

|                           | <u>Amount Claimed</u>             | <u>Amount Revised</u>                   |
|---------------------------|-----------------------------------|---|
| 1. Cost of Repair (w/gst) | \$ 21,759.66(\$20,366.13 + 7%gst) | \$ 11,342.00 (\$10,600.00 + 7% gst)     |
| 2. Loss of Rental         | \$ 1,155.00(10 days with 7%gst)   | \$ 1,070.00 (10 days x \$100.00 +7%gst) |
| 3. LTA search fee         | \$ 7.49                           | \$ 7.49                                 |
| Total                     | \$ 22,922.15                      | <b>\$ 12,419.49</b>                     |

Total amount of claim (**Liability 100%**)

**\$12,419.49**

\*\*\*Recommended 8 repair days + 1 days PRI + 1 Sunday = 10 days.

All the relevant documents had been uploaded in Merimen for your perusal.

For your approval/Instruction in Merimen please.



## Print Received Message

This mail is associated with :

**\*GBE3602T (7213232310SG)**  
**[YP2481B]**

TP

PHARMED IMPORT & EXPORT PTE LTD

Aug 2 2018 3:30PM

[CHIANG KANG ENTERPRISES]

Tan Lim Motor Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 11/12/2018 14:14 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12419.49) - GBE3602T - Claim Handler: Lee, Ming-Yao

Approved:12419.49:Please proceed to settle claim at best term. Kindly ensure all docs are in order.



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref: TP002082018

Date: 03/09/2018

Your Ref: YP2481B

WITHOUT PREJUDICE

Claims Department - Motor Claims

c/o MH ASIA PACIFIC INSURANCE PLC

Dear Sir/Madam,

ACCIDENT INVOLVING GBB3602T & YP2481B ON 02.08.2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf:-

☐ Original survey report / \_\_\_\_\_ copies of photographs \_\_\_\_\_

☒ Original Tax-invoice number TP0218/032

☒ Original rental invoice number 17181240

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☒ Vehicle search result

☒ Authorisation To Act

☐ \_\_\_\_\_

\*Survey under insurance instruction - LK

|       |  |              |
|-------|--|--------------|
| a)    | Cost of repair (inclusive GST)   | \$ 11,342.00 |
| b)    | Survey fees / Photographs as per request   | \$           |
| c)    | Vehicle Search fees / GIA / Insurance Report fees / Reporting fees   | \$ 7.49      |
| d)    | Loss of hire / use / rental / expenses / rental fees   | \$ 1,155.60  |
| e)    | Scene photographs  | \$           |
| f)    | Administrative charges to negotiate settlement<br>(Waive if 100% offer made without acknowledge timeframe) | \$           |
| g)    |  | \$           |
| Total |  | \$ 12,505.09 |

\* Driver's injury and other losses excluded in this claim.

If you are agreeable to the above, please sign and exchange voucher for our client's signature and payment issued directly to Tan Lim Motor Pte Ltd within 21 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC6/AIG18014119/Ufa3**

4<sup>th</sup> September 2018

**CHIANG KANG ENTERPRISE COMPANY PTE LTD**

4 Petain Road,  
Petain Court,  
Singapore 208086.

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING YP 2481B, GBE 3602T AND GBE 8247C ALONG HOUGANG AVENUE 3 ON 02.08.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

  
Pohkin, Chong  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

AUTHORIZATION TO ACT  
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Phurmed Import & Export Pte Ltd ("the third party claimant")  
of 152 Paya Lebar Road #05-06 Chipoint @ Paya Lebar (S) 404020 (address),  
owner of GBE 3602T (vehicle no.) hereby authorize  
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. GBE 3602T that was  
damaged pursuant to the accident which occurred on 02/08/2018 (date) along  
Hougang Avenue 3 (location)  
involving vehicle no/s YP 2481B ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

☐ I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 03 day of August (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, Tan Lim Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$11,342.00 (Repair Cost), S\$1,070.00 (Loss of Use/Rental), S\$7.49 (Disbursement) for vehicle no. GBE 3602T that was damaged pursuant to the accident which occurred on 02/08/2018 (date) along Hougang Avenue 3 (location) involving vehicle no/s YP 2481B. This is pursuant to the inspection conducted on 03/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Pharmed Import & Export Pte Ltd ("the third party claimant") of vehicle no. GBE 3602T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBE 3602T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13<sup>th</sup> (day) of December (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

**TAX-INVOICE**  
**NUMBER: TP0818/032**

(Please quote our reference number TP002082018 for payment)



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

Pharmed Import & Export Pte Ltd

Date: 24/08/2018

Vehicle No: GBE3602T  
Model: TOYOTA HIACE VAN T

| Description                                    | Amount      |
|--|-------------|
| To lump sum repair as recommended by surveyor. | \$10,600.00 |
| Reimbursement of LTA search fees.              | \$7.00      |

|            |             |
|------------|-------------|
| Sub Total  | \$10,607.00 |
| Add 7% GST | \$742.49    |
| Total      | \$11,349.49 |

  
\_\_\_\_\_  
Tan Lim Motor Pte Ltd

No. 51 Defu Lane 10 Singapore 539216  
Tel : 6858 5151 (24 hours) Fax : 6858 0877  
email@timotor.com.sg www.timotor.com.sg  
Co. Reg. No.: 199503065M GST Reg. No. : M2-8922054-2



Global Advance Leasing

51 Delfi Lane 10 Singapore 539216 Telephone: 6100 0425

Business Registration Number: B52935825E

GST Reg No: 200409785W

**Bill To:** PHARMED IMPORT & EXPORT PTE LTD (CAO TAN LIM MOTOR PTE LTD)  
152 PAYA LEBAR ROAD  
#05-06 CITIPPOINT @ PAYA LEBAR  
SINGAPORE 409020

**Tax Invoice** : 17181240  
**Date** : 13 AUG 2018  
**Agreement No.** : ST7075

| Vehicle No | Description  | Total Amount             |
|------------|--|--------------------------|
| SJR5026E   | Mitsubishi Grandis 2.4L 16V 4WD<br>Rental Charges From 03-08-2018 to 13-08-2018<br>3.0 days @ \$120.00 per day<br>1.0 week @ \$720.00 per week | SGD 360.00<br>SGD 720.00 |

PAID  
20 AUG 2018  
BY:                     

Sub-Total 1,080.00  
Add: GST (7.00%) 75.60  
Amount Payable (SGD) 1,155.60

SINGAPORE DOLLAR: ONE THOUSAND ONE HUNDRED FIFTY-FIVE AND CENTS SIXTY ONLY.

Cheque should be crossed "A/C Payee Only" and should contain the words "GLOBAL ADVANCE LEASING".

Please write your invoice number on the reverse side of the cheque.

Payment should be made within 7 days from invoice.

Interest at 24% per annum on overdue account.

For bill enquiry, please call 6100 0425 / 9018 0988.





# GLOBAL ADVANCE LEASING

Biz Reg: B029000000  
GST Reg No: 294447780W  
C/o 51 De La Salle Drive, #03-01/02  
Tel: 6733-1111

Agreement: 7075

|  |  |
|--|--|
| Vehicle No <u>SJR 5026 E</u> Make & Model <u>Mit. Grandis</u> Date <u>03.08.2018</u>   |  |
| Hirer <u>Pharmad Import &amp; Export Pte Ltd</u> Class 2 / 2A / 2B / 3 / 4 / 5   |  |
| Name <u>Pharmad Import &amp; Export Pte Ltd</u> Date Out <u>03.08.2018</u>   |  |
| Address <u>152 Paya Lebar Road #05-06</u> Time Out <u>1030 hrs</u> KM Out <u>192435</u>  |  |
| Contact Person <u>Citipriya @ Paya Lebar (409020)</u> PETROL <u>E</u> <u>1/4</u> <u>1/2</u> <u>3/4</u> <u>F</u>  |  |
| 1st Driver <u>Seth Eng #1037</u> Date In <u>13.08.2018</u>   |  |
| Name <u>509 Woodlands Drive</u> Time In <u>0850 hrs</u> KM In <u>193677</u>  |  |
| Address <u>#1037A</u> PETROL <u>E</u> <u>1/4</u> <u>1/2</u> <u>3/4</u> <u>F</u>  |  |
| (H/P) <u>1037A</u>   |  |
| Passport/NTIC No <u>1037A</u>  |  |
| Driving Licence No <u>1037A</u>  |  |
| Country of Issue <u>1037A</u>  |  |
| Additional Driver <u>Class 2 / 2A / 2B / 3 / 4 / 5</u>   |  |
| Name <u>1037A</u>  |  |
| Address <u>1037A</u>   |  |
| (H/P) <u>1037A</u>   |  |
| Passport/NTIC No <u>1037A</u>  |  |
| Driving Licence No <u>1037A</u>  |  |
| Country of Issue <u>1037A</u>  |  |
| Non Waivable Excess <u>1037A</u>   |  |
| The Hirer acknowledges a \$ <u>1037A</u> accident applies  |  |
| X <u>1037A</u>   |  |
| Collision Damage Waiver (CDW)  |  |
| The Hirer may limit his liability for any damage arising from collision to E <u>1037A</u> by purchasing CDW and paying the specified sum.  |  |
| X <u>1037A</u>   |  |
| Personal Accident Insurance (PAI)  |  |
| PAI may be purchased at a specified premium. The Hirer acknowledges that the insurance is written by an external agent and that he has received, read and understood the policy cover. |  |
| X <u>1037A</u>   |  |
| Special Instructions <u>1037A</u>  |  |
| Check Out / Check In <u>03.08.2018</u>   |  |
| Date Out <u>03.08.2018</u>   |  |
| Time Out <u>1030 hrs</u> KM Out <u>192435</u>  |  |
| PETROL <u>E</u> <u>1/4</u> <u>1/2</u> <u>3/4</u> <u>F</u>  |  |
| Date In <u>13.08.2018</u>  |  |
| Time In <u>0850 hrs</u> KM In <u>193677</u>  |  |
| PETROL <u>E</u> <u>1/4</u> <u>1/2</u> <u>3/4</u> <u>F</u>  |  |
| Mode of Payment  |  |
| Cash / Cheque / Company Billing / Credit Card / Others   |  |
| Cheque / Card Details: <u>1037A</u>  |  |
| Expiry Date: <u>1037A</u>  |  |
| Rental Charges   |  |
| 03 Days @ \$ <u>120.00</u> /day \$ <u>360.00</u>   |  |
| 01 Week @ \$ <u>40.00</u> /week \$ <u>40.00</u>  |  |
| Month @ \$ <u>100.00</u> /month \$ <u>100.00</u>   |  |
| SUBTOTAL \$ <u>1155.60</u>   |  |
| CDW \$ <u>1037A</u>  |  |
| PAI \$ <u>1037A</u>  |  |
| Petrol Top Up \$ <u>1037A</u>  |  |
| Delivery / Collection fee \$ <u>1037A</u>  |  |
| Misc \$ <u>1037A</u>   |  |
| Misc \$ <u>1037A</u>   |  |
| Less \$ <u>1037A</u>   |  |
| Pre-Payment / Deposit (\$ <u>1037A</u> )   |  |
| Misc (\$ <u>1037A</u> )  |  |
| Total Due \$ <u>1155.60</u>  |  |
| Charges Subject to Final Audit   |  |
| Refundable Deposit   |  |
| Deposit \$ <u>1037A</u>  |  |
| Date of Refund <u>1037A</u>  |  |
| Refund Acknowledgement X <u>1037A</u>  |  |
| For Official Use   |  |
| Invoice No: <u>17181040</u> Date <u>12.08.2018</u>   |  |
| Receipt No <u>1037A</u> Date <u>1037A</u>  |  |

## Important Notes

1. Rental Vehicle is strictly for Corporate use only and may not be used for other purposes without prior consent of the owner.
2. Only persons authorized by Global Advance Leasing may use the vehicle.
3. All parking and traffic violations, fines and penalties shall be levied on any traffic violations redirected.
4. The Hirer shall be responsible for any damage to the vehicle.
5. In the event of an accident, the Hirer shall report to the police and the owner.

We have read and agreed to the terms and conditions of this agreement and certify that the information given is true and correct. If I/we opt to pay by credit / charge card, I agree that all amounts payable shall be deemed to have been made on the applicable credit card charge slip.

X

(Hirer's signature)

(Authorized Person's signature)

(Global Advance Leasing)

**Enquire Vehicle & Owner Information [ Vehicle No. YP2481B As At 02 Aug 2018 / 16:10:00 ]**

**Law Firm Search Details**

**Search Reason:** Insurance claim in relation to traffic accident

**Law Firm Case No.:** GBE3602T

**Current Owner Details**

**Owner ID Type:** Company

**Owner ID:** 198304039K

**Owner Name:** CHIANG KANG ENTERPRISES COMPANY PTE. LTD.

**Registered Address Type:** Private Residential (Condo Apt or House) / Shopping / Office Complexes

**Registered Block/House No.:** 4

**Registered Street Name:** PETAIN ROAD

**Registered Unit No.:** -

**Registered Building Name:** PETAIN COURT

**Registered Postal Code:** 200785

**Current Vehicle Details**

**Vehicle No.:** YP2481B

**Make Description/Model:** HINO / HINO XZU710R-HKCHS3

**Insurance Company Name:** AIG ASIA PACIFIC INSURANCE PTE. LTD.



# Thank you

Lee Ming Hui Kelvin has successfully logged out.

Your last login date and time was 03 Aug 2018, 10:16:40.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

| S/No. | Asset Type | Asset ID | Asset Owner ID | Transaction Type                                 | Transaction Amount(\$\$) | Log Date/Time             |
|-------|------------|----------|----------------|--|--------------------------|---------------------------|
| 1     | Vehicle    | YP2481B  |                | 15.17 Days Veh Owner Info<br>10.17 Days Veh Firm | 7.49                     | 03 Aug 2018 /<br>10:17:39 |

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt   | Adj Submitted                                   | Ins Auth'd | Status  |
|------|---|---------------|--|---|---|------------|---|
| Main | 03 Aug 2018<br><a href="#">Edit Reg</a> |               | 03 Aug 2018<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$10,600.00</b><br><a href="#">Edit Estimates</a> | <b>S\$10,600.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main   | Reference  | Claim Details          | Documents  | Show All |         |             |              |            |       |
|--|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>  |  |                        |  |          |         |             |              |            |       |
| Insured:   | <b>CHIANG KANG ENTERPRISES COMPANY PTE LTD</b> , Co. Reg. No.: 198304039K  |                        |  |          |         |             |              |            |       |
| Main Claimant:   | <b>PHARMED IMPORT &amp; EXPORT PTE LTD</b> , Co. Reg. No.: 198400783H  |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:  | <b>GBE3602T</b>  | Date of Loss:          | 02/08/2018 15:00 - :59<br>[32 Months and 27 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:  | <b>TP / 7213232310SG</b>   | Policy/Cover Note No.: | (Comprehensive)  |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):  | <b>YP2481B</b>   | Policy No. (Claimant): | 8-V0013923-MVR-R001  |          |         |             |              |            |       |
|  |  | Excess:                |  |          |         |             |              |            |       |
| Repairer:  | <b>Tan Lim Motor Pte Ltd (Defu)</b> 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151   |                        |  |          |         |             |              |            |       |
| Handling Insurer:  | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com |                        |  |          |         |             |              |            |       |
| Claimant's Insurer:  | <b>QBE Insurance (Singapore) Pte Ltd (HQ)</b> - Tel: 62246633  |                        |  |          |         |             |              |            |       |
| Adjuster:  | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 15/08/2018]        |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>  |  |                        |  |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (11/12/2018): Alert - Adj Mandate Approved (S\$12419.49) - GBE3602T - Claim Handler: Lee, Ming-...</li> <li>AIG_SG (06/08/2018): No OI GIA Report (YP2481B VS GBE3602T)</li> <li>AIG_SG (06/08/2018): Request To Upload TP GIA Report</li> </ul> |  |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>  |  |                        |  |          |         |             |              |            |       |
| Due Date   | Priority   | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.  |  |                        |  |          |         |             |              |            |       |

## Claim Documents

\*GBE3602T (7213232310SG)  
[YP2481B]

TP



















































PHARMED IMPORT & EXPORT PTE LTD



















































Aug 2 2018 3:30PM

[CHIANG KANG ENTERPRISES COMPANY PTE LTD]

Tan Lim Motor Pte Ltd

|                         |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  |              |           |             |                 |  |  |
|-------------------------|-----------------|--|--|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|--------------|-----------|-------------|-----------------|--|--|
| Upload Documents        |                 |  | Upload Photos  |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View         |           |             | View in Browser |  |  |
| Video                   |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  | 1 per page   |           | <div></div> | <div></div>     |  |  |
| No                      | Finalized On    |  | LKK Auto Consultants Pte Ltd (HQ)  |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail    |           | Print       |                 |  |  |
| 1                       | 06/08/18 15:20  |  | Video - Accident   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load MP4  |             |                 |  |  |
|                         |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  |              |           |             |                 |  |  |
| Letters/Correspondences |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  | 1 per page   |           | <div></div> | <div></div>     |  |  |
| No                      | Finalized On    |  | LKK Auto Consultants Pte Ltd (HQ)  |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail    |           | Print       |                 |  |  |
| 1                       | (Draft)         |  | Third Party Express Settlement – Payment Breakdown   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Edit      |             |                 |  |  |
|                         |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  |              |           |             |                 |  |  |
| Assessment Reports      |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  | 1 per page   |           | <div></div> | <div></div>     |  |  |
| No                      | Finalized On    |  | AIG Asia Pacific Insurance Pte. Ltd. (SG)  |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail    |           | Print       |                 |  |  |
| 1                       | 13/08/18 12:02  |  | Accident Statement<br><small>From:OD - Reg. No: YP2481B, Claimant: CHIANG KANG ENTERPRISES COMPANY PTE LTD</small> |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load HTML |             |                 |  |  |
|                         |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  |              |           |             |                 |  |  |
| Photos/Images           |                 |  |  |  |  |                    |  |  |              |  |  |              |  |  | 3 per page   |           | <div></div> | <div></div>     |  |  |
| No                      | Relabel/Reorder |  | LKK Auto Consultants Pte Ltd (HQ)  |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail    |           | Print       |                 |  |  |
| 1                       | 04/08/18 12:28  |  | Chassis Number   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 2                       | 04/08/18 12:28  |  | Odometer Reading   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 3                       | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 4                       | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 5                       | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 6                       | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 7                       | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 8                       | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 9                       | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 10                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 11                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 12                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 13                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 14                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 15                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 16                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 17                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 18                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 19                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 20                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 21                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 22                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 23                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 24                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 25                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 26                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  | <div>1</div> | Load JPG  | <div></div> |                 |  |  |
| 27                      | 04/08/18 12:34  |  | General View   |  |  |                    |  |  |              |  |  |              |  |  |              | Load JPG  | <div></div> |                 |  |  |

| Video |                |                                   | 1 per page   | <input checked="" type="checkbox"/> |
|-------|----------------|-----------------------------------|--|-------------------------------------|
| No    | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
|       |                |                                   |             | <input checked="" type="checkbox"/> |
| 28    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 29    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 30    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 31    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 32    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 33    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 34    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 35    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 36    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49    | 04/08/18 12:34 | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 50    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 51    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 52    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 53    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 54    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 55    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 56    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 57    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 58    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 59    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 60    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 64    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 65    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 66    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 67    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 68    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 69    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 70    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 71    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 72    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 73    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 74    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 75    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 76    | 04/08/18 12:34 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |

| Video |                |                                   | 1 per page   | <input checked="" type="checkbox"/> |
|-------|----------------|-----------------------------------|--|-------------------------------------|
| No    | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 77    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 78    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 79    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 80    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 81    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 82    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 83    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 84    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 85    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 86    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 87    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 88    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 89    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 90    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 91    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 92    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 93    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 94    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 95    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 96    | 04/08/18 12:34 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 97    | 04/08/18 12:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 98    | 04/08/18 12:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 99    | 04/08/18 12:35 | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 100   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 101   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 102   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 103   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 104   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 105   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 106   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 107   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 108   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 109   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 110   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 111   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 112   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 113   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 114   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 115   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 116   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 117   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 118   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 119   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 120   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 121   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 122   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 123   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 124   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 125   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 126   | 04/08/18 12:35 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |



| Video         |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No            | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 127           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 128           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 129           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 130           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 131           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 132           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 133           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 134           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 135           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 136           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 137           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 138           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 139           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 140           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 141           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 142           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 143           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 144           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 145           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 146           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 147           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 148           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 149           | 04/08/18 12:35  | General View                      |            | <input checked="" type="checkbox"/> |
| 150           | 13/12/18 09:27  | Reinspection Photo-after repair   |            | <input checked="" type="checkbox"/> |
| 151           | 13/12/18 09:27  | Reinspection Photo-after repair   |            | <input checked="" type="checkbox"/> |
| 152           | 13/12/18 09:27  | Reinspection Photo-after repair   |            | <input checked="" type="checkbox"/> |
| 153           | 13/12/18 09:27  | Reinspection Photo-after repair   |            | <input checked="" type="checkbox"/> |
| 154           | 13/12/18 09:27  | Reinspection Photo-after repair   |            | <input checked="" type="checkbox"/> |
| 155           | 13/12/18 09:27  | Reinspection Photo-after repair   |            | <input checked="" type="checkbox"/> |
| 156           | 13/12/18 09:27  | Reinspection Photo-after repair   |            | <input checked="" type="checkbox"/> |
| Documentation |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 06/08/18 15:19  | TP GIA REPORT                     |            |                                     |
| 2             | 10/08/18 00:50  | TP ESTIMATE - MARKED.             |            |                                     |
| 3             | 13/08/18 10:28  | Non reporting letter              |            |                                     |
| 4             | 04/09/18 16:51  | LETTER TO OI                      |            |                                     |
| 5             | 23/11/18 16:45  | RENTAL RECEIPT                    |            |                                     |
| 6             | 14/12/18 12:03  | WORKSHOP INVOICE                  |            |                                     |
| 7             | 14/12/18 12:03  | AUTHORISATION TO ACT FORM         |            |                                     |
| 8             | 14/12/18 12:03  | Release Voucher                   |            |                                     |
| 9             | 14/12/18 12:03  | LTA SEARCH                        |            |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

|                   |                    |        |                    |
|-------------------|--------------------|--------|--------------------|
| Vehicle No:       | YP2481B (Insd veh) | Model: | TOYOTA HIACE 3.0 D |
|                   | GBE3602T (TP veh)  |        | TURBO 5 DR (M)     |
| Date of Accident: | 02/08/2018         |        |                    |

|                       |   |                              |  |
|-----------------------|---|------------------------------|--|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate       | : | \$                           | 24,273.25                              |
| Final Repair Cost     | : | \$                           | 11,342.00                              |
| Loss of Use           | : | \$                           | _____ days at \$0.00 per day           |
| Rental (if any)       | : | \$                           | 1,070.00 10 days                       |
| LTA / GIA Search Fee  | : | \$                           | 7.49                                   |
| Others:               | : | \$                           | 0.00                                   |
|                       | : | \$                           |  |
| Final Settlement Sum  | : | \$                           | 12,419.49                              |

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_100\_\_\_\_\_(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_100\_\_\_\_\_(%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                       |   |              |
|--|-----------------------|---|--------------|
| 1)                                     | Tan Lim Motor Pte Ltd | : | \$ 12,419.49 |
| 2)                                     |                       | : | \$           |
| 3)                                     |                       | : | \$           |
| 4)                                     |                       | : | \$           |

JOANNE LEE KHANG MIN

14 Dec  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18014119/UFA3Q2

Date: 14/12/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: GBE3602T

Insured Vehicle No: YP2481B

Date of Loss: 02/08/2018

Nature of Claim: TP

Claim No: 7213232310SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE3602T

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: 1KD2560762

Reg. Date: 06/11/2015 (Man. Year: 2015)

Chassis No: JTFHT02P000179801

Colour: White

Odometer: 69423 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185 R15

Rear Tyre Size: 185 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS   | Repairer's       | Adjuster's       | Difference       | Diff %       |
|--|------------------|------------------|------------------|--------------|
| Parts  | 16,065.28        | 9,305.80         | 6,759.48         | 42.08        |
| Miscellaneous Items  | 0.00             | 0.00             | 0.00             |              |
| Labour   | 6,620.00         | 3,960.00         | 2,660.00         | 40.18        |
| Paintwork Labour   | 0.00             | 0.00             | 0.00             |              |
| Towing   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>                          | <b>22,685.28</b> | <b>13,265.80</b> | <b>9,419.48</b>  | <b>41.52</b> |
| <b>Approved Total (Overridden) (S\$)</b>                     |                  | <b>10,600.00</b> |                  |              |
| (S\$)  | 22,685.28        | 10,600.00        | 12,085.28        | 53.27        |
| <b>+ GST 7.00/7.00% (S\$)</b>                                | <b>1,587.97</b>  | <b>742.00</b>    | <b>845.97</b>    | <b>53.27</b> |
| <b>Nett Amount (S\$)</b>                                     | <b>24,273.25</b> | <b>11,342.00</b> | <b>12,931.25</b> | <b>53.27</b> |
| <b>+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)</b> |                  | 1,070.00         |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                                |                  | 7.49             |                  |              |
| <b>Nett Liability (S\$)</b>                                  |                  | <b>12,419.49</b> |                  |              |

### INSPECTION

Date of Assignment: 03/08/2018

Date Inspected: 03/08/2018 Inspected At:

Tan Lim Motor Pte Ltd (Defu)  
51 Defu Lane 10  
Singapore 539216

Estimated Period of Repair: 8.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Chong Poh Kin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition              | Repairer's  | Amount       |
|-----|-----|----------|---|------------------------|-------------|--------------|
| 1   | 1   |          | *TAILGATE LID                             | Badly Dented           | 1,855.00 FL | *1,855.00 FL |
| 2   | 1   |          | *TAILGATE LID TOYOTA STICKER              | Necessary              | 48.50 FL    | *48.50 FL    |
| 3   | 1   |          | *TAILGATE LID HIACE STICKER               | Necessary              | 48.50 FL    | *48.50 FL    |
| 4   | 1   |          | *TAILGATE LID OUTER GARNISH               | Grazed                 | 185.00 FL   | *185.00 FL   |
| 5   | 1   |          | *TAILGATE LID LOCK                        | Twisted / Jammed       | 285.00 FL   | *285.00 FL   |
| 6   | 1   |          | *TAILGATE LID LOCK STICKER                | Twisted                | 78.50 FL    | *78.50 FL    |
| 7   | 1   |          | *TAILGATE LID WEATHERSTRIP                | Twisted                | 368.00 FL   | *368.00 FL   |
| 8   | 1   |          | *TAILGATE LID KEY LOCK (NPA)              | Not Necessary          | 0.00 FL     | *- FL        |
| 9   | 2   |          | *TAILGATE LID DAMPER STAY (NPA)           | Not Necessary          | 0.00 FL     | *- FL        |
| 10  | 2   |          | *TAILGATE LID SIDE CATCH                  | Not Necessary          | 70.00 FL    | *- FL        |
| 11  | 2   |          | *TAILGATE LID SIDE CATCH LATCH            | Not Necessary          | 6.00 FL     | *- FL        |
| 12  | 1   |          | *TAILGATE LID LOCK ACTUATOR (NPA)         | Not Necessary          | 0.00 FL     | *- FL        |
| 13  | 1   |          | *TAILGATE LID INNER TRIMBOARD             | Deformed / Warped      | 456.80 FL   | *456.80 FL   |
| 14  | 10  |          | *TAILGATE LID INNER TRIMBOARD CLIPS       | Necessary              | 45.00 FL    | *45.00 FL    |
| 15  | 2   |          | *TAILGATE LID DRAIN GROMMED (NPA)         | Not Necessary          | 0.00 FL     | *- FL        |
| 16  | 1   |          | *TAILGATE LID CENTRE EMBLEM BADGE         | Necessary              | 78.00 FL    | *78.00 FL    |
| 17  | 1   |          | *REAR WINDSHIELD GLASS                    | Shorted                | 1,289.00 FL | *1,289.00 FL |
| 18  | 1   |          | *REAR WINDSHIELD GLASS WEATHERSTRIP (NPA) | No such part           | 0.00 FL     | *- FL        |
| 19  | 2   |          | *REAR LICENCE PLATE LAMP                  | Not Necessary          | 170.00 FL   | *- FL        |
| 20  | 1   |          | *REAR WIPER MOTOR                         | Not Necessary          | 685.00 FL   | *- FL        |
| 21  | 1   |          | *REAR WIPER ARM (NPA)                     | Not Necessary          | 0.00 FL     | *- FL        |
| 22  | 1   |          | *REAR WIPER ARM COVER (NPA)               | Not Necessary          | 0.00 FL     | *- FL        |
| 23  | 1   |          | *REAR WIPER BLADE (NPA)                   | Not Necessary          | 0.00 FL     | *- FL        |
| 24  | 1   |          | *THIRD BRAKE LIGHT (NPA)                  | Not Necessary          | 0.00 FL     | *- FL        |
| 25  | 1   |          | *REAR LAMP                                | N/S Broken             | 645.40 FL   | *322.70 FL   |
| 26  | 1   |          | *N/S REAR LAMP VERTICAL PANEL OUTER       | Badly Dented           | 303.70 FL   | *303.70 FL   |
| 27  | 1   |          | *N/S REAR LAMP VERTICAL PANEL INNER       | Repair                 | 458.70 FL   | *- FL        |
| 28  | 1   |          | *N/S REAR LAMP INNER 1/4 PANEL            | Badly Dented           | 45.60 FL    | *45.60 FL    |
| 29  | 1   |          | *N/S REAR LAMP LOWER APRON                | Cracked                | 102.60 FL   | *102.60 FL   |
| 30  | 1   |          | *N/S REAR WHEEL MUDGUARD                  | Badly Dented / Buckled | 1,451.00 FL | *1,451.00 FL |
| 31  | 1   |          | *REAR END PANEL                           | Badly Dented           | 798.50 FL   | *798.50 FL   |
| 32  | 1   |          | *REAR END PANEL INNER TOP GARNISH         | Twisted                | 128.00 FL   | *128.00 FL   |
| 33  | 1   |          | *REAR BUMPER                              | Distorted              | 395.00 FL   | *395.00 FL   |
| 34  | 1   |          | *REAR BUMPER BEAM                         | No such part           | 232.10 FL   | *- FL        |
| 35  | 1   |          | *REAR BUMPER SIDE RETAINER                | N/S Cracked            | 54.00 FL    | *27.00 FL    |
| 36  | 4   |          | *REAR BUMPER SIDE RETAINER HOLDER CLIPS   | Not Necessary          | 18.00 FL    | *- FL        |
| 37  | 1   |          | *SPARE TYRE -CARRIAGE DECK                | Bent                   | 269.80 FL   | *269.80 FL   |
| 38  | 1   |          | *REAR EXHAUST BOX                         | Not Necessary          | 945.00 FL   | *- FL        |
| 39  | 2   |          | *REAR EXHAUST BOX MOUNT                   | Not Necessary          | 90.00 FL    | *- FL        |
| 40  | 1   |          | *FRONT BUMPER                             | Dented / Deformed      | 500.30 FL   | *500.30 FL   |
| 41  | 1   |          | *FRONT BUMPER REINFORCEMENT TOP           | Bent                   | 382.70 FL   | *382.70 FL   |
| 42  | 1   |          | *FRONT BUMPER BEAM BOTTOM                 | Repair                 | 345.00 FL   | *- FL        |
| 43  | 2   |          | *FRONT BUMPER SIDE HOLDER                 | Not Necessary          | 245.20 FL   | *- FL        |
| 44  | 2   |          | *FRONT BUMPER SIDE RETAINER               | Not Necessary          | 340.20 FL   | *- FL        |
| 45  | 2   |          | *FRONT BUMPER TOW COVER                   | Not Necessary          | 40.00 FL    | *- FL        |
| 46  | 2   |          | *FRONT BUMPER SPOT LAMP GARNISH           | Not Necessary          | 100.00 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 47  | 1   |          | *FRONT BUMPER CENTRE AIR GRILLE | Cracked       | 480.00 FL   | *480.00 FL   |
| 48  | 2   |          | *HEAD LAMP                      | Cracked       | 1,276.00 FL | *1,276.00 FL |
| 49  | 1   |          | *RADIATOR GRILLE                | Cracked       | 334.20 FL   | *334.20 FL   |
| 50  | 1   |          | *RADIATOR GRILLE BRACE PANEL    | Repair        | 61.50 FL    | *- FL        |
| 51  | 1   |          | *AIR-CON CONDENSOR              | Not Necessary | 1,431.90 FL | *- FL        |
| 52  | 1   |          | *RADIATOR ASSY                  | Not Necessary | 2,257.67 FL | *- FL        |
| 53  | 1   |          | *TAILGATE LID 70KM/H STICKER    | Necessary     | 25.00 FS    | *10.00 FS    |
| 54  | 1   |          | *TAILGATE LID ACCESSORY STICKER | Necessary     | 100.00 FS   | *100.00 FS   |
| 55  | 1   |          | *REAR LICENCE PLATE             | Bent          | 80.00 FS    | *15.00 FS    |
| 56  | 1   |          | *SET REVERSE CAMERA LENS        | Shorted       | 600.00 FS   | *300.00 FS   |
| 57  | 1   |          | *SUNDRICE AND CLIPS             | Not Necessary | 180.00 FS   | *- FS        |
| 58  | 1   |          | *SET REAR BUMPER PARKING SENSOR | Shorted       | 450.00 FS   | *200.00 FS   |
| 59  | 1   |          | *FRONT LICENCE PLATE            | Bent          | 80.00 FS    | *15.00 FS    |

F=Franchise part. S=SpocNett. L=ListItemDisc.

Sub Total (S\$) 20,915.37 12,194.40

- List Item Discount on L Items 25.00/25.00% (S\$) 4,850.09 2,888.60

Total Parts (S\$) 16,065.28 9,305.80

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | TOWING CHARGES  | New      | 100.00          | 0.00            |
| 2                               | TO CHECK ELECTRICAL LIGHTING CONCERNED  | New      | 80.00           | 30.00           |
| 3                               | TO RUST-PROOFING OF THE AFFECTED AREAS  | New      | 250.00          | 100.00          |
| 4                               | TO REINSTALL OF REAR BUMPER PARKING SENSOR  | New      | 150.00          | 50.00           |
| 5                               | TO REMOVE AND REFIT INTERIRO<br>FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE<br>REPAIR   | New      | 280.00          | 0.00            |
| 6                               | TO REMOVE AND REFIT REAR WINDSCREEN GLASS   | New      | 180.00          | 120.00          |
| 7                               | TO REPAIR AND REALIGN REAR EXHAUST BOX  | New      | 180.00          | 0.00            |
| 8                               | TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND<br>PERFORM WATERSEEPAGE TEST  | New      | 150.00          | 60.00           |
| 9                               | TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND<br>PARALLEL MEASUREMENT AND CORRECT TO<br>MANUFACTURER SPECIFICATION WITH HYDRAULIC<br>PNEUMATIC JACK | New      | 550.00          | 0.00            |
| 10                              | TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF<br>PARTS ,VACUUM AND CHARGE-IN GAS   | New      | 200.00          | 0.00            |
| 11                              | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE<br>NECESSARY PORTION ,REMOVE AND RENEWAL OF<br>PARTS ,ADJUST AND REALIGN THE SAME                            | New      | 2,900.00        | 2,200.00        |
| 12                              | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION  | New      | 1,600.00        | 1,400.00        |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>6,620.00</b> | <b>3,960.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >