

AlGAsia Insured's Veh No : YP2481B
Date of Accident : 02 August 2018

not Allowed
3/8/18
The photo taken by
8 day.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual
Chassis No : JTFHT02P000179801

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>Book 3.00</i>	\$ 1,855.00
02	1 pc	tailgate lid Toyota Sticker <i>neu</i>	\$ 48.50
03	1 pc	tailgate lid Hiace sticker <i>neu</i>	\$ 48.50
04	1 pc	tailgate lid outer garnish <i>garnish</i>	\$ 185.00
05	1 pc	tailgate lid lock <i>twi/gm</i>	\$ 285.00
06	1 pc	tailgate lid lock sticker <i>twi</i>	\$ 78.50
07	1 pc	tailgate lid weatherstrip <i>twi</i>	\$ 368.00
08	1 pc	tailgate lid key lock <i>11</i>	\$ 0.00
09	2 pc	tailgate lid damper stay @ \$.00 <i>11</i>	\$ 0.00
10	2 pc	tailgate lid side catch @ \$35.00 <i>11</i>	\$ 70.00
11	2 pc	tailgate lid side catch latch @ \$3.00 <i>11</i>	\$ 6.00
12	1 pc	tailgate lid lock actuator	\$ 0.00
13	1 pc	tailgate lid inner trimboard <i>Del/warp</i>	\$ 0.00
14	10 pc	tailgate lid inner trimboard clips @ \$4.50 <i>neu</i>	\$ 45.00
15	2 pc	tailgate lid drain grommed @ \$.00 <i>n1</i>	\$ 0.00
16	1 pc	tailgate lid centre emblem badge <i>neu</i>	\$ 0.00
17	1 pc	rear windshield glass <i>shrub</i>	\$ 0.00
18	1 pc	rear windshield glass weatherstrip	\$ 0.00
19	2 pc	rear license plate lamp @ \$85.00 <i>11</i>	\$ 170.00
20	1 pc	rear wiper motor <i>n1</i>	\$ 685.00
21	1 pc	rear wiper arm <i>11</i>	\$ 0.00
22	1 pc	rear wiper arm cover <i>11</i>	\$ 0.00
23	1 pc	rear wiper blade <i>11</i>	\$ 0.00
24	1 pc	third brake light <i>11</i>	\$ 0.00
25	2 pc	rear lamp @ \$322.70 <i>n/s BRO</i>	\$ 645.40
26	1 pc	n/s rear lamp vertical panel outer <i>3.15.00</i>	\$ 0.00
27	1 pc	n/s rear lamp vertical panel inner <i>n</i>	\$ 0.00
28	1 pc	n/s rear lamp inner 1/4 panel <i>3.15.00</i>	\$ 0.00
29	1 pc	n/s rear lamp lower apron <i>cm</i>	\$ 0.00
30	1 pc	n/s rear wheel mudguard <i>3.15.00/2uc</i>	\$ 1,451.00
31	1 pc	rear end panel <i>3.15.00</i>	\$ 798.50
32	1 pc	rear end panel inner top garnish <i>twi</i>	\$ 0.00
33	1 pc	rear bumper <i>Dis</i>	\$ 395.00
34	1 pc	rear bumper beam <i>ns</i>	\$ 232.10
35	2 pc	rear bumper side retainer @ \$27.00 <i>n/s cm</i>	\$ 54.00
36	4 pc	rear bumper side retainer holder clips @ \$4.50 <i>n1</i>	\$ 18.00
37	1 pc	spare tyre - carriage deck <i>bu</i>	\$ 0.00
38	1 pc	rear exhaust box <i>11</i>	\$ 945.00
39	2 pc	rear exhaust box mount @ \$45.00 <i>11</i>	\$ 90.00

Handwritten marks and notes in the right margin of the table, including checkmarks, crosses, and symbols like 'x', '11', '12', '13', '14', '15', '16', '17', '18', '19', '20', '21', '22', '23', '24', '25', '26', '27', '28', '29', '30', '31', '32', '33', '34', '35', '36', '37', '38', '39'.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : YP2481B

Date of Accident : 02 August 2018

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual

Chassis No : JTFHT02P000179801

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
40	1 pc	front bumper <i>no/oe</i>	\$ 500.30
41	1 pc	front bumper reinforcement top <i>but</i>	\$ 382.70
42	1 pc	front bumper beam bottom <i>R</i>	\$ 345.00
43	2 pc	front bumper side holder @ \$122.60 <i>11</i>	\$ 245.20
44	2 pc	front bumper side retainer @ \$170.10 <i>11</i>	\$ 340.20
45	2 pc	front bumper tow cover @ \$20.00 <i>11</i>	\$ 40.00
46	2 pc	front bumper spot lamp garnish @ \$50.00 <i>11</i>	\$ 100.00
47	1 pc	front bumper centre air grille <i>one</i>	\$ 480.00
48	2 pc	head lamp @ \$638.00 <i>one</i>	\$ 1,276.00
49	1 pc	radiator grille <i>one</i>	\$ 334.20
50	1 pc	radiator grille brace panel <i>R</i>	\$ 61.50
51	1 pc	air-con condensor <i>11</i>	\$ 1,431.90
52	1 pc	radiator assy <i>11</i>	\$ 2,257.67
			\$ 16,268.17
		Less 25 %	\$ 4,067.04
			\$ 12,201.13
		<u>SPECIAL NETT ITEMS</u>	
53	1 pc	tailgate lid 70km/h sticker <i>one</i>	\$ 25.00
54	1 pc	tailgate lid accessory sticker <i>one</i>	\$ 100.00
55	1 pc	rear license plate <i>but</i>	\$ 80.00
56	1 pc	reverse camera lens <i>shut</i>	\$ 600.00
57	1 pc	sundrice and clips <i>11</i>	\$ 180.00
58	1 pc	rear bumper parking sensor <i>shut</i>	\$ 450.00
59	1 pc	front license plate <i>but</i>	\$ 80.00
			\$ 1,515.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Towing charges.	\$ 100.00
02		To check electrical lighting concerned.	\$ 80.00
03		To rust-proofing of the affected areas.	\$ 250.00
04		To reinstall of rear bumper parking sensor.	\$ 150.00
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 280.00
06		To remove and refit rear windscreen glass.	\$ 180.00
07		To repair and realign rear exhaust box.	\$ 180.00
08		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : YP2481B

Date of Accident : 02 August 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Pharmed Import & Export Pte Ltd

Date : 03 August 2018

Estimate To Repair GBE3602T - Toyota Hiace Van Turbo 5 DR Manual

Chassis No : JTFHT02P000179801

S/No	Quantity	Description	Amount
09		<u>LABOUR & MISC. CHARGES</u> To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 11 550.00 X
10		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 11 200.00 X
11		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,900.00 2200
12		Putty and spray painting of the affected portion.	\$ 1,600.00 1400
			\$ 6,620.00
		Total	\$ 20,336.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: