



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

02/08/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AXA

Xico Tony

Accident date: 28/07/2018

Estimated repair cost for vehicle no: SLH9049S TOYOTA ALTIS 1.6 A '16

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Boot Lid		\$781.90 *
2	1	Rear Boot Lid Emblem Logo		\$122.10 *
3	1	Rear Boot Lid Corolla Logo		\$123.05 *
4	1	Rear Boot Lid Altis Logo		\$141.45 *
5	1	Rear Boot Lid Centre Chrome Moulding	NA	\$374.50 *
6	2	Rear Boot Lid Side Reflector	NA \$361.90	\$723.80 *
7	1	Rear Boot Lid Number Plate		\$50.00 *
8	1	Rear Boot Lid Inner Lock		\$374.45 *
9	1	Rear Boot Lid Inner Rubber		\$231.35 *
10	1	Rear Boot Lid Camera (Special Nett)		\$550.00 *
11	2	Rear Tail Lamp	\$374.45	\$748.90 *
12	2	Rear Tail Lamp Lower Bracket	\$134.45	\$268.90 *
13	1	Rear Bumper Demand		\$561.60 ✓
14	8	Rear Bumper Clip	\$6.50	\$52.00 30 ✓
15	2	Rear Bumper Side Retainer	\$134.10	\$268.20 ✓
16	1	Rear Bumper Reinforcement Best		\$374.50 ✓
17	1	Rear Bumper Reverse Sensor		\$380.00 200(SW) ✓
18	1	Rear End Panel		\$649.20 *
19	1	Rear End Panel Top Garnish		\$321.10 *
20	1	Rear Spare Tyre Panel Top Cover		\$328.25 *

Subtotal :- \$7,425.25

12343

92572

S.N: 200

Labour charges

To remove & refit cushion	\$280.00 X
To remove & refit reverse sensor	\$100.00 60
To remove & refit rear camera	\$180.00 X
To check wiring	\$60.00 30
Tuff kote	4.3 790 \$150.00 X.
Panel beating	\$1,000.00 200
Spray painting	\$1,000.00 200
Subtotal :-	<u>\$2,770.00</u>
Total:-	<u>\$10,195.25</u>

Consentants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King
06/08/18 H/S.

03 Days.

total 1915.72

4/5: 15K.

15K 2500