

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1807/022
Policy No:	5098537097	Date of Loss:	30/07/2018
Vehicle Reg. No.:	SJF6299R	Driveable?	no
Driver Age:	18/09/1986	Third Party Vehicle No.:	GBC6614A
Any Injuries?	no	Contact No:	91006191
Insured/Claimant:	CHEN CHEN	Driver:	CHEN CHEN

Make/Model:	Toyota, Vios - MR053HY420	Vehicle Reg. Date:	05 Jun 2008
Vehicle Colour:	BLACK	Engine Number:	1NZX754153
Chassis No:	MR053HY9305065240	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	7

Description of Accident/loss HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	1,897.50
Miscellaneous Items	185.00
Labour	1,010.00
Paintwork Labour	870.00
Towing	0.00

Gross Total(S\$):	3,962.50
GST 7.00%(S\$):	277.38
Nett Amount(S\$):	4,239.88

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not allowed
han
2/8/18
3/8/18
take photo after sign
mercus
6h.

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BOOT LID <i>3.500</i>	180.00	180.00	+10.00	198.00 ✓
2	1	REAR BOOT LID HINGE LH <i>2</i>	22.00	22.00	+10.00	24.20 X
3	1	REAR BOOT LID HINGE RH <i>2</i>	22.00	22.00	+10.00	24.20 X
4	1	REAR BOOT LID OUTER HANDLE GARNISH <i>set</i>	130.00	130.00	+10.00	143.00 ✓
5	1	REAR NUMBER PLATE LAMP <i>11</i>	60.00	60.00	+10.00	66.00 X
6	1	REAR BOOT LID LOCK <i>twi</i>	35.00	35.00	+10.00	38.50 ✓
7	1	REAR BOOT LID OUTER KEY LOCK <i>11</i>	120.00	120.00	+10.00	132.00 X
8	1	REAR BOOT LID TOYOTA LOGO <i>set</i>	30.00	30.00	+10.00	33.00 ✓
9	1	REAR BOOT LID VIOS EMBLEM <i>set</i>	20.00	20.00	+10.00	22.00 ✓
10	1	REAR BOOT LID SPORT E EMBLEM <i>set</i>	22.00	22.00	+10.00	24.20 ✓
11	1	REAR BUMPER <i>Dis</i>	160.00	160.00	+10.00	176.00 ✓
12	1	REAR BUMPER SIDE RETAINER LH <i>set</i>	30.00	30.00	+10.00	33.00 ✓
13	1	REAR BUMPER SIDE RETAINER RH <i>set</i>	30.00	30.00	+10.00	33.00 ✓
14	1	REAR BUMPER BRACKET LH <i>set</i>	12.00	12.00	+10.00	13.20 ✓
15	1	REAR BUMPER BRACKET RH <i>set</i>	12.00	12.00	+10.00	13.20 ✓
16	1	REAR BUMPER REFLECTOR LH	30.00	30.00	+10.00	33.00 ?
17	1	REAR BUMPER REFLECTOR RH <i>one</i>	30.00	30.00	+10.00	33.00 ✓
18	1	REAR BUMPER LOWER SPOILER <i>Dis</i>	280.00	280.00	+10.00	308.00 ✓
19	1	REAR TAILLAMP LH <i>one</i>	75.00	75.00	+10.00	82.50 ✓
20	1	REAR TAILLAMP RH <i>one</i>	75.00	75.00	+10.00	82.50 ✓
21	1	REAR END PANEL <i>3.500</i>	180.00	180.00	+10.00	198.00 ✓
22	1	REAR END PANEL TOP GARNISH	70.00	70.00	+10.00	77.00 ?
23	1	REAR BOOT LID RUBBER <i>twi</i>	100.00	100.00	+10.00	110.00 ✓
Total Parts (\$\$)						1,897.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE <i>set</i>	30.00	30.00	0.00	30.00 ✓
2	1	REAR REVERSE SENSOR <i>set</i>	120.00	120.00	0.00	120.00 ✓
3	1	REAR BUMPER CLIPS <i>set</i>	20.00	20.00	0.00	20.00 ✓
4	1	REAR END PANEL TOP GARNISH CLIP <i>11</i>	15.00	15.00	0.00	15.00 X
Sub Total (\$\$)						185.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	100.00	0.00	100.00 60
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 50
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	800.00	0.00	800.00 750

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Gross Labour Cost (\$)						1,010.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	30.00	30.00	0.00	30.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	40.00	40.00	0.00 <i>u</i>	40.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	0.00	800.00 <i>780</i>
Gross Labour Cost (\$)						870.00

< END OF ESTIMATES >