

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61

Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1807/022
Policy No:	5098537097	Date of Loss:	30/07/2018
Vehicle Reg. No.:	SJF6299R	Driveable?	no
Driver Age:	18/09/1986	Third Party Vehicle No.:	GBC6614A
Any Injuries?	no	Contact No:	91006191
Insured/Claimant:	CHEN CHEN	Driver:	CHEN CHEN

Make/Model:	Toyota, Vios - MR053HY420	Vehicle Reg. Date:	05 Jun 2008
Vehicle Colour:	BLACK	Engine Number:	1NZX754153
Chassis No:	MR053HY9305065240	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	7

Description of Accident/loss HEAD TO REAR
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	1,897.50
Miscellaneous Items	185.00
Labour	1,010.00
Paintwork Labour	870.00
Towing	0.00
Gross Total(S\$):	3,962.50
GST 7.00%(S\$):	277.38
Nett Amount(S\$):	4,239.88

This claim is handled by: Shaun Toh L M

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BOOT LID	180.00	180.00	+10.00	198.00
2	1	REAR BOOT LID HINGE LH	22.00	22.00	+10.00	24.20
3	1	REAR BOOT LID HINGE RH	22.00	22.00	+10.00	24.20
4	1	REAR BOOT LID OUTER HANDLE GARNISH	130.00	130.00	+10.00	143.00
5	1	REAR NUMBER PLATE LAMP	60.00	60.00	+10.00	66.00
6	1	REAR BOOT LID LOCK	35.00	35.00	+10.00	38.50
7	1	REAR BOOT LID OUTER KEY LOCK	120.00	120.00	+10.00	132.00
8	1	REAR BOOT LID TOYOTA LOGO	30.00	30.00	+10.00	33.00
9	1	REAR BOOT LID VIOS EMBLEM	20.00	20.00	+10.00	22.00
10	1	REAR BOOT LID SPORT E EMBLEM	22.00	22.00	+10.00	24.20
11	1	REAR BUMPER	160.00	160.00	+10.00	176.00
12	1	REAR BUMPER SIDE RETAINER LH	30.00	30.00	+10.00	33.00
13	1	REAR BUMPER SIDE RETAINER RH	30.00	30.00	+10.00	33.00
14	1	REAR BUMPER BRACKET LH	12.00	12.00	+10.00	13.20
15	1	REAR BUMPER BRACKET RH	12.00	12.00	+10.00	13.20
16	1	REAR BUMPER REFLECTOR LH	30.00	30.00	+10.00	33.00
17	1	REAR BUMPER REFLECTOR RH	30.00	30.00	+10.00	33.00
18	1	REAR BUMPER LOWER SPOILER	280.00	280.00	+10.00	308.00
19	1	REAR TAILLAMP LH	75.00	75.00	+10.00	82.50
20	1	REAR TAILLAMP RH	75.00	75.00	+10.00	82.50
21	1	REAR END PANEL	180.00	180.00	+10.00	198.00
22	1	REAR END PANEL TOP GARNISH	70.00	70.00	+10.00	77.00
23	1	REAR BOOT LID RUBBER	100.00	100.00	+10.00	110.00

Total Parts (\$\$) 1,897.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE	30.00	30.00	0.00	30.00
2	1	REAR REVERSE SENSOR	120.00	120.00	0.00	120.00
3	1	REAR BUMPER CLIPS	20.00	20.00	0.00	20.00
4	1	REAR END PANEL TOP GARNISH CLIP	15.00	15.00	0.00	15.00

Sub Total (\$\$) 185.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	100.00	0.00	100.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	800.00	0.00	800.00

Estimates On Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Gross Labour Cost (S\$)						1,010.00

Estimates On Paint Work Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	30.00	30.00	0.00	30.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	40.00	40.00	0.00	40.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	0.00	800.00
Gross Labour Cost (S\$)						870.00

< END OF ESTIMATES >