



India International Insurance Pte Ltd
64 Cecil Street #05 IOB Building
Singapore 049711

CarCrafters Singapore Pte Ltd
48 Toh Guan Road East
#05-155, Enterprise Hub
Singapore 608586

Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

Date : 3/8/2018

Vehicle Num : SJW8017K

Make/Model : AUDI A5 2.0 SPORTSBACK

Chassis No : WAUZZZ8T4AA050943

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR BUMPER	1 pc	\$ 1,080.00	\$ 1,080.00
2	BUMPER REINFORCEMENT	1 pc	\$ 390.00	\$ 390.00
3	ATTACHMENT STRIP	1 pc	\$ 14.00	\$ 14.00
4	REAR LOWER SPOILER	1 pc	\$ 160.00	\$ 160.00
5	END PANEL	1 pc	\$ 800.00	\$ 800.00
6	BUMPER GUIDE PIECE LH	1 pc	\$ 32.00	\$ 32.00
7	BUMPER GUIDE PIECE RH	1 pc	\$ 32.00	\$ 32.00
8	PARKING SENSOR	3 pcs	\$ 140.00	\$ 420.00
9	TAILLIGHT INNER RH	1 pc	\$ 500.00	\$ 500.00
10	TAILLIGHT OUTER RH	1 pc	\$ 720.00	\$ 720.00
11	REAR FENDER RH	1 Set	\$ 1,500.00	\$ 1,500.00
	TOTAL PARTS			\$ 5,648.00
	LABOUR			
1	To remove/ replace/ refit & panel beat of rear bumper, rear fender RH, end panel, rear boot lid & other affected area			\$ 300 1,200.00
2	To putty & respray rear bumper, end panel, rear boot lid, rear fender RH & other affected accident area			\$ 400 1,000.00
3	To check accident affected wiring system & recover.			\$ 30 50.00
4	To recode & decode engine management system & fault code clearing after repair works.			\$ 100.00
5	To remove & refit the parking sensor.			\$ 30 50.00
	TOTAL			\$ 8,048.00
	GST 7%			\$ 563.36
	GRAND TOTAL			\$ 8,611.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tamplin 9795749
wp
16/8/18 c 230 pm
Lumpsum Pao
Resurvey after repair.
04 days
Sun @ 11:00 am