

25/02/2018

ASS. REC. BY:

REF CS/CTI18014136/Kqd3

n2

Special Instruction:

Surveyor:

MUNIM

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

31/11/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 7682D

Insured:

GBH 5474S

at Workshop in/s:

City Auto

Tel:

6453 1235

of

160 Sin Ming Drive #05-01

Policy No:

DMCVSN 3045681800

Claim No:

8NM18D03772002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/07/2018

61811801pm @ BIK 8 Sin Ming Ind. Est.

CA / REV / REP. / REV 24 HRS

Gup

H.O.D. Endorsement:

Date/Time:

9:54am @ 31/8/2018

Person Contacted:

Vronica

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 7682D - NA / CTI 18013988 / r3

D.O.A: 31/07/2018

GBH 5474S - NA / CTI 18013988 / r3

D.O.A: 31/07/2018

11/11 81489.95 encl & confirm (Red @ 387.36, 20%)

(06/11/13) wef

ASS. REC. BY:

REF: CTI

ASSIGNMENT

From: Date: 06/08/18

Estimated Cost:

OD: ☒ TP / ☒ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SLO 7682D

at Workshop m/s: City Auto

of BIK & Sin Ming Ind. Est #01-60

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

1pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLO 7682D Yr Regn: 07, 17

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toy Allion A, c.c. 1496

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 23950 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NZT260. 3185743

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ SRim / ☐ STD A/Rim or

Tyre Size: F:

R: 215/45R17

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 31/7/18

D.O.I. 6/8/18

Survey held at

Des. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/8 File pass to Nivita

RECEIVED 11 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 11/10 10:55

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

Report Format:

MER-TP

Lump Sum / I.B.I. (\$) 1489.95

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18014136/Kqd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERSINGAPORE 079909

Date : 03-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5474S	Veh. Inspected	SLQ 7682D
Policy No.	DMCVSN3045681800	Coverage (\$)	0.00
Claim No.	SNM18D03772C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	03/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/07/2018	Inspection Date	06/08/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2018		03 Aug 2018 08:59 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S GCS PAINTING PTE LTD, Co. Reg. No.: 201511764W		
Main Claimant:	PHUA CHYE HUAT, ID: S0986632I		
Vehicle Reg. No.:	SLQ7682D	Date of Loss:	31/07/2018 14:00 - :59
Claim Type:	TP / SNM18D03772C02	Policy/Cover Note No.:	DMCVSN3045681800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH5474S	Policy No. (Claimant):	5092620217-01
		Excess:	S\$0.00
Repairer:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/08/2018]		
Driver/Custodian (Insured):	SEOW KIM BA (64 / Male), NRIC: S2740849D, Tel: +6586190571		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

* Survey only

CHINA TAIPING INSURANCE (S) PTE LTD

3

ANSON RD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: PHUA CHYE HUAT

Contact : 90011216

Fax No. : 62247175

Estimate : QUOT201808-000038(00)

Date : 02/08/2018

Vehicle No. : SLQ7682D

Make/Model : TOYOTA ALLION A15-G PACKAGE
CVT 2WD

Mileage (km) : 0

Chassis No. : NZT2603185743

Accident Date : 31/07/2018 00:00:00

Claim No. : GBH5474S

Reference : SLQ7682D

Policy No. : 5092620217-01

Not Authorized

1489.95

Resurvey After Paint

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Bonnet <i>925.10</i>	1.0	1,106.30	1,106.30 ✓
2	Bonnet lock	1.0	107.80	107.80 X
3	Front grille <i>381.50</i>	1.0	482.30	482.30 ✓
List Total :				1,696.40
25% Discount S\$				424.09
				1,272.31
LABOUR :				
	-To knock jackout damaged parts, panel beating welding, align, refix and to renew accident parts	1.0	200.00	200.00 <i>1500</i>
	- Spray painting on affected & replace parts	1.0	400.00	400.00 <i>3600</i>
				600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O. E.

Total S\$ 1,872.31

GST 7% S\$ 131.06

Amount Due S\$ 2,003.37

NA

for CITY AUTO PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014136/KQD3N2

Date: 11/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3045681800
Claimant Vehicle No :	SLQ7682D	Insured Vehicle No :	GBH5474S
Date of Loss:	31/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03772C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ7682D	Engine No:	1NZF110794
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603185743
Reg. Date:	21/07/2017 (Man. Year: 2016)	Odometer:	23450 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,272.30	979.95	292.35	22.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	510.00	90.00	15.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,872.30	1,489.95	382.35	20.42
+ GST 7.00/7.00% (S\$)	131.06	104.30	26.76	20.42
Nett Amount (S\$)	2,003.36	1,594.25	409.11	20.42

INSPECTION

Date of Assignment:	03/08/2018	
Date Inspected:	06/08/2018 Inspected At:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01., Sin Ming AutoCity, Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ7682D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,106.30 FL	*925.10 FL
2	1		*BONNET LOCK	Repair	107.80 FL	*- FL
3	1		*FRONT GRILLE	Cut	482.30 FL	*381.50 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,696.40	1,306.60
- List Item Discount on L Items 25.00/25.00% (S\$)					424.10	326.65
Total Parts (S\$)					1,272.30	979.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	200.00	150.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	400.00	360.00
Gross Labour Cost (S\$)			600.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >