

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: EQ INSURANCE

DATE: 1/8/2018
VEHICLE NO: SLA5888A
MODEL: BMW 520I
YEAR: 2012
ACCIDENT DATE: 1/8/2018
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BONNET	1	Rs RESTORE
FRONT GRILLE	2	\$ 422.80
FRONT GRILLE CLIPS	10	\$ 30.00
FRONT EMBLEM	1	\$ 155.70
FRONT GRILLE INNER AIR GUIDE	1	\$ 367.50
FRONT BUMPER CLIPS	10	\$ 50.00
FRONT BUMPER RETAINER	2	\$ 322.60
FRONT BUMPER BRACKET	2	\$ 388.60
FRONT BUMPER LOWER CENTRE GRILLE	1	\$ 267.80
FRONT BUMPER LOWER GRILLE - L&R	2	\$ 314.60
FRONT BUMPER TOP RUBBER	1	\$ 198.10
FRONT BUMPER SPONGE	1	\$ 299.70
FRONT REINFORCEMENT	1	\$ 891.20
SUPPORT PANEL - TOP	1	\$ 422.30
SUPPORT AIR GUIDE	1	\$ 675.10
HEADLAMP	2	\$ 4,895.40
HEADLAMP PANEL	2	\$ 466.80
HEADLAMP WIPER NOZZLE	2	\$ 632.40

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

LH FRONT FENDER	1		RESTORE
RH FRONT FENDER	1		RESTORE
INTERCOOLER	1	\$	? 1,978.40
CONDENSER	1	\$	? 1,786.40
RADIATOR	1	\$	? 1,788.30
FRONT SENSOR	2 A	\$	? 1,024.80
FRONT SENSOR WIREHARNESS	1	\$	? 453.80
BOOTLID	1		RESTORE
REAR EMBLEM	1	\$	X 155.70
BOOTLID LAMP	2	\$	X 899.40
REAR BUMPER CLIPS	10	\$	X 50.00
REAR BUMPER RETAINER	2	\$	X 322.60
REAR BUMPER BRACKET	2	\$	X 388.60
REAR BUMPER SPONGE	1	\$	? 298.40
REAR REINFORCEMENT	1	\$	? 791.30
END PANEL	1	\$	X 985.40
SPARE TYRE PANEL	1		RESTORE
END PANEL TOP GARNISH	1	\$	X 276.50
REAR WEATHER STRIP	1	\$	X 214.20
TAILLAMP	1	\$	X 1,986.60
REVERSE SENSOR	2 A	\$	? 1,024.80
REVERSE SENSOR WIRE HARNESS	1	\$	? 453.80
REAR EXHAUST PIPE FINISHER	1 A L Hinner	\$	cut 1,088.40
REAR EXHAUST PIPE MUFFLER	2	\$	Rx 3,326.70
REAR EXHAUST PIPE MOUNTING	2	\$	X 212.60

TOTAL:	\$	30,307.30
DISCOUNT 10%:	\$	3,030.73
	\$	<u>27,276.57</u>

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

S/NET

FRONT NUMBER PLATE	1		
FRONT BUMPER - M MODEL	1	\$	3,243.10 <i>can ✓</i>
REAR BUMPER - M MODEL	1	\$	2,987.10 <i>de ✓</i>
REAR BUMPER DIFFUSER - M MODEL	1	\$	934.40 <i>can -</i>
COOLANT	1	\$	80.00 <i>?</i>
END PANEL SEALANT	1	\$	80.00 <i>x</i>

TOTAL: \$ 7,324.60

LABOUR

PRICE

LABOUR FOR FACILITATE REPAIR - FRONT PORTION	\$	1,400.00 <i>500</i>
LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$	1,600.00 <i>300</i>
TO RESPRAY AFFECTED AREAS - BONNET	\$	300.00 <i>220</i>
TO RESPRAY AFFECTED AREAS - FRONT BUMPER	\$	300.00 <i>220</i>
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER	\$	300.00 <i>x</i>
TO RESPRAY AFFECTED AREAS - LH FRONT FENDER	\$	300.00 <i>x</i>
TO RESPRAY AFFECTED AREAS - BOOTLID	\$	300.00 <i>x</i>
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$	300.00 <i>220</i>
TO RESPRAY AFFECTED AREAS - END PANEL	\$	300.00 <i>x</i>
TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL	\$	300.00 <i>x</i>
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$	150.00 <i>40</i>
TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP GAS	\$	250.00 <i>120 ?</i>

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

TO REMOVE AND REMOVE RADIATOR INCLUDING WATER PRESS TEST	\$	250.00	120 ? photo.
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$	350.00	60
TO REMOVE AND REFIT REAR EXHAUST PIPE FOR FACILITATE REPAIR	\$	350.00	120
TO REMOVE AND REFIT REVERSE SENSOR AND FRONT SENSOR	\$	150.00	60
TO RESET WARNING LIGHT	\$	550.00	200
SUNDARIES	\$	80.00	30
RUST PROOFING	\$	100.00	X
TOTAL:	\$	7,630.00	

TOTAL:	\$	42,231.17
7% GST:	\$	2,956.18
	\$	45,187.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

62563561
Tanjil 97495749
WP'

3/8/18 @ 1145

Resurvey before/after paint

Resurvey check items

sur @ lkh auto. com

7 days

2777