

ASS. REC. BY:

REF

CS/MSG18014160/ Utd3et Special Instruction:

Surveyor
William

Make

ASSIGNMENT (Office)

From (Person):

Manicea chung

of

MSG

Date/Time:

03/08/2018

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV? CS

To Inspect Vehicle No:

GBC 2731X

Insured:

YN 7608G

at Workshop m/s

Ten Lim Motor

Tel:

68585151

of

51 Defu Lane 10

Policy No:

29067890MKC

Claim No:

566302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5:40pm 3/8/18

Person Contacted:

Caymen

Vehicle IN OUT

Date/Time	Action/Instruction <input checked="" type="checkbox"/> Estimate	
	GBC 2731X - CCG/ LER 17009402/ Uwg3q2	DOA: 14/11/17
	YN 7608G-X	5/9/18- VNI yet
6/8/18-	called weep vehicle not in yet (caymen)	19/9/18- vehicle still not in
16/8/18-	called weep vehicle not in yet (william)	1/10/18- VNI yet
15/8/18-	called weep vehicle not in yet (william)	9/10/18 - vehicle not in
29/8/18-	called weep VNI (caymen)	

Siriyon Merong

REF: MS1G

ASSIGNMENT

From: _____ Date: 16/10/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 2731X

at Workshop m/s Tan Lim Motor

of 51 Defu Lane 10

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: GBC2731X Yr Regn: 10, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM

Make: Toyota Dynis c.c. 2982

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 208850 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35480K201636

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-215

R: 155-212

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 2116.

IDAC Accident Rport: _____ Consistent?: Yes or No

G/A / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up LTA 10264

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 9 mm L/Bal. 6 mm

D.O.A. 30/1/18 D.O.I. 16/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>3 yrs. 3 mths.</u>
<u>19/10 @ 4:37pm</u>	<u>Received preli advise via menmen.</u>
<u>26/10/18</u>	<u>L/S @ 2250 confirmed with MR / ye (led. 2634.95! 53%) cost plus + labour = L/S.</u>
RECEIVED 29 OCT 2018	

Date/Time, File Pass to? : Preli. Report

19/10 Type : Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Report Format: TP

Lump Sum / I.B.I.: (\$ 2250)

Add Fee: Site Insp (\$ _____))

Interview (\$ _____))

Tech. Invs (\$ _____))

Weekend (\$ _____))

Survey Fee:	<u>150</u>
Transportation:	
Others:	<u>10</u>
TOTAL	<u>160</u>

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 19 Oct 2018

Preliminary Advice

Insured Vehicle No	: YN7608G	Accident Date	: 30/07/2018
TP Vehicle No	: GBC2731X	Assignment Date	: 03/08/2018
Make	: TOYOTA DYNA 1.5T	Est. Duration of Repair	: 4.00
Date of Inspection	: 16/10/2018		
Inspection At	: TAN LIM MOTOR PTE LTD (DEFU) 51 DEFU LANE 10 SINGAPORE 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,884.95
Revised Amount	:S\$	2,212.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,212.30

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2018 Sendback Est	01 Aug 2018 14:17 S\$4,884.95	03 Aug 2018 15:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	Zhao Yang Geotechnic Pte Ltd , Co. Reg. No.: 199701464D		
Main Claimant:	SEMGAS (S) PTE LTD , Co. Reg. No.: 200206783Z		
Vehicle Reg. No.:	GBC2731X	Date of Loss:	30/07/2018 17:00 - :59 [81 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566302	Policy/Cover Note No.:	29067890MKC Coverage: 29/01/2018 - 28/01/2019
Vehicle Reg. No. (Insured):	YN7608G	Policy No. (Claimant):	5086909136-01
		Excess:	
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/08/2018]		
Driver/Custodian (Insured):	Muamar Bin Sarip (/ Male), NRIC: S8339424B		
Adj Asg. Remarks:	SJE Agree Please appoint LKK Auto - Marcus Chua and contact LAM WEI SHONG @ 6858 5151 Liability (Non-reporting)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/07/2018 17:28
Date Of Accident	30/07/2018 17:10
Exact Location Of Accident	JALAN EUNOS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC2731X
Insured/Policyholder	
Name Of Registered Owner	SEMGAS (S) PTE LTD
Co Reg No	200206783Z
Email Address	IRENECHEONG@UNIONENERGY.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-66031796

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 1.5T-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	DELIVERY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086909136-01
Cover Note Number	01.01.2018 TO 31.12.2018

Driver

Name of Driver	GAO YONGLIANG
Passport No/FIN	G2428480N
Date Of Birth	08/02/1986
Occupation	OUTDOOR
Date Of Driving Pass	09/04/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91218874
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	224 TELOK KURAU ROAD #04-03
Postcode	423836
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 30/07/208 at about 1710hrs, I stopped my vehicle (A: GBC2731X) after the yellow box on the second lane from left along Jalan Eunus heading towards Still Road direction due to traffic light was red. Suddenly I felt an impact from my vehicle's rear portion and realised that vehicle (B: YN7608G) had hit onto my vehicle's rear portion. After the accident, I felt headache. Vehicle A (GBC2731X) - No passenger on board. Vehicle B (YN7608G) - unaware number of passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7608G
Vehicle Make/Model/Colour	MITSUBISHI FUSO
Details Of Properties	LORRY
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUAMAR BIN MOHD SARIP
NRIC/Passport Number	S8339424B
Contact Number	8290 2101
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT PORTION
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	GAO YONGLIANG
Approximate Age	32
Injuries Sustain	HEADACHE
Injured person in which vehicle?	GBC2731X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GI& Records Management Centre established by the General Insurance Association of Singapore (GI&A) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GI&A") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GI&A to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be stored / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 31/07/18 01750h

Reporting Centre Personnel's Signature
Name: Lam NP. Sheng
NRIC/FIN No.: 6168640321

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	6783Z

Vehicle Details

Vehicle No.:	GBC2731X
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	1KD2113627
Chassis No.:	JTFAT35Y80K201636
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	20 Oct 2011
First Registration Date:	20 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$1,249.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Oct 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,900.00
COE Rebate Amount:	\$10,264.00
Total Rebate Amount:	\$10,264.00

The information contained herein is correct as at 31 Jul 2018

OK

*Not ahead
LKK
d/s
Hdy.
16/10/18
Take photo of the scene*



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

*16/10/18 @ 11:50h
LKK - MMS*

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
Zhao Yang Geotechnic Pte Ltd
2 Tuas Drive 2
Singapore 638637

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP045072018
Policy No:		Date of Loss:	30/07/2018
Vehicle Reg. No.:	GBC2731X	Driveable?	YES
Part At Fault:	UNKNOWN	Driver (Insured):	MUAMAR BIN SARIP
Driver (TP):	GAO YONGLIANG		
Make/Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Vehicle Reg. Date:	20/10/2011
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	1KD2113627	Chassis No:	JTFAT35Y80K201636
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Description of Accident/Loss
ON 30/07/208 AT ABOUT 1710HRS, I STOPPED MY VEHICLE (A: GBC2731X) AFTER THE YELLOW BOX ON THE SECOND LANE FROM LEFT ALONG JALAN EUNOS HEADING TOWARDS STILL ROAD DIRECTION DUE TO TRAFFIC LIGHT WAS RED. SUDDENLY I FELT AN IMPACT FROM MY VEHICLE'S REAR PORTION AND REALISED THAT VEHICLE (B: YN7608G) HAD HIT ONTO MY VEHICLE'S REAR PORTION. AFTER THE ACCIDENT, I FELT HEADACHE.

VEHICLE A (GBC2731X) - NO PASSENGER ON BOARD.

VEHICLE B (YN7608G) - UNAWARE NUMBER OF PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

Parts		Amount
Miscellaneous Items		3,154.95
Labour		0.00
Paintwork Labour		1,030.00
Towing		700.00
		0.00
	Gross Total (\$\$)	4,884.95
	+ GST 7.00% (\$\$)	341.95
	Nett Amount (\$\$)	5,226.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: LAM WEI SHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Aug 2018)
Parts: N/A TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Tan Lim Motor Pte Ltd/GBC2731X/01/08/2018 14:17
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*tailgate lid <i>na/80</i>	0.00	0.00	*600.00 F
2	1		*tailgate lid 70 km/h sticker <i>na 10</i>	0	0.00	*20.00 FS
3	1		*tailgate lid Union sticker <i>na 80</i>	0	0.00	*250.00 FS
4	1		*tailgate lid Flammable Gas sticker <i>na 80</i>	0	0.00	*100.00 FS
5	1		*tailgate lid Danger highly flammable sticker <i>na 80</i>	0	0.00	*100.00 FS
6	1		*rear cargo deck end panel <i>na x</i>	0.00	0.00	*750.00 F
7	1		*rear cargo deck end panel dyna sticker <i>na x</i>	0	0.00	*100.00 FS
8	2		*rear lamps <i>na x</i>	0.00	0.00	*140.00 F
9	2		*rear lamp panels <i>na x</i>	0.00	0.00	*60.00 F
10	1		*rear licence plate <i>na 14</i>	0	0.00	*50.00 FS
11	1		*rear licence plate panel <i>na x</i>	0.00	0.00	*65.00 F
12	2		*rear licence plate lamps <i>na x</i>	0.00	0.00	*36.00 F
13	1		*reverse sensor assy <i>shhd 200</i>	0	0.00	*450.00 FS
14	1		*foot step U pedal bracket <i>na x</i>	0.00	0.00	*30.00 F
15	1		*side gate lid lock handle <i>na x</i>	0.00	0.00	*26.00 F
16	1		*side gate lid lock latch <i>na x</i>	0.00	0.00	*30.00 F
17	2		*side gate lid stoppers <i>na x</i>	0.00	0.00	*16.00 F
18	2		*side gate lid stopper brackets <i>na x</i>	0.00	0.00	*60.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **2,883.00**
 + Margin on L,N Items 15.00% (\$\$) 271.95
Total Parts (\$\$) 3,154.95

Tan Lim Motor Pte Ltd/GBC2731X/01/08/2018 14:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

p-1064
labour - 1220

2284

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New	500 700.00
Labour Items			
2	To reinstall of reverse parking sensor.	New	50 120.00
3	To check electrical lighting concerned.	New	20 60.00
4	To rust-proofing of the affected areas.	New	50 100.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	600 750.00
Gross Labour Cost (S\$)			1,730.00

Tan Lim Motor Pte Ltd/GBC2731X/01/08/2018 14:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1220

51 Defu Lane 10 Singapore 539216
 Tel : 6858 5151 (24 hours) Fax : 6858 0877
 email@tlmotor.com.sg www.tlmotor.com.sg
 Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2018 Sendback Est	01 Aug 2018 14:17 S\$4,884.95	03 Aug 2018 15:44 Edit Adj Rpt	S\$2,250.00 Edit Estimates	S\$2,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS									
Insured:	Zhao Yang Geotechnic Pte Ltd , Co. Reg. No.: 199701464D								
Main Claimant:	SEMGAS (S) PTE LTD , Co. Reg. No.: 200206783Z								
Vehicle Reg. No.:	GBC2731X	Date of Loss:	30/07/2018 17:00 - :59 [81 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 566302	Policy/Cover Note No.:	29067890MKC Coverage: 29/01/2018 - 28/01/2019						
Vehicle Reg. No. (Insured):	YN7608G	Policy No. (Claimant):	5086909136-01						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/09/2018]								
Driver/Custodian (Insured):	Muamar Bin Sarip (/ Male), NRIC: S8339424B								
Adj Asg. Remarks:	SJE Agree Please appoint LKK Auto - Marcus Chua and contact LAM WEI SHONG @ 6858 5151 Liability (Non-reporting)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBC2731X (566302)
[YN7608G]
TP
SEMGAS (S) PTE LTD
Jul 30 2018 5:00PM
[Zhao Yang Geotechnic Pte Ltd]
Tan Lim Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>
Letters/Correspondences				1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On			Thumbnail Print
1	03/08/18 10:41	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Non Reporting Letter to OI		Load HTM
Assessment Reports				1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On			Thumbnail Print
1	01/08/18 08:57	Tan Lim Motor Pte Ltd (Defu) Accident Statement		Load HTM
2	01/08/18 14:17	Repairer Estimates		Load HTM
No	Finalized On			Thumbnail Print
1	19/10/18 16:33	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice		Load HTM
Photos/Images				3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail Print
1	16/10/18 13:09	LKK Auto Consultants Pte Ltd (HQ) Odometer Reading		Load JPG <input checked="" type="checkbox"/>
2	16/10/18 13:09	Chassis Number		Load JPG <input checked="" type="checkbox"/>
3	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
4	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
5	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
6	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
7	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
8	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
9	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
10	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
11	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
12	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
13	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
14	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
15	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
16	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
17	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
18	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
19	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
20	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
21	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
22	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
23	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
24	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
25	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
26	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
27	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>
28	16/10/18 13:09	General View		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
30	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
31	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
32	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
33	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
34	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
37	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
38	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/10/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/10/18 08:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/10/18 08:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/10/18 08:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/10/18 08:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/08/18 10:55	SJE AGREE LKK Auto – Marcus Chua	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014160/UTD3E2
Date: 30/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 29067890MKC
Claimant Vehicle No : GBC2731X	Insured Vehicle No : YN7608G
Date of Loss: 30/07/2018	Nature of Claim: TP Claim No: 566302

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC2731X	Engine No: 1KD2113627
Make & Model: TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No: JTFAT35Y80K201636
Reg. Date: 20/10/2011 (Man. Year: 2011)	Odometer: 208850 km
Colour: Blue	Engine Capacity: 2982 cc
Market Value/New Car Price: N/A	Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15	Rear Tyre Size: 155R12
Front Left Side: Falken 6 mm	Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm	Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,154.95	1,064.00	2,090.95	66.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	720.00	310.00	30.10
Paintwork Labour	700.00	500.00	200.00	28.57
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,884.95	2,284.00	2,600.95	53.24
Approved Total (Overridden) (S\$)		2,250.00		
	(S\$) 4,884.95	2,250.00	2,634.95	53.94
	+ GST 7.00/7.00% (S\$) 341.95	157.50	184.45	53.94
	Nett Amount (S\$) 5,226.90	2,407.50	2,819.40	53.94

INSPECTION

Date of Assignment: 03/08/2018	Present Location: Tan Lim Motor Pte Ltd (Defu)
Date Inspected: 16/10/2018	Inspected At: Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10 Singapore 539216
Estimated Period of Repair: 4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Oct 2018)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC2731X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*tailgate lid	Dented/Bent	600.00 F	*600.00 F
2	1		*tailgate lid 70 km/h sticker	Necessary	20.00 FS	*10.00 FS
3	1		*tailgate lid Union sticker	Necessary	250.00 FS	*80.00 FS
4	1		*tailgate lid Flammable Gas sticker	Necessary	100.00 FS	*80.00 FS
5	1		*tailgate lid Danger highly flammable sticker	Necessary	100.00 FS	*80.00 FS
6	1		*rear cargo deck end panel	Repair	750.00 F	*- F
7	1		*rear cargo deck end panel dyna sticker	Not fitted	100.00 FS	*- FS
8	2		*rear lamps	Not Necessary	140.00 F	*- F
9	2		*rear lamp panels	Repair	60.00 F	*- F
10	1		*rear licence plate	Bent	50.00 FS	*14.00 FS
11	1		*rear licence plate panel	Repair	65.00 F	*- F
12	2		*rear licence plate lamps	Not Necessary	36.00 F	*- F
13	1		*reverse sensor assy	Shorted	450.00 FS	*200.00 FS
14	1		*foot step U pedal bracket	Repair	30.00 F	*- F
15	1		*side gate lid lock handle	Not Necessary	26.00 F	*- F
16	1		*side gate lid lock latch	Not Necessary	30.00 F	*- F
17	2		*side gate lid stoppers	Not Necessary	16.00 F	*- F
18	2		*side gate lid stopper brackets	Repair	60.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,883.00	1,064.00
+ Margin on L,N Items 15.00/0.00% (S\$)	271.95	0.00
Total Parts (S\$)	3,154.95	1,064.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Putty and spray painting of the affected portion.	New	700.00	500.00
<u>Labour Items</u>				
2	To reinstall of reverse parking sensor.	New	120.00	50.00
3	To check electrical lighting concerned.	New	60.00	20.00
4	To rust-proofing of the affected areas.	New	100.00	50.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	750.00	600.00
Gross Labour Cost (S\$)			1,730.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >