

ASS. REC. BY:

REF:

CS/CTI18014162/H1vd3

Special Instruction:

Surveyor
Trennen

Tauhikh

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 3/8/18 @ 2.25pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STD 4039A

Insured:

9BB1576P

at Workshop m/s

Vermogen

Tel:

66944919

of

6 Buroi Seetor

Policy No:

DMCVSN3063561700

Claim No:

SNM18D 03789C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/07/2018

CA / REV / REP. / REV 24 HRS

Lup

6/8/18

H.O.D. Endorsement:

Date/Time:

5.54pm @ 3/8/18

Person Contacted:

Edmond

Vehicle:

☒ IN / OUT

Date/Time

Action/Instruction

☒

Estimate

STD 4039A X

9BB1576P- NA / RSI13002780/13

DOA: 7/2/2013

4/9/16

Is \$50.50 confirmed by email (Ref 10.727.24, 68/5)

Tanjin

REF:

CTI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Sal. or Market Value: _____
IDAC Accident Report: _____ Consistent? Yes or No
QIA / PR Seen: _____ Consistent? Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle IN / OUT
Date / Time: _____ Action / Instruction: _____

☒	☐
N/S	O/S
☐	☐

Veh No: SLD4039A Yr Regn: 2016 June
Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Vezel CC: 1496
Colour: Blue A/C: Insured / Std / Nil / NA
Sp Reading: 198355 T/Radio: Insured / Std / Nil / NA
Eng No: _____
Cr No: R4111/5266
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / SRM / STD A/Rim or
Tyre Size: F: 215 / 60 R16
R: 215 / 60 R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Roadstone
Front: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: _____ D.O.I: 6/8/18 e25574
Survey held at: Vormagen
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Frt
The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 05 SEP 2018

UperTime. File Pass to? ☐ : Preli. Report
_____ ☐ : Final Report
Days Of Repair: 4
Resurvey No. of Trip: 1
Add Fee: ☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Insp. (\$)
☐ Wheeling (\$)
Survey Fee: _____
Transportation: _____
3 + RS: \$
1.2 hrs: _____
1.0 hrs: _____
TOTAL: _____
Report Format: Merimen
Lump Sum / L.B. (\$): 5050/2
4/9- typist



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014162/T1vd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 03-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 1576P	Veh. Inspected	SLD 4039A
Policy No.	DMCVSN3063561700	Coverage (\$)	0.00
Claim No.	SNM18D03789C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	03/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/07/2018	Inspection Date	06/08/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2018		03 Aug 2018 14:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLD4039A	Date of Loss:	25/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03789C02	Policy/Cover Note No.:	DMCVSN3063561700
Vehicle Reg. No. (Insured):	GBB1576P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/08/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/08/2018 13:56
Date Of Accident	25/07/2018 19:20
Exact Location Of Accident	EUNOS AVE 4 OSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD4039A
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995127
Cover Note Number	

Driver

Name of Driver	LOO SWEE FONG
NRIC No	S2576210Z
Date Of Birth	18/01/1967
Occupation	OUTDOOR
Date Of Driving Pass	24/02/1994
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	6 BENOI SECTOR
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO FOLLOWING ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB1576P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Eunos Ave 4 OSCP

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to police report - T/20180725 /2140

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

EDMOND

Reporting Centre Personnel's Signature
Name:
NRIC/PRC No.:





SLD4039A

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 25/7/2018

Vehicle Reg. No. : SLD4039A
Vehicle Reg. Date: 15-Jun-2016
Make / Model : H. VEZEL 1.5X A
Engine No. : L15B4035272
Chassis No. : RU11115266

COST OF CLAIMS

Parts Cost / List Items :	\$	14,877.80
Plus/Less 20%	\$	2,975.56
Total Cost / List :	\$	11,902.24
Special Nett Items :	\$	225.00
Total Parts Amount :	\$	12,127.24
Total Labour Amount :	\$	3,650.00
Gross Total :	\$	15,777.24
GST % : 7%	\$	1,104.41
Nett Amount :	\$	16,881.65

Surveyor Name and Company :

Tan Jiah 97495749
Date of survey : 6/8/18 @ 3:55 pm
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint After Paint
Authorize/Not Authorize/Without Prejudice Without Prejudice
Email : sur@lkkauto.com
Fax No : 62564315

This claim is handled by : PAULO BALDOZ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature :
Date :

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No.: SLD4039A
 Vehicle Reg. Date: 15/6/2016
 Make / Model: H. VEZEL 1.5X A
 Engine No.: L15B4035272
 Chassis No.: RU11115266

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Headlamp LH 1784-50	OK ✓	\$ 2,540.00		
2	1	Headlamp lower bracket LH	? ✓	\$ 55.00	new ✓	
3	1	Front bumper	OK ✓	\$ 1,085.00		
4	1	Front bumper lower	X nm	\$ 480.00		
5	1set	Front bumper clips	OK ✓	\$ 50.00		
6	1	Front bumper retainer LH	OK ✓	\$ 114.00		
7	1	Front bumper reinforcement	X ?	\$ 361.00		
8	1set	Front bumper reinforcement garnish	X ?	\$ 175.20		
9	1	Front bumper lower lip	X	\$ 194.00		
10	1set	Front bumper lower lip clips	X	\$ 35.00		
11	1	Front bumper fog lamp LH	X	\$ 387.70		
12	1	Front bumper fog lamp garnish LH	X	\$ 62.00		
13	1	Front fender LH	X	\$ 660.00		
14	1	Front fender inner shield LH	X	\$ 165.00		
15	1	Front fender arch garnish LH	X	\$ 192.00		
16	1set	Front fender arch garnish clips	X	\$ 50.00		
17	1	Front grille base	OK ✓ ?	\$ 510.00		
18	1	Front grille garnish	OK ✓	\$ 251.20		
19	1	Front grille chrome	OK ✓	\$ 1,150.00		
20	1	Front grille side bracket	OK ✓ ?	\$ 279.00		
21	1	Front grille centre bracket	OK ✓ ?	\$ 139.50		
22	1	Front grille clips	OK ✓	\$ 35.00		
23	1	Front grille logo	OK ✓	\$ 52.00		
24	1	Front support panel	X	\$ 576.20		
25	1	Front support panel top garnish	X	\$ 185.00		
26	1set	Front support panel top garnish clips	X	\$ 35.00		
27	1	Front support lower panel	X	\$ 422.20		
28	1	Bonnet	OK ✓	\$ 1,130.00		
29	2	Bonnet hinge LH/RH	X	\$ 124.00		
30	1	Bonnet insulator	X	\$ 160.50		
31	1	Bonnet insulator clips	X	\$ 50.00		
32	2	Bonnet rubber side	X	\$ 66.80		
33	1	Bonnet rubber centre	X ✓	\$ 35.20		
34	1	Front shock absorber LH	X ✓	\$ 675.00		
35	1	Front shock absorber mounting LH	X	\$ 78.20		
36	1	Front shock absorber bearing LH	X	\$ 97.60		
37	1	Front shock absorber dust cover LH	X	\$ 65.00		
38	1	Front shock absorber stopper LH	X	\$ 38.10		
39	1	Front knuckle arm LH	X	\$ 390.00		
40	1	Front lower arm LH	X	\$ 350.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD4039A
 Vehicle Reg. Date: 15/6/2016
 Make / Model : H. VEZEL 1.5X A
 Engine No. : L15B4035272
 Chassis No. : RU11115266

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Front wheel bearing LH	✓	\$ 181.40		
42	1	Front wheel hub LH	X	\$ 245.00		
43	1	Front rim LH	N/A	\$ 950.00		
44	1	Front tyre LH	X		\$ 180.00	
45	1	Front number plate with frame	X		\$ 45.00	
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SLD4039A

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 25/7/2018

Vehicle Reg. No. : SLD4039A
Vehicle Reg. Date: 15-Jun-2016
Make / Model : H. VEZEL 1.5X A
Engine No. : L15B4035272
Chassis No. : RU11115266

COST OF CLAIMS

Parts Cost / List Items :	\$	14,877.80
Plus/Less <u>20%</u>	\$	2,975.56
Total Cost / List :	\$	11,902.24
Special Nett Items :	\$	225.00
Total Parts Amount :	\$	12,127.24
Total Labour Amount :	\$	3,650.00
Gross Total :	\$	15,777.24
GST % : <u>7%</u>	\$	1,104.41
Nett Amount :	\$	16,881.65

Surveyor Name and Company :

Tan Jia 97495744
Date of survey : 6/8/18 @ 3:55 pm
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@lklauto.com
Fax No : 62564315
HP No : _____

This claim is handled by : PAULO BALDOZ

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD4039A
Vehicle Reg. Date: 15/6/2016
Make / Model : H. VEZEL 1.5X A
Engine No. : L15B4035272
Chassis No. : RU11115266

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Headlamp LH	OK	\$ 2,540.00		
2	1	Headlamp lower bracket LH	* ?	\$ 55.00	✓	
3	1	Front bumper	OK	\$ 1,085.00		
4	1	Front bumper lower	X	\$ 480.00		
5	1set	Front bumper clips	OK	\$ 50.00		
6	1	Front bumper retainer LH	OK	\$ 114.00		
7	1	Front bumper reinforcement	X ?	\$ 361.00		
8	1set	Front bumper reinforcement garnish	X ?	\$ 175.20		
9	1	Front bumper lower lip	X	\$ 194.00		
10	1set	Front bumper lower lip clips	X	\$ 35.00		
11	1	Front bumper fog lamp LH	X	\$ 387.70		
12	1	Front bumper fog lamp garnish LH	X	\$ 62.00		
13	1	Front fender LH	X	\$ 660.00		
14	1	Front fender inner shield LH	X	\$ 165.00		
15	1	Front fender arch garnish LH	X	\$ 192.00		
16	1set	Front fender arch garnish clips	X	\$ 50.00		
17	1	Front grille base	* ?	\$ 510.00	✓	
18	1	Front grille garnish	OK	\$ 251.20		
19	1	Front grille chrome	OK	\$ 1,150.00		
20	1	Front grille side bracket	* ?	\$ 279.00	✓	
21	1	Front grille centre bracket	* ?	\$ 139.50	✓	
22	1	Front grille clips	OK	\$ 35.00		
23	1	Front grille logo	OK	\$ 52.00		
24	1	Front support panel	X	\$ 576.20		
25	1	Front support panel top garnish	X	\$ 185.00		
26	1set	Front support panel top garnish clips	X	\$ 35.00		
27	1	Front support lower panel	X	\$ 422.20		
28	1	Bonnet	OK	\$ 1,130.00		
29	2	Bonnet hinge LH/RH	X	\$ 124.00		
30	1	Bonnet insulator	X	\$ 160.50		
31	1	Bonnet insulator clips	X	\$ 50.00		
32	2	Bonnet rubber side	Y	\$ 66.80		
33	1	Bonnet rubber centre	Y	\$ 35.20		
34	1	Front shock absorber LH	Y	\$ 675.00		
35	1	Front shock absorber mounting LH	X	\$ 78.20		
36	1	Front shock absorber bearing LH	X	\$ 97.60		
37	1	Front shock absorber dust cover LH	X	\$ 65.00		
38	1	Front shock absorber stopper LH	X	\$ 38.10		
39	1	Front knuckle arm LH	X	\$ 390.00		
40	1	Front lower arm LH	X	\$ 350.00		

P = 7390.70 - 20% = 5912.56

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4039A**
 Vehicle Reg. Date: **15/6/2016**
 Make / Model : **H. VEZEL 1.5X A**
 Engine No. : **L15B4035272**
 Chassis No. : **RU11115266**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Front wheel bearing LH	✓	\$ 181.40		
42	1	Front wheel hub LH	✗	\$ 245.00		
43	1	Front rim LH	✗	\$ 950.00		
44	1	Front tyre LH	✗		\$ 180.00	
45	1	Front number plate with frame	✗		\$ 45.00	
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

Final - 6972.50
2/5 = 5550/-

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 4 September 2018 5:21 PM
To: 'ezel.t@vermogen-group.com'; Taufikh (LKKAUTO)
Cc: 'Pila Ng'; eric.g@vermogen-group.com; 'Minoko Chan'; 'Baldoz Juan Paulo Bongon'; desmond@vermogen-group.com; SUR
Subject: RE: FINALISE TP SLD4039A (DOA: 25/07/2018)

Dear Ezel,

WITHOUT PREJUDICE

Finalise @ \$5050/- in 4 days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ezel.t@vermogen-group.com <ezel.t@vermogen-group.com>
Sent: Tuesday, 4 September 2018 12:44 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: 'Pila Ng' <pila@vermogen-group.com>; eric.g@vermogen-group.com; 'Minoko Chan' <minoko@vermogen-group.com>; 'Baldoz Juan Paulo Bongon' <paulo.b@vermogen-group.com>; desmond@vermogen-group.com
Subject: RE: FINALISE TP SLD4039A (DOA: 25/07/2018)

Dear Veron,

I've also just checked the list price of headlamp it's \$1784.50

Could we finalise @ \$5050/- in 4 days.

Thanks & Regards,
Ezel Tejano

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Tuesday, September 4, 2018 10:27 AM
To: ezel.t@vermogen-group.com; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: FINALISE TP SLD4039A (DOA: 25/07/2018)

Dear Ezel,

WITHOUT PREJUDICE

Offer Lump Sum \$4850/- @ 4 working days.

Headlamp LH price-\$1450.90

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ezel.t@vermogen-group.com <ezel.t@vermogen-group.com>

Sent: Monday, 3 September 2018 12:00 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: FINALISE TP SLD4039A (DOA: 25/07/2018)

Hi Taufikh,

As requested.

Thanks & Regards,

Ezel Tejano

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>

Sent: Monday, September 3, 2018 9:23 AM

To: ezel.t@vermogen-group.com

Cc: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>

Subject: RE: FINALISE TP SLD4039A (DOA: 25/07/2018)

Hi Ezel,

Can forward the resurvey photos for the check items replaced?

Regards

Taufikh

Lkk AUTO

From: ezel.t@vermogen-group.com [<mailto:ezel.t@vermogen-group.com>]

Sent: Thursday, 30 August 2018 12:50 PM

To: 'Taufikh (LKKAuto)'; 'SUR'

Cc: 'Baldoz Juan Paulo Bongon'; eric.g@vermogen-group.com; 'Vmg admin'; 'Luis Tan'; 'Pila Ng'; 'Minoko Chan'; 'Paul Tan'; desmond@vermogen-group.com

Subject: FINALISE TP SLD4039A (DOA: 25/07/2018)

Dear Taufikh,

Kindly check and confirm finalise COR with \$5,550.00 before 7% gst (lump sum) in 4 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you.

Best Regards,
Ezel Tejano
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6358 3031
Fax: 6694 4929

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2018		03 Aug 2018 14:25 Edit Adj Rpt	S\$5,050.00 Edit Estimates	S\$5,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, ID: -								
Main Claimant:	LCRF PTE LTD								
Vehicle Reg. No.:	SLD4039A	Date of Loss:	25/07/2018 00:00 - :59 [25 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03789C02	Policy/Cover Note No.:	DMCVSN3063561700						
Vehicle Reg. No. (Insured):	GBB1576P	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/08/2018]								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLD4039A (SNM18D03789C02)**
[GBB1576P]
TP
LCRF PTE LTD
Jul 25 2018 12:00AM
[-]
Vermogen Ace Pte Ltd (benoi)

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	04/09/18 17:29	General View							Load PDF		
2	04/09/18 17:29	Reinspection Photo							Load PDF		
Documentation									1 per page		☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	03/08/18 14:24	PRS							Load PDF		
2	03/08/18 14:24	TP GIA							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014162/VD3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3063561700

Claimant Vehicle
No: SLD4039A

Insured Vehicle
No: GBB1576P

Date of Loss: 25/07/2018

Nature of Claim: TP

Claim
No: SNM18D03789C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD4039A**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4035272

Reg. Date: 15/06/2016 (Man. Year: 2016)

Chassis No: RU11115266

Colour: Blue

Odometer: 198355 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Roadstone 6 mm

Rear Left Side: Roadstone 6 mm

Front Right Side: Roadstone 6 mm

Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,127.24	5,308.16	6,819.08	56.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,060.00	2,590.00	70.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,777.24	6,368.16	9,409.08	59.64
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	15,777.24	5,050.00	10,727.24	67.99
+ GST 7.00/7.00% (S\$)	1,104.41	353.50	750.91	67.99
Nett Amount (S\$)	16,881.65	5,403.50	11,478.15	67.99

INSPECTION

Date of Assignment: 03/08/2018

Date Inspected: 06/08/2018 Inspected At:

Vermogen Ace Pte Ltd (benoi) (HQ)
6 Benoi Sector
Singapore 629904

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2018)	
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLD4039A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cracked	2,540.00 FL	*1,784.50 FL
2	1		*HEADLAMP LOWER BRACKET LH	Necessary	55.00 FL	*55.00 FL
3	1		*FRONT BUMPER	Deformed	1,085.00 FL	*1,085.00 FL
4	1		*FRONT BUMPER LOWER	Not Necessary	480.00 FL	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
6	1		*FRONT BUMPER RETAINER LH	Necessary	114.00 FL	*114.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	361.00 FL	*- FL
8	1		*SET FRONT BUMPER REINFORCEMENT GARNISH	Not Necessary	175.20 FL	*- FL
9	1		*FRONT BUMPER LOWER LIP	Not Necessary	194.00 FL	*- FL
10	1		*SET FRONT BUMPER LOWER LIP CLIPS	Not Necessary	35.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	387.70 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	62.00 FL	*- FL
13	1		*FRONT FENDER LH	Not Necessary	660.00 FL	*- FL
14	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	165.00 FL	*- FL
15	1		*FRONT FENDER ARCH GARNISH LH	Not Necessary	192.00 FL	*- FL
16	1		*SET FRONT FENDER ARCH GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
17	1		*FRONT GRILLE BASE	Cracked	510.00 FL	*510.00 FL
18	1		*FRONT GRILLE GARNISH	Cracked	251.20 FL	*251.20 FL
19	1		*FRONT GRILLE CHROME	Cut	1,150.00 FL	*1,150.00 FL
20	1		*FRONT GRILLE SIDE BRACKET	Deformed	279.00 FL	*279.00 FL
21	1		*FRONT GRILLE CENTRE BRACKET	Deformed	139.50 FL	*139.50 FL
22	1		*FRONT GRILLE CLIPS	Necessary	35.00 FL	*35.00 FL
23	1		*FRONT GRILLE LOGO	Necessary	52.00 FL	*52.00 FL
24	1		*FRONT SUPPORT PANEL	Not Necessary	576.20 FL	*- FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	185.00 FL	*- FL
26	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	35.00 FL	*- FL
27	1		*FRONT SUPPORT LOWER PANEL	Not Necessary	422.20 FL	*- FL
28	1		*BONNET	Bent	1,130.00 FL	*1,130.00 FL
29	2		*BONNET HINGE LH/RH	Not Necessary	124.00 FL	*- FL
30	1		*BONNET INSULATOR	Not Necessary	160.50 FL	*- FL
31	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FL	*- FL
32	2		*BONNET RUBBER SIDE	Not Necessary	66.80 FL	*- FL
33	1		*BONNET RUBBER CENTRE	Not Necessary	35.20 FL	*- FL
34	1		*FRONT SHOCK ABSORBER LH	Not Necessary	675.00 FL	*- FL
35	1		*FRONT SHOCK ABSORBER MOUNTING LH	Not Necessary	78.20 FL	*- FL
36	1		*FRONT SHOCK ABSORBER BEARING LH	Not Necessary	97.60 FL	*- FL
37	1		*FRONT SHOCK ABSORBER DUST COVER LH	Not Necessary	65.00 FL	*- FL
38	1		*FRONT SHOCK ABSORBER STOPPER LH	Not Necessary	38.10 FL	*- FL
39	1		*FRONT KNUCKLE ARM LH	Not Necessary	390.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT LOWER ARM LH	Not Necessary	350.00 FL	*- FL
41	1		*FRONT WHEEL BEARING LH	Not Necessary	181.40 FL	*- FL
42	1		*FRONT WHEEL HUB LH	Not Necessary	245.00 FL	*- FL
43	1		*FRONT RIM LH	Not Necessary	950.00 FL	*- FL
44	1		*FRONT TYRE LH	Not Necessary	180.00 FS	*- FS
45	1		*FRONT NUMBER PLATE WITH FRAME	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,102.80	6,635.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,975.56	1,327.04
Total Parts (S\$)	12,127.24	5,308.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA.FRT BONNET ,FRT BUMPER ,FRT BUMPER REINFORCEMENT ,FRT SUPPORT PANEL,FRT SUPPORT LOWER PANEL ,FRT FENDER LH	New	1,500.00	400.00
2	TO PUTTY ,RESPRAY PAINTING AND POLISH ACCIDENT AREA.FRT BONNET ,FRT BUMPER ,FRT BUMPER REINFORCEMENT ,FRT SUPPORT PANEL ,FRT SUPPORT LOWER PANEL ,FRT FENDER LH	New	1,500.00	600.00
3	TO RUST PROOF AFFECTED AREAS	New	150.00	30.00
4	TO REMOVE AND REPLACE FRONT SUSPENSION PARTS TO ASSIST REPAIR	New	250.00	0.00
5	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$\$)			3,650.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >