

SMRT Accident Vehicle Repair Estimates

PIP

CIA

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4902K
 Ref. No : TAX/07/18/2142
 Reg. Date : 06/11/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : RAMACHANDRAN S/O SITARENGAN
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 29/07/2018 02:30:00 PM
 Accident Reported Date / Time : 30/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097294
 Special Instruction to ARC,if any :
 SHB9967X(TRANSCAB)
 Prepared Date : 30/07/2018 12:02:51 PM



LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405766628 Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------|---------------------------|--|
| Total Labour Charges : | 0.00 | 0.00 |
| Total Spray Painting Charges : | 180.00 | 0.00 |
| Total Material Charges : | 1,119.64 | 1,119.64 |
| Other Charges : | 120.00 | 0.00 |
| TOTAL : | 1,419.64 | 0.00 |
| Lum Sum Total : | 0.00 | 0.00 |
| No. of Repair Days : | 2.00 | 0.00 1.00 |
| Prepared / Adjusted By : | | |
| Arc / Surveyor Sing Off Date : | 30/07/2018 06:36:47 PM | |



Prepared / Adjusted Date :
Remarks :

Prepared Date : 30/07/2018 06:35:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------|--------------------|-------------------------------------|
| Total Labour | | |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO RESPRAY VIEW MIRROR | 180.00 | 0.00 |
| Total Spray Painting & Panel Beating | 180.00 | 0.00 100 |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------------|----------------------|-------------------------------------|
| TO REMOVE AND REFIX WING MIRROR | 120.00 | 0.00 |
| Total Other Costs | 120.00 80 | 0.00 50 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NAZ LKX
1/8/18 1615
PIP
AFTER REPAIR PHOTO
~~2 DAYS~~
1 Day

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|------------------------------------|---------|----------|-------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|--------------------------------|
| 87910-47330 | | 6505600 | MIRROR ASSY, RH | 1 | 1,307.10 | 25.00 | 980.32 | Replace | Replace | No CRK <i>X SVC</i> |
| 81730-52090 | | 6505466 | MIRROR LAMP RH | 1 | 65.30 | 10.00 | 58.77 | Replace | Replace | No <i>CRK</i> |
| 879157-4010 | | 6505598 | COVER, OUTER MIRROR, RH | 1 | 107.40 | 25.00 | 80.55 | Replace | Replace | No <i>XR</i> |
| TOTAL MATERIALS | | | | | | | | 1,119.65 | 1,119.64 | |
| TOTAL MATERIALS(Discounted) | | | | | | | 1,119.64 | 1,119.64 | | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|--------------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | | |