


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4902K
Ref. No : TAX/07/18/2142
Reg. Date : 06/11/2015
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : RAMACHANDRAN S/O SITARENGAN
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 29/07/2018 02:30:00 PM
Accident Reported Date / Time : 30/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097294
Special Instruction to ARC,if any :
SHB9967X(TRANSCAB)
Prepared Date : 30/07/2018 12:02:51 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405766628

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	0.00	0.00
Total Spray Painting Charges :	180.00	0.00
Total Material Charges :	1,119.64	1,119.64
Other Charges :	120.00	0.00
TOTAL :	1,419.64	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	2.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	30/07/2018 06:36:47 PM	30/07/2018 06:38:11 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 30/07/2018 06:35:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	180.00	0.00
Total Spray Painting & Panel Beating	180.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	120.00	0.00
Total Other Costs	120.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
87910-47330		6505600	MIRROR ASSY, RH	1	1,307.10	25.00	980.32	Replace	Replace	No
81730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace	No
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace	No
TOTAL MATERIALS							1,119.65	1,119.64		
TOTAL MATERIALS(Discounted)							1,119.64	1,119.64		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									