

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3550T

DATE 31/7/2018 11:11

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X Repair</i>			\$ 562.30
	Front Bumper Bracket Top (RH) <i>X</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>X</i>			\$ 24.60
	SUB TOTAL			\$ 609.30
	LESS 20%			\$ 121.86
	DISCOUNTED TOTAL			\$ 487.44
	Labour Charge			<i>100</i>
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 1,087.44
<p><i>1 Call 10/11/14</i></p> <p><i>31/7/18 1430 L</i></p> <p><i>2 Days</i></p> <p><i>P/P</i></p> <p><i>After part p/L</i></p> <div data-bbox="893 1323 1380 1722" data-label="Text"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				