

SMRT Accident Vehicle Repair Estimates

AIG PIP

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5760B
 Ref. No : TAX/07/18/2141
 Reg. Date : 12/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TAI KIAN HAN
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 28/07/2018 11:20:00 PM
 Accident Reported Date / Time : 30/07/2018 12:00:00 AM
 Surveyor is Required? : No
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 29/07/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097295
 Special Instruction to ARC, if any :
 TOWED \$60 / This case OD change to BP case.
 Prepared Date : 30/07/2018 12:03:33 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU903575842

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 2,052.00	0.00
Total Material Charges	: 5,269.43	5,269.43
Other Charges	: 1,357.76	0.00
TOTAL	: 9,693.19	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: <u>6.00</u>	0.00 <u>4.00</u>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 31/07/2018 02:36:26 PM	31/07/2018 04:14:24 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 31/07/2018 02:31:27 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/31/2018 2:31:40 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00
Total Labour	1,014.00	0.00 800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 50
TO RESPRAY REAR FENDER LH	378.00	0.00 200
RESPRAY WHEEL CAP	180.00	0.00 50
TO RESPRAY CENTER PILLAR LH	180.00	0.00 100
Total Spray Painting & Panel Beating	2,052.00	0.00 1,000

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00 50
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	593.76	0.00 / net
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 50
TO TRANSFER DOOR MECHANISM	240.00	0.00 100
TO REPLACE SUNDRY PARTS	100.00	0.00 X 00
TO WASH AND VACUUM	60.00	0.00 X 00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
Total Other Costs	1,357.76	0.00

NA2 LKK
2/8/18 1130
P/P
4 DAYS
BEFORE PAINT PHOTO

- Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be authorized and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7586047900			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	25.00	432.00	Replace	Replace	No <i>XR</i>
6700247162			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	25.00	937.20	Replace	Replace	No <i>DT</i>
8572047140			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR, LH	1	768.60	10.00	691.74	Replace	Replace	No <i>?</i>
6980221010			DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	1	230.80	25.00	173.10	Replace	Replace	No <i>?</i>
6700447210			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	25.00	932.93	Replace	Replace	No <i>XR</i>
6789647010			WEATHERSTRIP, REAR DOOR, NO.2, LH	1	33.20	25.00	24.90	Replace	Replace	No <i>XSVL</i>
6878052031			HINGE ASSY, REAR DOOR, LOWER LH	1	73.30	25.00	54.98	Replace	Replace	No <i>XSVL</i>
6876020122			HINGE ASSY, REAR DOOR, UPPER LH	1	83.30	25.00	62.48	Replace	Replace	No <i>XSVL</i>
6863047050			CHECK ASSY, REAR DOOR	1	153.50	25.00	115.13	Replace	Replace	No <i>?</i>
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No <i>XR</i>
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace	No <i>XSVL</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <i>/mc</i>
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace	No <i>/mc</i>
5380247100			FENDER SUB-ASSY, FR, LH	1	933.10	25.00	699.82	Replace	Replace	No <i>XR</i>
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No <i>/mc</i>
6131247040			PILLAR, CENTER BODY, OUTER LH	1	313.40	25.00	235.05	Replace	Replace	No <i>XR</i>
TOTAL MATERIALS								5,269.44	5,269.43	
TOTAL MATERIALS(Discounted)							5,269.43	5,269.43		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
5380247100		FENDER SUB-ASSY, FR, LH	1	933.10	25.00	699.82	Replace	Replace	No
7537447100		EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No
6131247000		PILLAR, CENTER BODY, OUTER LH	1	313.40	25.00	235.05	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						974.54			