



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR TEHC INTERNATION PTE LTD
 11 WOODLANDS CLOSE
 #10-30/31 WOODLANDS 11
 SINGAPORE 737853

POLICY NO : THIRD PARTY CLAIMS
 YOUR REF : SLU7056R
 OUR REF : TP5925
 VEHICLE NO : GZ6718D
 MAKE/MODEL : Nissan Cabstar
 DATE OF ACCIDENT : 28.7.18


SURVEY BY

DATE : 01.08.18

1 PC TAILBOARD		S\$ <i>bt</i> 1,339.70	NETT
2 PCS TAILBOARD HINGES	125.00	<i>Rp</i> 375.00	"
1 PC TAILBOARD NISSAN STICKER		<i>net</i> 74.00	"
2 PCS TAILLAMP ASSY	248.60	<i>eng</i> 497.20	"
		S\$ 2,285.90	
	LESS 10%	228.59	
		S\$ 2,057.31	
1 PC SAFETY BAR		S\$ <i>bt</i> 500.00	S/NETT
1 PC TAILBOARD 70KM/HR STICKER		<i>net</i> 20.00	"
1 PC TAILBOARD "13 PAX" STICKER		<i>net</i> 20.00	"
1 PC TAILBOARD "NISSAN CABSTAR" STICKER		<i>net</i> 20.00	"
1 PC REAR NUMBER PLATE		<i>bt</i> 45.00	<i>30</i> "
		S\$ 605.00	
TO CHECK WIRING FUNCTION		S\$ <i>✓</i> 30.00	
TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL		<i>30</i> 50.00	
LABOUR CHARGES		<i>500</i> 700.00	
TO PUTTY AND SPRAY PAINTING CHARGES		<i>500</i> 700.00	
		<u>S\$ 4,142.31</u>	

SIN DOLLARS: FOUR THOUSAND ONE HUNDRED FOURTY-TWO AND CENTS THIRTY-ONE ONLY.

YOUR FAITHFULLY,


 CYS AUTOMOBILE SERVICES PTE LTD

Taufiqurrahman 97495749
- wp'
2/8/18 @ 920
Resumy after repair
5 days
Taufiqurrahman@khaunto.com