

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF1022D
 Ref. No : TAX/07/18/2135
 Reg. Date : 17/12/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : SELVADURAI S/O SENGALRAYAN
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 28/07/2018 08:20:00 AM
 Accident Reported Date / Time : 28/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097267
 Special Instruction to ARC, if any :
 GBA9462L
 Prepared Date : 28/07/2018 11:14:21 AM



LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

-wpr

30/7/18 1630

Lumpsum

Resurvey after repair.

Sur & Lkkauto.com

5 days.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105754484

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 3,168.00	0.00
Total Material Charges	: 9,148.43	9,148.43
Other Charges	: 1,300.00	0.00
TOTAL	: 14,799.43	0.00
Lum Sum Total	: 14,800.00	0.00
No. of Repair Days	: 8.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 30/07/2018 02:13:19 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 30/07/2018 08:58:14 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/30/2018 2:12:50 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,183.00	0.00
Total Labour	1,183.00	0.00 600

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY RIM	360.00	0.00 100
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY FRONT PILLAR RH	180.00	0.00 X
TO RESPRAY VIEW MIRROR	180.00	0.00 100
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR DOOR RH	378.00	0.00 X
TO RESPRAY REAR FENDER RH	378.00	0.00 X
TO REPSRAY REAR BUMPER	378.00	0.00 X
Total Spray Painting & Panel Beating	3,168.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 80.
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 60 40
TO TRANSFER DOOR MECHANISM	240.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	0.00 30
TO REMOVE AND REFIT TYRE	240.00	0.00 30.
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,300.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>de</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>new</i>	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace <i>int</i>	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>ht</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>new</i>	No
53827-47030			FENDER PROTECTOR FRT/RH SIDE	1	113.90	25.00	85.42	Replace	Replace <i>?</i>	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>my</i>	No
53851-47040			FENDER LINER PAD, FR WHEEL, RH	1	49.30	25.00	36.97	Replace	Replace <i>?</i>	No
42611--47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>ant</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>?</i>	No
48510-80574			SHOCK ABSORBER FRT/RH	1	394.20	25.00	295.65	Replace	Replace <i>?</i>	No
48609-47040			SHOCK ABSORBER MOUNTNG FRT, RH/LH	1	193.80	25.00	145.35	Replace	Replace <i>?</i>	No
48619-28010			SHOCK ABSORBER BEARING, FRT LH/RH	1	34.00	25.00	25.50	Replace	Replace <i>?</i>	No
48820-47020			STABILIZER BAR LINK FRT/RH/LH	1	195.00	25.00	146.25	Replace	Replace <i>?</i>	No
43202-47030			STEERING KNUCKLE LH FRT	1	580.80	25.00	435.60	Replace	Replace <i>?</i>	No
43550-47011			WHEEL HUB FRT	1	549.70	25.00	412.27	Replace	Replace <i>?</i>	No
48068-47050			LOWER ARM FRT/RH	1	625.90	25.00	469.42	Replace	Replace <i>?</i>	No
43330-49185			JOINT ASSY, LWR BALL	1	195.60	25.00	146.70	Replace	Replace <i>?</i>	No
45046-49225			TIE ROD END RH	1	159.30	25.00	119.47	Replace	Replace <i>?</i>	No
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>ht</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>new</i>	No
58730-12120			HINGE LOWER RHF, DOOR	1	90.10	25.00	67.57	Replace	Replace <i>Kr</i>	No
58710-12151			HINGE UPPER RHF, DOOR	1	80.50	25.00	60.37	Replace	Replace <i>ht</i>	No
58610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.72	Replace	Replace <i>Ry</i>	No
51131-47030			PILLAR, FR BODY	1	363.10	25.00	272.32	Replace	Replace <i>ht</i>	No
37910-47330		6505600	MIRROR ASSY, RH	1	1,307.10	25.00	980.32	Replace	Replace <i>?</i>	No
31730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace <i>one</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace <i>cut</i>	No
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace <i>not consistent</i>	No
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace <i>nm</i>	No <i>n</i>
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace <i>nm n</i>	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace <i>nm n</i>	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>nm n</i>	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace <i>nm n</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>x</i>	No <i>nm</i>
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>x</i>	No <i>nm</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>x</i>	No <i>nm</i>
TOTAL MATERIALS								11,435.61	11,435.54	
TOTAL MATERIALS(Discounted)							9,148.43	9,148.43		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									