

Lee Ming Yao | CC3 / AIG 180 14190 , T1W0352

LKK:
IDAC:

Surveyor: MTH DOI: 30/7/2018 Date / Time: 30/7/2018
Registered in Merimen: 5/8/2018

Pre-assign / CCU / FTE



Insured Vehicle No. : SKL 2222 U
Name of Insured : Levy Siew Amen
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A: 27/7/2018
Is driver the owner? (YES / NO) Nature of Accident :
If NO, Driver Name / Age : Levy Siew Amen @ 41yrs
Driver Tel No. : 98299292 W/L: YES/NO)

Claim No. : 203531403966
Policy No. : 2150434114
Make / Model : M-BENZ S400
Place of Accident : PIE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability : % Final ? Yes / No

SKL 2222 U → SHB 5332D → SJL 4282 U



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP: SMP1, W
Tel:
Liability: TP
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
<u>12/8</u>	Non-Reporting ltr (1st):	
<u>14/8</u>	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
<u>20/8/18</u>	After call ltr to OI:	<u>20/8/18</u>
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost:	<u>P10</u> S\$ <u>7,760.65</u> (<u>11</u> days) Reduction: <u>69</u> %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>26/09/19</u> Confirm with <u>Lee Gok</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u> (Assessed / Assessed) BOLA S/N No. : <u>28</u>	If NO or B 28, Ass. Lia : <u>100%</u>
Repair Cost:	S\$ <u>7760.65</u>	<u>ODD involved in 3-C</u> <u>ODD is the last veh</u>
Loss of Rental (LOR):	S\$ <u>1572.90</u> (<u>14</u> days) x <u>112.35</u>	
Loss of Use (LOU):	S\$ <u>700.00</u> (\$ <u>50</u> x <u>14</u> days)	
Loss of Income (LOI):	S\$ _____ (\$ _____ x _____ days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/>	[Tick only one]	
GIA/LTA Search	S\$ <u>7.00</u>	
Medical:	S\$ _____	
Disbursement:	S\$ _____ (e.g. Tow/Independent)	
Legal Cost	S\$ _____	
Total:	S\$ <u>10040.55</u> Global Sum S\$: <u>10,040.00</u>	
FINAL PAYMENT	Date/Time: _____ Confirm with: _____	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$ <u>10,040.00</u> Name 1: <u>SHIRT TAXIS PTE LTD</u>	
Payee 2: (Strike if N.A.)	S\$ _____ Name 2: _____	
Payee 3: (Strike if N.A.)	S\$ _____ Name 3: _____	

LOI: 112.35 x 14 = 1572.90
LOU: 50 x 14 = 700.00

1) Claim status: Normal / Reject / Private Settle
2) Report Format:
3) Survey fee: \$320.00

08/1/13

Surveyor: Taupha

REF:

A16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: 7B-2% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB5332D Regn: 2016, Manly

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius c.c. 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN 364105-767915

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 275

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/7/10 D.O.I. 30/7/18 @ 1635

Survey held at SMART W/L

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Battery weak</u>
	<u>P/P \$7,760.65</u>
	<u>CRAB: 48,053.74 (57%)</u>
	<u>AT: 17,119.05 (69%)</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

1) _____
 Date/Time, File Return to?

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	

Report Format : _____
 Lump Sum / I.B.I. (\$) _____


9-8-18 / 12:41
8-8-18 / 16:47

SMRT Accident Vehicle Repair Estimates

30-7-18 / 16:47


Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5332D
 Ref. No : TAX/07/18/2133
 Reg. Date : 13/05/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHHI AIK KIONG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 27/07/2018 05:35:00 PM
 Accident Reported Date / Time : 28/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Taufikh
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 27/07/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097265
 Special Instruction to ARC, if any :
 TOWED \$90 / SKL2222U - AIG - LKK p/p
 Before paint photo ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/
 EMAIL: sur@lkkauto.com
 Prepared Date : 28/07/2018 10:29:32 AM



Recording Camera
 Radio Antenna
 1st witness _____ Date 31-7-18
 2nd witness _____ Date _____

Vehicle to Wega Date in: 31/7 Towing: Aug
 Time in: 17:21 Driver: _____
 Wega Job No: 07/04459
 Vehicle sent to SMRT Date in: 8-08-18 Towing: _____
 Time in: 15:02 Driver: _____
 Inspected by (SMRT): _____



Attached Supplementary

QC 8/8/18 17.13 reject
 RIAR - Penda Dent No Repair & Spray
 11/8/18 10:29 P 053

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105767915 Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,197.00	1,300.00
Total Spray Painting Charges	: 3,492.00	1,200.00
Total Material Charges	: 8,094.39	4,625.65
Other Charges	: 2,031.00	635.00
TOTAL	: 15,814.39	7,760.65
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 14.00	10.00
Prepared / Adjusted By	:	TAUFIK (LKK)
Arc / Surveyor Sign Off Date	: 28/07/2018 03:29:43 PM	30/07/2018 04:47:50 PM

M

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/07/2018 03:29:44 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1808-0285 Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : 13/8 Prepared Date :

4625.65
1300
+ 1835

7760.65

\$7760.69 *

10 days

Email 24/3

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	200.00
TO REPAIR REAR PORTION	1,859.00	1,100.00
Total Labour	2,197.00	1,300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100.00
TO RESPRAY REAR FENDER RH	378.00	200.00
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 <i>x n</i>
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 <i>x n</i>
TO RESPRAY SPOILER	180.00	100.00
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00 <i>x n</i>
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00
TO RESPRAY REAR CHASSIS LH	180.00	0.00
TO RESPRAY REAR CHASSIS RH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
Total Spray Painting & Panel Beating	3,492.00	1,200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

5689

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	90.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	50.00
TO ALIGN CHASSIS	350.00	0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REMOVE AND REFIT BATTERY ASSY HV	250.00	0.00
TO REPLACE SUNDRY PARTS	100.00	30.00
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00
Total Other Costs	2,031.00	635.00

2031

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	100.00	0.00	Replace	Repair	No <i>X</i>
90467-07211			BUMPER CLIPS	0	2.10	25.00	0.00	Replace	Not given	No <i>X nm</i>
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <i>ht</i>
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No <i>de</i>
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace <i>3</i>	No <i>see</i>
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.33	Replace	Check	No <i>X nm</i>
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Check	No <i>X nm</i>
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Check	No <i>X nm</i>
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Check	No <i>X nm</i>
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No <i>ms</i>
61604-47090			FENDER RR/RH	1	766.80	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No <i>see</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>see</i>
62710-47130			QUARTER GLASS RR/RH	0	846.50	25.00	0.00	Replace	Not given	No <i>X nm</i>
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No <i>see</i>
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Check	No <i>X nm</i>
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Replace <i>5</i>	No <i>see</i>
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.18	Replace	Check	No <i>X nm</i>
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No <i>ht</i>
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No <i>see</i>
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No <i>see</i>
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No <i>see</i>
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No <i>see</i>
68810-47010			TAILGATE DOOR HINGE LH/RH	0	58.30	25.00	0.00	Replace	Not given	No <i>X nm</i>
68960-0W532			TAILGATE DOOR STAY LH	0	241.50	25.00	0.00	Replace	Not given	No <i>X nm</i>
68950-0W542			TAILGATE DOOR STAY RH	0	241.50	25.00	0.00	Replace	Not given	No <i>X nm</i>
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.08	Replace	Replace <i>5</i>	No <i>bt</i>

6438.50

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.78	Replace	Check	No <i>X</i>
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace <i>S</i>	No <i>✓</i>
67938-47031C0			TAILGATE TRIM, LH	0	85.90	25.00	0.00	Replace	Not given	No <i>X</i>
67937-47031C0			TAILGATE TRIM, RH	0	88.30	25.00	0.00	Replace	Not given	No <i>X</i>
67751-47040C0			TAILGATE TRIM, LOWER	0	180.70	25.00	0.00	Replace	Not given	No <i>X</i>
67750-47071C0			TAILGATE, BOARD ASSY	0	246.90	25.00	0.00	Replace	Not given	No <i>X</i>
76801-47070-B0			TAILGATE OUTSIDE GARNISH	0	504.90	25.00	0.00	Replace	Not given	No <i>X</i>
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace	No <i>✓</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>✓</i>
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace	No <i>✓</i>
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace	No <i>✓</i>
	REAR		NUMBER PLATE	0	30.00	0.00	0.00	Replace	Not given	No <i>X</i>
			NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No <i>X</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No <i>✓</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>✓</i>
76085-47910		6505620	SPOILER REAR	0	953.70	25.00	0.00	Replace	Not given	No <i>X</i>
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>✓</i>
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No <i>✓</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>✓</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No <i>✓</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>S</i>	No <i>✓</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No <i>✓</i>
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace <i>S</i>	No <i>✓</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>✓</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>✓</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No <i>✓</i>
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.68	Replace	Check	No <i>X</i>
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No <i>X</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>✓</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace <i>S</i>	No <i>✓</i>

4793

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace S	No ✓ de
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No ✓ de
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Replace O	No ✓ ht
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace S	No ✓ de
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Check	No X
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Check	No X
58415-47030			BOARD, RR FLOOR	1	392.30	25.00	294.23	Replace	Check	No X
64997-47020			BOX, DECK FLOOR, LH	1	196.80	25.00	147.60	Replace	Check	No X
58427-47040			SPACER, RR FLOOR	0	130.60	25.00	0.00	Replace	Not given	No X
58402-47010B1			BOARD SUB-ASSY, RR	0	122.80	25.00	0.00	Replace	Not given	No X
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	100.00	0.00	Replace	Repair	No R
64777-47090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Replace S	No ✓ de
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.78	Replace	Check	No X
64778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.78	Replace	Check	No X
	COMMON		BREAKDOWN SIGN	1	35.00	0.00	35.00	Replace	Check	No X
57604-47030			MEMBER SUB-ASSY, RR LH	0	174.10	25.00	0.00	Replace	Not given	No X
57603-47030			MEMBER SUB-ASSY, RR RH	0	174.10	25.00	0.00	Replace	Not given	No X
58303-47301			FLOOR PANEL RR/LH	0	102.00	25.00	0.00	Replace	Not given	No X
58302-47030			FLOOR PANEL RR/RH	1	209.90	100.00	0.00	Replace	Repair	No R
58336-12090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Check	No X
58327-47020			EXHAUST HEAT SHIELD, REAR	1	107.40	25.00	80.55	Replace	Check	No X
17430-37380			EXHAUST TAIL PIPE	0	656.20	25.00	0.00	Replace	Not given	No X
17565-22030			SUPPORT, EXHAUST REAR	0	33.60	25.00	0.00	Replace	Not given	No X
TOTAL MATERIALS							6188.20	8,094.43	4,625.65	
TOTAL MATERIALS(Discounted)								8,094.39	4,625.65	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

25124.70x

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5332D
 Ref. No : TAX/07/18/2133
 Reg. Date : 13/05/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHHI AIK KIONG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 27/07/2018 05:35:00 PM
 Accident Reported Date / Time : 28/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 27/07/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097265
 Special Instruction to ARC,if any :
 TOWED \$90 / SKL2222U
 Prepared Date : 28/07/2018 10:29:32 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjim 9749 5749

wp

30/7/18 @ 1635

Resury before paint

sure@lkkauto.com

8 days

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105767915

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges	: 2,197.00	0.00
Total Spray Painting Charges	: 3,492.00	0.00
Total Material Charges	: 13,446.93	13,446.93
Other Charges	: 2,031.00	0.00
TOTAL	: 21,166.93	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 14.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 28/07/2018 03:29:43 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/07/2018 03:29:44 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	0.00 200
TO REPAIR REAR PORTION	1,859.00	0.00 900
Total Labour	2,197.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 X
TO RESPRAY SPOILER	180.00	0.00 100
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 X
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR CHASSIS LH	180.00	0.00 X
TO RESPRAY REAR CHASSIS RH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 X
Total Spray Painting & Panel Beating	3,492.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	0.00 80
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO ALIGN CHASSIS	350.00	0.00 X
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 170
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND REFIT BATTERY ASSY HV	250.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00
Total Other Costs	2,031.00	0.00 /

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace	No
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace	No
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
68810-47010			TAILGATE DOOR HINGE LH/RH	2	58.30	25.00	87.45	Replace	Replace	No
68960-0W532			TAILGATE DOOR STAY LH	1	241.50	25.00	181.12	Replace	Replace	No
68950-0W542			TAILGATE DOOR STAY RH	1	241.50	25.00	181.12	Replace	Replace	No
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace ?	No
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace ?	No
67938-47031C0			TAILGATE TRIM, LH	1	85.90	25.00	64.42	Replace	Replace X	No
67937-47031C0			TAILGATE TRIM, RH	1	88.30	25.00	66.22	Replace	Replace X	No
67751-47040C0			TAILGATE TRIM, LOWER	1	180.70	25.00	135.52	Replace	Replace X	No
67750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.17	Replace	Replace X	No
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace X	No
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace <i>del</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>del</i>	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace <i>del</i>	No
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace <i>del</i>	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace X	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace X	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace <i>del</i>	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>del</i>	No
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace X	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>del</i>	No
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace <i>del</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>del</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>del</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace <i>del</i>	No
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>del</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>del</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>del</i>	No
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace ?	No
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace ?	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>del</i>	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace ?	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace ?	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace ?	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ?	No
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.27	Replace	Replace ?	No
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace ?	No
58415-47030			BOARD, RR FLOOR	1	392.30	25.00	294.22	Replace	Replace ?	No
64997-47020			BOX, DECK FLOOR, LH	1	196.80	25.00	147.60	Replace	Replace ?	No
58427-47040			SPACER, RR FLOOR	1	130.60	25.00	97.95	Replace	Replace	No
58402-47010B1			BOARD SUB-ASSY, RR	1	122.80	25.00	92.10	Replace	Replace X	No
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace Rx	No
64777-47090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Replace ?	No
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.77	Replace	Replace ?	No
64778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.77	Replace	Replace ?	No
	COMMO N		BREAKDOWN SIGN	1	35.00	0.00	35.00	Replace	Replace ?	No
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10	25.00	130.57	Replace	Replace X	No
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.57	Replace	Replace X	No
58303-47301			FLOOR PANEL RR/LH	1	102.00	25.00	76.50	Replace	Replace X	No
58302-47030			FLOOR PANEL RR/RH	1	209.90	25.00	157.42	Replace	Replace	No
58336-12090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Replace ?	No
58327-47020			EXHAUST HEAT SHIELD, REAR	1	107.40	25.00	80.55	Replace	Replace ?	No
17430-37380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Replace X	No
17565-22030			SUPPORT, EXHAUST REAR	2	33.60	25.00	50.40	Replace	Replace X	No

TOTAL MATERIALS

13,447.11 13,446.93

TOTAL MATERIALS(Discounted)

13,446.93 13,446.93

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Print Received Message

This mail is associated with :

***SHB5332D (3035314039SG)**
[SKL2222U]

TP

SMRT TAXIS PTE LTD

Jul 27 2018 5:00PM

[LEONG SIEW KHUEN]

SMRT Automotive Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/09/2019 16:36 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10040.59) - SHB5332D - Claim Handler: Lee, Ming-Yao

Approved:10040.59:COR \$7,760.69 LOR \$1,572.90 LOI \$700.00 - 14 days @ S\$50.00/day LTA \$7.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2018 Edit Reg		30 Jul 2018 00:00 Edit Adj Rpt	S\$7,760.65 Edit Estimates	S\$7,760.65 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEONG SIEW KHUEN, ID: S1234166J		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB5332D	Date of Loss:	27/07/2018 17:00 - :59 [26 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3035314039SG	Policy/Cover Note No.:	2100434114 (Comprehensive) Coverage: 02/11/2017 - 01/11/2018
Vehicle Reg. No. (Insured):	SKL2222U	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (16/09/2019): Alert - Adj Mandate Approved (S\$10040.59) - SHB5332D - Claim Handler: Lee, Ming-...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB5332D (3035314039SG)
[SKL2222U]**

TP

SMRT TAXIS PTE LTD

Jul 27 2018 5:00PM

[LEONG SIEW KHUEN]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▼
Letters/Correspondences			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/08/18 17:04	Accident Statement <small>From: OD - Reg. No: SKL2222U, Claimant: LEONG SIEW KHUEN</small>	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/09/19 17:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
3	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/09/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
32	05/09/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
33	05/09/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
59	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
60	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
61	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
62	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
63	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
64	05/09/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
65	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	05/09/19 17:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
87	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
88	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
89	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
90	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
91	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
92	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
93	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
94	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
95	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
96	05/09/19 17:21	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
97	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
98	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
99	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
100	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
101	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
102	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
103	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
104	05/09/19 17:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/18 22:38	TP ESTIMATE-MARKED		Load PDF
2	05/08/18 22:38	TP GIA REPORT		Load PDF
3	30/05/19 17:29	LETTER TO OI		Load PDF
4	30/05/19 17:29	LTA SEARCH		Load PDF
5	30/05/19 17:29	RENTAL MILEAGE		Load PDF
6	30/05/19 17:29	RENTAL RECEIPT		Load PDF
7	01/10/19 09:37	LOD		Load PDF
8	01/10/19 09:37	AUTHORISATION TO ACT		Load PDF
9	01/10/19 09:37	RELEASE VOUCHER		Load PDF
10	01/10/19 09:37	WORKSHOP INVOICE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKL2222U (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHB5332D (TP veh)		
Date of Accident:	27/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$		25,179.70
Final Repair Cost	:\$		10,040.00
Loss of Use	:\$		14.00 days at \$50.00 per day
Rental (if any)	:\$		14 days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$		10,040.00
Is Third Party Workshop GIA Registered?		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO (Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
		BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)	
		* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	_____		

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:\$	10,040.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

01 Oct
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18014190/T1HA3S2
Date: 01/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100434114
Claimant Vehicle No : SHB5332D **Insured Vehicle No :** SKL2222U
 Date of Loss: 27/07/2018 Nature of Claim: TP Claim No: 3035314039SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB5332D**
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR6588295
 Reg. Date: 13/05/2016 (Man. Year: 2015) Chassis No: JTDKN36U105767915
 Colour: Maroon Odometer: 0 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,584.70	4,750.65	12,834.05	72.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,595.00	3,010.00	4,585.00	60.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	25,179.70	7,760.65	17,419.05	69.18
	+ Loss of Use (14.0 x S\$50.00/day) (S\$)	700.00		
	+ Car Rental (14.0 x S\$112.35/day) (S\$)	1,572.90		
	+ Doc/Search Fee (S\$)	7.00		
	Nett Liability (S\$)	10,040.55		
	Global Sum Settlement (S\$)	10,040.00		

INSPECTION

Date of Assignment: 30/07/2018
 Date Inspected: 30/07/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 11.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET, FR BUMPER (DISC 25%)	Necessary	110.40 F	*82.80 F
2	1		*EMBLEM FRONT (DISC 25%)	Missing	86.50 F	*64.87 F
3	1		*TAIL LAMP BRACKET, RH (DISC 25%)	Necessary	30.70 F	*23.02 F
4	1		*TAILGATE ASY (DISC 25%)	Bent	1,007.90 F	*755.92 F
5	1		*TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	Necessary	29.40 F	*22.05 F
6	1		*TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	Necessary	29.40 F	*22.05 F
7	1		*MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
8	1		*TAILGATE DOOR LOCK (DISC 25%)	Bent	444.10 F	*333.07 F
9	1		*TAILGATE DOOR WEATHERSTRIP (DISC 25%)	Cut	353.40 F	*265.05 F
10	1		*EMBLEM REAR (DISC 25%)	Necessary	60.30 F	*45.22 F
11	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.92 F
12	1		*NAME PLATE (PRIUS) (DISC 25%)	Necessary	60.80 F	*45.60 F
13	1		*NAME PLATE (TOYOTA) (DISC 25%)	Necessary	51.90 F	*38.92 F
14	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
15	1		*BUMPER CLIPS (DISC 25%)	Necessary	21.00 F	*15.75 F
			10pcs			
16	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.27 F
17	1		*ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	Deformed	139.60 F	*104.70 F
18	1		*ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	Deformed	139.60 F	*104.70 F
19	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Necessary	94.80 F	*71.10 F
20	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Necessary	94.80 F	*71.10 F
21	1		*BUMPER LIP REAR (DISC 25%)	Deformed	228.90 F	*171.67 F
22	1		*BUMPER LIP COVER RR/LH (DISC 25%)	Deformed	72.20 F	*54.15 F
23	1		*BUMPER LIP COVER RR/LH (DISC 25%)	Deformed	72.20 F	*54.15 F
24	1		*UNDER COVER SUB-ASSY, RR FLOOR (DISC 25%)	Deformed	514.50 F	*385.87 F
25	1		*END PANEL (DISC 25%)	Bent	602.10 F	*451.57 F
26	1		*END PANEL COVER, DECK TRIM HOLE (DISC 25%)	Deformed	46.10 F	*34.57 F
27	1		*CUSHION, SPARE WHEEL (DISC 25%)	Deformed	230.80 F	*173.10 F
28	1		*ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	Cracked	157.40 F	*141.66 F
29	1		*NUMBER PLATE	Bent	15.00 F	*15.00 F
			(SN)			
30	1		*NUMBER PLATE FRAME (SN)	Deformed	12.00 F	*12.00 F
31	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
32	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
33	1		*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F
34	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
35	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
36	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
37	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
38	1		*SENSOR REVERSE (SN)	Not Working	180.00 F	*180.00 F
39	1		*BUMPER CLIPS	Not Necessary	2.10 F	*-F
40	1		*BUMPER GRILLE SUB-ASSY, LOWER	Not Necessary	311.10 F	*-F
41	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*-F
42	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*-F
43	1		*GRILLE, RADIATOR	Not Necessary	310.60 F	*-F
44	1		*QUARTER GLASS RR/RH	Not Necessary	846.50 F	*-F
45	1		*TAIL LAMP RH	Not Necessary	557.80 F	*-F
46	1		*TROUGH, BACK DOOR	Not Necessary	110.90 F	*-F
47	1		*TAILGATE DOOR HINGE LH/RH	Not Necessary	58.30 F	*-F
48	1		*TAILGATE DOOR STAY LH	Not Necessary	241.50 F	*-F
49	1		*TAILGATE DOOR STAY RH	Not Necessary	241.50 F	*-F
50	1		*TAILGATE LOCK, COVER	Not Necessary	15.70 F	*-F
51	1		*TAILGATE TRIM, LH	Not Necessary	85.90 F	*-F
52	1		*TAILGATE TRIM, RH	Not Necessary	88.30 F	*-F
53	1		*TAILGATE TRIM, LOWER	Not Necessary	180.70 F	*-F
54	1		*TAILGATE, BOARD ASSY	Not Necessary	246.90 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
55	1		*TAILGATE OUTSIDE GARNISH	Not Necessary	504.90 F	*-F	
56	1		*NUMBER PLATE	Not Necessary	30.00 F	*-F	
57	1		*NUMBER PLATE FRAME	Not Necessary	12.00 F	*-F	
58	1		*SPOILER REAR	Not Necessary	953.70 F	*-F	
59	1		*BUMPER SEAL, RR LH	Not Necessary	88.90 F	*-F	
60	1		*BUMPER SEAL, RR RH	Not Necessary	65.70 F	*-F	
61	1		*END PANEL COVER, DECK TRIM, RR	Not Necessary	121.10 F	*-F	
62	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*-F	
63	1		*BOX, DECK FLOOR, RR	Not Necessary	649.70 F	*-F	
64	1		*BOX, RR FLOOR, BOARD	Not Necessary	679.60 F	*-F	
65	1		*BOARD, RR FLOOR	Not Necessary	392.30 F	*-F	
66	1		*BOX, DECK FLOOR, LH	Not Necessary	196.80 F	*-F	
67	1		*SPACER, RR FLOOR	Not Necessary	130.60 F	*-F	
68	1		*BOARD SUB-ASSY, RR	Not Necessary	122.80 F	*-F	
69	1		*CARRIER, SPARE	Not Necessary	19.70 F	*-F	
70	1		*PROTECTOR, SPARE	Not Necessary	143.70 F	*-F	
71	1		*BREAKDOWN SIGN	Not Necessary	35.00 F	*-F	
72	1		*MEMBER SUB-ASSY, RR LH	Not Necessary	174.10 F	*-F	
73	1		*MEMBER SUB-ASSY, RR RH	Not Necessary	174.10 F	*-F	
74	1		*FLOOR PANEL RR/LH	Not Necessary	102.00 F	*-F	
75	2		*REINFORCEMENT, RR	Not Necessary	69.20 F	*-F	
76	1		*EXHAUST HEAT SHIELD, REAR	Not Necessary	107.40 F	*-F	
77	1		*EXHAUST TAIL PIPE	Not Necessary	656.20 F	*-F	
78	1		*SUPPORT, EXHAUST REAR	Not Necessary	33.60 F	*-F	
79	1		*BUMPER FRT	Repair	482.00 F	*-F	
80	1		*FENDER RR/RH	Repair	766.80 F	*-F	
81	1		*SPARE TYRE PANEL	Repair	667.70 F	*-F	
82	1		*FLOOR PANEL RR/RH	Repair	209.90 F	*-F	
83	1		*SOLAR FILM (SN)	Necessary	125.00 F	*125.00 F	
					Total Parts (\$\$)	17,584.70	4,750.65

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	2,197.00	1,300.00
2	SPRAY PAINT.	New	3,492.00	1,200.00
3	TOWING CHARGE.	New	126.00	90.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	40.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	50.00
6	TO ALIGN CHASSIS.	New	350.00	0.00
7	TO REMOVE & REFIT REAR QUARTER GLASS RH	New	120.00	0.00
8	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	60.00
9	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	120.00
10	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	60.00
11	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
12	TO INSPECT RR LIGHTING, MECHANISM & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	30.00
13	TO REMOVE AND REFIT BATTERY ASSY HV.	New	250.00	0.00
14	TO REPLACE SUNDRY PARTS.	New	100.00	30.00
15	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			7,595.00	3,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >