



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



LONPAC INSURANCE BHD 100 BEACH ROAD #19-00, SHAW TOWER SINGAPORE 189702 ATTN.: MOTOR CLAIMS FAX:		NAME: One Kian ADDRESS: 27 Ewe Boon Road #09-01 Singapore 259330 TEL: 96640990		WIP: 21079 EXCESS: DATE: 2-Aug-18	
VEH NO:	SKW6886U	DATE IN:		CONTACT PERSON:	Vion 63957877
CHASSIS NO:	JM6KE1031E0225810	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	CX5	DATE REG.:	30-Dec-13	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER 2 / DR.	1	MKD49-50-031ABB		\$ 974.30
2	FOAM, FROMT BUMPER / CNA	1	MKD53-50-111		\$ 94.30
3	FASTENER, FOAM / MLC	2	MFD01-68-AC3		\$ 11.80
4	FRONT REINFORCEMENT X NM	1	MKD53-50-070		\$ 584.80
5	CLIP, FRONT BUMPER / MLC	2	MBGV4-56-145		\$ 5.40
6	CLIP, FRONT BUMPER / MLC	6	MC274-50-133		\$ 21.00
7	PLATE SET CENTER X NM	1	MKD45-56-381		\$ 15.10
8	BRACKET TOP, GRILLE / BT	1	MKD45-50-716		\$ 58.20
9	RETAINER TOP, GRILLE / MLC	1	MKD45-50-0K1B		\$ 45.40
10	RIVET, GRILLE	5	MBN8F-50-355		\$ 27.00
11	RIVET, GRILLE / MLC	2	MS51S-51-833		\$ 7.60
12	MASCOT, FRONT / MLC	1	MKD45-51-741		\$ 68.00
13	GRILLE, RADIATOR KE /	1	MKD45-50-710G		\$ 647.40
14	COVER LHS, FRONT GRILLE X / NM	1	MKD45-50-164		\$ 21.60
15	COVER RHS, FRONT GRILLE X / NM	1	MKD45-50-154		\$ 21.60
16	PIN LOCATOR, FRONT GRILLE /	2	MKD45-50-1K5A		\$ 5.40
17	GROMMET, FRONT GRILLE / MLC	2	MKD45-50-ES1		\$ 5.40
18	FASTENER, FRONT GRILLE /	6	MGD7A-50-EA1		\$ 18.00
19	FRONT PANEL UPPER / BT	1	MKD53-53-150D		\$ 136.80
20	FRONT SUPPORT PANEL / BR	1	MKD51-53-110		\$ 516.40
21	PLATE SET, SUPPORT PANEL ?	1	MKD45-50-1C0		\$ 87.30
22	FASTENER, PLATE SET / MLC	3	MGD7A-50-EA1		\$ 9.00
23	STAY LOCK / BT	1	MKD53-52-15Y		\$ 38.80
24	CONDENSER ?	1	MKF03-61-480B		\$ 1,101.70
25	RING, A/C DISCHARGE HOSE ?	1	MBBM4-61-J17		\$ 10.10
26	RING, A/C SUCTION HOSE ?	1	MGJ6E-61-J19		\$ 6.70
27	RADIATOR ?	1	MPE01-15-200B		\$ 1,011.50
28	FAN COWLING ?	1	MPE01-15-210		\$ 347.60
29	RADIATOR SPARE TANK ?	1	MPE01-15-351A		\$ 65.80
30	LABEL, CAUTION / MLC	1	MKF49-61-439		\$ 3.30

31	LABEL, CAUTION / <i>mc</i>	1	MPE01-15-031		\$ 3.30
32	BONNET / <i>BT</i>	1	MKDY3-52-31XA		\$ 1,169.20
33	HINGE LHS, BONNET <i>X</i> <i>mc</i>	1	MKD53-52-420A		\$ 41.90
34	HINGE RHS, BONNET <i>X</i> <i>mc</i>	1	MKD53-52-410A		\$ 41.90
35	WEATHERSTRIP, BONNET / <i>mc</i>	1	MKD53-56-770		\$ 74.60
36	INSULATOR, BONNET / <i>re</i>	1	MKD62-56-681A		\$ 149.70
37	FASTENER, BONNET / <i>mc</i>	11	MTD11-56-694		\$ 27.50
38	LOCK, BONNET / <i>BT</i>	1	MKD77-56-620B		\$ 223.70
39	HEADLAMP LHS / <i>mc</i>	1	MKH24-51-041D		\$ 2,104.70
40	HEADLAMP RHS / <i>mc</i>	1	MKD78-51-031C		\$ 2,484.50
41	HID CONTROL UNIT <i>X</i> <i>mc</i>	2	MBHN3-51-0H3		\$ 1,791.00
42	GASKET, CONTROL UNIT <i>X</i> <i>mc</i>	2	MC236-51-0B2		\$ 27.20
43	CLIP, HEADLAMP / <i>mc</i>	4	MDR61-50-133		\$ 24.40
44	RIVET, HEADLAMP / <i>mc</i>	2	MB092-51-833		\$ 6.60
45	RADIATOR COOLANT ?	5			\$ 68.50
46	AIR DUCT ?	1	MPY2V-13-200B		\$ 126.90
47	AIR RESONATOR ?	1	MPE01-13-195A		\$ 88.40
48	CLIP, RESONATOR ?	2	ML33X-13-209		\$ 5.60
49	AIR CLEANER LOWER CASE ?	1	MPY1A-13-3AY		\$ 88.20
TOTAL PARTS					\$ 14,515.10
LESS 10%					\$ 1,451.51
TOTAL PARTS COST					\$ 13,063.59

Labour Description

1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1980	\$ 3,300.00
2	MZ-SP-SFRT04	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET.	1260	\$ 3,150.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	330	\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	330 ?	\$ 660.00
5		TO TRANSFER FRONT WASHER JET AND WASHER PIPE.	NN X	\$ 660.00
6	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	✓	NETT \$ 70.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	NN X	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00

10	MZ-BR-SUNDRI	SUNDRIES.	20	NETT	\$ 100.00
				TOTAL LABOUR	\$ - \$ 9,450.00
				TOTAL PARTS	\$ - \$ 13,063.59
				TOTAL	\$ - \$ 22,513.59
				LESS EXCESS	\$ - \$ -
				TOTAL AFTER EXCESS	\$ -
				GST 7%	\$ - \$ -
				GRAND TOTAL	\$ - \$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
 CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
 WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
 PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

6-7 Days.
 Refac paint photos.
 Gmo Qw ap - 82880282
 15/8/18.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: