

4 LCR 14197, Gwa3s2

PKK:

PAC:

ASSIGNMENT

Surveyor:

DOI:

Date/Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

EP 998C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Auto Bolt Services



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
6/18	EP 998C X;	Non-Reporting ltr (1st):	
	SLH 2994J - CS/SMO/8009902/Tind332; 00131/19	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	2018/11/19 email
2018/11/19	Email letter to OI	After call ltr to OI:	01/12/18
		Documentation Check List:	Handler Typist
	Report TP CCU	Notification ltr (if non-pickup)	☒
21/4/19	File pass to typist type report	After call ltr to OI:	☒
24/4/19	Email to ALG to seek mandati	Authorisation To Act:	☒
24/4/19	Mandate approve via merimen	Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By:			
FINALIZATION Date/Time: Confirm with:		Confirm by:	
Repair Cost:	SS (days) Reduction: %	Email ☐	Call ☐
FINAL SETTLEMENT Date/Time: 25/4/19 Confirm with Kai Ling		Email ☐	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. 1015	If NO or B 28, Ass. Lia:	
Repair Cost:	SS 13375.00		
Loss of Rental (LOR):	SS (days)		
Loss of Use (LOU):	SS 720.00 (\$120 x 6 days)		
Loss of Income (LOI):	SS (\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	SS 7.45		
Medical:	SS	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	SS (e.g. Tow/ Independent)	2) Report Format:	
Legal Cost	SS	3) Survey fee:	
Total:	SS 14102.45	Global Sum SS:	
FINAL PAYMENT Date/Time: Confirm with:		Email ☐	
Payee 1:	SS 14102.45	Name 1: Auto Bolt Services Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT 21/4/19

(08/11/13) wof

ASS. REC. BY:

REF:

A19

2980E

ASSIGNMENT

From: _____ Date: 07/08/18

Estimated Cost: _____

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: EP 998C

at Workshop m/s: Auto Bolt

of 8 keuki St Ave 4 # 03-55

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record) After 12pm

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$126K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EP 998C Yr Regn: 18 Mar 2013

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jaguar XJ 3.0 c.c. 2995

Colour: black A/C: Insured / Std / NI / NA

Sp. Reading: 132412 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SAJAC12A3D8V44881

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 ZR 19

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 07-08-18

Survey held at w/s 5pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s hit

The ☒ UIC Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/1/19 Confirm US \$12500 with 6 working days

(2nd = \$12691.60
50%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$))

☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL

Jaguar & Land Rover Specialists

Company Reg no: 201436686E

Email: autoboltsvc@Singnet.com.sg

VEHICLE NUMBER : EP 998 C

MAKE & MODEL : JAGUAR XJ-3.0 PREMIUM LUXURY LWB (A)

ITEM	DESCRIPTION	Qty	
1	FRONT BUMPER ASSY <i>Cut</i>	1	\$3,880.50
2	FRONT BUMPER FOAM <i>X NN</i>	1	\$452.40
3	FRONT BUMPER BRACKET RHF <i>/ De</i>	1	\$120.00
4	FRONT BUMPER PARKING AID SENSOR BRACKET <i>X Can</i>	4	\$248.00
5	FRONT BUMPER PARKING AID SENSOR RHF <i>X</i>	1	\$400.00
6	FRONT BUMPER CLIP <i>/ MC</i>	20	\$100.00
7	FRONT BUMPER PARKING AID HARNESS <i>X NN</i>	1	\$960.00
8	HEADLAMP RHF <i>X / Scr</i>	1	\$4,100.80
9	WHEELARCH RHF <i>/ Cut</i>	1	\$562.80
10	FENDER PANEL RHF <i>/ One</i>	1	\$2,195.50
11	FRONT BUMPER LOWER GRILLE CHROME RHF <i>X</i>	1	\$408.60
12	FRONT BUMPER LOWER GRILLE RHF <i>X</i>	1	\$321.60
13	FRONT SHOCK ABSORBER RH <i>X NN</i>	1	\$1,457.65
14	FRONT SHOCK ABSORBER RH MOUNTING <i>X</i>	1	\$225.90
15	FRONT SHOCK ABSORBER RH ISOLATOR <i>X</i>	1	\$253.15
16	FRONT RH UPPER WISHBONE <i>/</i>	1	\$880.60
17	FRONT RH FORWARD WISHBONE <i>/ MT</i>	1	\$880.60
18	FRONT RH LATERAL WISHBONE <i>/</i>	1	\$780.00
19	FRONT RH VERTICAL LINK <i>/</i>	1	\$1,362.70
20	FRONT RH HUB AND BEARING <i>/ MC</i>	1	\$916.30
21	FRONT RH WHEEL <i>(800 \$3N) / Cut</i>	1	\$2,173.00
22	FRONT RH TYRE <i>X NN</i>	1	\$500.00

Parts Sub Total 12221.34 \$23,170.10

Discount 5% 5% : 11610.27 \$1,158.50

Parts Total \$22,011.60

Labour LKK Auto Consultants hence notify

1	To R & R accident damage parts, to cut/weld, knock and realign accident affected area	1	\$1,200.00	1400
2	To putty and respray accident affected area	1	\$1,500.00	400
3	To rust proof accident affected area.	1	\$180.00	60
4	To check front parking aid and replace.	1	\$300.00	60

Acknowledged by Repairer

Signature:

Date:

13310.21
10% : 11950

13197.44
5% : 12837.56
+ 800 (400 500)
+ 900
14237.56
100/100 12500

Labour Total	\$5,130.00
Parts Total	\$22,011.60
TOTAL	\$27,141.60
GST 7%	\$1,899.91
Grand Total	\$25,241.69

25/9/60

Eno. Gary - 82880282

UKK

~~part by part~~ L/S 10%

before paint photos / After repair photos.

Alignment ~~report~~ report before and After.

07/8/18.

6 Days.

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

13717.25

3 X wish Bone - 560 /

Hub bearing - ~~180~~ 530

lateral - 450

Shock - 600+

Rim - 1900

Bumper - 2600 ~ 2800

Head lamp - 4500 ~ 5000

Tire - 2800.

Arch - 600 ~ 700

Customer:		Date:	7/8/2018 5:45 PM
Company:		VIN:	
License No:	EP998C	Technician:	HANN
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

JAGUAR/DAIMLER, XJ SERIES, 2010-2012, RHD Except India

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	6°25'	7°55'	---
		Right	---	5°53'	7°23'	---
	Camber	Left	-0°49'	-1°15'	0°15'	-0°49'
		Right	-0°36'	-0°51'	0°39'	-0°36'
	Toe	Left	0°19'	-0°01'	0°11'	0°18'
		Right	-1°06'	-0°01'	0°11'	-1°05'
Total		-0°47'	-0°02'	0°22'	-0°47'	
Rear	Camber	Left	-1°19'	-1°25'	0°05'	-1°19'
		Right	-1°08'	-1°25'	0°05'	-1°08'
	Toe	Left	0°10'	-0°01'	0°11'	0°10'
		Right	0°11'	-0°01'	0°11'	0°11'
		Total	0°21'	-0°02'	0°22'	0°21'
	Thrust Angle		0°01'	-0°08'	0°08'	0°01'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		---	---	---	---
	Right		---	---	---	---
Included Angle	Left		---	---	---	---
	Right		---	---	---	---
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Maximum Turns	Left		---	---	---	---
	Right		---	---	---	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		0.20"	---	---	0.20"
	Rear		-0.41"	---	---	-0.41"
Track Width Diff.			-0.22"			-0.22"
Wheel Base Diff.			0.61"			0.62"
Front Ride Height	Left		0.00"	15.31"	16.50"	0.00"
	Right		0.00"	15.31"	16.50"	0.00"
Rear Ride Height	Left		0.00"	15.24"	16.42"	0.00"
	Right		0.00"	15.24"	16.42"	0.00"
Frame Angle						---

SJ89333A

SKC29682

124

Your password will expire in 11 days. [Click here to change it.](#)

- Pre repair inspection request - EP998C VS SLH2994J (OI) DOA 31/07/2018

From: Mithoosingh, Aashweenjeetkaur

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Sent: 2/8/2018 3:26:22 PM

Attachments:  tmpF0E7.tif

Hi,

Please refer to the enclosed request from Auto Bolt Services Pte Ltd.

Claim no : 8922637423SG003

Case Owner : JOANE TIK-CHAP BOYOGAN

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Autobolt Services Pte Ltd [mailto:autoboltsvc@singnet.com.sg]

Sent: Thursday, August 02, 2018 3:13 PM

To: Mithoosingh, Aashweenjeetkaur

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLH2994J AND EP998C ON 31/07/2018

Hi Aashween,

I will go for your propose of LKK Auto Consultants Pte Ltd, surveyor (Marcus Chua).

Thanks & Best Regards

Alvin Ong

Auto Bolt Services Pte Ltd

8 Kaki Bukit Avenue 4 #03-55 Singapore 415875

Tel: 97766206 or Tel: 98511300

From: Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>

Sent: Thursday, 2 August, 2018 1:52 PM

To: autoboltsvc@singnet.com.sg

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>;

Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>;

Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLH2994J AND EP998C ON 31/07/2018

Without Prejudice

Your Reference : EP998C

Our Reference : 8922637423SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd

21/8/18 2018
4.22pm
Alvin @ 90687204
vehicle not in

Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

02-08-18:01:47PM; From:

To: 68357416

1 / 1

EP 998 C . Arrange 2 days for pre-inspection for direct settlement.

Dear Motor Claim Dept,

Please arrange pre-repair survey for EP 998 C.

Detail,

Our Client : EP 998 C

Your Insured : SLH 2994 J

DOA : 31 July 2018

Thanks & Regards
Auto Bolt Services Pte Ltd
8 Kaki Bukit Avenue 4 #03-55 Singapore 415875
Tel: 90687204 ALVIN ONG
Email: autoboltsvc@singnet.com.sg
Like us on our Facebook page @ Auto Bolt Services Pte Ltd

View Received Message

This mail is associated with :

***EP998C (8922637423SG)
[SLH2994J]**

TP
MITUL RATILAL PAKIKH
Jul 31 2018 12:00AM
[LCRF PTE LTD]
Auto Bolt Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/04/2019 16:23 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14275.00) - EP998C - Claim Handler: Cheok, Lee Wai

Approved:14275.00.

DOCUMENTS SUMMARY

There are no documents.

AUTO BOLT SERVICES PTE LTD
Jaguar & Land Rover Specialists
Company Reg no: 201436686E
Email: autoboltsvc@singnet.com.sg

Tel: 9068 7204

Fax: 6384 1067

Letter of Demand

Re : Accident involving my vehicle no. EP 998C and vehicle no.
SWH 2994J on 31/07/2018 at 15:05 HRS PM/AM along
JUNCTION OF JALAN SULTAN AND NORTH BRIDGE ROAD

We refer to the above matter.

Attach copies of the following for your kind perusal :

Vehicle Repair cost / Excess	\$ 12500/-
Vehicle Rental Fee for _____ days @	\$
\$ _____ per day	\$
Loss of use for <u>6</u> days @	\$ 900/-
\$ <u>150</u> per day	\$ 7.45
Police search fee/police report fee/LTA search fee	\$
Others	\$
Total :	\$ 13407.45

Your faithfully,

Alvin Ong
Hp : 9068 7204

Premier@Kaki Bukit
8 Kaki Bukit Avenue 4
#03-55 Singapore 415875
Email: autoboltsvc@singnet.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018 Edit Reg		02 Aug 2018 00:00 Edit Adj Rpt	S\$12,500.00 Edit Estimates	S\$12,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	MITUL RATILAL PAKIKH, ID: S1712980E		
Vehicle Reg. No.:	EP998C	Date of Loss:	31/07/2018 00:00 - :59 [64 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8922637423SG	Policy/Cover Note No.:	0999994765 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH2994J	Policy No. (Claimant):	2100333976-05
		Excess:	
Repairer:	Auto Bolt Pte Ltd (HQ) Bk 8, KAKI BUKIT AVENUE 4, PREMIER @ KAKI BUKIT,, #08-18, 415875 Kaki Bukit - Tel: 90687204		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Cheok, Lee Wai] Cheok.Leewai@aig.com		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (24/04/2019): Alert - Adj Mandate Approved (S\$14275.00) - EP998C - Claim Handler: Cheok, Lee W...
- AIG_SG (15/08/2018): Re: Request for OI GIA report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***EP998C (8922637423SG)**
[SLH2994J]
TP
MITUL RATILAL PAKIKH
Jul 31 2018 12:00AM
[LCRF PTE LTD]
Auto Bolt Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	18/02/19 11:32	Video - Accident												1	Load MP4					
Letters/Correspondences															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit					
Assessment Reports															1 per page		☒			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	15/08/18 09:18	Accident Statement From:SC – Reg. No: SLH2994J, Claimant: LCRF PTE LTD												1	Load HTM					
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	02/04/19 09:52	General View												1	Load JPG	☒				
2	02/04/19 09:52	General View												1	Load JPG	☒				
3	02/04/19 09:52	General View												1	Load JPG	☒				
4	02/04/19 09:52	General View												1	Load JPG	☒				
5	02/04/19 09:52	General View												1	Load JPG	☒				
6	02/04/19 09:52	General View												1	Load JPG	☒				
7	02/04/19 09:52	General View												1	Load JPG	☒				
8	02/04/19 09:52	General View												1	Load JPG	☒				
9	02/04/19 09:52	General View												1	Load JPG	☒				
10	02/04/19 09:52	General View												1	Load JPG	☒				
11	02/04/19 09:52	General View												1	Load JPG	☒				
12	02/04/19 09:52	General View												1	Load JPG	☒				
13	02/04/19 09:52	General View												1	Load JPG	☒				
14	02/04/19 09:52	General View												1	Load JPG	☒				
15	02/04/19 09:52	General View												1	Load JPG	☒				
16	02/04/19 09:52	General View												1	Load JPG	☒				
17	02/04/19 09:52	General View												1	Load JPG	☒				
18	02/04/19 09:52	General View												1	Load JPG	☒				
19	02/04/19 09:52	General View												1	Load JPG	☒				
20	02/04/19 09:52	General View												1	Load JPG	☒				
21	02/04/19 09:52	General View												1	Load JPG	☒				
22	02/04/19 09:52	General View												1	Load JPG	☒				
23	02/04/19 09:52	General View												1	Load JPG	☒				
24	02/04/19 09:52	General View												1	Load JPG	☒				
25	02/04/19 09:52	General View												1	Load JPG	☒				

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
26	02/04/19 09:52	General View	 Load JPG	☒
27	02/04/19 09:52	Chassis Number	 Load JPG	☒
28	02/04/19 09:52	Odometer Reading	 Load JPG	☒
29	02/04/19 09:53	Photo After Spray	 Load JPG	☒
30	02/04/19 09:53	Photo After Spray	 Load JPG	☒
31	02/04/19 09:53	Photo After Spray	 Load JPG	☒
32	02/04/19 09:53	Photo After Spray	 Load JPG	☒
33	02/04/19 09:53	Photo After Spray	 Load JPG	☒
34	02/04/19 09:53	Photo After Spray	 Load JPG	☒
35	02/04/19 09:53	Photo After Spray	 Load JPG	☒
36	02/04/19 09:53	Photo After Spray	 Load JPG	☒
37	02/04/19 09:53	Photo After Spray	 Load JPG	☒
38	02/04/19 09:53	Photo After Spray	 Load JPG	☒
39	02/04/19 09:53	Photo After Spray	 Load JPG	☒
40	02/04/19 09:53	Photo After Spray	 Load JPG	☒
41	02/04/19 09:53	Photo After Spray	 Load JPG	☒
42	02/04/19 09:53	Photo After Spray	 Load JPG	☒
43	02/04/19 09:53	Photo After Spray	 Load JPG	☒
44	02/04/19 09:53	Photo After Spray	 Load JPG	☒
45	02/04/19 09:53	Photo After Spray	 Load JPG	☒
46	02/04/19 09:53	Photo After Spray	 Load JPG	☒
47	02/04/19 09:53	Photo After Spray	 Load JPG	☒
48	02/04/19 09:53	Photo After Spray	 Load JPG	☒
49	02/04/19 09:53	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/18 21:28	ACKNOWLEDGEMENT EMAIL TO AIG DD 02.08.2018	 Load PDF	
2	05/08/18 21:28	EMAIL FROM AIG DD 02.08.2018	 Load PDF	
3	05/08/18 21:28	NOTIFICATION FROM WORKSHOP	 Load TIF	
4	10/08/18 01:04	TP ESTIMATE - MARKED	 Load PDF	
5	10/08/18 01:04	TP GIA REPORT	 Load PDF	
6	10/08/18 01:04	ALIGNMENT REPORT	 Load PDF	
7	20/08/18 15:51	Email letter to OI Accident involving Vehicle SLH 2994J & EP 998C on 31.07.2018	 Load PDF	
8	24/04/19 15:23	LETTER TO OI	 Load PDF	
9	24/04/19 15:55	Email to AIG to seek mandate.	 Load PDF	
10	02/05/19 11:55	AUTHORISATION TO ACT	 Load PDF	
11	02/05/19 11:55	LTA SEARCH	 Load PDF	
12	02/05/19 11:55	RELEASE VOUCHER	 Load PDF	
13	02/05/19 11:55	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH2994J (Insd veh)	Model:	JAGUAR XJ 3.0 (A)
	EP998C (TP veh)		
Date of Accident:	31/07/2018		

Global Sum Settlement	: [] Yes	: [X] No
Repair Estimate	: \$	26,955.01
Final Repair Cost	: \$	13,375.00
Loss of Use	: \$	720.00
Rental (if any)	: \$	6.00 days at \$120.00 per day
LTA / GIA Search Fee	: \$	7.45
Others:	: \$	
	: \$	
Final Settlement Sum	: \$	14,102.45
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)		
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks _____		

Payment Instruction: Payee's Breakdown			
1)	Auto Bolt Services Pte Ltd	: \$	14,102.45
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

02 May
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18014197/GWA3S2
Date: 02/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994765
Claimant Vehicle No: EP998C Insured Vehicle No: SLH2994J
Date of Loss: 31/07/2018 Nature of Claim: TP Claim No: 8922637423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EP998C
Make & Model: JAGUAR XJ, 3.0 (A) Engine No: 12111411350306PS
Reg. Date: 18/03/2013 (Man. Year: 2012) Chassis No: SAJAC12A3D8V44881
Colour: Black Odometer: 132412 km
Engine Capacity: 2995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45ZR19 Rear Tyre Size: 245/45ZR19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,011.60	13,037.57	8,974.03	40.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	900.00	2,280.00	71.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,191.60	13,937.57	11,254.03	44.67
Approved Total (Overridden) (S\$)		12,500.00		
(S\$)	25,191.60	12,500.00	12,691.60	50.38
+ GST 7.00/7.00% (S\$)	1,763.41	875.00	888.41	50.38
Nett Amount (S\$)	26,955.01	13,375.00	13,580.01	50.38
+ Loss of Use (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		14,102.45		

INSPECTION

Date of Assignment: 02/08/2018
Date Inspected: 07/08/2018 Inspected At: Auto Bolt Pte Ltd (HQ)
Blk 8, KAKI BUKIT AVENUE 4, PREMIER @ KAKI
BUKIT., #08-18
Singapore 415875
Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Cut	3,860.50 FL	*3,010.90 FL
2	1		*FRONT BUMPER FOAM	Not Necessary	452.40 FL	*- FL
3	1		*FRONT BUMPER BRACKET RHF	Deformed	120.00 FL	*51.04 FL
4	4		*FRONT BUMPER PARKING AND SENSOR BRACKET	Not Necessary	248.00 FL	*- FL
5	1		*FRONT BUMPER PARKING AND SENSOR RHF	Not Necessary	400.00 FL	*- FL
6	20		*FRONT BUMPER CLIP	Necessary	100.00 FL	*52.00 FL
7	1		*FRONT BUMPER PARKING AND SENSOR HARNESS	Not Necessary	960.00 FL	*- FL
8	1		*HEADLAMP RHF	Scratched	4,100.80 FL	*4,100.80 FL
9	1		*WHEELARCH RHF	Cut	562.80 FL	*562.80 FL
10	1		*FENDER PANEL RHF	Buckled	2,195.50 FL	*2,195.50 FL
11	1		*FRONT BUMPER LOWER GRILLE CHROME RHF	Not Necessary	408.60 FL	*- FL
12	1		*FRONT BUMPER LOWER GRILLE RHF	Not Necessary	321.60 FL	*- FL
13	1		*FRONT SHOCK ABSORBER RH	Not Necessary	1,467.65 FL	*- FL
14	1		*FRONT SHOCK ABSORBER RH MOUNTING	Not Necessary	225.90 FL	*- FL
15	1		*FRONT SHOCK ABSORBER RH ISOLATOR	Not Necessary	253.15 FL	*- FL
16	1		*FRONT RH UPPER WISHBONE	Bent	880.60 FL	*560.00 FL
17	1		*FRONT RH FORWARD WISHBONE	Bent	880.60 FL	*560.00 FL
18	1		*FRONT RH LATERAL WISHBONE	Bent	780.00 FL	*560.00 FL
19	1		*FRONT RH VERTICAL LINK	Bent	1,362.70 FL	*1,014.40 FL
20	1		*FRONT RH HUB AND BEARING	Necessary	916.30 FL	*530.00 FL
21	1		*FRONT RH TYRE	Not Necessary	500.00 FL	*- FL
22	1		*FRONT RH WHEEL	Cut	2,064.36 FS	*500.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	23,061.46	13,697.44
- List Item Discount on L Items 5.00/5.00% (\$\$)	1,049.86	659.87
Total Parts (\$\$)	22,011.60	13,037.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R ACCIDENT DAMAGE PARTS, TO CUT / WELD, KNOCK AND REALIGN ACCIDENT AFFECTED AREA.	New	1,200.00	400.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	1,500.00	400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	180.00	60.00
4	TO CHECK FRONT PARKING AID AND REPLACE.	New	300.00	40.00
Gross Labour Cost (\$\$)			3,180.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >