

Jaguar & Land Rover Specialists
Company Reg no: 201436686E
Email: autoboltsvc@Singnet.com.sg

VEHICLE NUMBER : EP 998 C

MAKE & MODEL : JAGUAR XJ-3.0 PREMIUM LUXURY LWB (A)

ITEM	DESCRIPTION	Qty	
1	FRONT BUMPER ASSY - <i>cut</i>	1	\$3,860.50
2	FRONT BUMPER FOAM	1	\$452.40
3	FRONT BUMPER BRACKET RHF	1	\$120.00
4	FRONT BUMPER PARKING AID SENSOR BRACKET	4	\$248.00
5	FRONT BUMPER PARKING AID SENSOR RHF	1	\$400.00
6	FRONT BUMPER CLIP - <i>MC</i>	20	\$100.00
7	FRONT BUMPER PARKING AID HARNESS	1	\$960.00
8	HEADLAMP RHF ?	1	\$4,100.80
9	WHEELARCH RHF	1	\$562.80
10	FENDER PANEL RHF - <i>Buc</i>	1	\$2,195.50
11	FRONT BUMPER LOWER GRILLE CHROME RHF	1	\$408.60
12	FRONT BUMPER LOWER GRILLE RHF	1	\$321.60
13	FRONT SHOCK ABSORBER RH	1	\$1,467.65
14	FRONT SHOCK ABSORBER RH MOUNTING	1	\$225.90
15	FRONT SHOCK ABSORBER RH ISOLATOR	1	\$253.15
16	FRONT RH UPPER WISHBONE	1	\$880.60
17	FRONT RH FORWARD WISHBONE	1	\$880.60
18	FRONT RH LATERAL WISHBONE	1	\$780.00
19	FRONT RH VERTICAL LINK	1	\$1,362.70
20	FRONT RH HUB AND BEARING - <i>MC</i>	1	\$916.30
21	FRONT RH WHEEL 130 (SN)	1	\$2,173.00
22	FRONT RH TYRE	1	\$500.00
Parts Sub Total			\$23,170.10
Discount 5%			\$1,158.50
Parts Total			\$22,011.60
Labour			
1	To R & R accident damage parts, to cut/weld, knock and realign accident affected area	1	\$1,200.00
2	To putty and respray accident affected area.	1	\$1,500.00
3	To rust proof accident affected area.	1	\$180.00
4	To check front parking aid and replace.	1	\$300.00

400

400

60

400

	Labour Total	\$5,130.00
	Parts Total	\$22,011.60
	TOTAL	\$27,141.60
	GST 7%	\$1,899.91
	Grand Total	\$25,241.59

Emu Quay - 82880282

UKK

part by part.

before paint photos. / After repair photos.

Alignment ~~report~~ report before and After.

07/8/18.

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: