

DOA: 02.08.18

**MODEL : TOYOTA PRIUS**

QTY	PARTS DESCRIPTION	TYPE	UNIT PRICE	AMOUNT
	REAR BUMPER			\$ <del>new</del> 458.60
	REAR BUMPER SIDE RETAINER			\$ <del>new</del> 112.70
	REAR BUMPER CLIPS			\$ <del>new</del> 22.00
	RETAINER, REAR BUMPER, SIDE, LH			\$ <del>new</del> ? 94.80
	SEAL, REAR BUMPER SIDE, LH			\$ X 88.90
	TAIL LAMP ASSY (UPPER)		old damage	\$ X 557.90
	TAIL LAMP ASSY (LOWER)			\$ X 548.40
	SUB TOTAL			\$ 1,883.30
	LESS 20%			\$ 376.66
	DISCOUNTED TOTAL			\$ 1,506.64
	Tanjiluh 97495749 - WP' 2/8/18 @ 415 pm 02 days. Resurvey before paint sur@lkkauto.com			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			\$ 200 350.00
	Date:			\$ 200 250.00
	Labour Charge			\$ ✓ 30.00
	Spray Painting Charge			\$ 30 120.00
	Wiring Charge			
	Remove/Refix Reverse Sensor			
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,256.64

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.