

u

**ETHOZ AUTOMOTIVE
SOLUTIONS LTD
22 TAMPINES STREET 92
SINGAPORE
528876**

Claim Reference:
Assessment Number: BK000027
Version: ETHOZASL/2
Date Calculated: 06/08/2018 05:39

Full Report - V1
Registration: GBF5534M
Printed: 14/08/2018 14:47

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ng Boon Kai	Date of Incident:	24/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	NV200
Sub Model:	BASE MODEL
Model Sheet Number:	Z89 01
Registration:	GBF5534M
Registration Month:	
Registration Year:	
VIN Number:	VSKYBAM20Z0139064
Odometer:	Not Known
Colour:	
Engine Number:	K9KC400D056301
Fuel Level:	%

Model Specs

AIR CONDITIONING	REAR SCREEN
FOG LAMPS	REAR WIPER
STANDARD EQUIPMENT	TYRES 175/70 HR 14
WHEELS 5.5J X 14	FULL WHEEL COVERS
PRODUCTION JAPAN	EMISSION STD EURO 5
TRANSPORTER	L/SLDG DOOR W/O GLAS
R/SLDG DOOR W/O GLAS	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Severity of Impact:
Vehicle Status on
Inspection:

Date of Inspection: 01/08/2018

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Claim Reference:
Assessment Number: BK000027
Version: ETHOZASL/2
Date Calculated: 06/08/2018 05:39

Full Report - V1
Registration: GBF5534M
Printed: 14/08/2018 14:47



Addresses

Cost Summary

Total Labour	\$315.00
Total of Additional Costs	\$10.00
Excess:	TBA
Grand Total Exc GST:	\$325.00
7 % GST:	\$22.75
Grand Total Inc GST:	\$347.75

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
2581	REPAIR REAR BUMPER	20.0*	90.00
1000	REPAIR TAILGATE LH	30.0*	135.00
LABOUR COST			
	Total Work Units	50.0	0.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	\$225.00
	Sub Total	5.0HRS	\$90.00
	Paint Labour	2.0HRS	\$315.00
	Total Labour	7.0HRS	

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$45.00/HR
WU Cost Price (\$)

1000	- TWO COAT METALLIC - PREPARE OFF VEHICLE TAILGATE LH REPAIR PAINTING <50%	20.0*	
LABOUR COST - PAINT			
	TIME(PAINT)	20.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	20.0	\$90.00
	Total Paintwork Labour	2.0HRS	Cost Price
MATERIAL COST - PAINT			
	Total Excluding Pearlescent Uplift		\$0.00
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$0.00

PARTS

Guide No. Qty Description
f: OEM Parts
g: Original

Part Number	Supplier	Bet.	Price (\$)
Sub Total			\$0.00
Mark Up From Cost	(15 %)		\$0.00

Price Valid: 01/06/2015

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Full Report - V1

Claim Reference:

Assessment Number: BK000027

Version: ETHOZASL/2

Date Calculated: 06/08/2018 05:39

Registration: GBF5534M
Printed: 14/08/2018 14:47

Total Parts

\$0.00

h: Secondhand

p: Parallel

x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description
LTA STICKER

SPECIALIST

Betterment
0%
Total Extras

Price
\$10.00
\$10.00

Final Calculation

\$0.00

Total Parts

Labour

Total Panel/Mechanical
Total Paintwork

\$225.00
\$90.00

\$315.00

Total Labour

Additional Costs

Corr Prot Materials External
Corr Prot Materials Internal
Cost of Specialist

\$0.00
\$0.00
\$10.00

\$10.00

Total of Additional Costs

\$0.00

Total Paint/Material Costs

\$325.00

Grand Total Excludes GST

\$22.75

GST @ 7 %

\$347.75

Grand Total Includes GST

Assessment Notes

S/A = \$10.00

L = \$315.00

OR = \$325.00

Repair days: 0).

confund.