

22/03/2002

ASS. REC. BY:

REF:

CS3/ALG18014224/G240362

Special Instruction:

Survivor:
Mimen

GUO Ding

ASSIGNMENT (Office)

From (Person):

Kesaral, Juelyn

of

ALG

Date/Time:

6/8/18 @ 10:00am

Estimated Cost:

Bill to:

OD-TP WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SLR 9377S

Insured:

SLT 9635L

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

Bike 2, Keiki 81st Ave # 01-1718

Policy No:

1700085455

Claim No:

08 98909301SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/07/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

10:33am @ 6/8/18

Person Contacted:

Melody

Vehicle: IN/OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|---------------------------------|
| | SLT 9377S - X |
| | SLT 9635L - X |
| | |
| 7/8/18 | Disassembled |
| 10/8/18 | After Repair |

PART Repair day?

PR 5
XAL

REF:

ALG.

C7909C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

N-51

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

2R9377S

Yr Regn:

31 Aug 2017

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1797

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

73847

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZVW400025958

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HABILEAD

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

06-08-18

Survey held at

w/s

4pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 SEP 2018.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

DAR.

Lump Sum / I.B.I: (\$

180

20

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18014236/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 06-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|--------------|---------------|----------------|------------|
| Insured Veh. | SDN 8292A | Veh. Inspected | GBF 645J |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | CHIN LEE YING | Assign Date | 06/08/2018 |

2. Vehicle Particulars & Condition

| | | |
|--------------|--------|--------------|
| Make & Model | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. |
| Chassis No. | | Colour |
| Odometer | - | Steering |
| Brakes | | Modification |
| General | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|------------|-----------------|------------|
| Accident Date | 01/08/2018 | Inspection Date | 06/08/2018 |
| Survey held at | - | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 01 Aug 2018 | | 06 Aug 2018 10:10 Assign | | | | New Assignment Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | Ian Michael Smith, ID: G1159301T, Tel: +6582992852 | | |
| Main Claimant: | DARWIN-51 CAR RENTAL PTE LTD, Co. Reg. No.: 201407909C | | |
| Vehicle Reg. No.: | SLR9377S | Date of Loss: | 30/07/2018 00:00 - :59 [10 Months and 30 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 0898909301SG | Policy/Cover Note No.: | 1700085955 (Comprehensive) Coverage: 17/11/2017 - 16/11/2018 |
| Vehicle Reg. No. (Insured): | SLT9635L | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051 | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn- | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/08/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Your password will expire in 7 days. [Click here to change it.](#)




- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 6/8/2018 10:12:23 AM

Attachments:  [01082018103939-0001.pdf](#)  [01082018111617.pdf](#)
 [01082018115409.pdf](#)

Hi LKK,

Case assigned to LKK in Merimen, please assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: SLR 9377 S
Your ref: SLT 9635 L

01 August 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL Aashweenjeetkaur.Mithoosingh@aig.com ONLY

NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : DARWIN-51 CAR RENTAL PTE LTD
VEHICLE NUMBER : SLR 9377 S
YOUR INSURED VEHICLE NUMBER : SLT 9635 L
ACCIDENT ON 30 July 2018 ALONG DUNEARN ROAD
AT ABOUT 16:40 HOURS

We refer to your email/fax dated **01 Aug 2018** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....
N-51 AUTOMOTIVE PTE LTD

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| Vehicle Owner Particulars | |
|--------------------------------|---------------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 7909C |
| Vehicle Details | |
| Vehicle No.: | SLR9377S |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 07 Aug 2018 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | PRIUS ALPHA 1.8S CVT |
| Primary Colour: | Black |
| Manufacturing Year: | 2017 |
| Engine No.: | 2ZR1983123 |
| Chassis No.: | ZVW400025958 |
| Maximum Power Output: | 100.0 kW (134 bhp) |
| Open Market Value: | \$29,656.00 |
| Original Registration Date: | 31 Aug 2017 |
| First Registration Date: | 31 Aug 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$18,519.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 30 Aug 2027 |
| PARF Rebate Amount: | \$13,889.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 30 Aug 2027 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$54,406.00 |
| COE Rebate Amount: | \$49,301.00 |
| Total Rebate Amount: | \$63,190.00 |

The information contained herein is correct as at 07 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 31/07/2018 16:52 |
| Date Of Accident | 30/07/2018 16:40 |
| Exact Location Of Accident | DUNEARN ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------------|
| Vehicle Registration Number | SLR9377S |
| Insured/Policyholder | |
| Name Of Registered Owner | DARWIN-51 CAR RENTAL PTE LTD |
| Co Reg No | 201407909C |
| Email Address | SALES@N51.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-68425151 |

Vehicle Particulars

| | |
|--|----------------------------------|
| Manufacturer | TOYOTA |
| Model | PRIUS ALPHA HYBRID-1.8 S CVT (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|---------------------------|
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | SD18V07071/VPZ/R01 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | CHOONG SITT KIONG |
| NRIC No | S1169003C |
| Date Of Birth | 19/11/1956 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 11/05/1979 |
| Driving Experience | 39 YEARS AND 2 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-93693326 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|---------------------------------|
| Address | BLK 649 PUNGGOL CENTRAL #12-392 |
| Postcode | 820649 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|----------------------------|
| Type Of Accident | COLLISION - MAJOR/MINOR RD |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SLT9635L |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

| | |
|-----------------|-------------------|
| Name | CHOONG SITT KIONG |
| Approximate Age | |

Injuries Sustain

Injured person in which vehicle?

SLR9377S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

BLK 649 PUNGGOL CENTRAL #12-392

Postcode

820649

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

VEHICLE A - SLR 9377S
VEHICLE B - SLT 9635L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG DUNBAR ROAD TOWARDS CITY DIRECTION.
I WAS ON THE FIRST LANE.

WHILE DRIVING STRAIGHT AHEAD, AT THE FRONT OF
TUAN SENH HOLDINGS BUILDING, WHILE GOING STRAIGHT, SUDDENLY
A VEHICLE TURNED OUT FROM THE RIGHT SIDE OF MY
VEHICLE, AND HIT ONTO THE REAR RIGHT OF MY VEHICLE.

ALIGHTED FROM MY VEHICLE AND REALIZED IT WAS A
VEHICLE WITH LICENCE PLATE NUMBER SLT 9635L THAT,
DIDN'T STOPPED AT THE STOP LINE AT THE TURNING POINT
(U TURN FROM BUKIT TIMAH ROAD) AND HIT ONTO MY
VEHICLE.

VEHICLE A - SLR 9377S
VEHICLE B - SLT 9635L

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

(13)Torn (14)Unconfirmed (15)Not Working

Aug 2005

No of Items: _____ Assessor: _____

(01)Best (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

Aug 2005
25/2

Vehicle No: SLR 9377 S

| NAC | INC | Item | CON | AC | Qty |
|------|--------|---------------------------------|-----|----|-----|
| 1372 | 995163 | Frt LH Shock Absorber | | | |
| 1373 | 991944 | Frt LH Shock Absorber Mounting | | | |
| 1374 | 990632 | Frt LH Coil Spring | | | |
| 1375 | 995198 | Frt LH Knuckle Arm | | | |
| 1376 | 995199 | Frt LH Knuckle Arm Bearing | | | |
| 1377 | 995178 | Frt LH Lower Arm | | | |
| 1378 | 995169 | Frt LH Upper Arm | | | |
| 1379 | 995183 | Frt LH Tie Rod | | | |
| 1380 | 995143 | Frt LH Drive Shaft | | | |
| 1381 | 990661 | Frt LH Control Arm | | | |
| 1382 | 992062 | Frt LH Trailing Arm | | | |
| 1383 | 991848 | Frt LH Leaf Spring | | | |
| 1384 | 991293 | Frt LH Brake Disc Rotor | | | |
| 1385 | 991281 | Frt LH Brake Caliper | | | |
| 1386 | 991292 | Frt LH Brake Pipe | | | |
| 1387 | 991287 | Frt LH Brake Hose | | | |
| 1388 | 991295 | Frt LH Brake Sensor Wire | | | |
| 1389 | 991989 | Frt Stay Bar Bracket | | | |
| 1390 | 994455 | Steering Rack & Pinion | | | |
| 1391 | 994435 | Steering Cross Member | | | |
| 1392 | 994519 | Frt Sub Frame | | | |
| 1393 | 992003 | Frt Sub Frame Mounting | | | |
| 1394 | 991217 | Frt Anti Roll Bar | | | |
| 1395 | 991219 | Frt Anti Roll Bar Linkage | | | |
| 1396 | 990887 | Engine Block | | | |
| 1397 | 990890 | Engine Block Gasket | | | |
| 1398 | 990972 | Engine Oil Sump | | | |
| 1399 | 990960 | Engine Oil | | | |
| 1400 | 992224 | Gear Box Assy | | | |
| 1401 | 992229 | Gear Box Gasket | | | |
| 1402 | 992241 | Gear Box Oil Sump | | | |
| 1403 | 992257 | Gear Oil | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1404 | 991134 | Floor Panel | | | |
| 1405 | 993719 | Rear LH Shock Absorber | | | |
| 1406 | 993723 | Rear LH Shock Absorber Mounting | | | |
| 1407 | 993170 | Rear LH Coil Spring | | | |
| 1408 | 993550 | Rear LH Knuckle Arm | | | |
| 1409 | 993551 | Rear LH Knuckle Arm Bearing | | | |
| 1410 | 993597 | Rear LH Lower Arm | | | |
| 1411 | 993884 | Rear LH Upper Arm | | | |
| 1412 | 995161 | Rear LH Drive Shaft | | | |
| 1413 | 995216 | Rear LH Control Arm | | | |
| 1414 | 993881 | Rear LH Trailing Arm | | | |
| 1415 | 993573 | Rear LH Leaf Spring | | | |
| 1416 | 992941 | Rear LH Brake Disc Rotor | | | |
| 1417 | 992937 | Rear LH Brake Caliper Assy | | | |
| 1418 | 990434 | Rear LH Brake Pipe | | | |
| 1419 | 992946 | Rear LH Brake Hose | | | |
| 1420 | 993819 | Rear Sub Frame | | | |
| 1421 | 993820 | Rear Sub Frame Mounting | | | |
| 1422 | 992813 | Rear Anti Roll Bar | | | |
| 1423 | 990168 | Rear Anti Roll Bar Linkage | | | |
| 1424 | 990202 | Axle Beam | | | |
| 1425 | 990170 | Rear Axle Panhard Rod | | | |
| 1426 | 990810 | Differential Assy | | | |
| 1427 | 992706 | Propeller Shaft | | | |

[illegible]

No of Items: _____ Assessor: _____

Original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI






































CLAIM SUBFOLDER TRACKING



























| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|--|--|------------|---|
| Main | 01 Aug 2018 | | 06 Aug 2018 10:10 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|-----------|--|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: Ian Michael Smith , ID: G1159301T, Tel: +6582992852 | | | | | | | | | |
| Main Claimant: DARWIN-51 CAR RENTAL PTE LTD , Co. Reg. No.: 201407909C | | | | | | | | | |
| Vehicle Reg. No.: SLR9377S | | Date of Loss: 30/07/2018 16:00 - :59 [10 Months and 30 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP / 0898909301SG | | Policy/Cover Note No.: 1700085955 (Comprehensive) Coverage: 17/11/2017 - 16/11/2018 | | | | | | | |
| Vehicle Reg. No. (Insured): SLT9635L | | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051 | | | | | | | | | |
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/08/2018] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLR9377S (0898909301SG)
[SLT9635L]
TP
DARWIN-51 CAR RENTAL PTE LTD
Jul 30 2018 4:00PM
[Ian Michael Smith]
N-51 Automotive Pte Ltd

| Upload Documents | | Upload Photos | Compose New Letter | Upload Video | Upload Audio | View <input type="button" value="View in Browser"/> | |
|----------------------|-----------------|-----------------------------------|--------------------|--------------|--------------|--|-------------------------------------|
| Photos/Images | | | | | | 3 per page <input type="button" value="v"/> | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | Thumbnail | Print |
| 1 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 07/08/18 13:47 | General View | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 14/08/18 12:10 | Dismantled Parts | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 14/08/18 12:10 | Dismantled Parts | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 14/08/18 12:10 | Dismantled Parts | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 14/08/18 12:10 | Dismantled Parts | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 14/08/18 12:10 | Dismantled Parts | | | |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 14/08/18 12:10 | Dismantled Parts | | | |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 14/08/18 12:10 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 14/08/18 12:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| | | | |
|--|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

| |
|--|
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18014224/GZ4D3E2

Date: 21/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1700085955

Claimant Vehicle No : SLR9377S

Insured Vehicle No : SLT9635L

Date of Loss: 30/07/2018

Nature of Claim: TP

Claim No: 0898909301SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR9377S

Make & Model: TOYOTA PRIUS ALPHA, 1.8 (A)

Engine No: 2ZR1983123

Reg. Date: 31/08/2017 (Man. Year: 2017)

Chassis No: ZVW400025958

Colour: Black

Odometer: 73847 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Habilead 6 mm

Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 06/08/2018

Date Inspected: 06/08/2018 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|--------------------------------|--------------------------|-------------|-------------|
| 1 | 1 | | *ROCKER PANEL GARNISH RH | Cracked | 0.00 F | *- F |
| 2 | 1 | | *REAR RH DOOR | Buckled | 0.00 F | *- F |
| 3 | 1 | | *REAR RH DOOR RUBBER | Dented | 0.00 F | *- F |
| 4 | 1 | | *REAR RH DOOR LOCK | Bent | 0.00 F | *- F |
| 5 | 1 | | *REAR RH DOOR INNER TRIM BOARD | Cracked | 0.00 F | *- F |
| 6 | 1 | | *REAR BUMPER | Dented | 0.00 F | *- F |
| 7 | 1 | | *REAR BUMPER SIDE RETAINER | Distorted | 0.00 F | *- F |
| 8 | 1 | | *REAR BUMPER REFLECTOR RH | Cracked | 0.00 F | *- F |
| 9 | 1 | | *REAR RH FENDER | Buckled | 0.00 F | *- F |
| 10 | 1 | | *REAR RH FENDER INNER SHIELD | Bent | 0.00 F | *- F |
| 11 | 1 | | *REAR RH WHEEL RIM | Cut | 0.00 F | *- F |
| 12 | 1 | | *REAR RH KNUCKLE ARM | Distorted | 0.00 F | *- F |
| 13 | 1 | | *REAR RH KNUCKLE ARM BEARING | Necessary | 0.00 F | *- F |
| 14 | 1 | | *REAR RH LOWER ARM | Bent | 0.00 F | *- F |
| F=Franchise part. | | | | | | |
| | | | | Total Parts (S\$) | 0.00 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >