

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: EFA/China0509 Date: 20th August 2018

Our Ref: CS1/LAW18013026/Bsbs2

M/s UNITED LEGAL ALLIANCE LLC

20 Maxwell Road #13-00 Maxwell House Singapore 069113

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGS 1075U INSURED VEHICLE: GBD 3110B ACCIDENT DATE: 15/06/2016

We thank you for your instruction on 02/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGS 1075U from M/s KTO Automobile Assessors.
- b) Survey report by AutoProbe Consultants with colour photographs.
- c) Final Repair Bill of SGS 1075U from M/s Automotive Road Solutions Pte Ltd.
- d) Singapore Accident Statement of Vehicles SGS 1075U and GBD 3110B.
- e) Colour damaged vehicle photographs of SGS 1075U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SGS 1075U

Make & Model : Mitsubishi Lancer 1.6 A

Year of Registration : 2007

Chassis Number : JMYSTCS3A7U004843

Engine Capacity : 1584 cc

- We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.