



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 06.08.2018

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claim Dept

ESTIMATE COST OF REPAIR TO VEHICLE SGN3973R TOYOTA WISH (YEAR 2006)

To Supply

1)	1pc	Rear bumper	\$	545.00	de
2)	1set	Rear bumper clip	\$	30.00	de
3)	1pc	Rear bumper right retainer	\$	87.57	x
4)	1pc	Rear end panel	\$	509.00	de
5)	1pc	Rear end panel top garnish	\$	268.66	de
6)	1set	Rear end panel top garnish clip	\$	40.00	de

Sub total L/charges	\$	1,480.23
Less: 25% discount	\$	370.05
	\$	1,110.18

To supply S.Nett Parts

1)	1set	Reverse sensor	\$	250.00	200
Sub total S.Nett Parts			\$	250.00	

L/charges

1)	To tuff kote	\$	50.00	20
2)	To remove & fit reverse sensor	\$	50.00	30
3)	To remove rear bumper, knock rear end panel & tail gate lower part, replace rear bumper & etc.	\$	650.00	500

- 4) To putty, respray painting rear bumper, rear end panel & tail gate. \$ ⁶⁰⁰ 800.00
To polish

Sub total L/charges	\$	1,550.00
Estimated Grand total	\$	2,910.18

Taufik 97495749
- WP

6/8/18 320 pm

4 ~~days~~ days

Resurvey after repair

sur@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: