

ASS. REC. BY:

REF: CS/ICS18014270/ Utd3/02

Special Instruction:

Survivor:
merimen

Merimen

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ECICS

Date/Time: 6/8/18 @ 2:05pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIZ 5260C

Insured:

at Workshop m/s:

Progressive Automotive

Tel:

6741 5336

of

B1K 3022A, UOI Rd 1 # 01-45/46

Policy No:

MPC17A00558201

Claim No:

DMPC18 00302H / JG

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 21/07/2018

CA / ☒ REV

REP. / REV 24 HRS

230pm (see p 90)

H.O.D. Endorsement:

Date/Time:

4:43pm @ 6/8/18

Person Contacted:

pei wen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SIZ 5260C - cc4/ICS18013616/Geb3 DOA: 21/07/2018
8/8-	Revert via email merimen
13/8-	approve by Janice Goh
13/8-	5:13pm - email to per wan authorise repair excess \$500/-

(08/11/13) wef

REF: JCS

ASS. REC. BY:

ASSIGNMENT

From:

Date: 21/8/18

Estimated Cost:

① TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJZ 5260C

at Workshop m/s

Progressive

of BLK 3022 A, ubi Rd 1 #01-45/46

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$500.00

(Client's Record)

2:30pm

Make of Veh:

(see and go)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

466

IDAC Accident Rpt:

Consistent?: Yes or No

GI A / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

1.8.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJZ5260C

Yr Regn:

12 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

BMW 523i

c.c.

2497

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

P6772

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W3ATP320502546809

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/7/18

D.O.I.

7/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 34164

21/8. 4th Dec 13

Repairer asking repair of plp because no second hand parts.

1/10/18 confirmed final bill 3433.50 with Ang. (Reel 13 N.30: 27%)

RECEIVED 01 OCT 2018

Date/Time, File Pass to?

☐

Preli. Report

11/10 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

250

S + RS, SI

10

Photos

Others

TOTAL

260

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

OD

Lump Sum / (B): (\$ 3433.50)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18014270/Utd3

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 06-08-2018



Code : ICS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJZ 5260C
Policy No.	MPC17A00558201	Coverage (\$)	0.00
Claim No.	DMPC1800302H/JG	Excess (\$)	500.00
Assign From	MERIMEN (JANICE GOH)	Assign Date	06/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/07/2018	Inspection Date	07/08/2018
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2018 13:18 Sendback Est	03 Aug 2018 13:23 S\$4,748.30	06 Aug 2018 14:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHUA SENG KHAI, ID: S1279163A, Tel: +6598008237, Email: CHUASENGKHAI@YAHOO.COM			
Vehicle Reg. No.:	SJZ5260C	Date of Loss:	21/07/2018 10:00 - :59 [91 Months and 20 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / DMPC1800302H/JG	Policy/Cover Note No.:	MPC17A00558201 (Comprehensive)	
		Excess:	S\$500.00	
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336			
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/08/2018]			
Driver/Custodian:	CHUA SENG KHAI (60 / Male), NRIC: S1279163A, Tel: +6598008237			

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9163A
Vehicle Details	
Vehicle No.:	SJZ5260C
Vehicle to be Exported:	No
Intended De-registration Date:	07 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	06947594N52B25AF
Chassis No.:	WBAFP32050C546809
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$39,742.00
Original Registration Date:	01 Dec 2010
First Registration Date:	01 Dec 2010
Transfer Count:	0
Actual ARF Paid:	\$39,742.00 19871
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2020
PARF Rebate Amount:	\$23,845.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$44,600.00
COE Rebate Amount:	\$10,319.00
Total Rebate Amount:	\$34,164.00

The information contained herein is correct as at 07 Aug 2018

OK

View Received Message

This mail is associated with :

SJZ5260C (DMPC1800302H/JG)

OD

Jul 21 2018 10:00AM

[CHUA SENG KHAI]

Progressive Automotive Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From ECICS Limited (HQ) (ECICS), sent on **13/08/2018 15:41 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3741.50) - SJZ5260C - Claim Handler: Janice Goh

Approved:3741.50.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 13 August 2018 5:13 PM
To: peiwen@progauto.com.sg
Cc: SUR
Subject: SJZ 5260C / OD / PROGRESSIVE

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJZ 5260C (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2008 Toyota Vios J Sports Renewed 5 Years COE.



\$0 Down Payment. Low Interest
Rate From 3.18%! Well
Maintained With Low Mileage!
StarAd


[Browse by Category](#)
[« Back \(1 2 \) Next »](#)
[Sort by](#)

37 vehicles

bmw 523

[Advertiser](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
Search Selection	bmw 523		Any	Any	2010	Any	
	BMW 5 Series 523i		\$43,800	\$13,370 /yr	28-Jun-2010	2,497 cc	
\$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Con 100% Accident Free! In House Loan Or Bank Loan Available! No Nee... 88 Motor Trading Posted: 07-Aug-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW							
	BMW 5 Series 523i Highline		\$47,000	\$13,710 /yr	21-May-2010	2,497 cc	15
Original Grey With Dark Grey Interior, Very Clean, Non-smoker, Well-maintained, PML Records, Accident-free. Posted: 07-Aug-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW							
	BMW 5 Series 523i		\$42,800	\$13,200 /yr	02-Jun-2010	2,497 cc	
PML Unit! Havana Brown On Beige, The Sporty BMW 5 Series Sets Unsurpass Standards For Style And Dynamics, Mainta The Most Widely Sold Premium Car In The World. Immaculate ... TS Wheeler Capital Pte Ltd Posted: 07-Aug-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW							
	BMW 5 Series 523i		\$48,888	\$11,840 /yr	08-Nov-2010	2,497 cc	
Well Maintained By Owner, Workshop And STA Evaluation Welcomed, Bank And High Loan Available! Posted: 06-Aug-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW							

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)
[Compare](#)




PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel:: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0818-6604
Policy No:	MPC17A00558201	Date of Loss:	21/07/2018
Vehicle Reg. No.:	SJZ5260C	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHUA SENG KHAI	Contact No:	+6598008237
Driver:	CHUA SENG KHAI		

Make/Model:	BMW 528i, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	01/12/2010
Vehicle Colour:	SILVER	Chassis No:	WBAFP32050C546809
Engine No:	06947594N52B25AF		
Odometer:	86183 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Handwritten notes:
 Not about excess \$500
 the
 p/p 3433-50
 the ph. before repair,
 7/8/18 3dy.

Description of Accident/Loss: STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Present Location: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	3,468.30
Miscellaneous Items	0.00
Labour	580.00
Paintwork Labour	700.00
Towing	0.00
Gross Total (\$\$)	4,748.30
+ GST 7.00% (\$\$)	332.38
Nett Amount (\$\$)	5,080.68

This claim is handled by: **SOO LEONG KEAT**

Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Aug 2018)**Parts:** 143 BMW 528i 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/SJZ5260C/03/08/2018 13:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>DrS</i>	0.00	0.00 <i>/</i>	*950.00 F <i>/</i>
2	1		*FRONT BUMPER SIDE HOLDER - LH <i>SmY</i>	0.00	0.00 <i>/</i>	*15.00 F <i>/</i>
3	10		*FRONT BUMPER CLIPS <i>me</i>	0.00	0.00 <i>/</i>	*20.00 F <i>/</i>
4	1		*FRONT BUMPER SENSOR - LH <i>AA</i>	0.00	0.00	*170.00 F <i>X</i>
5	1		*FRONT BUMPER FOAM - LH <i>u7</i>	0.00	0.00	*38.00 F <i>X</i>
6	1		*FRONT FENDER - LH <i>2</i>	0.00	0.00	*550.00 F <i>X</i>
7	1		*FRONT FENDER COWLING - LH <i>AA</i>	0.00	0.00	*90.00 F <i>X</i>
8	10		*FRONT FENDER COWLING CLIPS <i>AA</i>	0.00	0.00	*20.00 F <i>X</i>
9	1		*FRONT HEADLAMP - LH <i>CAC</i>	0.00	0.00 <i>/</i>	*1,300.00 F <i>/</i>

F=Franchise part.

Sub Total (\$\$)	3,153.00
+ Margin on L,N Items 10.00% (\$\$)	315.30
Total Parts (\$\$)	3,468.30

Progressive Automotive Pte Ltd/SJZ5260C/03/08/2018 13:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2285
12
2513.5

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINTING ON LHR FENDER & REAR BUMPER	New	550 700.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS.	New	350 500.00
3	TO CHECK WIRING	New	20.00 ✓
4	TO RESET CHECK LIGHT	New	11 60.00 X
Gross Labour Cost (S\$)			1,280.00

Progressive Automotive Pte Ltd/SJZ5260C/03/08/2018 13:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

343350



友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S : PROGRESSIVE CAR CARE PTE LTD

BLK 3022A #01-45,
UBI ROAD 1
SINGAPORE 408716

006604

NO: YLH211653
PAGE: 1
DATE: 11/09/2018
A/C CODE: LYPCC001
TERMS: 30 DAYS
P/O NO: SJZ5260C

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
1	5111 7 285 961	FRT BUMPER 5111 7 246 863	2N-1A	1	950.00	950.00 ✓
	5111 1 908 077 ✓	SPREADER RIVET	YDS	10	2.00	20.00 ✓
3	5111 7 207 931	SPACER LH	1N-44D1	1	15.00	15.00 ✓
4	6311 7 271 909	HEAD LAMP LH	1N-33A	1	1,300.00	1,300.00 ✓
TOTAL QUANTITY:			13	TOTAL	SIN 2,285.00	
				ADD GST @ 7%	159.95	
				GRAND TOTAL	<u>SIN 2,444.95</u>	

DELIVERY

Print / KXM / 11/09/2018 9:56:18 AM

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18014270/UTD3N2

Date: 04/10/2018

REFERENCE

Insured/Claimant: CHUA SENG KHAI Policy No: MPC17A00558201
Date of Loss: 21/07/2018 Nature of Claim: OD Claim No: DMPC1800302H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJZ5260C
Make & Model: BMW 528i, 2.0 D/AB 2WD 4DR GAS/D NAV (A) Engine No: 06947594N52B25AF
Reg. Date: 01/12/2010 (Man. Year: 2010) Chassis No: WBAFP32050C546809
Colour: Silver Odometer: 86772 km
Engine Capacity: 2497 cc
Market Value/New Car Price: S\$46,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,468.30	2,513.50	954.80	27.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	580.00	370.00	210.00	36.21
Paintwork Labour	700.00	550.00	150.00	21.43
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,748.30	3,433.50	1,314.80	27.69
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	4,748.30	2,933.50	1,814.80	38.22
+ GST 7.00/7.00% (S\$)	332.38	205.35	127.03	38.22
Nett Amount (S\$)	5,080.68	3,138.85	1,941.83	38.22

INSPECTION

Date of Assignment: 06/08/2018 Present Location: Progressive Automotive Pte Ltd (HQ)
Date Inspected: 07/08/2018 Inspected At: Progressive Automotive Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2018)
Parts:	143	BMW 528i 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ5260C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Distorted	950.00 F	*950.00 F
2	1		*FRONT BUMPER SIDE HOLDER - LH (WCP)	Bent	15.00 F	*15.00 F
3	10		*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
4	1		*FRONT BUMPER SENSOR - LH (WCP)	Not Necessary	170.00 F	*- F
5	1		*FRONT BUMPER FOAM - LH (WCP)	Not Necessary	38.00 F	*- F
6	1		*FRONT FENDER - LH (WCP)	Repair	550.00 F	*- F
7	1		*FRONT FENDER COWLING - LH (WCP)	Not Necessary	90.00 F	*- F
8	10		*FRONT FENDER COWLING CLIPS (WCP)	Not Necessary	20.00 F	*- F
9	1		*FRONT HEADLAMP - LH (WCP)	Cracked	1,300.00 F	*1,300.00 F
					Sub Total (S\$)	3,153.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	315.30
					Total Parts (S\$)	3,468.30
						2,285.00
						2,513.50

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINTING ON LHR FENDER & REAR BUMPER	New	700.00	550.00
<u>Labour Items</u>				
2	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS.	New	500.00	350.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO RESET CHECK LIGHT	New	60.00	-
Gross Labour Cost (\$\$)			1,280.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >