Traveling Ass. REC. BY REF. CS. PC	1.180 14292/ Klad	3 Special Instruction
CUS KAND ASSIG	GNMENT (Office)	× 19
From (Person). JULINIA YONG	FEI	Date/Time 6/8/2018@3:22pm
Estimated Cost	Bill to:	215,150.0
OD (TP) WS/TP RES/OD RES/EVA/INV/	MV7CS S632B	nsured: SHB 4037 M
at Workshop m/s Premier A		Tel 6544 6682
of 23 chengi south Ave	2#03-02	027-18002
Policy No:)1800 5903 MFSH
Sum Insured:	Excess	9.1900 39 03 1 1 31 1
Make of Veh:		D.O.A. 63 08 2008
CA / REV / REP. / REV 24 HRS (W) Date/Time: 3.26pm 6k R	ooted wee dek	Vehice IN / DUT
Date/Time Action/Instruction () Esti	male	
SHC GG32 B-NA INCI	note of I	010121111111
SHB 403-1M-CCA A	3022006/81	DIA: 21/11/2013
02/8/18@ 3 my vensed to Joa	ene Your by 1	K/UB3 DOA: 13/2/2018
	J. J.	50 9

.

(08/11/13) REF:	Ĭ
airreum Kolvin	
	GNMENT CITY (1228 29
From: Date:	Veh No: SHC 6632B Yr Regn: 29 Jan , 2015
EstimatedCost	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taki / Prime Mover /
OD ITP INS ITP RES I OD RES I EVA I INV I MV	Truck / Trailer or
To Inspec Vehicle No:	Make: KIA optima co 1.685
at Workstop m/s	Colour Silver A/C: Instred / Std / NI / NA
01	Sp.Reading 434934 T/Radio: Ins@ed / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: KNALA414MF577748X
Claims No	Gen. Cond: Good / Fair / Poor / Burnt
Sum In suled: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nil / S/Rim / STØ3/Rim or
	Tyre Size: F: 205/65R16
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
NS 200 C	TOYO/YOKO or Ham Kest
Ball or Market Value:	Front 7 Rear 2
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 1 mm R/Bal. 1 mm . "
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 1 mm L/Bal. 1 mm
Est. Repairs:	D.O.A. 3/8/68 D.O.I. 6/8/8
Lum Sum: % 3 Val.: Yes or No	Survey held at Prenier
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Dale:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	17. 73
13/8/18 Chand 4/5 \$ 1000 / 2 Rgs. CR	d to 711, (2%) FCI
DECEMED 1	ANG 2018
RECEIVED 1 4 /	AUG 2018.
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 100
2) Add Fee:	
	:Interview (\$-) Photos 26
Report Format:	; Tech, Invs (\$) Others
Lump Sum / J.B.T.: (S COD 0)	:Weekend (\$
/	TOTAL 226



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Autom	nobile
FIRS	ST CAPITAL INSU	RANCE LTD	Ref : CS/FCI180142	92/K1qd3
	6 ROBINSON ROAD 216-01 CITY HOUSESINGAPORE 068877 Date : 06-08-2018			
1.		Policy Particula	ars :- THIRD PARTY CLA	IM
	Insured Veh.	SHB 4037M	Veh. Inspected	SHC 6632B
	Policy No.	N. 110000 2000 2000 2000 2000 2000 2000 2	Coverage (\$)	0.00
	Claim No.	D18005903MFSH	Excess (\$)	0.00
	Assign From	CWS (JOANNE YONG)	Assign Date	06/08/2018
2.		Vehicle P	articulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	(#)	Steering	
ĺ	Brakes		Modification	
	General			
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
3	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Descr	iption of Damages	
5.		Gen	eral Information	A CONTRACTOR OF THE RESERVE
•	Accident Date	03/08/2018	Inspection Date	06/08/2018
	Survey held at	PREMIER AUTOMOTIVE S		
	San of mora at		JE 2 #01-02 SINGAPORE 486	6443
5a.			Remarks	
		ON WAS CONDUCTED ON A"		
	B)IN ACCORDAN	CE TO YOUR INSTRUCTIONS	S, WE HAVE NOT AUTHORIS	SED REPAIRS.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18005903MFSH

Date: 07 August 2018

Our Ref: CS/FCI18014292/K1qd3

The Motor Claims Department First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6632B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on <u>06/08/2018</u> at the premises of M/s <u>PREMIER AUTOMOTIVE</u>, and have the following to report:-

Workshop Estimate Amount	: S\$	1,711.00	
Revised Estimate Amount	: S\$	1,261.00	
"Check" Items Amount	: S\$	-	
Market Value	: S\$	-	
LTA Reimbursement Value	: <u>S</u> \$	*	
Nett Value	: S\$	2	

Description of Damage: The vehicle sustained damages at the o/s body.



Yours faithfully

Kalvin Ang Automotive Assessor



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

06-08-2018

Our Ref No. D18005903MFSH

Accident Date

03-08-2018

Claim Type. Third Party

Insured Vehicle

SHB4037M

Third Party Vehicle. SHC6632B

Survey Location

23 CHANGI SOUTH AVENUE 2 #03-02

Contact Person.

GOH WEE DEK

Contact No.

62148880/65446682

Fax No. 62141511

Survey Type

WITHOUT PREJUDICE: ACCIDENT NOT REPORTED (EST. COR - \$1,711.00)

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

PREMIER AUTOMOTIVE

SERVICES PTE LTD

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Attention, NIL

Officer Incharge

JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 7 August 2018 3:27 PM

To:

'Claim Workflow System'; assignments

Cc:

JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR

Subject:

RE: SURVEY ASSESSMENT - D18005903MFSH/1

Attachments:

CSFCI18014292K1qd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 6632B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 6 August 2018 3:27 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18005903MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Monday, 6 August 2018 3:21 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005903MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

29 Jan 2015 / 08:39:33

Receipt No .:

AACCK001-AX239-150129-000009

Asset Type:

Vehicle

Transaction Amount:

\$66,097.00

Asset ID:

SHC6632B

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

01.02 Register New Vehicle (AA)

Business Transaction Reference No.:

20150129083933441013

Vehicle No.:

SHC6632B

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date:

29 Jan 2015

Original Registration Date:

29 Jan 2015

Vehicle Make:

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5575484

Engine No.:

D4FDEH313261

Motor No.:

Trailer Chassis No.:

Propellant:

Passenger Capacity:

Engine Capacity:

1685

Diesel 4

Power Rating:

Unladen Weight: Maximum Laden 1584 2050

Weight

Silver

Primary Color:

Secondary Color. Manufacturing Year:

2014

Open Market Value:

\$20,693.00

Minimum PARF Benefit: \$8,082.00

PARF Eligibility:

No. of Transfer:

Effective Ownership

Date/Time:

29 Jan 2015 08:39:33

COE No .:

2015012901001594H

COE Expiry Date:

28 Jan 2023

COE Bid Category:

Actual QP/PQP Paid

Amount:

\$52,486.00

Lifespan Expiry Date:

28 Jan 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

3-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6632 B

1 pc	o/s mirror Assy B. km		\$	590.00
	1 C. D. L. Pepair	Less 10%	\$	59.00
L-00-70-10-10-1	From ob windsom Pillary reper		S	531.00
S/NETT				
1 set	o/s door sticker		\$	100.00
	Sundry NEC		\$	50.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s windscreen pillar		\$	450.00
	To putty and spray painting on o/s mirror, front o/s windscreen pillar, front o/s door		\$	500.00 Ko
	To apply rustproofing on the repaired and replaced panels.		\$	80:00 4-4
			\$	1,711.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahi ICICIN 6/8/18 1605hr. 2 Pays Us Affer Rep. 2 photo LKK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged partial during resurvey
To display damaged partial during resurvey
Third Herry
Third Herry
Third Herry
Third Herry
Third Herry
To see the second state of the second spray resurveyed and
Supplement to see the second spray resurveyed and
Supplement to the second state of the second spray resurveyed to the supplement of the second state of the second spray resurveyed and
Acknowledged by Repairer
Signatures:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Auton	nobile
FIRST CAPITAL INSUI	RANCE LTD	Ref : CS/FCI180142	92/K1qd3n2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 15-08-2018 Code: FCI2	
1.	Policy Particula	ars :- THIRD PARTY CLA	IM
Insured Veh.	SHB 4037M	Veh. Inspected	SHC 6632B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005903MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	06/08/2018
2.	Vehicle Pa	articulars & Condition	
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5575484	Colour	SILVER
Odometer	434934	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	205/65 R16	HANKOOK	7 mm
L/H Front Tyre	205/65 R16	HANKOOK	7 mm
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm
4.	Descri	iption of Damages	
THE VEHICLE SU	STAINED DAMAGES AT THE	O/S BODY.	
DAMAGES SEE D	ETAILS.		
5.	Gen	eral Information	
Accident Date	03/08/2018	Inspection Date	06/08/2018
Survey held at	PREMIER AUTOMOTIVE SI	ERVICES PTE LTD	
	23 CHANGI SOUTH AVENU	JE 2 #01-02 SINGAPORE 486	5443
5a.		Remarks	
B)THE INSPECTION	NSISTENT TO ACCIDENT REI ON WAS CONDUCTED ON A' CE TO YOUR INSTRUCTION	WITHOUT PREJUDICE" BAS	SIS. SED REPAIRS.
5b.	Estim	ate Days of Repair	
ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Da	ys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6632B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	O/S MIRROR ASSY	BROKEN	590.00	590.00
1	O/S FRONT DOOR (NPA)	TO REPAIR SEE LABOUR	-	
1	FRONT O/S WINDSCREEN PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-59.00	-59.00
	No. of the contract of the con		531.00	531.00
	SPECIAL NETT ITEMS			
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
	775 102		150.00	120.00
	LABOUR			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE FRONT O/S WINDSCREEN PILLAR.INCLUSIVE OF THE REPAIR OF O/S FRONT DOOR.		450.00	200.00
	TO PUTTY AND SPRAY PAINTING ON O/S MIRROR,FRONT O/S WINDSCREEN PILLAR,FRONT O/S DOOR.		500.00	410.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	8
			1,030.00	610.00
	GRAND TOTAL		1,711.00	1,261.00

RECOMMENDED COST OF LUMP SUM REPAIRS	1,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18014292/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

H.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.