



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20180716/0210		LOCATION OF FIRE: Along Bishan Flyover towards Lornie Road Near lamp post no. 161 Singapore	
FIRE REPORTED ON : 16 July 2018			
TIME OF CALL : 07:55:52 hrs			
STATION COVERAGE : Bishan Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Nissan car (SBZ3318D).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel jet from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. The front part of the car including the headlights and windscreen were also damaged. The dashboard and interior of the car sustained heat and smoke damage. SCDF crew forced the bonnet open for firefighting.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY: EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.