NS CASE OWNER	ccb, LCK 180 1	4315, U pa3// 1xx
Surveyor.	MANN DOI: ASSIGNM	Date / Time:
Pre-assign / CCU	C R 40291)	Claim No. : 999 98 4966
Insured Tel No. Excess Sec II :SS Is driver the owner.	DOA: WINOLE	Make / Model : WAWA 3
If NO, Driver Nam Driver Tel 1		OI GIA REPORT: 92S / NO ; TP GIA REPORT: Y / NO Insured Liability: % Final? Yes / No
INSRS: WSP: VXX Tel: Linbility: RMKS:	INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS:
Date/Time		
14/8	SURBOND JUNIOURINGSTHA	STAGE DATE / PIC Non-Reporting ltr (1st) Non-Reporting ltr (2nd) Non-Reporting ltr (Final)
Halle -	Old rear ended Tp.	Notification itr (if non-pickup): Call OI: After call itr to OI: CB years)
2/4/8 -	DV sert	Documentation Check List: Handler Typist Notification ltr (if non-pickup)
4/10/18	Aleparsto Mei Kwanto clue	After call litr to OI: Authorization To Act: Release Voucher:
	RECEIVED 0 4 GC	Final Repair Bill: Car Rennal Invoice: Towing Invoice LTA / GIA
		Medical Bill:
0		Mandate/Reject Instruction LOD Payment Breakdown Form
PRELIMINARY ADVICE	Date/Time: Sent By:	Post-Repair Photos:
FINALIZATION	Date/Time: Confirm with:	Others: Confirm by:
Repair Cost.	S\$ (days) Reduction:	% Email Call
FINAL SETTLEMENT	Date/Time, 3 4 6 Confirm with Venu	Email Call
Final Liability: Repair Cost 1681	% (Agreed / Assessed) BOLA S/N No.: 17	If NO or B 28, Ass. Lia :
Loss of Rental (LOR):	SS (days)	California in management
Loss of Use (LOU):	S\$ 450.00 (\$150 x 3 days)	Malio
Loss of Income (LOI): LOR only LOU only	S\$ (\$ x daya) LOR + LOI	6 10/18
GIA/LTA Search	SS -	
Medical:	55	1) Claim status: Semal/Reject/Private Settle
Disbursement: Legal Cost	S\$ (e.g. Tow/ Independent)	2) Report Format:
Total:	S\$ 3125. W Global Sum SS:	13) Survey IDE: 43.
FINAL PAYMENT	Date/Time 3 W Confirm with: YAM	Email Galf
Payor 1:		anice He Utd
Payee 2: (Strike if N.A.) Payee 3: (Strike if N.A.)	\$\$ Name 2: \$\$ Name 3:	

Date : Time

Action / Instruction

Person Contacted

LIS# 2500 (Red# 20541.82/ 89(7.)

The U/C / Chassis frame / Body Structure affected the to collision

Constrain File Pass (c)	: Preli. Report	Day	rs Of Repair:		
Total Class File Report of	: Final Report	Res	survey No. of Trip:	Sunery Fire.	
		Add Fee:	Site Insp. (\$) _1-81_9	
			Interview (\$	1 Perci	
Report Format			Techs love (\$	Cont	
Lump Sum / LB L (\$			Waghani 15	24 7	

78 SHENTON WAY

SINGAPORE 079120

#07-16 AIG BLDG

700

M/S AIG ASIA PACIFIC INS PTE LTD

Vfix Auto Service Ptr. Ltd 60 Kaki Bukit Ave 6 Ark@KB

Singapore 417892

Email: contact@vfoauto.com.sg Tel: 6448 9268 Fax: 6445 2368 UEN / GST Reg No 201602964H

ESTIMATE

DATE

= 06/08/2018

ACC DATE

: 04/08/2018

REF NO

: VFIX - TP20180509

POLICY NO

Attention: Motor Claim Department

RE: VEHICLE NO:XD7022K VOLVO FMX

		DESCRIPTION				MOUNT SS ,
1	2	SUSPENSION ARM R+L		2,300.00	JULI	4,600.00 X
2	2	SUSPENSION BELLOW	1820 x22 3040	1,880.00	DIS	3,760.00
3	1	STEERING RACK			47	5,882.80 ×
4	1	TRACK ROD			11	1.985.00 X
5	1	CENTER BELLOW			11	1,852.00 X
					S	18,079.80
				LESS 10%	5	1,807.98
					5	16,271.82

apply hot-works where necessary straighten/repair rear chassis member	AMO	DUNT SS
To remove damaged parts with all necessary components/attachments	40.7	4,000.00
apply hot-works where necessary straighten repair rear chassis member	100	
repale new parts refit align into position with all necessary components attachments		

- 2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials
- 3 To remove, replace rear steering rod with all necessary components attachments
- 4 To conduct rear wheel alignment

GRAND TOTAL: \$ 23,041.82

SINGAPORE DOLLARS: TWENTY THREE THOUSAND FORTY ONE &

CENTS EIGHTY TWO ONLY

LKK Auto Consultants hence notify

the Repairer of the following:

- To result by deforigation spray pointing
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third butly survey is on a "Without Frequence" basis.
- No illegal modification(s) is allowed.
- Supplementary ham(s) must be resurreyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signatured

Date:





SINGAPORE 079120

M/S AIG ASIA PACIFIC INS PTE LTD 78 SHENTON WAY #07-16 AIG BLDG

Vfix Auto Service Pte Ltd 60 Kaki Bukit Ave 6 Ark即KB

Singapore 417892

Email: contact@vfixauto.com.sg Tel: 6448 9268 Fax: 6445 2368 UEN / GST Reg No.: 201602964H

ESTIMATE

: 06/08/2018 DATE ACC DATE : 04/08/2018

REF NO

: VFIX - TP20180509

AMOUNT S\$

POLICY NO

Attention: Motor Claim Department

RE: VEHICLE NO:XD7022K VOLVO FMX

LABOUR & MISCELLANEOUS:

		DESCRIPTION	TAX DESCRIPTION OF	AN	MOUNT SS
1	2	SUSPENSION ARM R+L	2,300.00		4,600.00
2	2	SUSPENSION BELLOW	1,880.00	DIS	3,760.00
3	1	STEERING RACK		117	5,882.80
4	1	TRACK ROD		11	1,985.00 €
5	1	CENTER BELLOW		11	1,852.00
				S	18,079.80
			LESS 10%	S	1,807.98
				S	16,271.82

1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten/repair rear chassis member		4,000.00
	repale new parts refit align into position with all necessary components attachments		
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials		1,800.00
3	To remove,replace rear steering rod with all necessary components attachments	M	850.00 X
4	To conduct rear wheel alignment	17	120.00
		S	6,770.00

GRAND TOTAL: \$ 23,041.82

SINGAPORE DOLLARS: TWENTY THREE THOUSAND FORTY ONE & CENTS EIGHTY TWO ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following: * To resurvey beforelatter spray painting

- To display damaged partis) during resurvey
- Parts prices are subject to confirmation . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- . Supplementary hem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hsiao Tong (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Monday, 1 October 2018 1:28 PM

To:

irenelsk@vfixauto.com.sg; Hsiao Tong (LKKAuto)

Cc:

'kentsh'; Admin A

Subject:

RE: ACCIDENT INVOLVING XD7022X & SLR8029D ON 04/08/2018 *** LKK REF:

CC6/LCR18014315/Upa3

Attachments:

FS LOD.PDF; XD7022K.PDF

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that : -

LKK ref	Officer in charge			
CC6/LCR18014315/Upa3	Hsiao Tong - 6742 3197			

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: irenelsk@vfixauto.com.sg <irenelsk@vfixauto.com.sg>

Sent: Monday, 1 October, 2018 11:53 AM

To: Admin A <admin-a@lkkauto.com>
Cc: 'kentsh' <kentsh@vfixauto.com.sg>

Subject: FW: ACCIDENT INVOLVING XD7022X & SLR8029D ON 04/08/2018

Dear Sir

Please find attached Letter of Demand for your kind perusal.

Thank you.

Best regards,

Irene Lee

Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 |

E: contact@vfixauto.com.sg |

T: +65 6455 2957 (Line 1); +65 6385 4138 (Line 2); +65 6448 9268 (Line 3) |

F: +65 6445 2368 |

From: irenelsk@vfixauto.com.sg <irenelsk@vfixauto.com.sg>

Sent: Wednesday, 29 August 2018 9:14 AM

To: marcuschua@lkkauto.com

Cc: irenelsk@vfixauto.com.sg; joannelsy@vfixauto.com.sg

Subject: RE: ACCIDENT INVOLVING XD7022X & SLR8029D ON 04/08/2018

Dear Marcus

We confirm estimate for your kind perusal as per attached.

Thank you.

Best regards,

Irene Lee

Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 |

E: contact@vfixauto.com.sg |

T: +65 6455 2957 (Line 1): +65 6385 4138 (Line 2): +65 6448 9268 (Line 3) |

F: +65 6445 2368 |

From: irenelsk@vfixauto.com.sg <irenelsk@vfixauto.com.sg>

Sent: Tuesday, 28 August 2018 10:41 AM

To: 'marcuschua@lkkauto.com' <marcuschua@lkkauto.com>

Subject: FW: ACCIDENT INVOLVING XD7022X & SLR8029D ON 04/08/2018

Dear Marcus

Please find attached after paint & confirmed estimate for your kind perusal.

Thank you.

Best regards.

Irene Lee

Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 |

E: contact@vfixauto.com.sg |

T: +65 6455 2957 (Line 1); +65 6385 4138 (Line 2); +65 6448 9268 (Line 3) [

F: +65 6445 2368 I

From: irenelsk@vfixauto.com.sg <irenelsk@vfixauto.com.sg>

Sent: Monday, 6 August 2018 3:30 PM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Subject: ACCIDENT INVOLVING XD7022X & SLR8029D ON 04/08/2018

Dear Catherine

Please find attached copy for your arrangement.

Best regards,

Irene Lee

Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 |

E: contact@vfixauto.com.sg |

T: +65 6455 2957 (Line 1); +65 6385 4138 (Line 2); +65 6448 9268 (Line 3) |

F: +65 6445 2368 |

27 SEPTEMBER 2018

Our Ref. No.: VFIX-TP20180509

MOTOR CLAIMS DEPT AIG ASIA PACIFIC INS PTE LTD

78 SHENTON WAY #07-16 AIG BLDG SINGAPORE 079120 O V F I X

Vfix Auto Service Pte Ltd 60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 Email: contact@vfixauto.com.sg Tel: 64552957 Fax: 64452368 UEN/GST Reg No.: 201602964H

WITHOUT PREJUDICE

Dear Sir / Madam

PROPERTY CLAIM ONLY

ACCIDENT INVOLVING XD7022K AND SLR8029D ON 04 AUG 2018 ALONG BKE TOWARDS PIE B/F KJE ENTRANCE

We refer to the above-mentioned accident.

We are writing on behalf of M/S KOK TONG TPT & ENG WORKS PTE LTD the registered owner of motor vehicle number XD7022K which was involved in the above accident.

We are instructed that the above accident was caused by the negligence and management of your insured's vehicle number SLR8029D. As a result of the above accident, our client's vehicle was damaged and our client's has been put to loss and expense, particulars of which are as follows:

TOTA	AL AMOUNTS							:S\$	3,132.45
3	LTA Fees							:S\$	7.45
2	Loss of Use	1	3	days	X	\$ 150.00)	:S\$	450.00
1	Cost of Repair							:S\$	2,675.00

We enclosed a list of the supporting documents :-

- (a) Original Final Repair Bill
- (b) LTA Tax Invoice
- (c) GIA / Police Report lodged by Our Client
- (d) Letter of Authority

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Any settlement reached is strictly without prejudice to and shall not affect any other claims arising from this accident. Settlement is solely for the items claimed only.

Yours Faithfully,

VFIX AUTO SERVICE PTE LTD

Ken Tan

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Monday, 1 October 2018 3:52 PM

To:

irenelsk@vfixauto.com.sq

Cc:

'kentsh'; Admin A

Subject:

RE: ACCIDENT INVOLVING XD7022X & SLR8029D ON 04/08/2018 *** LKK REF:

CC6/LCR18014315/Upa3

Without Prejudice

Hī.

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$3,050.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, ≠02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Monday, 1 October 2018 1:28 PM

To: irenelsk@vfixauto.com.sg; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'kentsh' <kentsh@vfixauto.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING XD7022X & SLR8029D ON 04/08/2018 *** LKK REF: CC6/LCR18014315/Upa3

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that : -

LKK ref Officer in charge



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

1022 AX 4022 XX

Print Date/Time :

06 Aug 2018 / 10:34:38

Receipt Date/Time

06 Aug 2018 / 10:34:25

Tax Invoice/Receipt

Receipt No.: (TNET-00000-180806-000506)

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLR8029D As at 04 Aug 2018/22:20:00 Insurance Co: AIG ASIA PACIFIC INSURANCE 1 Insurance Enquiry - SLR8029D Enquiry Fee 20180806103333718881	PTE LTO.	7.00	0.49	7,49
	Sub-Total	7.00	0.49	7,49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	.00000000008539	Credit Can /Masteri		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 4 September 2018 12:35 PM

To:

'Eileen, May Hwee Yap'

Subject:

ACCIDENT INVOLVING SLR 8029D(AIG) & XD 7022K ALONG/AT BKE TWDS KJE

BEFORE EXIT 5 ON 04/08/2018

Your Ref: SLR 8029D

Our Ref: CC6/LCR18014315/Upa3

Dear Sirs/Madam.

ACCIDENT INVOLVING SLR 8029D(AIG) & XD 7022K ALONG/AT BKE TWDS KJE BEFORE EXIT 5 ON 04/08/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from XD 7022K against your insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) To: AIG ASIA PACIFIC INS PTE LTD 78 SHENTON WAY #07-16 AIG BLDG SINGAPORE 079120

Dear Sir / Madam,	
Claimant	
ACCIDENT INVOLVING XD7022K AND SLR8029D ON 04/08/2018 A BKE TOWARDS PIE B/F KJE ENTRANCE	Τ
I/We. KOK TONG TRANSPORT & ENGINEERING WORKS P. L. am/are the registered owner of motor car no. XD7022K	of
Please be informed that I have assigned all compensation monies due to me/us in the above accident to VFIX AUTO SERVICE PTE LTD.	ie
I/We hereby authorized you to release all monies pertaining to the above mentioned accides to VFIX AUTO SERVICE PTE LTD and forward the settlement cheque to VFIX AUTO SERVICE PTE LTD whom I/we have authorized to collect the said compensation monies.	
Thank you,	

Signature of Claimant &

Company Stamp if applicable

IC no.: 199904117E Date: 27/09/18 Signature of Witness

Trene

IC no.: \$1527552I Date: 27/09/18

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, VFIX AUTO SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,675.00 (Repair Cost), S\$450.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. XD 7022K that was damaged pursuant to the accident which occurred on 04/08/2018 (date) along BKE TWDS PIE B4 KJE ENTRANCE (location) involving vehicle no/s SLR 8029D. This is pursuant to the inspection conducted on 07/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD (the third party claimant") of vehicle no. XD 7022K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to XD 7022K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this O3 (day) of OCT (month) 2018 (year)

LKK

Signed by appointed surveyor

Signed by "the workshop" (with chop)

*** This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.



Vflx Auto Service Pte Ltd 60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 Email: contact@vfixauto.com.sg Tel: 64552957 Pax: 64452368 UEN/GST Reg No.: 201602964H

FINAL REPAIR BILL

AIG ASIA PACIFIC INS PTE LTD

78 SHENTON WAY #07-16 AIG BLDG SINGAPORE 079120 DATE : 27/09/2018 VEHICLE NO : XD7022X

MAKE/MODEL : VOLVO FMX420

ACC DATE :

: 04/08/2018

CLAIM NO

: VFIX-TP20180509

POLICY NO

60

AMOUNT'S\$

LUMP SUM REPAIR COST

Repair Amount 7% GST 2,500.00 175.00

Total

2,675.00

SINGAPORE DOLLARS: TWO THOUSAND SIX HUNDRED & SEVENTY FIVE ONLY

VFIX AUTO SERVICE PTE LTD

Ken Tan

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpi		Adj Su	bmitted	Ins Auth'ed	d St	atus	
Main	06 Aug 2018 Edit Reg		07 Aug 2018 00:00 Edit Adj Rpt	\$\$2,50		S\$2,5	800.00 Rpt		Re	Pending for Survey Report Cancel Case	
	Main	∏ R	eference		Claim Det	ails		Docume	ents	٦.	Show All
CLAIM SU	BFOLDER DE	TAILS				I	Created I	by adjuster)	1		
Insured:	LCRF PTE	LTD, Co. Reg. N	io.: 201624597K								
Main Claimant:	KOK TON	G TRANSPORT &	ENGINEERING W	ORKS PT	LTD, C	o, Reg.	No.: 19990	14117E			
Vehicle Reg No.:	XD7022	к			Date of I			22:00 - :59 and 25 Days	From LTA	Reg Date	(Man Yr)]
Claim Type:	TP / 378	2626758SG			Policy/Co Note No.		0999994775 (Comprehensive)				
Vehicle Reg No. (Insured):	SLR80290	•		Policy No (Claiman		DMCVSN1804891800					
					Excess:						
Repairer:	Vfix Auto	Service Pte Ltd	(HQ) 60 Kaki Bukit	Ave 6, AR	KØKB, 417	7892 Kai	ki Bukit - T	el: 64552957	,		
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expres	s) - Tel:	5-6419-30	J 000	Handled by	Olea, Mario	cel] Marice	.Olea@aig	j.com
Claimant's Insurer:	China Tai	ping Insurance (Singapore) Pte. Li	td. (HQ)	Tel: 6389	6111					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	. [Handled	by MA	RCUS CHU	A] [Fina	I Rpt due	16/08/	2018]
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compe	se Case Ma
 AIG_SG 	(07/08/2018):	Request To Upi	oad TP GIA Report								
ALL ASSO	CIATED TAS	KS⊞				Vie	w All S	earch Tasks	Create N	ew Task	Complet
Due Date	Priority	Type Task	Group Subject	Hand	lier A	ssigned		Completed (reated Or	
No results.		- Iber Same	a. Lap			- signed		Compressed (-	carea or	Don

Claim Documents

*XD7022K (3782626758SG)

[SLR8029D]

TP

KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD

Aug 4 2018 10:00PM

[LCRF PTE LTD]

Vfix Auto Service Pte Ltd

Let	ters/Corresponder	nces	1 per p	nage 🔽	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ph	otos/Images		3 per p	age V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	_
1	08/08/18 20:34	Odometer Reading	0	Load JPG	V
2	08/08/18 20:34	Chassis Number	0	Load JPG	V
3	08/08/18 20:35	General View	0	Load JPG	2
4	08/08/18 20:35	General View	0	Load JPG	Z
5	08/08/18 20:35	General View	0	Load JPG	V
6	08/08/18 20:35	General View	0	Load JPG	[2]
7	08/08/18 20:35	General View	0	Load JPG	V
8	08/08/18 20:35	General View	0	Load JPG	V
9	08/08/18 20:35	General View	0	Load JPG	V
10	08/08/18 20:35	General View	0	Load JPG	V
11	08/08/18 20:35	General View	0	Load JPG	V
12	08/08/18 20:35	General View	0	Load JPG	V
13	08/08/18 20:35	General View	0	Load JPG	V
14	08/08/18 20:35	General View	0	Load JPG	V
15	08/08/18 20:35	General View	0	Load JPG	V
16	08/08/18 20:35	General View	0	Load JPG	V
17	08/08/18 20:35	General View	0	Load JPG	V
18	08/08/18 20:35	General View	0	Load JPG	V
19	08/08/18 20:35	General View	0	Load JPG	V
20	08/08/18 20:35	General View	0	Load JPG	V
21	08/08/18 20:35	General View	0	Load JPG	2
22	08/08/18 20:35	General View	0	Load JPG	V
23	08/08/18 20:35	General View	0	Load JPG	V
24	08/08/18 20:35	General View	0	Load JPG	V
25	08/08/18 20:35	General View	0	Load JPG	V
26	08/08/18 20:35	General View	0	Load JPG	V
27	08/08/18 20:35	General View	0	Load 3PG	V
28	08/08/18 20:35	General View	0	Load JPG	Z
29	08/08/18 20:35	General View	0	Load 3PG	V
30	08/08/18 20:35	General View	0	Load JPG	V
31	08/08/18 20:35	General View	0	Load JPG	V
32	08/08/18 20:35	General View	0	Load JPG	12
33	08/08/18 20:35	General View	0	Load JPG	V
14	08/08/18 20:35	General View	0	Load JPG	-

Page 2 of 2

Let	ers/Corresponder	nces	1 per	page V	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
	A December 1 and 1				V
35	08/08/18 20:35	General View	0	Load JPG	V
36	08/08/18 20:35	General View	0	Load JPG	V
37	10/08/18 17:56	Reinspection Photo	0	Load JPG	~
38	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
39	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
40	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
41	10/08/18 17:56	Reinspection Photo	0	Load JPG	2
42	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
43	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
44	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
45	10/08/18 17:56	Reinspection Photo	0	Load 3PG	₩.
46	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
47	10/08/18 17:56	Reinspection Photo	0	Load JPG	W
48	10/08/18 17:56	Reinspection Photo	0	Load JPG	2
49	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
50	10/08/18 17:56	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per p	age 🔽	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	(2)	Thumbnall	
1	12/08/18 22:56	TP ESTIMATE-MARKED	0	Load PDF	
2	14/08/18 08:28	TP GIA REPORT	0	Load PDF	
3	15/10/18 09:01	WORKSHOP INVOICE	0	Load PDF	
4	15/10/18 09:01	AUTHORISATION TO ACT FORM	0	Load PDF	
5	15/10/18 09:01	Release Voucher	Ö	Load POF	
6	15/10/18 09:01	LETTER TO OI	0	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	-	Thumbnail	Print
1	07/08/18 09:21	OI GIA REPORT	0	Load PDF	-

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other perces.	

NOTE: TO BE COMPLETED BY SURVE	COF	O
--------------------------------	-----	---

TEAM		
I = A M		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR8029D (Insd veh)	Model:	VOLVO FMX420 12.8 D 84RT	
	XD7022K (TP veh)			SC (M)	
Date of Accident: 04/08/2018					
Global Sum Settlen	nent : [] Yes		[X] No		
Repair Estimate	ion 1 Too	s	24,654.75		
Final Repair Cost		s	2,675.00		
Loss of Use		: 5	450.00	3.00 days at \$150.00 per day	
Rental (if any)		5	0.00	days	
LTA / GIA Search F	ee	s	0.00	33/3	
Others:		s	0.00		
BC-7, 100, 0207		: \$	38045		
Final Settlement Su	m	: \$	3,125.00		
pelow)	kshop GIA Registered	? [Agreed Liability_		
Charles and account of the second	(%)	chain e	Assessed Liability	Yes/ No BOLA Scenario No: (*):(%) ses where BOLA does not apply.	
Remarks					
Payment Instruction	n: Payee's Breakdowr	1			
Vfix Auto Servi	ce Pte Ltd		: \$	3,125.0	
2)			: \$		
JOANNE I	EE KHANG MIN		15 Oct 2018		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/LCR18014315/UPA3Q2

Date:

15/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994775

Claimant Vehicle XD7022K

Insured Vehicle No:

SLR8029D

No: Date of Loss:

04/08/2018

Nature of Claim:

TP

Claim No: 3782626758SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

XD7022K

Make & Model:

VOLVO FMX420, 12.8 D 84RT SC (M)

Engine No:

D13379246

Reg. Date:

10/04/2013 (Man. Year. 2012)

Chassis No: Odometer:

YV2JG10G7DA740282 447308 km

Colour Engine Capacity:

12777 oc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

315/80 R22.5

Rear Tyre Size:

315/80 R22.5 (D/D)

Front Left Side: Front Right Side: Triangle 6 mm Triangle 6 mm Rear Left Side: Rear Right Side: Triangle 6/6/6/6 mm Triangle 6/6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,271.82	2,736.00	13,535.82	83.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,770.00	400.00	6,370.00	94.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,041.82	3,136.00	19,905.82	86.39
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	23,041.82	2,500.00	20,541.82	89.15
+ GST 7.00/7.00% (S\$)	1,612.93	175.00	1,437.93	89.15
Nett Amount (S\$)	24,654.75	2,675.00	21,979.75	89.15
+ Loss of Use (3.0 x S\$15	50.00/day) (S\$)	450.00		
Ne	tt Liability (S\$)	3,125.00		

INSPECTION

Date of Assignment:

07/08/2018

Date Inspected:

07/08/2018 Inspected At: Vfix Auto Service Pte Ltd (HQ)

60 Kaki Bukit Ave 6, ARK@KB

Singapore 417892

Estimated Period of Repair:

3.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*SUSPENSION ARM R+L	Serviceable	4,600.00 FL	*-FL
2	2		*SUSPENSION BELLOW	Distorted	3,760.00 FL	*3,040.00 FL
3	1		*STEERING RACK	Not Necessary	5,882.80 FL	*-FL
4	1		*TRACK ROD	Not Necessary	1,985.00 FL	*-FL
5	1.		*CENTER BELLOW	Not Necessary	1,852.00 FL	*-FL
F=Fra	nchise	part L=ListIter	nDisc.	Experience to recently	13 13 01 13 4 0 12 3	55-4000-4
				Sub Total (S\$)	18,079.80	3,040.00
			- List Item Discount or	L Items 10.00/10.00% (S\$)	1,807.98	304.00
				Total Parts (S\$)	16,271.82	2,736.00
			Report was unsu	bmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ ATTACHMENTS APPLY HOT-WORKS WHER NECESSARY STRAIGHTEN /REPAIR REAR CHASSIS MEMBER REPLACE NEW PARTS REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS ATTACHMENTS	New E	4,000.00	400.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,800.00	0.00
3	TO REMOVE, REPLACE REAR STEERING ROD WITH ALL NECESSARY COMPONENTS ATTACHMENTS	New	850.00	0.00
4	TO CONDUCT REAR WHEEL ALIGNMENT	New	120.00	0.00
	Gross Labo	ur Cost (S\$)	6,770.00	400.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >