

ASS. REC. 177

REF: CS/CTI/18014328/ NHd3 Capital Instruction

Revised

SW/VEH/1
maximen

NAZ

ASSIGNMENT (Office)

From (Person):

Jamyn Tay

CTI

Date/Time:

3/8/2018 @ 1:48pm

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.:

SGV 3210S

Insured:

CB 6270 B

at Workshop m/s:

Kah Motor

Tel:

8288 6309

of:

15 Ubi Rd 4

Policy No.:

DMBISN1442331703

Claim No.:

SNM18 D03797C02

Sum Insured:

Excess:

Make of Veli:

(Client's Record)

D.O.A.

27/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

3/8/18 @ 2:54pm

Person Contacted:

Anikka

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SGV 3210S - X

CB 6270 B - CS/MSG/16011561/KH/bn2

DOA: 20/6/16

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Aug 2018		03 Aug 2018 13:48 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	MOHD ROSLI BIN MOHD SURATI		
Vehicle Reg. No.:	SGV3210S	Date of Loss:	27/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03797C02	Policy/Cover Note No.:	DMB1SN1442331703
Vehicle Reg. No. (Insured):	CB6270B	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/08/2018]		
Adj Asg. Remarks:	EST \$3322.53, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014328/Ntd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 07-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	CB 6270B	Veh. Inspected	SGV 3210S
Policy No.	DMB1SN1442331703	Coverage (\$)	0.00
Claim No.	SNM18D03797C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	07/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/07/2018	Inspection Date	07/08/2018
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/07/2018 16:25
Date Of Accident	27/07/2018 10:30
Exact Location Of Accident	OPEN CP @ AH HOOD RD BLK 103
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV3210S
Insured/Policyholder	
Name Of Registered Owner	MOHD ROSLI BIN MOHD SURATI
NRIC No	S1474653F
Email Address	MROSLI@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96865824
Alternative Phone No	OFFICE-96865824

Vehicle Particulars

Manufacturer	HONDA
Model	MOBILIO-1.5 RS BASIC (A)
Exact Purpose for which vehicle was being used at time of accident.	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	MOHD ROSLI BIN MOHD SURATI
NRIC No	S1474653F
Date Of Birth	05/03/1961
Occupation	INDOOR
Date Of Driving Pass	29/04/1982
Driving Experience	36 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96865824
Fax Number	
Contact Number	OFFICE-96865824
EEmail Address	MROSLI@SINGNET.COM.SG

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name JURONG EAST NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: NO. 92 BOON LAY WAY , POSTCODE: 609962 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8999999 - FAX NO: 66655791
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS ANNEX D&E POLICE REPORT NO. T/20180727/2091

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO LARGE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number CB6270B
 Vehicle Make/Model/Colour WHITE
 Details Of Properties
 Vehicle Category BUS
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Vehicle No SGV 37105

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Witnessed by Reporting Centre Personnel

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan



CP @ Ah Hood Road
near to Bk 103

Please continue to Annex E

Vehicle No SGV 32105

Annex E

Describe Circumstances of the Accident

As per police report no:

T1

Declaration

I/We declare the foregoing particulars are true in every respect.

 22/7/18

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20180727/2091

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

1 of 3

Report No. T/20180727/2091

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/07/2018 16:13		Vide Report No.:		Station Diary No.: 55	
Informant's Particulars					
Name of Informant: MOHD ROSLI BIN MOHD SURATI			Address: APT BLK 331 JURONG EAST AVENUE 1 #07-1728 SINGAPORE 600331		
ID Type / ID No.: NRIC NO / S1474653F			Contact No.:		Mobile: 96865824
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 57	Date of Birth: 05/03/1961	Type of Informant: Vehicle Owner		
Race: Malay		Language:		Institution / School Name:	
Occupation: Safety Officer		Driving Licence Information: Class: 2B,2A,3		Date of Expiry:	

General Information of the Accident					
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 27/07/2018 10:30	Type of Location: Car Park	
Location: Along Road 1 AH HOOD ROAD Block 103 Ah Hood Road Open Space Carpark, Lot 248					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic	
Type of Collision: Side Swiped				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CB6270B	Bus/Coach/Minibus				No Damage	0
SGV3210S	Car	HONDA	Mobilio	Grey	Seriously Damaged	0



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT18003200	Page	1
Registration No	: SGV32105	Date	: 31. Jul 2018	Customer No.	: WZC008
Chassis No	: MRHDD4870GP000292	Svc Advisor	:	Engine No	: L15Z12873546
Model	: MOBILIO YM 2016	Date Time	: 31. Jul 2018 9:40:41 PM	Surveyor Name	:
Owner's Name	: MOHD ROSLI BIN MOHD SURATI	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: MOHD ROSLI BIN MOHD SURATI OWNER INSURER: LIBERTY ACC DATE: 27/07/2018 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: CB6270B							
67010-TRD-T00ZZ	PANEL COMPR.FR.DOOR	1	650.00	25	487.50 ✓	34.13	521.63 ✓ D1	
67324-TRD-T01	TAPER.FR.DOOR SASH	1	30.50	25	22.87 ✓	1.60	24.47 ✓ N	
72310-TE7-K02	WEATHERSTRIPR.FR.DOOR	1	39.90	25	29.92	2.09	32.01 ✓ N	
72140-TRD-T01	HANDLE ASSYR.FR.DOOR OUTSIDE	1	64.90	25	48.67 ✓	3.41	52.08 ✓ SC	
72145-TG1-T01	CYLINDERR.DOOR	1	39.90	25	29.92 ✓	2.09	32.01 ✓ N	
93403-06012-08	BOLT WASHER 6X12	4	0.60	25	1.80 ✓	0.13	1.93 ✓ N	
72135-SDA-A01	STRIKER ASSYDOOR LOCK	1	15.10	25	11.32 ✓	0.79	12.11 ✓ N	
72120-TG2-K01ZC	HANDLE ASSYR.INSIDE	1	13.80	25	10.35 ✓	0.72	11.07 ✓ N	
72110-TG1-T01	LATCH ASSYR.FR.DOOR POWER	1	69.30	25	51.97	3.64	55.61 ✓ X2	
72335-TG4-U00	WEATHERSTRIP,R.FR.DOOR INNER	1	28.30	25	21.22	1.49	22.71 ✓ X2	
72235-TE7-K01	RUNCHANNELR.FR.DOOR	1	52.70	25	39.52	2.77	42.29 ✓ X2	
72230-TG1-T01	SASHR.FR.DOOR FR.LOWER	1	19.00	25	14.25	1.00	15.25 ✓ X2	
72211-TE7-K01	REGULATOR ASSYR.FR.DOOR	1	81.80	25	61.35	4.29	65.64 ✓ X2	
72231-TG1-T01	SASHR.FR.DOOR CENTER LOWER	1	16.00	25	12.00	0.84	12.84 ✓ X2	
72215-TE7-K01	MOTOR ASSYR.FR.WINDOW	1	110.00	25	82.50	5.78	88.28 ✓ X2	
					Sum Item	925.16	64.77	989.93
BOSUN	SUNDRIES	1	100.00 40		100.00 ✓	7.00	107.00	
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	600.00 300		600.00 ✓	42.00	642.00	
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	180.00 160		180.00 ✓	12.60	192.60	



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 Registration No : SGV3210S
 Chassis No : MRHDD4870GP000292
 Model : MOBILIO YM 2016
 Owner's Name : MOHD ROSLI BIN MOHD SURATI
 Ins Policy No. :
 Date of Accident :

Document No. : SQT18003200 Page 2
 Date : 31. Jul 2018
 Customer No. : WZC008
 Svc Advisor :
 Engine No : L15Z12873546
 Date | Time : 31. Jul 2018 9:40:41 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKDR12K	STRAIGHTEN ALIGN FR R DOOR.	1	700.00	6.50 560	700.00	49.00	749.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	600.00	5.80 450	600.00	42.00	642.00
Sum Labor					<u>2180.00</u>	<u>152.60</u>	<u>2,332.60</u>

Survey By _____
 Date & Time _____
 Excess _____
 Status _____
 Signature _____

Total Amount 3,105.16 217.37 3,322.53
 Total (Inclusive of GST) 3,322.53

NAZ LK
 7/8/18 1800
 . PIP
 4 DAYS

LKK Auto Consultants hence notify the Reparer of the following:
 • To resurvey defoliated spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Reparer
 Signature _____
 Date: _____

Printed on 1/8/2018 3:51:07 PM

This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHDD4870GP000292
License No: SGV3210S
Mileage: 27027
Engine No: L15Z12873546

Document No: SVO18046287
Printed By: ANIKKALAI
Order Date: 8. August 2018
Order Time: 8:55:45 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Includ GST
67010-TRD-T00ZZ	PANEL COMPR.FR.DOOR	1	650.00	25	487.50	34.13	521.63
67324-TRD-T01	TAPER.FR.DOOR SASH	1	30.50	25	22.87	1.60	24.47
72140-TRD-T01	HANDLE ASSYR.FR.DOOR OUTSIDE	1	64.90	25	48.67	3.41	52.08
72145-TG1-T01	CYLINDERR.DOOR	1	39.90	25	29.92	2.09	32.01
93403-06012-08	BOLT WASHER 6X12	4	0.60	25	1.80	0.13	1.93
72135-SDA-A01	STRIKER ASSYDOOR LOCK	1	15.10	25	11.32	0.79	12.11
72120-TG2-K01ZC	HANDLE ASSYR.INSIDE	1	13.80	25	10.35	0.72	11.07
	SUM PARTS:				612.43	42.87	655.30
BOSUN		1	40.00		40.00	2.80	42.80
	SUNDRIES						
BKDR12R	1438 REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST & ALIGN FR R DR.(N)	1	300.00		300.00	21.00	321.00
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	160.00		160.00	11.20	171.20
BKDR12K	1466 STRAIGHTEN ALIGN FR R DOOR.	1	560.00		560.00	39.20	599.20
BP01R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	1	450.00		450.00	31.50	481.50
	SUM LABOUR:				1,510.00	105.70	1,615.70
	TOTAL SGD				2,122.43	148.57	2,271.00

Total Payable (SGD)

2,271.00

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Aug 2018		03 Aug 2018 13:48 Edit Adj Rpt	S\$2,122.43 Edit Estimates	S\$2,122.43 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, ID: -								
Main Claimant:	MOHD ROSLI BIN MOHD SURATI								
Vehicle Reg. No.:	SGV3210S	Date of Loss:	27/07/2018 00:00 - :59 [19 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03797C02	Policy/Cover Note No.:	DMB1SN1442331703						
Vehicle Reg. No. (Insured):	CB6270B	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 15/08/2018]								
Adj Asg. Remarks:	EST \$3322.53, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGV3210S (SNM18D03797C02)
[CB6270B]
TP
MOHD ROSLI BIN MOHD SURATI
Jul 27 2018 12:00AM
[-]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/08/18 12:34	Video - Accident	Load AVI	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/08/18 23:58	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/08/18 12:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
15	19/08/18 12:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
16	19/08/18 12:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	19/08/18 12:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	19/08/18 12:43	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/08/18 13:47	REPAIR EST	Load PDF	
2	03/08/18 13:47	TP GIA	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014328/NTD3Q2
Date: 10/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMB1SN1442331703	
Claimant Vehicle No: SGV3210S	Insured Vehicle No: CB6270B	
Date of Loss: 27/07/2018	Nature of Claim: TP	Claim No: SNM18D03797C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV3210S	Engine No:	L15Z12873546
Make & Model:	HONDA MOBILIO, 1.5 RS Basic (A)	Chassis No:	MRHDD4870GP000292
Reg. Date:	16/12/2016 (Man. Year: 2016)	Odometer:	27027 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,025.16	652.43	372.73	36.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,470.00	610.00	29.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,105.16	2,122.43	982.73	31.65
+ GST 7.00/7.00% (S\$)	217.36	148.57	68.79	31.65
Nett Amount (S\$)	3,322.52	2,271.00	1,051.52	31.65

INSPECTION

Date of Assignment:	03/08/2018		
Date Inspected:	07/08/2018	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	4.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts: M1-MPV	HONDA MOBILIO 1.5 RS Basic (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGV3210S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL COMPR.FR.DOOR	Dented	487.50 FS	*487.50 FS
2	1		*TAPER.FR.DOOR SASH	Necessary	22.87 FS	*22.87 FS
3	1		*WEATHERSTRIPR.FR.DOOR	Serviceable	29.92 FS	*- FS
4	1		*HANDLE ASSYR.FR.DOOR OUTSIDE	Scratched	48.67 FS	*48.67 FS
5	1		*CYLINDERR.DOOR	Necessary	29.92 FS	*29.92 FS
6	4		*BOLT WASHER 6X12	Necessary	1.80 FS	*1.80 FS
7	1		*STRIKER ASSYDOOR LOCK	Necessary	11.32 FS	*11.32 FS
8	1		*HANDLE ASSYR.INSIDE	Necessary	10.35 FS	*10.35 FS
9	1		*LATCH ASSYR.FR.DOOR POWER	Serviceable	51.97 FS	*- FS
10	1		*WEATHERSRTIP ,R.FR.DOOR INNER	Serviceable	21.22 FS	*- FS
11	1		*RUNCHANNELR.FR.DOOR	Serviceable	39.52 FS	*- FS
12	1		*SASHR.FR.DOOR FR.LOWER	Serviceable	14.25 FS	*- FS
13	1		*REGULATOR ASSYR.FR.DOOR	Serviceable	61.35 FS	*- FS
14	1		*SASHR.FR.DOOR CENTER LOWER	Serviceable	12.00 FS	*- FS
15	1		*MOTOR ASSYR.FR.WINDOW	Serviceable	82.50 FS	*- FS
16	1		*SUNDRIES	Necessary	100.00 FS	*40.00 FS
Total Parts (S\$)					1,025.16	652.43

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & TRANSFER ITEMS TO NEW FR R DR.ADJUST	New	600.00	300.00
2	RESET & CALLIBRATE SMART ENTRY SYSTEM	New	180.00	160.00
3	STRAIGHTEN ALIGN FR R DOOR	New	700.00	560.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	600.00	450.00
Gross Labour Cost (S\$)			2,080.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >