

1/2/2018

INS. CASE OWNER:

Both

CS3 / AXA

1700

2395

U 63-2

LKK:
IDAC:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

2/2/17

Date / Time:

2/2/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFC 7860B

Name of Insured:

Ateak Hussein

Insured Tel No.:

HP:

A4508052

Excess Sec II :\$S

D.O.A.:

4/2/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

10420482

Policy No.:

GA0684611

Make / Model:

NISSAN

Place of Accident:

MUMBO AVE 1 TO GUYANA

EAST AVE 2

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SJN 6989R

INSRS:
WSP:
Tel:
Liability:
RMKS:

j-mart

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
14/2/17	Non-Reporting ltr (1st):	
14/2	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☐
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

RECEIVED 06 AUG 2018

RECEIVED 07 AUG 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$S	(days) Reduction:	%
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28. Ass. Lia:
Repair Cost:	\$S		
Loss of Rental (LOR):	\$S	(days)	
Loss of Use (LOU):	\$S	(\$ x days)	
Loss of Income (LOI):	\$S	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		[Tick only one]	
GIA/LTA Search	\$S		
Medical:	\$S		
Disbursement:	\$S	(e.g. Tow/ Independent)	
Legal Cost	\$S		
Total:	\$S	Global Sum \$S:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$S	Name 1:	
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

in charge bml
\$200 - \$100

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2017 12:16
Date Of Accident	04/02/2017 09:45
Exact Location Of Accident	ALONG ALJUNIED AVE 1 TO GEYLANG EAST AVE 2
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFC7860B
Insured/Policyholder	
Name Of Registered Owner	ALTAFF HUSSIEN
NRIC No	S2015025D
Email Address	ALTAFFHUSSIEN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94508052
Alternative Phone No	Others-94508052

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	AXA Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA068416/1
Cover Note Number	

Driver

Name of Driver	ALTAFF HUSSIEN
NRIC No	S2015025D
Date Of Birth	13/03/1952
Occupation	Outdoor
Date Of Driving Pass	23/02/1979
Driving Experience	37 Years And 11 Months
Gender	Male
Mobile Number	(Local) +65-94508052
Fax Number	
Contact Number	Others-94508052
Email Address	ALTAFFHUSSIEN@GMAIL.COM

Address	BLK 103 LENGKONG TIGA #03-383
Postcode	410103
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head on collision
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN6989R
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Accident Sketch Plan Pg.1

Describe Circumstances of the Accident

ON 04/02/2017 AT AROUND 09:45AM I WAS DRIVING ALONG ALJUNIED AVE 1 TOWARDS GEYLANG EAST AVE 2


WHEN I SAW THE TRAFFIC LIGHT WAS STILL IN MY MOVING FAVOUR, I FORWARD AHEAD TOWARD GEYLANG EAST AVE 2. AT THIS POINT, THE VEHICLE "B" SJN6989R FROM THE DIRECTION OF GEYLANG EAST CENTRAL MOVE FORWARD AS A RESULT BOTH OUR VEHICLE CAUSING A HEAD TO HEAD COLLISION.

REMARKS: OWN DAMAGED CLAIMS

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD Claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) /
Date & Time


Witnessed by Reporting Centre Personnel

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

4YA

6-Feb-17

Our ref: TP/4245/17

Ong Son Chik

RE : Estimate cost for vehicle no : SJN 6989R

1 pc	bonnet	
1 pc	headlamp rh	
1 pc	frt bumper	
1 pc	frt bumper fog lamp rh	348.45
1 pc	frt bumper fog lamp cover rh	49.11
1 pc	frt bumper chrome rh	
1 pc	frt bumper retainer rh	
1 pc	frt bumper fog lamp cover chrome rh	
10 pc	frt bumper clip	
1 pc	frt bumper reinforcement	
1 pc	frt bumper sponge	
1 pc	frt grille	439.52
1 pc	frt fender rh	775.94
1 pc	frt fender VVT-I emblem rh	
1 pc	frt fender inner shield rh	
10 pc	frt fender inner shield clip rh	
1 pc	frt fender inner garnish rh	
1 pc	frt support panel	
1 pc	frt wiper tank	
1 pc	frt wiper tank motor	
1 pc	frt door rh	
1 pc	frt door protector rh	
2 pc	frt door hinges	
1 pc	frt door protector chrome rh	
1 pc	rocker garnish rh	
1 pc	frt wheel housing rh	
1 pc	radiator spare tank	
1 pc	frt shock absorber rh	
1 pc	frt shock absorber mounting rh	
1 pc	frt knuckle arm rh	
1 pc	frt knuckle bearing rh	
1 pc	frt lower arm rh	445.61
1 pc	ABS sensor	
1 pc	frt caliper rh	
1 pc	frt disc rotor rh	
1 pc	frt disc shaft rh	
	driveshaft	1834.20

\$	1,400.50	X
\$10	1,158.00	✓
D.S	550.00	✓
Buo	475.00	✓
D.S	110.00	✓
CAR	120.00	✓
5-1	95.00	✓
\$10	120.00	✓
ner	50.00	✓
11	435.80	X
7011	148.50	✓
CAR	498.50	✓
D.S	810.00	✓
ner	48.00	✓
7011	158.00	✓
ner	50.00	✓
11	158.00	X
soften	995.00	✓
D.S	185.00	✓
Dyed	224.80	✓
AS/Ref	1,450.00	✓
ner	125.00	✓
11	190.00	X
ner	35.00	✓
waged/12	599.80	✓
11	785.00	X
11	145.00	X
Buc	435.80	✓
111	153.70	✓
bed	547.00	✓
ner	158.00	✓
Buc	600.00	✓
11	236.60	X
11	995.00	X
11	485.00	X
\$10	1,885.00	✓
	16,616.00	

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : Estimate cost for vehicle no : SJN 6989R

bal brought forward

1 pc frt cross member assembly 2447.30
1 pc steering rack & pinion 2781.90
1 pc engine dust cover

\$ 16,616.00

20/12/16 2,785.00
26/12/16 3,270.00
26/12/16 86.10
22,757.10
5,689.28
17,067.83

16563.63
12422.72

Less 25%

1 pc frt tyre rh
1 pc frt tyre rim rh

212.00

400.00 snett 60% 1205.00
400.00
60.00
1,600.00 1200
1,600.00 1200
30.00
120.00 80
120.00 100
80.00 60
450.00 350
21,927.83
1,534.95
23,462.77
3600
16022.72

Towing.
Panel beating.
Spray painting.
Wiring.
Computer Alignment.
Top-up gas.
Transfer door parts.
Undercarriage.

Plus 7% GST

SD: Twenty-Three Thousand Four Hundred Sixty-Two & Seventy-Seven Cents Only.

Not Arred

12,800/2

10 day

7/2/17

confirmed 29/1/18

Summit layer

consultants hence notify
of the following:
before/after spray painting
red part(s) during resurvey
subject to confirmation
is on a "Without Prejudice" basis
ion(s) is allowed
n(s) must be resurveyed and
proval from Insurance Company
paier

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

6-Feb-17

Our ref: TP/4245/17

Ong Son Chik

RE : Estimate cost for vehicle no : SJN 6989R

1 pc	bonnet
1 pc	headlamp rh
1 pc	frt bumper
1 pc	frt bumper fog lamp rh
1 pc	frt bumper fog lamp cover rh
1 pc	frt bumper chrome rh
1 pc	frt bumper retainer rh
1 pc	frt bumper fog lamp cover chrome rh
10 pc	frt bumper clip
1 pc	frt bumper reinforcement
1 pc	frt bumper sponge
1 pc	frt grille
1 pc	frt fender rh
1 pc	frt fender VVT-I emblem rh
1 pc	frt fender inner shield rh
10 pc	frt fender inner shield clip rh
1 pc	frt fender inner garnish rh
1 pc	frt support panel
1 pc	frt wiper tank
1 pc	frt wiper tank motor
1 pc	frt door rh
1 pc	frt door protector rh
2 pc	frt door hinges
1 pc	frt door protector chrome rh
1 pc	rocker garnish rh
1 pc	frt wheel housing rh
1 pc	radiator spare tank
1 pc	frt shock absorber rh
1 pc	frt shock absorber mounting rh
1 pc	frt knuckle arm rh
1 pc	frt knuckle bearing rh
1 pc	frt lower arm rh
1 pc	ABS sensor
1 pc	frt caliper rh
1 pc	frt disc rotor rh
1 pc	frt disc shaft rh

\$	cl	1,400.50	x
	Sno	1,158.00	✓
	D.S	550.00	✓
	Sno	475.00	✓
	D.S	110.00	✓
	cl	120.00	✓
	Sno	95.00	✓
	Sno	120.00	✓
	ren	50.00	✓
	17	435.80	x
		148.50	?
	cl	498.50	?
	D.S	810.00	✓
	ren	48.00	✓
	Torn	158.00	✓
	ren	50.00	✓
	17	158.00	x
	ren	995.00	✓
	D.S	185.00	✓
		224.80	?
	DD/Set	1,450.00	✓
	ren	125.00	✓
		190.00	x
	ren	35.00	✓
	waged/se	599.80	✓
		785.00	?
		145.00	?
	Sno	435.80	✓
		153.70	?
	cl	547.00	✓
	ren	158.00	✓
	Sno	600.00	✓
		236.60	?
	17	995.00	x
	17	485.00	x
	Sno	1,885.00	✓
		16,616.00	

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : Estimate cost for vehicle no : SJN 6989R

bal brought forward \$ 16,616.00

1 pc	frt cross member assembly	2,785.00	?
1 pc	steering rack & pinion	3,270.00	3x
1 pc	engine dust cover	86.10	
		22,757.10	
	Less 25%	5,689.28	
		17,067.83	

1 pc	frt tyre rh	400.00	snett 60% 210
1 pc	frt tyre rim rh	400.00	
Towing.		60.00	
Panel beating.		1,600.00	1200
Spray painting.		1,600.00	1200
Wiring.		30.00	
Computer Alignment.		120.00	80
Top-up gas.		120.00	100
Transfer door parts.		80.00	60
Undercarriage.		450.00	350
		21,927.83	
	Plus 7% GST	1,534.95	
		23,462.77	

SD: Twenty-Three Thousand Four Hundred Sixty-Two & Seventy-Seven Cents Only.

Not Arund
w/ku
h/c 3
10 day.
7/2/17

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2017		21 Feb 2017 15:01 Edit Adj Rpt	S\$12,800.00 Edit Estimates	S\$12,800.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ALTAFF HUSSIEEN, ID: S2015025D, Tel: +6594508052		
Main Claimant:	ONG SON CHIK, ID: S7270032E		
Vehicle Reg. No.:	SJN6989R	Date of Loss:	04/02/2017 00:00 - :59 [95 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0420482	Policy/Cover Note No.:	GA068416 (Comprehensive)
Vehicle Reg. No. (Insured):	SFC7860B	Policy No. (Claimant):	5042172417-06
		Excess:	S\$0.00
Repairer:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578, 539186 Defu Lane - Tel: 63430934		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Tan Wancong - 68804832]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/08/2018]		
Driver/Custodian (Insured):	ALTAFF HUSSIEEN (), NRIC: S2015025D, Tel: +6594508052		
Adj Asg. Remarks:	LKK APPOINTED AS SJE. PLS CONDUCT PRS.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (21/02/2017): WP/ PRI Assignment - C0420482/GA068416

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJN6989R (C0420482)**
[SFC7860B]
TP
ONG SON CHIK
Feb 4 2017 12:00AM
[ALTAF HUSSIEEN]
J-mart Motor Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
Assessment Reports					1 per page ▼ ☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/17 15:42	Adjuster Immediate Advice		Load HTM	
Documentation					1 per page ▼ ☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	20/02/17 12:27	SJN6989R TP GIA_ABS		Load PDF	
2	20/02/17 12:27	SFC7860B INS GIA_ABS		Load PDF	
3	21/02/17 15:00	[BSA Law Chambers Law] SJE-LKK		Load PDF	
4	20/07/18 17:42	GA068416-Certificate of Insurance.pdf		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/02/17 10:13	LKK INSPECTION PHOTOS		Load PDF	
2	22/02/17 10:13	LKK RE-INSPECTION PHOTOS		Load PDF	
3	09/03/17 09:16	LETTER TO OI		Load PDF	
4	07/08/18 13:08	INVOICE NO DATED 09.03.2017		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA17002395/UEA3S2-1
Date: 07/08/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: GA068416
Claimant Vehicle No : SJN6989R **Insured Vehicle No :** SFC7860B
 Date of Loss: 04/02/2017 Nature of Claim: TP Claim No: C0420482

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN6989R**
 Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 1AZE128370
 Reg. Date: 10/02/2009 (Man. Year: 2008) Chassis No: MR053BK4107041757
 Colour: Silver Odometer: 317966 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,867.82	13,007.30	4,860.52	27.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	3,080.00	980.00	24.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,927.82	16,087.30	5,840.52	26.64
Approved Total (Overridden) (\$\$)		12,800.00		
(\$\$)	21,927.82	12,800.00	9,127.82	41.63
+ GST 7.00/7.00% (\$\$)	1,534.95	896.00	638.95	41.63
Nett Amount (\$\$)	23,462.77	13,696.00	9,766.77	41.63

INSPECTION

Date of Assignment: 21/02/2017
 Date Inspected: 07/02/2017 Inspected At: J-mart Motor Pte Ltd (HQ)
 Estimated Period of Repair: 10.0 days Blk 5 Defu Lane 10, #01-578
 Singapore 539186

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2018)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN6989R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (CONSISTENT)	Repair	1,400.50 FL	*- FL
2	1		*HEADLAMP RH (CONSISTENT)	Broken	1,158.00 FL	*1,158.00 FL
3	1		*FRT BUMPER (CONSISTENT)	Distorted	550.00 FL	*550.00 FL
4	1		*FRT BUMPER FOG LAMP RH (CONSISTENT)	Broken	475.00 FL	*348.45 FL
5	1		*FRT BUMPER FOG LAMP COVER RH (CONSISTENT)	Distorted	110.00 FL	*89.11 FL
6	1		*FRT BUMPER CHROME RH (CONSISTENT)	Cracked	120.00 FL	*120.00 FL
7	1		*FRT BUMPER RETAINER RH (CONSISTENT)	Bent	95.00 FL	*95.00 FL
8	1		*FRT BUMPER FOG LAMP COVER CHROME RH (CONSISTENT)	Broken	120.00 FL	*120.00 FL
9	10		*FRT BUMPER CLIP (CONSISTENT)	Necessary	50.00 FL	*50.00 FL
10	1		*FRT BUMPER REINFORCEMENT (CONSISTENT)	Not Necessary	435.80 FL	*- FL
11	1		*FRT BUMPER SPONGE (CONSISTENT)	Torn	148.50 FL	*148.50 FL
12	1		*FRT GRILLE (CONSISTENT)	Cracked	498.50 FL	*439.52 FL
13	1		*FRT FENDER RH (CONSISTENT)	Distorted	810.00 FL	*775.94 FL
14	1		*FRT FENDER VVT-I EMBLEM RH (CONSISTENT)	Necessary	48.00 FL	*48.00 FL
15	1		*FRT FENDER INNER SHIELD RH (CONSISTENT)	Torn	158.00 FL	*158.00 FL
16	10		*FRT FENDER INNER SHIELD CLIP RH (CONSISTENT)	Necessary	50.00 FL	*50.00 FL
17	1		*FRT FENDER INNER GARNISH RH (CONSISTENT)	Not Necessary	158.00 FL	*- FL
18	1		*FRT SUPPORT PANEL (CONSISTENT)	Bent / Twisted	995.00 FL	*995.00 FL
19	1		*FRT WIPER TANK (CONSISTENT)	Distorted	185.00 FL	*185.00 FL
20	1		*FRT WIPER TANK MOTOR (CONSISTENT)	Damaged	224.80 FL	*224.80 FL
21	1		*FRT DOOR RH (CONSISTENT)	Dented / Bent	1,450.00 FL	*1,450.00 FL
22	1		*FRT DOOR PROTECTOR RH (CONSISTENT)	Necessary	125.00 FL	*125.00 FL
23	2		*FRT DOOR HINGES (CONSISTENT)	Repair	190.00 FL	*- FL
24	1		*FRT DOOR PROTECTOR CHROME RH (CONSISTENT)	Necessary	35.00 FL	*35.00 FL
25	1		*ROCKER GARNISH RH (CONSISTENT)	Warped / Deformed	599.80 FL	*599.80 FL
26	1		*FRT WHEEL HOUSING RH (CONSISTENT)	Repair	785.00 FL	*- FL
27	1		*RADIATOR SPARE TANK (CONSISTENT)	Not Necessary	145.00 FL	*- FL
28	1		*FRT SHOCK ABSORBER RH (CONSISTENT)	Buckled	435.80 FL	*435.80 FL
29	1		*FRT SHOCK ABSORBER MOUNTING RH (CONSISTENT)	Twisted	153.70 FL	*153.70 FL
30	1		*FRT KNUCKLE ARM RH (CONSISTENT)	Bent	547.00 FL	*547.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*FRT KNUCKLE BEARING RH (CONSISTENT)	Necessary	158.00 FL	*158.00 FL
32	1		*FRT LOWER ARM RH (CONSISTENT)	Buckled	600.00 FL	*445.61 FL
33	1		*ABS SENSOR (CONSISTENT)	Serviceable	236.60 FL	*- FL
34	1		*FRT CALIPER RH (CONSISTENT)	Not Necessary	995.00 FL	*- FL
35	1		*FRT DISC ROTOR RH (CONSISTENT)	Not Necessary	485.00 FL	*- FL
36	1		*FRT DRIVESHAFT RH (CONSISTENT)	Broken	1,885.00 FL	*1,834.20 FL
37	1		*FRT CROSS MEMBER ASSEMBLY (CONSISTENT)	Dented / Bent	2,785.00 FL	*2,442.30 FL
38	1		*STEERING RACK & PINION (CONSISTENT)	Bent / Jammed	3,270.00 FL	*2,781.90 FL
39	1		*ENGINE DUST COVER (CONSISTENT)	Deformed / Torn	86.10 FL	*86.10 FL
40	1		*FRT TYRE RH (LOCAL PURCHASE) (@ \$200.00 DISC 60%) (CONSISTENT)	Cut	400.00 FS	*120.00 FS
41	1		*FRT TYRE RIM RH (CONSISTENT)	Dented / Bent	400.00 FS	*400.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) 23,557.10 17,169.73

- List Item Discount on L Items 25.00/25.00% (S\$) 5,689.28 4,162.43

Total Parts (S\$) 17,867.82 13,007.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING.	New	60.00	60.00
2	PANEL BEATING.	New	1,600.00	1,200.00
3	SPRAY PAINTING.	New	1,600.00	1,200.00
4	WIRING.	New	30.00	30.00
5	COMPUTER ALIGNMENT.	New	120.00	80.00
6	TOP-UP GAS.	New	120.00	100.00
7	TRANSFER DOOR PARTS.	New	80.00	60.00
8	UNDERCARRIAGE.	New	450.00	350.00
Gross Labour Cost (S\$)			4,060.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >