

SS. REC. BY:

REF

C8/FCI18014352/Klgd3n7

Special Instruction:

Surveyor

CWS

Kevin

ASSIGNMENT (Office)

From (Person):

Serene Ler

of

FEI

Date/Time:

7/8/18 @ 2:37pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.:

SHB 8702A

Insured:

SHB 4329X

at Workshop m/s:

Premier Automotive

Tel:

654 46689

of

No. 23 Cheryi South Ave 2 #03-02

Policy No.:

Claim No.:

D18005924MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/08/2018

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement:

Date/Time:

2:37pm @ 7/8/18

Person Contacted:

Vincent

Vehicle ☒ IN ☒ OUT

Date/Time

Action/Instruction (/) Estimate

SHB 8702A - NS / INC18014281 / K/vb

DOA: 03/08/2018

SHB 4329X - NS / INC18014281 / K/vb

DOA: 3/8/2018

08/8/18 @ 2:34pm REVISSED to Serene Ler by email.

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 8702A Yr Regn: 25 Nov, 2013Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685Colour: Silver A/C: Insu~~re~~ / Std / Nil / NASp. Reading: 399401 T/Radio: Insu~~re~~ / Std / Nil / NA

Eng/No: _____

C/No: KNAH M4'4AE545/1969Gen. Cond: Good / ~~Bad~~ / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Har Kerk.

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 3/8/11 D.O.I. 7/8/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Front.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/9/11 Charged 4/5 \$1500 / 3 Rep. (led to 7576.30, 63%) FCI4/5

RECEIVED 13 SEP 2011

Date/Time, File Pass to?

☐ : Prell. Report1) 1/1/11 thru☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: 8Lump Sum / I.B./ (\$ 1500)135505028263



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014352/K1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4329X	Veh. Inspected	SHB 8702A
Policy No.		Coverage (\$)	0.00
Claim No.	D18005924MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/08/2018	Inspection Date	07/08/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005924MFSH

Date: 08 August 2018

Our Ref: CS/FCI18014352/K1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8702A

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/08/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 4,026.20 .
Revised Estimate Amount	: S\$ 1,888.60 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-08-2018	Our Ref No. D18005924MFSH
Accident Date	03-08-2018	Claim Type. Third Party
Insured Vehicle	SHB4329X	Third Party Vehicle. SHB8702A
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: NO EST. COR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 8 August 2018 2:34 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005924MFSH/1
Attachments: CSFCI18014352K1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SHB 8702A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 7 August 2018 4:28 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005924MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 7 August 2018 2:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005924MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Enquire Transaction History**Transaction History Details**

Log Date/Time:	25 Nov 2013 / 10:00:38	Receipt No.:	AACCK001-AX239-131125-000005
Asset Type:	Vehicle	Transaction Amount:	\$75,658.00
Asset ID:	SHB8702A	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131125100038289208		
Vehicle No.:	SHB8702A		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	25 Nov 2013		
Original Registration Date:	25 Nov 2013		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5451969		
Engine No.:	D4FDDH308743		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,721.00		
Minimum PARF Benefit:	\$7,332.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	25 Nov 2013 10:00:38		
COE No.:	2013112501000899M		
COE Expiry Date:	24 Nov 2021		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$63,297.00		
Lifespan Expiry Date:	24 Nov 2021		
Owner ID Type:	Company		

PREMIER TAXIS	HIRER RELIEF / SUPER RELIEF
VEHICLE NO.	SHB 8702A
CONTACT NO.	9682 4554
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7710741Z



Name
SOH TECK HUAT

Race
CHINESE
Date of birth
19-04-1977 Sex
M
Country of birth

S7710741Z



NRIC No: S7710741Z



Date of issue
19-09-2007

APT BLK 107 JALAN BUKIT MERAH #02-1826
SINGAPORE 160107
NRIC No: S7710741Z

Date: 05/05/2010

No: 6488793

NP 428A

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7710741Z**
Name

SOH TECK HUAT

Birth Date: **19 Apr 1977**
Issue Date: **28 Oct 2017**



4102752

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B Motorcycles ≤ 200 cc
Class 2A Motorcycles between 201 cc and 400 cc
Class 2 Motorcycles > 400 cc
Class 3 Motor cars with unladen weight ≤ 3000kg with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight ≤ 2500kg

EFFECTIVE DATE

07 May 1997
28 Jul 1998
21 Dec 1999
04 Dec 1999



Licence No: S7710741Z

Land Transport Authority



VOCATIONAL LICENCE

Licence No: **S7710741Z**

Name: **SOH TECK HUAT**

Issue Date: **3/4/2014**

Please visit www.lta.gov.sg to check the status of this vocational licence

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

7-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8702 A

1 pc	Front bumper <i>X repair</i>	\$ 531.00
1 pc	Front bumper emblem @ \$44.00 <i>✓ ne</i>	\$ 44.00
1 pc	Front bumper n/s side retainer @ \$16.00 <i>X see</i>	\$ 16.00
1 pc	Front bumper o/s fog lamp cover @ \$66.00 <i>X see</i>	\$ 66.00
1 pc	Front bumper o/s protector @ \$51.00 <i>X see</i>	\$ 51.00
1 pc	Front o/s fender @ \$384.00 <i>X repair</i>	\$ 384.00
1 pc	o/s mirror assy @ \$590.00 <i>Broken</i>	\$ 590.00
1 pc	Front o/s wheel cover @ \$116.00 <i>X repair</i>	\$ 116.00
		\$ 1,798.00
	Less 10%	\$ 179.80
		\$ 1,618.20

S/NETT

1 pc	Front bumper clips <i>✓ ne</i>	\$ 48.00
1 pc	Front o/s fender sticker <i>X "</i>	\$ 30.00
1 set	o/s door stickers <i>✓ ne</i>	\$ 100.00

To check wheel alignment	\$ 80.00 <i>X "</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>X "</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 850.00 <i>400</i>
To putty and spray painting on front bumper, front o/s fender, o/s mirror assy, front o/s door, o/s rocker panel garnish	\$ 1,000.00 <i>770</i>
To apply rustproofing on the repaired and replaced panels.	\$ 120.00 <i>X "</i>
	\$ 4,026.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kali 10/09
7/8/18 1600h
3 Dgs
4/5
After Repair photo

Acknowledged by Repairer
Signature:
Date:

4/5 \$1500

10/9/18
confirmed 4/5 \$1500/3h



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014352/K1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4329X	Veh. Inspected	SHB 8702A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005924MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	07/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5451969	Colour	SILVER	
Odometer	399401	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	7 mm	
L/H Front Tyre	205/65 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/08/2018	Inspection Date	07/08/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8702A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER N/S SIDE RETAINER	SERVICEABLE	16.00	-
1	FRONT BUMPER O/S FOG LAMP COVER	SERVICEABLE	66.00	-
1	FRONT BUMPER O/S PROTECTOR	SERVICEABLE	51.00	-
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	384.00	-
1	O/S MIRROR ASSY	BROKEN	590.00	590.00
1	FRONT O/S WHEEL COVER	TO REPAIR SEE LABOUR	116.00	-
	LESS 10% DISCOUNT		-179.80	-63.40
			1,618.20	570.60
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
			178.00	148.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT O/S FENDER AND FRONT O/S WHEEL COVER.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT O/S FENDER, O/S MIRROR ASSY, FRONT O/S DOOR, O/S ROCKER PANEL GARNISH.		1,000.00	770.00

Report Ref No. CS/FCI18014352/K1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			2,230.00	1,170.00
	GRAND TOTAL		4,026.20	1,888.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00

Report Ref No. CS/FCI18014352/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.