

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 13th August 2018

To : LKK

By Fax:

Attn : Mr Bryan

Tel :

VEHICLE NO : FBB 3628K

Honda CB 400

ACCIDENT DATE: 27th July 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Meter Assembly	1	1,450.00
2 Handle Bar	1	190.00
3 Head Lamp	1	580.00
4 Head Lamp Bracket	1	195.00
5 Brake Lever	1	95.00
6 Balancer Bent End	1 set	260.00
7 Front Mudguard	1	350.00
8 Fork Tube RH	1	320.00
9 Brake Disc	1	390.00
10 Radiator Assembly	1	820.00
11 Crash Bar	1	250.00
12 Clutch Cover	1	135.00
13 Yoshimura pipe	1	1,450.00
14 Front Rim	1	1,150.00
15 Rear Box	1	320.00
16 RPM Cable	1	130.00
	Sub-Total	8,085.00
	Less 10%	808.50
	Sub-Total	7,276.50

VEHICLE NO : FBB 3628K

Honda CB 400

Nett items

1	Towing fees	50.00
2	To remove & replace necessary parts, alignment etc	280.00
3	Remove & replace clutch, engine cover & top up engine oil	180.00
4	Remove & replace front fork tube, top up fork oil & replace front Rim	220.00
5	Putty & touch up necessary paint work	250.00

Sub-Total	980.00
Nett Total	8,256.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you



SG 98 MOTOR PTE LTD