

ASS. REC. BY:

REF: CS/ASML8014361/Nrd302

Special Instruction:

Surveyor: Ndz

ASSIGNMENT (Office)

From (Person): Peter Wang

of

ASM(AXA)

Date/Time:

07/08/2018

Estimated Cost:

Bill to:

 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN1944A

Insured:

at Workshop m/s

CYS Automobile

Tel:

6219 2098 / 8163010

of

28 woodlands Ind. park El # 07-17Ah Jim

Policy No:

Claim No:

88M00R3Z

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

5/8/2018

(Client's Record)

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:07am @ 7/8/18

Person Contacted:

Wee sin

Vehicle:

 IN OUT

Date/Time	Action/Instruction (✓) Estimate
	letter (✓) Estimate pending DL & Company authorization
	<u>YN1944A-X</u>
<u>7/8/18</u>	Revert thru smart claim ; Authouse repair
	Confirm with Wee sin \$ 6350.00 (L/s) @ 6 days
	Red 4377.50, 41%.

Surveyor

MAZ

REF:

AXA

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YN 1944A Yr Regn: 9 FEB 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBUCHI MIT FE83 c.c 2,977

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 584,969 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FE83BEA20472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 7.00/R16 LT

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 5 mm

L/Bal. 6 mm L/Bal. 5 mm

D.O.A. 5/8/18 D.O.I. 7/8/18

Survey held at CYS AUTOMOBILES

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NAZ, PLS SEE MY REMARKS
	RECEIVED 05 OCT 2018
	AXA OD

Date/Time, File Pass to? : Preli. Report

1) typist : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:	<u>250</u>
Transportation:	
S + RS. SI	
Photos	
Others	
TOTAL	<u>250</u>

- Add Fee:
- : Site Insp (\$ _____)
 - : Interview (\$ _____)
 - : Tech. Invs (\$ _____)
 - : Weekend (\$ _____)

Report Format: OD

Lump Sum H.B.I: (\$ 6350.00)

◀ Service Request Details

10:07
veh ✓
hui xing
~~8/2/18~~
NAZ

Claim

S8M00R3Z

Reference

None ✎

Loss Date

August 5, 2018

Request Date

August 6, 2018

Due Date

August 14, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

YN1944A

Make

MITSUBISHI

Model
FE83BE6SRDEA

Service Address

...

Primary Contact/Insured

PJI CONTRACT PTE LTD
29 WOODLANDS INDUSTRIAL PARK, E2, 757461, Singapore
65674755

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Wkshop: CYS Automotive Excess: \$500 Pending midnight investigation To survey WP

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE



SENT

8/6/18 11:17 PM

FROM

WANG Peter

SUBJECT

Pls get DL & Company authorization letter

BODY

Pls get DL & Company authorization letter



RATAN BHOSALE Pragati

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Monday, August 06, 2018 3:14 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: OUR REF: YN1944A POLICY NO: VCA/P2067333 - KINDLY ARRANGE OD SURVEY
Attachments: ESTIMATE.pdf; GIA REPORT.pdf

Categories: Pragati

Our Ref: YN1944A
Policy No: VCA/P2067333

WITHOUT PREJUDICE


Dear Sir,

ACCIDENT INVOLVING YN1944A AND SHB6333U ALONG YISHUN RING ROAD ON 05 AUGUST 2018

Attached herewith estimate and GIA report for your attention.

Kindly arrange OD survey at 38 Woodlands Industrial Park E1 #07-17 S(757700). Thanks

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD
38 Woodlands Industrial Park E1 #07-17 S(757700)
Tel: 62192098 Fax: 62192096
Email: cysauto@singnet.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18014361/Nrd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 07-08-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YN 1944A
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00R3Z	Excess (\$)	500.00
Assign From	SMARTCLAIM (PETER WANG)	Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/08/2018	Inspection Date	07/08/2018
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 07.08.2018

Survey Details:

Date of loss	07.08.2018
Date of appointment	07.08.2018
Date of survey	07.08.2018
Location of survey	CYS AUTOMOBILE

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	YN 1944A
Make and Model	MINIBUS MITSUBISHI FE83BE6SRDEA
Date of registration	09-Feb-11
Excess	\$500.00
Market Value	\$28,000.00
Parf Rebate	\$8,777.00
Nett Loss	\$19,223.00

Repair details:

Initial Estimate	\$10,727.50
------------------	-------------

Proposed/Revised repair cost:

Parts	\$4,037.50
Check items (estimate)	\$3,547.50
Labour	\$1,880.00
Total	\$9,465.00
Lump Sum(if applicable)	\$

Number of days for repair	6
---------------------------	---



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Vehicle sustained damages at front portion. Damages consistent. DL and Authorisation letter uploaded. We have not authorize repair.

Mandate:

Liability(TP)		%
Proposed repair cost		\$
Loss of use		\$ no. of days
Loss of rental		\$ no. of days
Loss of income		\$ no. of days
LTA search fees		\$
Others		\$
Proposed Total		#VALUE!

⏪ Pls authorize if there is no mechanical/brake issue

Type

🔔 Question

Message

We already received investigation update from APAC. DL & Company authorization letter received. Pls authorize if there is no mechanical/brake issue. Excess: \$500.

Reply

« YN 1944A IA UPLOADED

Type

🔔 Question

Message

Dear Peter, Please be informed IA has been uploaded. We have sent authorize repair email to the repairer on 08.08.2018. Thanks. Jannice

Reply

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, August 08, 2018 6:05 PM
To: cysauto@singnet.com.sg
Cc: SUR
Subject: YN 1944A AXA OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YN 1944A (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5667K
Vehicle Details	
Vehicle No.:	YN1944A
Vehicle to be Exported:	No
Intended De-registration Date:	08 Aug 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FE83BE6SRDEA
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	4M42A85349
Chassis No.:	FE83BEA20472
Maximum Power Output:	-
Open Market Value:	\$34,691.00
Original Registration Date:	09 Feb 2011
First Registration Date:	09 Feb 2011
Transfer Count:	0
Actual ARF Paid:	\$1,735.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$35,111.00
COE Rebate Amount:	\$8,777.00
Total Rebate Amount:	\$8,777.00

The information contained herein is correct as at 08 Aug 2018

OK

MV 28K.

FREE VALUATION
 Let us tell you how much your car can sell for!
 No obligations and it's FREE!

How much is my car worth?

Mitsubishi FE83 Price Range Depreciation 2011 Vehicle Type

Advanced Search

Home » Used Cars » Hong Yun Auto Trading » Mitsubishi Fuso Canter FE83

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



Fancy Yellow Diamond 3.02ct. VS1 (GIA)
 (2) Diamonds 1.02ct.tw Internally Flawless Color: E (2 GIA Certificate)



Center Cushion Diamond 6.02ct. VS1 - Colour: H (GIA Certificate)

JEWELLERY PUBLIC AUCTION

SEIZED ASSETS OVER 900 ITEMS
Saturday, 11th August
 Preview: 11:00am
 Auction: 1pm - 5pm
Mandarin Orchard Hotel
 333 Orchard Rd.
 SINGAPORE



Click For More INFORMATION

Mitsubishi Fuso Canter FE83

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$33,800
Depreciation	\$10,810 /yr <small>View models with similar depreciation</small>
Reg Date	23-Sep-2011 <small>(3yrs 1mth 14days COE left)</small>
Manufactured	2011
Mileage	-
Transmission	Manual
Engine Cap	2,977 cc
Curb Weight	2,440 kg
Fuel type	Diesel
Features	-
Accessories	-
COE	\$34,009
OMV	\$33,002
ARF	\$1,651
Dereg Value	\$10,631 as of today (change)
No. of Owners	3
Type of Veh	Truck
Category	Premium Ad Car
Availability	Available

Add to Shortlist Add to Compare Add a Note

Posted on: 27-Jun-2018 | Last Updated on: 27-Jul-2018

Tags: Mitsubishi Fuso, 2011 Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi

Upfront Payment

Transfer Fee	\$25	<small>more Financial Info</small>
Down Payment	\$3,380 (change)	<small>Maximum Show Case</small>
1st Instalment	\$908	
Total Upfront Payment	\$4,313 (excluding insurance)	

Estimates based on 90% loan at 3.4% interest rate. Check with seller for exact figure.



Seller's Information

Company: Hong Yun Auto Trading
 + 65 6338 1111
 + 10 years since 2008 established

Address: 112 Woodlands Industrial Park E3
 Search cars near by this location

Phone No: 63626939

Contact Person: Ong Poh Kwee View profile

Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally.

Find out the market value for your car. Get a free Car Valuation.

[View Valuation](#)

Recommended for you

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2018 13:53
Date Of Accident	05/08/2018 23:30
Exact Location Of Accident	ALONG YISHUN RING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN1944A
Insured/Policyholder	
Name Of Registered Owner	PJI CONTRACT PTE LTD
Co Reg No	199705667K
Email Address	PYIMOE@PJICON.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62679750

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FE83BE6SRDEA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P2067333
Cover Note Number	

Driver

Name of Driver	BOOMINATHAN KAMALAHASAN
Passport No/FIN	G2316830N
Date Of Birth	10/05/1993
Occupation	OUTDOOR
Date Of Driving Pass	19/06/2014
Driving Experience	4 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81827645
Fax Number	
Contact Number	
Email Address	NOEMAIL

Nature Of Damage


No. Of Passenger (Including Driver)

SKETCH PLAN

Yishun Ring Road

A = YN1944A

B = SHB6333M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the ABOVE mention DATE & time. I WAS travelling straight along Yishun Ring Road, vehicle B in front of me suddenly stopped. He did not signal his intention at all. I couldn't stop in time and collided onto the REAR portion of the taxi.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Yvonne Toh
 NRIC/FIN No.:



redefining / insurance



AXA INSURANCE SINGAPORE PTE LTD
☎ 1800-880 4888 (Within Singapore)
(65) 6880 4888 (International)
☎ (65) 6338 2522
🌐 www.axa.com.sg

Letter of Authorisation for Lump Sum Repair

1. I, [Name] [NRIC] PJI Contract Pte Ltd, the owner of vehicle [no.] YN1944A. ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorisation for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Singapore Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorised.

Signed and acknowledged by:



B. [Signature]

Signature of policyholder

Date:

[Signature]



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East 1
#07-17 Admiralty Industrial Park
Singapore 757700
Tel: 6219 2098 (3lines) Fax: 6219 2096

Name and signature of workshop personnel including workshop stamp

Date:



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR AXA INSURANCE SINGAPORE PTE LTD POLICY NO : VCA/P2067333
 8 SHENTON WAY #27-01 OUR REF : OD 2922
 AXA TOWER , (S) 068811 VECHICLE NO : YM 1944 A
 ATTN: MOTOR CLAIMS DEPT. MAKE/MODEL : MIT FE83
 DATE OF ACCIDENT : 05.08.18

SURVEY BY

DATE : 06.08.18

1 PC FRONT WINDSCREEN GLASS RUBBER			S\$	220.00	/arc
1 PC FRONT PANEL				600.00	/DT
1 PC FRONT CORNER PANEL RH				250.00	/DT
1 PC FRONT CORNER PANEL RUBBER RH				50.00	/BT
1 PC FRONT GRILLE				320.00	/CRK
1 PC FRONT GRILLE EMBLEM				45.00	/SCR
1 PC FRONT GRILLE "FUSO" EMBLEM				75.00	/SCR
1 PC SIGNAL LAMP RH				150.00	/CRK
1 PC SIDE LAMP RH				90.00	/CRK
1 PC HEADLAMP ASSY RH				360.00	/CRK
1 PC HEADLAMP INNER RUBBER RH				25.00	X SUC
1 PC FRONT BUMPER				550.00	/DT
2 PCS FRONT BUMPER BRACKET	100.00			200.00	/BT
3 PCS BRAKE HOSE	80.00			240.00	X SUC
2 PCS HEATER HOSE	65.00			130.00	X SUC
1 PC AIR-CON ALUMINIUM PIPE				75.00	/BT
1 PC AIR-CON UNIT PIPE				135.00	/BT
1 PC HORN				110.00	X SUC
1 PC CABIN MOUNTING				375.00	X SUC
1 PC CABIN BRACKET				160.00	X SUC
1 PC AIR-CON COLLING COIL				1,600.00	X CRK
2 PCS FRONT DOOR HINGES	110.00			220.00	/BTX NNΔ
1 PC FRONT DOOR PILLAR RH				750.00	X SUC
1 PC FRONT DOOR STEP GARNISH RH				320.00	/scr photo Δ
			S\$	7,050.00	
		PLUS 15%		1,057.50	
			S\$	8,107.50	
1 PC FRONT NUMBER PLATE			S\$	45.00	S/NETT /CRK
1 SET FRONT GRILLE CLIPS				25.00	/arc
			S\$	70.00	

----- P/G 2



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd


ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1	SS	8,107.50
TO REMOVE AND REFIX FRONT WINDSCREEN GLASS	SS	420.00 <i>XANT 50</i>
TO DISMANTLE AND REFIX DASHBOARD		300.00 <i>XANT 100 200</i>
TO REMOVE AIR-CON CONDENSER,PIPE,DRIER AND TOP-UP AIR-CON GAS		120.00 <i>✓ 40 80 90</i>
TO DISMANTLE AND REFIX COOLING COIL		150.00 <i>✓ 50 100</i>
TO CHECK WIRING FUNCTION		30.00 <i>✓</i>
SPRAY PAINTING CHARGES		1,000.00 <i>800</i>
LABOUR CHARGES		900.00 <i>800</i>
	<u>SS</u>	<u>10,727.50</u>

SIN DOLLARS: TEN THOUSAND SEVEN HUNDRED TWENTY-SEVEN AND CENTS FIFTY ONLY

YOUR FAITHFULLY,



 CYS AUTOMOBILE SERVICES PTE LTD

*NAZ CEC
 7/8/18 1645
 6 Days
 L/S*


6/9/18

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

10797.50



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR AXA INSURANCE SINGAPORE PTE LTD POLICY NO : VCA/P2067333
 8 SHENTON WAY #27-01 OUR REF : QD 2922
 AXA TOWER, (S) 068811 VEHICLE NO : YN1 1944 A
 ATTN: MOTOR CLAIMS DEPT. MAKE/MODEL : MIT FE83
 DATE OF ACCIDENT : 05.08.18

SURVEY BY

DATE : 06.08.18

- 1 PC FRONT WINDSCREEN GLASS RUBBER
- 1 PC FRONT PANEL
- 1 PC FRONT CORNER PANEL RH
- 1 PC FRONT CORNER PANEL RUBBER RH
- 1 PC FRONT GRILLE
- 1 PC FRONT GRILLE EMBLEM
- 1 PC FRONT GRILLE "FUSO" EMBLEM
- 1 PC SIGNAL LAMP RH
- 1 PC SIDE LAMP RH
- 1 PC HEADLAMP ASSY RH
- 1 PC HEADLAMP INNER RUBBER RH
- 1 PC FRONT BUMPER
- 2 PCS FRONT BUMPER BRACKET
- 3 PCS BRAKE HOSE
- 2 PCS HEATER HOSE
- 1 PC AIR-CON ALUMINIUM PIPE
- 1 PC AIR-CON UNIT PIPE
- 1 PC HORN
- 1 PC CABIN MOUNTING
- 1 PC CABIN BRACKET
- 1 PC AIR-CON COLLING COIL
- 2 PCS FRONT DOOR HINGES
- 1 PC FRONT DOOR PILLAR RH
- 1 PC FRONT DOOR STEP GARNISH RH

5260.00
 6049.00

100.00
 80.00
 65.00

110.00

PLUS 15%

S\$	220.00	/acc
	600.00	/DT
	250.00	/DT
	50.00	/BT
	320.00	/CRIC
	45.00	/SCR
	75.00	/scr
	150.00	/CRK
	90.00	/CRK
	360.00	/CRK
	25.00	? X
	550.00	/DT
	200.00	/BT
	240.00	? X
	130.00	? X
	75.00	? BT
	135.00	? BT
	440.00	? X
	375.00	? X
	460.00	? X
	1,600.00	? CRK
	220.00	/BT
	750.00	SVL
	320.00	/scr
S\$	7,050.00	
	1,057.50	
S\$	8,107.50	

- 1 PC FRONT NUMBER PLATE
- 1 SET FRONT GRILLE CLIPS

70.00

S\$	45.00	S/NETT /scr
	25.00	/acc
S\$	70.00	

PIG 2




進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd
 ROC Reg. No :A05041/2001E GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1		S\$ 8,107.50
TO REMOVE AND REFIX FRONT WINDSCREEN GLASS		S\$ 420.00 <i>XANT 80</i>
TO DISMANTLE AND REFIX DASHBOARD		300.00 <i>XANT 150 200</i>
TO REMOVE AIR-CON CONDENSER,PIPE,DRIER AND TOP-UP AIR-CON GAS		120.00 ? /
TO DISMANTLE AND REFIX COOLING COIL		150.00 ? /
TO CHECK WIRING FUNCTION		30.00 /
SPRAY PAINTING CHARGES	2100.00	1,000.00 <i>800</i>
LABOUR CHARGES		900.00 <i>800</i>
	<u>28299.00</u>	<u>S\$ 10,727.50</u>

SIN DOLLARS: TEN THOUSAND SEVEN HUNDRED TWENTY-SEVEN AND CENTS FIFTY ONLY

YOUR FAITHFULLY



 CYS AUTOMOBILE SERVICES PTE LTD

NAZ LEC
 71818 1645
 6 PMJ
 L/S
 AFTER REPAIR PHOTO

LC = \$66.50



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR AXA INSURANCE SINGAPORE PTE LTD POLICY NO : VCA/P2067333
 8 SHENTON WAY #27-01 OUR REF : OD 2922
 AXA TOWER , (S) 068811 VECHICLE NO : YN1 1944 A
 ATTN: MOTOR CLAIMS DEPT. MAKE/MODEL : MIT FE83
 DATE OF ACCIDENT : 05.08.18

SURVEY BY

DATE : 06.08.18

1 PC FRONT WINDSCREEN GLASS RUBBER		S\$	220.00	/ALC
1 PC FRONT PANEL			600.00	/DT
1 PC FRONT CORNER PANEL RH			250.00	/DT
1 PC FRONT CORNER PANEL RUBBER RH			50.00	/BT
1 PC FRONT GRILLE			320.00	/CRK
1 PC FRONT GRILLE EMBLEM			45.00	/SCR
1 PC FRONT GRILLE "FUSO" EMBLEM			75.00	/SCR
1 PC SIGNAL LAMP RH			150.00	/CRK
1 PC SIDE LAMP RH			90.00	/CRK
1 PC HEADLAMP ASSY RH			360.00	/CRK
1 PC HEADLAMP INNER RUBBER RH			25.00	? X
1 PC FRONT BUMPER			550.00	/DT
2 PCS FRONT BUMPER BRACKET	100.00		200.00	/BT
3 PCS BRAKE HOSE	80.00		240.00	? X
2 PCS HEATER HOSE	65.00		130.00	? X
1 PC AIR-CON ALUMINIUM PIPE			75.00	? BT
1 PC AIR-CON UNIT PIPE			135.00	? BT
1 PC HORN			110.00	? X
1 PC CABIN MOUNTING			375.00	? X
1 PC CABIN BRACKET			160.00	? X
1 PC AIR-CON COLLING COIL			1,600.00	? CRAI
2 PCS FRONT DOOR HINGES	110.00		220.00	/BT
1 PC FRONT DOOR PILLAR RH			750.00	X SVL
1 PC FRONT DOOR STEP GARNISH RH			320.00	/SCR
		S\$	7,050.00	
	PLUS 15%		1,057.50	
		S\$	8,107.50	
1 PC FRONT NUMBER PLATE		S\$	45.00	S/NETT /CRK
1 SET FRONT GRILLE CLIPS			25.00	/ALC
		S\$	70.00	

----- P/G 2



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd


ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1	S\$ 8,107.50
TO REMOVE AND REFIX FRONT WINDSCREEN GLASS	S\$ 420.00 <i>X 1111 80</i>
TO DISMANTLE AND REFIX DASHBOARD	300.00 <i>X 1111 100 200</i>
TO REMOVE AIR-CON CONDENSER,PIPE,DRIER AND TOP-UP AIR-CON GAS	120.00 ? /
TO DISMANTLE AND REFIX COOLING COIL	150.00 ? /
TO CHECK WIRING FUNCTION	30.00 /
SPRAY PAINTING CHARGES	1,000.00 <i>800</i>
LABOUR CHARGES	900.00 <i>800</i>
	<u>S\$ 10,727.50</u>

SIN DOLLARS: TEN THOUSAND SEVEN HUNDRED TWENTY-SEVEN AND CENTS FIFTY ONLY

YOUR FAITHFULLY,



CYS AUTOMOBILE SERVICES PTE LTD

NAZ LK
 7/18/18 1645
 6 PM
 L/S
 AFTER BEFORE PHOTO



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

TAX INVOICE

Invoice No **7620**

M/S AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPT.

POLICY NO : VCA/P2067333
OUR REF : OD 2922
VEHICLE NO : YM 1944 A
MAKE/MODEL : MIT FE83
DATE OF ACCIDENT : 05-Aug-18
DATE : 05-Oct-18


SURVEY BY

TO AGREE AT THE SUM AT

	S\$	6,350.00
LESS EXCESS		500.00
	S\$	5,850.00
GST 7%		409.50
	S\$	<u>6,259.50</u>

SIN DOLLARS: SIX THOUSAND TWO HUNDRED FIFTY-NINE AND CENTS FIFTY ONLY

YOURS FAITHFULLY,


FOR CYS AUTOMOBILE SERVICES PTE LTD

Claim No.

To:

Date: 15. 8. 18

Satisfaction & Discharge Voucher

I/We hereby declare that the repairs to my/our

..... No. YN1944A have been

completed to my/our satisfaction and I/We agree that the payment of the account

of \$ 6259.50 (Dollars Six Thousand Two Hundred

Fifty-Nine And Cents Fifty Only

paid to **CYS Automobile Services Pte Ltd**

for such repair are in full discharge of my/our claim under Policy

No. VCA/P 2067333 in respect of the damages caused in the

accident which occurred on the 5 day of August 2018

x B. [Signature] 
Signature of Assured

NAME: [Signature]

NRIC No.  進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ADDRESS: 38 Woodlands Industrial Park East 1
#07-17 Admiralty Industrial Park
Singapore 757700
Tel: 6219 2088 (3lines) Fax: 6219 2086

Janice Lee (LKKAuto)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Friday, October 05, 2018 5:16 PM
To: Janice Lee (LKKAuto)
Subject: RE: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - TAX INV & DV
Attachments: TAX INV.jpg; DV.jpg

Dear Ms Janice Lee,

WITHOUT PREJUDICE

Attached herewith Tax Invoice and DV for your attention. Kindly let us have your respective cheque made in favour of "CYS AUTOMOBILE SERVICES PTE LTD" without delay. Thanks

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD
38 Woodlands Industrial Park E1 #07-17 S(757700)
Tel: 62192098 Fax: 62192096
Email: cysauto@singnet.com.sg

From: Janice Lee

(LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Friday, October 05, 2018 3:39 PM
To: CYSAUTO <cysauto@singnet.com.sg>
Subject: RE: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - FINALISATION

Dear Wee Sin,

Confirm L/S \$6,350 @ 6 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO [mailto:cysauto@singnet.com.sg]
Sent: Friday, October 05, 2018 3:08 PM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Subject: RE: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - FINALISATION
Importance: High

Dear Ms Janice Lee,

WITHOUT PREJUDICE

Refer, tele-conversation between Mr Simon and Mr Lim a moment ago.

Dismantle and top-up air-con gas	\$ 90
Dismantle and refix cooling coil	\$ 100

Therefore, we have re-calculate the repair cost at \$6,350 based on lump sum.

Kindly confirm. thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Janice Lee

(LKKAuto) [<mailto:JaniceLee@lkkauto.com>]

Sent: Friday, October 05, 2018 12:15 PM

To: CYSAUTO <cysauto@singnet.com.sg>

Subject: RE: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - AUTHORISATION FOR LUMP SUM REPAIR

Dear Wee Sin,

Kindly confirm L/S \$6,250.00 @ 6 DAYS

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO [<mailto:cysauto@singnet.com.sg>]

Sent: Friday, October 05, 2018 11:51 AM

To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Subject: FW: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - AUTHORISATION FOR LUMP SUM REPAIR


Importance: High

Dear Ms Janice Lee,

WITHOUT PREJUDICE

As per requested. Thanks

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: CYSAUTO

[<mailto:cysauto@singnet.com.sg>]

Sent: Wednesday, August 08, 2018 12:59 PM

To: 'Janice Lee (LKKAuto)' <JaniceLee@lkkauto.com>

Subject: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - KINDLY AUTHORIZE REPAIR

Importance: High

Dear Ms Janice Lee,

WITHOUT PREJUDICE

Attached herewith Authorization Letter and driver's License for your attention.

Kindly check and authorize repair. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Janice Lee

(LKKAuto) [<mailto:JaniceLee@lkkauto.com>]

Sent: Wednesday, August 08, 2018 12:34 PM

To: cysauto@singnet.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: YL 1944A AXA

Dear Hui Xin,

As spoken, Kindly get a copy of driving license and company authorization letter.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lèe (LKKAuto)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Tuesday, September 04, 2018 4:37 PM
To: Janice Lee (LKKAuto); naz@lkkauto.com.sg
Subject: FW: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - FINALISATION & PHOTOS FOR YN1944A
Attachments: FINALISATION.pdf; AFTER REPAIR PHOTO 1.jpg; AFTER REPAIR PHOTO 2.jpg; AFTER REPAIR PHOTO 3.jpg
Importance: High

Dear Mr Naz,

WITHOUT PREJUDICE

Attached herewith estimate and after repair photos for your attention.

We have calculate the repair cost at \$6,650 based on lump sum.

Kindly confirm. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD
38 Woodlands Industrial Park E1 #07-17 S(757700)
Tel: 62192098 Fax: 62192096
Email: cysauto@singnet.com.sg

From: CYSAUTO

[mailto:cysauto@singnet.com.sg]

Sent: Wednesday, August 08, 2018 12:59 PM

To: 'Janice Lee (LKKAuto)' <JaniceLee@lkkauto.com>

Subject: OUR REF: YN1944A AXA POLICY NO: VCA/P2067333 - KINDLY AUTHORIZE REPAIR

Importance: High

Dear Ms Janice Lee,

WITHOUT PREJUDICE

Attached herewith Authorization Letter and driver's License for your attention.

Kindly check and authorize repair. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Janice Lee

(LKKAuto) [<mailto:JaniceLee@lkkauto.com>]

Sent: Wednesday, August 08, 2018 12:34 PM

To: cysauto@singnet.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: YL 1944A AXA

Dear Hui Xin,

As spoken, Kindly get a copy of driving license and company authorization letter.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18014361/Nrd3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 09-10-2018	
ATTN : PETER WANG		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	YN 1944A
Policy No.	VCA/P2067333	Coverage (\$)	0.00
Claim No.	S8M00R3Z	Excess (\$)	500.00
Assign From	PETER WANG	Assign Date	07/08/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI FE83BE6SRDEA	c.c	2977
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	FE83BEA20472	Colour	WHITE
Odometer	584969	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	7.00 R16LT	BRIDGESTONE	6 mm
L/H Front Tyre	7.00 R16LT	BRIDGESTONE	6 mm
R/H Rear Tyre	7.00 R16LT	BRIDGESTONE	5 mm
L/H Rear Tyre	7.00 R16LT	BRIDGESTONE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/08/2018	Inspection Date	07/08/2018
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700		
5a. Remarks			
A)THE MARKET VALUE IS S\$28,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 1944A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN GLASS RUBBER (CONSISTENT)	NECESSARY	220.00	220.00
1	FRONT PANEL (CONSISTENT)	DENTED	600.00	600.00
1	FRONT CORNER PANEL RH (CONSISTENT)	DENTED	250.00	250.00
1	FRONT CORNER PANEL RUBBER RH (CONSISTENT)	BENT	50.00	50.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	320.00	320.00
1	FRONT GRILLE EMBLEM (CONSISTENT)	SCRATCHED	45.00	45.00
1	FRONT GRILLE "FUSO" EMBLEM (CONSISTENT)	SCRATCHED	75.00	75.00
1	SIGNAL LAMP RH (CONSISTENT)	CRACKED	150.00	150.00
1	SIDE LAMP RH (CONSISTENT)	CRACKED	90.00	90.00
1	HEADLAMP ASSY RH (CONSISTENT)	CRACKED	360.00	360.00
1	HEADLAMP INNER RUBBER RH (CONSISTENT)	SERVICEABLE	25.00	-
1	FRONT BUMPER (CONSISTENT)	DENTED	550.00	550.00
2	FRONT BUMPER BRACKET @\$100.00 (CONSISTENT)	BENT	200.00	200.00
3	BRAKE HOSE @\$80.00 (CONSISTENT)	SERVICEABLE	240.00	-
2	HEATER HOSE @\$65.00 (CONSISTENT)	SERVICEABLE	130.00	-
1	AIR-CON ALUMINIUM PIPE (CONSISTENT)	BENT	75.00	75.00
1	AIR-CON UNIT PIPE (CONSISTENT)	BENT	135.00	135.00
1	HORN (CONSISTENT)	SERVICEABLE	110.00	-
1	CABIN MOUNTING (CONSISTENT)	SERVICEABLE	375.00	-
1	CABIN BRACKET (CONSISTENT)	SERVICEABLE	160.00	-
1	AIR-CON COLLING COIL (CONSISTENT)	CRACKED	1,600.00	1,600.00
2	FRONT DOOR HINGES @\$110.00 (CONSISTENT)	NOT NECESSARY	220.00	-
1	FRONT DOOR PILLAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	750.00	-
1	FRONT DOOR STEP GARNISH RH (CONSISTENT)	SCRATCHED	320.00	320.00
	COST PLUS 15%		1,057.50	756.00
			8,107.50	5,796.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	CRACKED	45.00	45.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT GRILLE CLIPS (SN) (CONSISTENT)	NECESSARY	25.00	25.00
			70.00	70.00
	LABOUR			
	TO REMOVE AND REFIX FRONT WINDSCREEN GLASS.		120.00	50.00
	TO DISMANTLE AND REFIX DASHBOARD.		300.00	200.00
	TO REMOVE AIR-CON CONDENSER, PIPE, DRIER AND TOP-UP AIR-CON GAS.		120.00	90.00
	TO DISMANTLE AND REFIX COOLING COIL.		150.00	100.00
	TO CHECK WIRING FUNCTION.		30.00	30.00
	SPRAY PAINTING CHARGES.		1,000.00	800.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR RH.		900.00	800.00
			2,620.00	2,070.00
	GRAND TOTAL		10,797.50	7,936.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,350.00
	LESS EXCESS			-500.00
	NETT LIABILITY			5,850.00

Report Ref No. CS/ASM18014361/Nrd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.