

GT 1

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

6-Aug-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8957 G

1 pc	Bootlid emblem	— <i>nc</i>	\$ 27.00	
1 pc	Bootlid CRDi	— <i>nc</i>	\$ 29.00	
1 pc	End panel	X <i>repair</i>	\$ 250.00	
1 pc	End panel garnish	✓ <i>on</i>	\$ 74.00	
1 pc	Rear bumper	— <i>Paint</i>	\$ 696.00	
1 pc	Rear bumper lower cover	— <i>ca</i>	\$ 206.00	
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	✓ <i>on</i>	\$ 58.00	
1 pc	Rear bumper inner sponge	— <i>ton</i>	\$ 114.00	
1 pc	Rear bumper reinforcement	— <i>ca</i>	\$ 607.00	
2 pcs	Rear bumper stay n/s & o/s @ \$53.00	✓ <i>Best</i>	\$ 106.00	
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	✓ <i>on</i>	\$ 36.00	
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	✓ <i>on</i>	\$ 36.00	
2 pcs	Rear o/s & n/s bumper reflector @ \$46.00	X <i>on</i>	\$ 92.00	
			\$ 2,331.00	
			Less 10%	\$ 233.10
			\$ 2,097.90	

### S/NETT

1 set	End panel inner garnish clips	X <i>nc</i>	\$ 20.00
1 set	Bootlid stickers	— <i>nc</i>	\$ 100.00
1 set	Reverse sensor	— <i>shaded</i>	\$ 200.00
Sundry			\$ 50.00 <i>20</i>
To dismantle / replace reverse sensor to new bumper and reset to the same			\$ 80.00 <i>30</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$ 60.00 <i>20</i>
To labour charge for dismantle and renew the accident damaged parts. To heat/weld cut-off the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, bootlid, etc			\$ 600.00
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, floorboard compartment			\$ 720.00
To apply rustproofing on the repaired and replaced panels.			\$ 1,100.00
			\$ 200.00 <i>20</i>
			\$ 4,757.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Final survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: *Kulir Udey*  
Date: *6/8/18*

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

10/9/18  
Grand total 4757.90 / 4757.90